This electronic collection of documents is provided for the convenience of the user and is Not a Certified Document –

The documents contained herein were originally issued and sealed by the individuals whose names and license numbers appear on each page, on the dates appearing with their signature on that page.

This file or an individual page shall not be considered a certified document.



STATE OF NORTH CAROLINA DIVISION OF HIGHWAYS

BERTIE COUNTY


LOCATION: BERTIE COUNTY:

BRIDGE #7 ON NC 45 ACROSS ROANOKE, MIDDLE AND CASHIE RIVERS


BETWEEN PLYMOUTH AND MERRY HILL

TYPE OF WORK: BRIDGE PRESERVATION WITH CONCRETE SUPERSTRUCTURE & SUBSTRUCTURE REPAIR,

PILE ENCAPSULATION AND FENDER REPLACEMENT.



VICINITY MAP - BERTIE CO.



DESIGN DATA

BERTIE COUNTY

BRIDGE #7 ADT 2012 = 410

PROJECT LENGTH

BERTIE COUNTY
#7 = 1.11 MILE

Prepared in the Office of:

DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS

STRUCTURES MANAGEMENT UNIT – PRESERVATION & REPAIR GROUP 1000 BIRCH RIDGE DR. RALEIGH, N.C. 27610

ERIC B. NELSON, P.E.

PROJECT ENGINEER


2012 STANDARD SPECIFICATIONS

I ETTING DATE.

LETTING DATE: JULY 19, 2017



GREGORY W. DICKEY, P.E.
PROJECT DESIGN ENGINEER



STATE OF NORTH CAROLINA DIVISION OF HIGHWAYS

BERTIE COUNTY

B-5941 46480.1.1 P.E. CONSTR. 46480.3.1


BERTIE COUNTY: LOCATION:

BRIDGE #7 OVER ROANOKE, MIDDLE AND CASHIE RIVERS BETWEEN PLYMOUTH AND MERRY HILL

BRIDGE PRESERVATION WITH CONCRETE SUPERSTRUCTURE & SUBSTRUCTURE REPAIR, PILE ENCAPSULATION AND FENDER REPLACEMENT. TYPE OF WORK:

INDEX OF SHEETS

1	TITLE SHEET
<i>1A</i>	INDEX OF SHEETS
S-1	BILL OF MATERIAL
S-2 THRU S-108	STRUCTURAL PLANS - BERTIE #7
F1 THRU F5	FENDER SYSTEM
<i>SN</i>	STANDARD NOTES



© BT 19 Z	© BT 20 <u> </u>	© BT	© BT 22 Z	© BT 23 	© BT 24 Z-	© BT 25 Z	© BT 26 Z	© BT 27 	© BT 28 Z	© BT 29 Z	© BT	© BT 31 	© BT	© BT	© BT 34	© BT 35 Z	© BT 36 Z	© BT 37 Z	© BT	© BT 39 Z	© BT 40 Z
ĺ																					
	60'-0" SPAN 20	60'-0" SPAN 21	60'-0" SPAN 22	60'-0" SPAN 23	60'-0" SPAN 24	60'-0" SPAN 25	60'-0" SPAN 26	60'-0" SPAN 27	60'-0" SPAN 28	60'-0" SPAN 29	60'-0"	60'-0"	60'-0" SPAN 32	60'-0" SPAN 33	60'-0" SPAN 34	60'-0" SPAN 35	60'-0" SPAN 36	60'-0" SPAN 37	60'-0"	60'-0" SPAN 39	60'-0" SPAN 40

© BT 40 Z	© BT 41 Z	© BT 42 <u>Z</u>	© BT 43 Z	© BT	€ BT 45 <u>Z</u>	© BT 46 Z	© BT 47 Z	© BT 48 <u>Z</u>	© BT 49 Z	© BT 50 Z	© BT 51 <u>Z</u>	© BT 52 Z	© BT 53∠	© BT 54 <u>Z</u>	© BT 55∠	€ BT 56 <u></u>	© BT 57 Z	© BT 58 Z	€ BT 59 <u>Z</u>	© BT 60 Z	© BT 61 <u>Z</u>
								į									ļ				
	60′-0″	60'-0"	60'-0"	60'-0"	60'-0"	60'-0"	60′-0″	60'-0"	60'-0"	60'-0"	60′-0″	60'-0"	60′-0″	60'-0"	60'-0"	60′-0″	60'-0"	60′-0″	60'-0"	60'-0"	60'-0"
l 	SPAN 41	SPAN 42	SPAN 43	SPAN 44	SPAN 45	SPAN 46	SPAN 47	SPAN 48	SPAN 49	SPAN 50	SPAN 51	SPAN 52	SPAN 53	SPAN 54	SPAN 55	SPAN 56	SPAN 57	SPAN 58	SPAN 59	SPAN 60	SPAN 61

© BT 61 Z-	© BT	© BT 63_	© BT 64 ;	€ BT 65 ;	© BT 66 Z	© BT 67 Z	© BT 68 <u></u>	© BT 69 Z	© BT 70 <u></u>	© BT 71 Z	© BT 72 Z	© BT 73 Z	© BT 74 Z	© BT 75 <u>Z</u>	© BT 76 Z	© BT 77 Z	© BT	© BT 79 	© BT 80 Z	© BT 81 Z	© BT 82 Z
																	ļ				
	60'-0"	60′-0″	60'-0"	60′-0″	60'-0"	60′-0″	60′-0″	60′-0″	60′-0″	60'-0"	60′-0″	60′-0″	60′-0″	60′-0″	60′-0″	60′-0″	60'-0"	60'-0"	60′-0″	60′-0″	60'-0"
F	SPAN 62	SPAN 63	SPAN 64	SPAN 65	SPAN 66	SPAN 67	SPAN 68	SPAN 69	SPAN 70	SPAN 71	SPAN 72	SPAN 73	SPAN 74	SPAN 75	SPAN 76	SPAN 77	SPAN 78	SPAN 79	SPAN 80	SPAN 81	SPAN 82

© BT 82 Z	© BT 83 	© BT 84∠	© BT 85 -	€ BT 86 Z	€ BT 87 :	€ BT 88 :	© BT 89 Z	€вт ⁹⁰ ∠	© BT 91 <u>Z</u>	© BT 92 Z	© BT 93 Z	€ BT 94 :	, -	FF EB#2
														! !
	60'-0" SPAN 83	60'-0" SPAN 84	60'-0" SPAN 85	60'-0" SPAN 86	60'-0" SPAN 87	60'-0" SPAN 88	60'-0" SPAN 89	60'-0" SPAN 90	60'-0" SPAN 91	60'-0" SPAN 92	60'-0" SPAN 93	60'-0" SPAN 94	60'-8" SPAN 95	
												44	41' - 4" TO F.F.	-

BERTIE COUNTY

BRIDGE NO.

PROJECT NO.____

SHEET 1 OF 2

SCOPE OF WORK:

- REMOVE AND REPAIR UNSOUND CONCRETE ON DECK.
- REMOVE AND REPLACE DAMAGED BRIDGE DECK JOINTS WITH NEW SILICONE JOINT SEALS.
- SHOTCRETE, GIRDER AND EPOXY COATING SUPERSTRUCTURE REPAIRS.
- CLEAN AND PAINT BEARINGS WITH HRCSA.
- SHOTCRETE SUBSTRUCTURE REPAIRS.
- PILE ENCAPSULATION.
- REPLACE FENDER SYSTEM.

GENERAL DRAWING BRIDGE #7 ON NC45 OVER THE ROANOKE RIVER

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION RALEIGH

B-5941


SHEET NO.

S-1

6/5/2017 Greg Dickey

REVISIONS NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P. D. BRYANT DATE : 10/2016 DRAWN BY R.WEISZ _ DATE : <u>3/2017</u> CHECKED BY : ____



GENERAL NOTES

EXISITING DIMENSIONS AND BRIDGE CONDITION ARE FROM BEST INFORMATION AVALIABLE. THE CONTRACTOR SHALL FIELD VERIFY THE INFORMATION SHOWN ON THE PLANS AND NOTIFY THE ENGINEER IF ACTUAL DIMENSIONS AND

- FOR SUBMITTAL OF WORKING DRAWINGS, SEE SPECIAL
- FOR FALSEWORK AND FORMWORK, SEE SPECIAL PROVISIONS.
- FOR CRANE SAFETY. SEE SPECIAL PROVISIONS.
- FOR GROUT FOR STRUCTURES, SEE SPECIAL
- FOR CONCRETE REPAIRS FOR DECK, SEE SPECIAL PROVISIONS
- FOR BRIDGE JOINT REMOVAL, SEE SPECIAL
- FOR SILICONE JOINT SEALANT, SEE SPECIAL PROVISIONS.
- FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.
- FOR REPAIRS TO PRESTRESSED GIRDERS, SEE SPECIAL PROVISIONS.
- FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR CLEANING AND PAINTING OF EXISTING BEARINGS WITH HRCSA, SEE SPECIAL PROVISIONS.

FOR PILE ENCAPSULATION, SEE SPECIAL PROVISIONS.

IT IS THE CONTRACTOR'S RESPONSIBILITY TO FOLLOW ALL STATE AND FEDERAL SAFETY REQUIREMENTS.

FOR CONTROL OF TRAFFIC AND LIMITS ON PHASING OF CONSTRUCTION, SEE TRANSPORTATION MANAGEMENT PLANS.

FOR SECURING OF VESSELS, SEE SPECIAL PROVISIONS.

FOR MAINTENANCE OF WATER TRAFFIC, SEE SPECIAL PROVISIONS.

FOR WORK IN, OVER, OR ADJACENT TO NAVIGABLE WATERS, SEE SPECIAL PROVISIONS.

FOR FENDER SYSTEM WORK, SEE SHT NO. F1 THRU F5.

FOR SPLICING OF PRESTRESSING STRANDS, SEE SPECIAL PROVISIONS.

LOCATION SKETCH

INFORMATION INDICATED ON THE LOCATION SKETCH SHALL BE CONSIDERED GENERAL INFORMATION ONLY. CONTRACTOR SHALL CONFIRM, THROUGH OTHER SOURCES, SPECIFIC INFORMATION REGARDING THE BRIDGES, ROADWAYS, UTILITIES, THE SURROUNDING AREA, AND ANY OTHER ASPECTS THAT MAY BE NECESSARY TO PERFORM AND COMPLETE THE PROJECT.

	TOTAL BILL OF MATERIAL																
BRIDGE	MOBILIZATION	∆ REINFORCING STEEL	BRIDGE JOINT REMOVAL	SILICONE JOINT SEALENT	DECK REPAIR	GIRDER REPAIR	SHOTCRETE REPAIRS	EPOXY COATING	PILE ENCAPSULATION	CLEANING AND PAINTING EXISTING BEARINGS WITH HRCSA	POLLUTION CONTROL	PAINTING CONTAINMENT	REMOVAL OF EXISTING FENDER SYSTEM	10"X 6" TREATED LUMBER	15" TREATED TIMBER PILE	HARDWARE	Δ SPLICING OF PRESTRESSING STRANDS
	LUMP SUM	LB	LF	LF	CF	CF	CF	SF	LF	EA	LUMP SUM	LUMP SUM	LUMP SUM	LF	LF	LB	EACH
BERTIE #7	LUMP SUM	10	875	875	15 . 5	35.7	898.7	54 . 6	736	752	LUMP SUM	LUMP SUM	LUMP SUM	1536	7320	4493	10

Δ A QUANTITY IS NOT ANTICIPATED, A TOKEN PAY ITEM IS INDICATED FOR PRICING PURPOSES, IN CASE UNANTICIPATED REPAIRS ARE ENCOUNTERED.



6/5/2017

Greg Dickey

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

		REVI:	SIO	NS		SHEET NO.
NO.	BY:	DATE:	NO.	BY:	DATE:	S-2
1			3			TOTAL SHEETS
2			4			

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

GENERAL DRAWING

BRIDGE #7 ON NC45 OVER THE ROANOKE RIVER

B-5941

COUNTY


PROJECT NO.____

BRIDGE NO.

SHEET 2 OF 2

BERTIE

. DATE : 12/2016 M.A.LEE DRAWN BY : R.WEISZ DATE : 3/2017 CHECKED BY : __




TYPICAL SECTION

(EXISTING) (LOOKING NORTH)
(SPANS 1-16 & 20-95, SPANS 17-19 SIMILAR)

PROJECT NO. B-5941

BERTIE COUNTY

BRIDGE NO. 7



STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

TYPICAL SECTION

CEA153463B6D43D...
6/5/2017

REVISIONS

SHEET NO.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

2

REVISIONS

REVISIONS

SHEET NO.


 DRAWN BY :
 P.D.BRYANT
 DATE :
 03/17

 CHECKED BY :
 R.WEISZ
 DATE :
 03/17



FOR SILICONE JOINT SEALANT, SEE SPECIAL PROVISIONS.


TOTAL JOINT REPLACEMENT = 35 LF PER JOINT



PLAN

SECTION D-D (PROPOSED)

JOINT SEAL DETAIL AT BENT



DECK REPAIR REMOVAL 35 L.F. 35 L.F. 0.15 C.F. 35 L.F. 0.9 C.F. 35 L.F. -2.25 C.F. 35 L.F. 19 35 L.F. 20 35 L.F. 1.75 C.F. 1.9 C.F. 29 35 L.F. 33 35 L.F. 0.9 C.F. 36 35 L.F. 1.65 C.F. 42 35 L.F. 2.75 C.F. 44 35 L.F. 1.5 C.F. 1.75 C.F. 45 35 L.F. 46 35 L.F. 54 35 L.F. -35 L.F. 35 L.F. 77 35 L.F. _ 80 35 L.F. _ 82 35 L.F. 35 L.F. 86 35 L.F. -90 35 L.F. 35 L.F. 35 L.F.

PROJECT NO. B-5941
BERTIE COUNTY
BRIDGE NO. 7

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH


JOINT REPAIR DETAIL

DETA

Pocusigned by:
Robbic Weisz

039163

CEA153463B6D43D							
6/5/2017			REVI	SIO	NS		SHEET NO.
OCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-4
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			



SECTION C-C (EXISTING)

IF THE EMBEDDED PORTION OF THE EXISTING PLASTIC WATERSTOP IS EXPOSED DURING REMOVAL OF UNSOUND CONCRETE, OR IF UNSOUND CONCRETE IS REMOVED WITHIN 2"OF THE WATERSTOP, THE ENTIRE CONCRETE DEPTH TO THE WATERSTOP SHALL BE REMOVED.

 DRAWN BY :
 M.A.LEE
 DATE :
 3/2017

 CHECKED BY :
 R.N.WEISZ
 DATE :
 4/2017

-	GIRDER, DIAPHRAGM, & UNDERDECK REPAIR TABLES													
_	APPROX. ACTUAL													
SPAN	MEMBER	BENT/SPAN LOCATION	APPROX. REPAIR AREA (S.F.)	ACTUAL REPAIR AREA (S.F.)	LOCATION	BAY	REPAIR TYPE							
			1	۱ ا ه ۱		DAI	_							
2	2	@ BENT 2	1		BOTTOM FLANGE	-	GIRDER REPAIR							
2	3	@ BENT 2	1.5		BOTTOM FLANGE	-	GIRDER REPAIR							
3	DIA.	@ BENT 2	6		INT. DIA.	3	SHOTCRETE							
3	DIA.	@ BENT 2	1.5		INT. DIA.	2	SHOTCRETE							
3	1	@ BENT 2	2		BOTTOM FLANGE	-	GIRDER REPAIR							
4	1 -	@ BENT 4	1		BOTTOM FLANGE	-	GIRDER REPAIR							
4	3	@ BENT 4	2.3		BOTTOM FLANGE		GIRDER REPAIR							
4	DECK	MIDSPAN	21		BOTTOM OF DECK	LT.EXT.	EPOXY COATING							
5	1	@ BENT 5	1.5		BOTTOM FLANGE	-	GIRDER REPAIR							
6	1	@ BENT 5	1.5		BOTTOM FLANGE	LT.EXT.	GIRDER REPAIR							
6	2	@ BENT 5	1		BOTTOM FLANGE	-	GIRDER REPAIR							
7	4	@ BENT 6	1		BOTTOM FLANGE	-	GIRDER REPAIR							
7	4	@ BENT 6	1		BOTTOM FLANGE	-	GIRDER REPAIR							
8	2	@ BENT 7	1		BOTTOM FLANGE	-	GIRDER REPAIR							
9	DIA.	@ BENT 8	2		EXT. DIA.	LT.EXT.	EPOXY COATING							
9	2	@ BENT 9	1.5		BOTTOM FLANGE	_	GIRDER REPAIR							
10	1	@ BENT 10	1		BOTTOM FLANGE	-	GIRDER REPAIR							
10	2	@ BENT 9	2.3		BOTTOM FLANGE	-	GIRDER REPAIR							
11	2	@ BENT 10	1.5		BOTTOM FLANGE	-	GIRDER REPAIR							
11	1	@ BENT 11	1		WEB	-	GIRDER REPAIR							
11	2	@ BENT 11	1		BOTTOM FLANGE	-	GIRDER REPAIR							
11	2	@ BENT 10	1		BOTTOM FLANGE	-	GIRDER REPAIR							
11	DECK	MIDSPAN	16		BOTTOM OF DECK	RT.EXT.	EPOXY COATING							
12	DIA.	@ BENT 11	2		INT.DIA.	3	SHOTCRETE							
12	DIA.	@ BENT 11	2		INT.DIA.	1	SHOTCRETE							
12	DIA.	@ BENT 11	3		EXT.DIA.	LT.EXT.	SHOTCRETE							
12	DIA.	@ BENT 12	3		EXT.DIA.	LT.EXT.	SHOTCRETE							
12	1	@ BENT 12	3		BOTTOM FLANGE	-	GIRDER REPAIR							
12	3	@ BENT 12	1		BOTTOM FLANGE	ı	GIRDER REPAIR							
13	3	@ BENT 12	1.5		BOTTOM FLANGE	ı	GIRDER REPAIR							
13	4	@ BENT 12	1		BOTTOM FLANGE	-	GIRDER REPAIR							
13	DIA.	@ BENT 12	3		DIAPHRAGM	1	SHOTCRETE							
13	2	@ BENT 13	1.5		BOTTOM FLANGE	-	GIRDER REPAIR							
13	2	@ BENT 13	1		BOTTOM FLANGE	-	GIRDER REPAIR							
14	2	@ BENT 13	1.5		BOTTOM FLANGE	-	GIRDER REPAIR							
14	3	@ BENT 14	1		BOTTOM FLANGE	-	GIRDER REPAIR							
15	4	@ BENT 15	2.3		BOTTOM FLANGE	-	GIRDER REPAIR							
16	2	@ BENT 15	3.8		BOTTOM FLANGE	-	GIRDER REPAIR							
17	DECK	MIDSPAN	2.3		BOTTOM OF DECK	LT.EXT.	EPOXY COATING							
21	1	@ BENT 22	1		BOTTOM FLANGE	-	GIRDER REPAIR							
21	DIA.	@ BENT 22	4		EXT.DIA.	LT.EXT.	EPOXY COATING							
22	1	@ BENT 21	1		BOTTOM FLANGE	-	GIRDER REPAIR							
23	1	@ BENT 23	1		BOTTOM FLANGE	-	GIRDER REPAIR							
23	4	@ BENT 23	3		BOTTOM FLANGE	-	GIRDER REPAIR							
25	2	@ BENT 24	1		BOTTOM FLANGE	_	GIRDER REPAIR							
25	1	@ BENT 25	1.5		BOTTOM FLANGE	-	GIRDER REPAIR							
25	4	@ BENT 25	1		BOTTOM FLANGE	_	GIRDER REPAIR							

		GIRDER, DIAPHRA	GM,& UN	DERDECK	REPAIR TAE	BLES	
			APPROX.	ACTUAL			
		BENT/SPAN	REPAIR AREA	RÉPÁTR AREA			REPAIR
SPAN	MEMBER	LOCATION	(S.F.)	(S.F.)	LOCATION	BAY	TYPE
26	3	@ BENT 25	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
26	1	@ BENT 26	1		BOTTOM FLANGE	-	GIRDER REPAIR
27	DIA.	@ BENT 26	8		DIAPHRAGM	3	SHOTCRETE
27	3	@ BENT 26	1		BOTTOM FLANGE	-	GIRDER REPAIR
28	3	@ BENT 28	1		BOTTOM FLANGE	-	GIRDER REPAIR
30	2	@ BENT 29	1		BOTTOM FLANGE	-	GIRDER REPAIR
31	3	@ BENT 30	4		BOTTOM FLANGE	_	GIRDER REPAIR
31	3	@ BENT 30	1		WEB	_	GIRDER REPAIR
32	DIA.	@ BENT 31	4		DIAPHRAGM	LT.EXT.	SHOTCRETE
33	4	@ BENT 32	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
33	DIA.	@ BENT 33	4		DIAPHRAGM	RT.EXT.	SHOTCRETE
39	2	@ BENT 38	1		BOTTOM FLANGE	-	GIRDER REPAIR
40	DIA.	@ BENT 39	4		DIAPHRAGM	3	SHOTCRETE
45	2	@ BENT 45	1		BOTTOM FLANGE	-	GIRDER REPAIR
46	3	@ BENT 45	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
48	2	@ BENT 48	1.5		BOTTOM FLANGE	_	GIRDER REPAIR
49	DIA.	@ BENT 48	1		EXT. DIA.	LT.EXT.	EPOXY COATING
50	DIA.	@ BENT 49	3		EXT. DIA.	RT.EXT.	EPOXY COATING
51	1	@ BENT 51	2.3		BOTTOM FLANGE	-	GIRDER REPAIR
51	DECK	MIDSPAN	2.3		BOTTOM OF DECK	RT.EXT.	EPOXY COATING
52	4	@ BENT 52	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
53	1	@ BENT 52	1		BOTTOM FLANGE	LT.EXT.	GIRDER REPAIR
53	4	@ BENT 52	1		BOTTOM FLANGE	-	GIRDER REPAIR
54	DECK	MIDSPAN	3		BOTTOM OF DECK	3	EPOXY COATING
60	1	@ BENT 59	2.3		BOTTOM FLANGE	-	GIRDER REPAIR
61	1	@ BENT 60	2		BOTTOM FLANGE	-	GIRDER REPAIR
61	1	@ BENT 61	2.3		BOTTOM FLANGE	-	GIRDER REPAIR
67	3	@ BENT 67	1		BOTTOM FLANGE	-	GIRDER REPAIR
67	3	@ BENT 67	1		BOTTOM FLANGE	-	GIRDER REPAIR
67	4	@ BENT 66	1		BOTTOM FLANGE	-	GIRDER REPAIR
68	2	@ BENT 67	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
70	3	@ BENT 69	1		BOTTOM FLANGE		GIRDER REPAIR
72	DIA.	@ BENT 71	3		EXT. DIA.	LT.EXT.	SHOTCRETE
72	DIA.	@ BENT 71	4		INT. DIA.	2	SHOTCRETE
76	1	@ BENT 76			BOTTOM FLANGE	-	GIRDER REPAIR
77	DIA.	@ BENT 77	6		INT. DIA.	3	SHOTCRETE
77	1	@ BENT 76	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
77	4	@ BENT 76	1		BOTTOM FLANGE	_	GIRDER REPAIR
77	4	@ BENT 77	2.3		BOTTOM FLANGE	-	GIRDER REPAIR
82	2	@ BENT 81	1		BOTTOM FLANCE	-	GIRDER REPAIR
82	2	@ BENT 82	2.3		BOTTOM FLANCE	-	GIRDER REPAIR
83	2	@ BENT 83	1		BOTTOM FLANCE	-	GIRDER REPAIR
85	2	@ BENT 84	1		BOTTOM FLANCE	-	GIRDER REPAIR
86	3	@ BENT 86	1.5		BOTTOM FLANCE	-	GIRDER REPAIR
88	2	@ BENT 87	1		BOTTOM FLANCE	-	GIRDER REPAIR
88	3	@ BENT 88	1		BOTTOM FLANCE	_	GIRDER REPAIR
88	3	@ BENT 88	1		BOTTOM FLANGE	-	GIRDER REPAIR

REPAIR QUANTITY TABLE											
CDANC 1 00		QUANT	ITIES								
SPANS 1-88	ESTI	МАТЕ		ACTUAI	L						
SHOTCRETE	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF						
DIAPHRAGMS	53.5	15.6									
GIRDGER REPAIR	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF						
GIRDERS	101.7	29.7									
EPOXY COATING		EA F		AREA SF							
UNDERDECK OR EXT.DIA.	54	1.6									

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT FOR DIAPHRAGM REPAIRS AND 1"CL TO SAWCUT FOR GIRDER REPAIRS. SEE REPAIR DETAILS SHEET S-103 & S-104.

- FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.
- FOR GIRDER REPAIR, SEE SPECIAL PROVISIONS.
- FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

PROJECT NO. B-5941

BERTIE COUNTY

BRIDGE NO. 7

SHEET 1 OF 2

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

GIRDER, DIAPHRAGM & UNDERDECK REPAIRS

Docusigned by:

Kohbic Wusy

CEA153463B6D43D...
6/5/2017

PAIR	CEA153463B6D43D							
	6/5/2017			REV:	ISION	٧S		SHEET NO
OCUMENT	NOT CONSTDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-5
		1			3			TOTAL SHEETS
		2			4			
	FINAL	PAIR CEA153463B6D43D OCUMENT NOT CONSIDERED	PAIR 6/5/2017 OCUMENT NOT CONSIDERED FINAL UNLESS ALL 1	PAIR CEA153463B6D43D OCUMENT NOT CONSIDERED FINAL UNLESS ALL NO. BY:	PAIR 6/5/2017 REV: OCUMENT NOT CONSIDERED FINAL UNLESS ALL 1	PAIR 6/5/2017 REVISION OCUMENT NOT CONSIDERED FINAL UNLESS ALL 1 OCUMENT NOT CONSIDERED 1 OCUMENT NOT CONSIDERED 3	PAIR 6/5/2017 REVISIONS OCUMENT NOT CONSIDERED FINAL UNLESS ALL 1 OCUMENT NOT CONSIDERED STATE: No. BY: 3	PAIR 6/5/2017 REVISIONS OCUMENT NOT CONSIDERED FINAL UNLESS ALL NO. BY: DATE: NO. BY: DATE:

 DRAWN BY :
 M.A.LEE
 DATE :
 12/2016

 CHECKED BY :
 R.WEISZ
 DATE :
 3/2017

	GIRDER, DIAPHRAGM, & UNDERDECK REPAIR TABLES						
SPAN	MEMBER	BENT/SPAN LOCATION	APPROX. REPAIR AREA (S.F.)	ACTUAL REPAIR AREA (S.F.)	LOCATION	BAY	REPAIR TYPE
88	4	@ BENT 88	1 . 5		BOTTOM FLANGE	-	GIRDER REPAIR
89	4	@ BENT 89	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
89	2	@ BENT 88	1		BOTTOM FLANGE	-	GIRDER REPAIR
89	3	@ BENT 88	1		BOTTOM FLANGE	-	GIRDER REPAIR
89	3	@ BENT 88	1		BOTTOM FLANGE	-	GIRDER REPAIR
89	3	@ BENT 89	1		BOTTOM FLANGE	-	GIRDER REPAIR
90	4	@ BENT 89	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
90	3	@ BENT 90	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
91	2	@ BENT 90	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
92	2	@ BENT 91	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
92	4	@ BENT 91	1 . 5		BOTTOM FLANGE	-	GIRDER REPAIR
93	3	@ BENT 92	1		BOTTOM FLANGE	-	GIRDER REPAIR
93	2	@ BENT 93	1.5		BOTTOM FLANGE	-	GIRDER REPAIR
94	1	@ BENT 94	1 . 5		BOTTOM FLANGE	-	GIRDER REPAIR
95	2	@ BENT 94	1		BOTTOM FLANGE	-	GIRDER REPAIR
95	2	@ BENT 94	1		BOTTOM FLANGE	-	GIRDER REPAIR

REPAIR QUANTITY TABLE						
SPANS 88-95		QUANT	ITIES			
3FAN3 00-33	ESTI	MATE	ACTUAL			
SHOTCRETE	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF	
DIAPHRAGMS	0.0	0.0				
GIRDGER REPAIR	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF	
GIRDERS	20.5	6.0				
EPOXY COATING	AREA SF			AREA SF		
UNDERDECK OR EXT.DIA.	0	.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT FOR DIAPHRAGM REPAIRS AND 1"TO SAWCUT FOR GIRDER REPAIRS. SEE REPAIR DETAILS SHEET S-103 & S-104.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR GIRDER REPAIR, SEE SPECIAL PROVISIONS.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

PROJECT NO. B-5941

BERTIE COUNTY

BRIDGE NO. 7

SHEET 2 OF 2

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

GIRDER, DIAPHRAGM & UNDERDECK REPAIRS


Robbic Weisy
CEA153463B6D43D...
6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

			SHEET NO.					
<u>- D</u>	NO.	BY:	DATE:	NO.	BY:	DATE:	S-6	
ا ا	1			3			TOTAL SHEETS	
	2			4				

 DRAWN BY :
 M.A.LEE
 DATE :
 12/2016

 CHECKED BY :
 R.WEISZ
 DATE :
 3/2017



REPAIR QUANTITY TABLE QUANTITIES REPAIRS END BENT 1 ESTIMATE ACTUAL AREA VOLUME AREA VOLUME SHOTCRETE REPAIRS SF CAP (VERTICAL FACE) 10.0 5.0 CAP (HORIZONTAL, CORNER) 0.0 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.



B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 1 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> SUBSTRUCTURE END BENT 1

Robbic Weisy CEA153463B6D43D...
6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET NO. REVISIONS S-7 DATE: NO. BY: DATE:

05-JUN-2017 13:13 R:\Structures\DGN\400_019_B5941_SMU_S8_EB.DGN gdickey

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 1 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 48.9 REPAIR QUANTITY TABLE. COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN STRUT & GIRDER REPAIR DETAILS" SHEET. 0.0 FOOTER 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 2 SPAN 1 PLAN TOP OF CAP _9.3 SF 15.0 SF-ELEVATION ELEVATION END VIEW END VIEW WEST SIDE SOUTH SIDE EAST SIDE NORTH SIDE PROJECT NO.____ BERTIE BRIDGE NO. _10.6 SF SHEET 2 OF 96 SPAN 2 SPAN 1 STATE OF NORTH CAROLINA - SHOTCRETE REPAIR DEPARTMENT OF TRANSPORTATION
RALEIGH PLAN BOTTOM OF CAP SUBSTRUCTURE Robbie Weisz CEA153463B6D43D...
6/5/2017 REVISIONS

QUANTITIES

VOLUME

CF

24.5

0.0

0.0

ACTUAL

VOLUME

CF

AREA

SF

B-5941

BENT 1

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT/ S.T.SANDOR R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 2 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA VOLUME SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 38.8 REPAIR QUANTITY TABLE. COLUMN 19.7 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN STRUT 0.0 & GIRDER REPAIR DETAILS" SHEET. FOOTER 0.0 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 3 SPAN 2 PLAN TOP OF CAP __10.4 SF _8.3 SF <u></u>15.0 SF 5.1 SF-/ 8.6 SF-\ ELEVATION ELEVATION END VIEW END VIEW WEST SIDE SOUTH SIDE EAST SIDE NORTH SIDE PROJECT NO.____ BERTIE BRIDGE NO. SHEET 3 OF 96 SPAN 3 SPAN 2 - SHOTCRETE REPAIR STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH PLAN BOTTOM OF CAP SUBSTRUCTURE BENT 2 Robbie Weisz CEA153463B6D43D...
6/5/2017 REVISIONS

QUANTITIES

CF

19.4

ACTUAL

VOLUME

CF

AREA

SF

B-5941

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT/ S.T.SANDOR R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 3 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 49.0 REPAIR QUANTITY TABLE. COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. STRUT 0.0 FOOTER 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 4 SPAN 3 PLAN TOP OF CAP ELEVATION ELEVATION END VIEW END VIEW WEST SIDE EAST SIDE NORTH SIDE SOUTH SIDE PROJECT NO.____ BERTIE BRIDGE NO. SHEET 4 OF 96 SPAN 4 SPAN 3 - SHOTCRETE REPAIR STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH PLAN BOTTOM OF CAP SUBSTRUCTURE BENT 3 Robbie Weisz CEA153463B6D43D...
6/5/2017 REVISIONS

QUANTITIES

VOLUME

CF

24.5

0.0

0.0

ACTUAL

VOLUME

CF

AREA

SF

B-5941

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

__ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u>

P.D.BRYANT/ S.T.SANDOR R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 4 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 24.0 REPAIR QUANTITY TABLE. COLUMN 17.4 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. STRUT 0.0 FOOTER 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 5 SPAN 4 PLAN TOP OF CAP _8.5 SF 2.1 SF— ___17**.**4 SF ELEVATION END VIEW ELEVATION END VIEW WEST SIDE EAST SIDE NORTH SIDE SOUTH SIDE PROJECT NO.____ BERTIE BRIDGE NO. SHEET 5 OF 96 SPAN 5 SPAN 4 - SHOTCRETE REPAIR STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH PLAN BOTTOM OF CAP SUBSTRUCTURE Robbie Weisz CEA153463B6D43D...
6/5/2017 REVISIONS DATE:

QUANTITIES

—13.4 SF

B-5941

BENT 4

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

S-11

VOLUME

CF

12.0

0.0

0.0

ACTUAL


VOLUME


CF

AREA

__ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u>

P.D.BRYANT/ S.T.SANDOR R.N.WEISZ





VOLUME

CF

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 7 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA VOLUME SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 27.3 REPAIR QUANTITY TABLE. COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. STRUT 0.0 FOOTER 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER SPAN 8 REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 7 PLAN TOP OF CAP __11.4 SF ELEVATION END VIEW ELEVATION END VIEW PROJECT NO.____ WEST SIDE NORTH SIDE EAST SIDE SOUTH SIDE BERTIE BRIDGE NO. SHEET 8 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH SPAN 8 SPAN 7 - SHOTCRETE REPAIR SUBSTRUCTURE PLAN BENT 7 BOTTOM OF CAP Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED __ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u> P.D.BRYANT/ S.T.SANDOR R.N.WEISZ CHECKED BY : _____

QUANTITIES

CF

13.7

0.0

0.0

ACTUAL


VOLUME

CF

AREA

B-5941

_ COUNTY



END VIEW WEST SIDE 0.8 SF-

NOTES:

SPAN 10

SPAN 9

SPAN 10 SPAN 9


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE							
DEDATES QUANTITIES							
REPAIRS BENT 9	ESTI	MATE	ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP	4.4	2.2					
COLUMN	41.1	20.6					
STRUT	0.0	0.0					
FOOTER	0.0	0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 10 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 9

Robbie Weisz CEA153463B6D43D...

REVISIONS DATE:

- SHOTCRETE REPAIR

ELEVATION SOUTH SIDE

PLAN

BOTTOM OF CAP

PLAN

TOP OF CAP

22.0 SF-

19.1 SF—

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT/ S.T.SANDOR R.N.WEISZ

SPAN 11 SPAN 10


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE							
REPAIRS BENT 10 QUANTITIES							
REPAIRS DENT TO	ESTI	MATE	ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP (VERTICAL FACE)	17.3	8.7					
COLUMN	7.5	3.8					
STRUT	0.0	0.0					
FOOTER	0.0	0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



SPAN 11 SPAN 10

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 11 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 10

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

- SHOTCRETE REPAIR

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 SHEET NO. REVISIONS S-17 DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT / S.T.SANDOR CHECKED BY: R.N. WEISZ

END VIEW

WEST SIDE

6 6

6 6

PLAN

TOP OF CAP

PLAN

BOTTOM OF CAP

END VIEW WEST SIDE

NOTES:


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE							
REPAIRS BENT 11 QUANTITIES							
REPAIRS DENT II	ESTI	MATE	ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP	11.9	6.0					
COLUMN	0.0	0.0					
STRUT	0.0	0.0					
FOOTER	0.0	0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



SPAN 12

SPAN 11

SPAN 12 SPAN 11

PLAN

TOP OF CAP

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 12 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 11

> > SHEET NO.

REVISIONS DATE:

- SHOTCRETE REPAIR

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

PLAN

BOTTOM OF CAP

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE							
REPAIRS BENT 12 QUANTITIES							
REPAIRS DENT 12	ESTI	MATE	ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP	15.4	7.7					
COLUMN	0.0	0.0					
STRUT	STRUT 0.0 0.0						
F00TER 0.0 0.0							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



SPAN 13 SPAN 12

PLAN

BOTTOM OF CAP

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 13 OF 96

- SHOTCRETE REPAIR

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 12

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 REVISIONS SHEET NO. S-19 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT / S.T.SANDOR R.N.WEISZ CHECKED BY : _____

05-JUN-2017 13:13 R:\Structures\DGN\400_043._B5941_SMU_S9 THRU S44_BENTS1thru34.DGN gdickey


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.


FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE							
REPAIRS BENT 13 QUANTITIES							
KEPAIKS DENI IS	ESTI	MATE	ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP	9.1	4.6					
COLUMN	0.0	0.0					
STRUT	0.0	0.0					
FOOTER	0.0	0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.





PLAN TOP OF CAP



__0.5 SF

SPAN 14 SPAN 13





ELEVATION NORTH SIDE

- SHOTCRETE REPAIR

B-5941 PROJECT NO.____ BERTIE COUNTY

BRIDGE NO.

SHEET 14 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 13

PocuSigned by:
Robbic Weish
CEA153463B6D43D...
6/5/2017

DOCUMENT NOT CONSIDERI FINAL UNLESS ALL SIGNATURES COMPLETED

		REVISIONS							
RED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-20		
IVLD	1			3			TOTAL SHEETS		
:D	2			4					

1.0 SF —

PLAN

BOTTOM OF CAP

END VIEW

WEST SIDE

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT / S.T.SANDOR R.N.WEISZ

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. & GIRDER REPAIR DETAILS" SHEET. FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. SPAN 15 SPAN 14 PLAN TOP OF CAP __16.0 SF __13.0 SF __17.9 SF END VIEW

EAST SIDE END VIEW
WEST SIDE **ELEVATION** ELEVATION SOUTH SIDE NORTH SIDE SPAN 15 SPAN 14 - SHOTCRETE REPAIR PLAN BOTTOM OF CAP

WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN

REPAIR QUANTITY TABLE								
DEDATES QUANTITIES								
REPAIRS BENT 14	ESTI	MATE	ACTUAL					
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF				
CAP	46.9	23.5						
COLUMN	0.0	0.0						
STRUT	0.0	0.0						
FOOTER	0.0	0.0						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 15 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 14

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS SHEET NO. S-21 DATE:

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. SPAN 16 SPAN 15 PLAN TOP OF CAP ∕-3.5 SF END VIEW

EAST SIDE <u>ELEVATION</u> **ELEVATION** END VIEW WEST SIDE SOUTH SIDE NORTH SIDE SPAN 16 SPAN 15 - SHOTCRETE REPAIR PLAN BOTTOM OF CAP

REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 15 ESTIMATE ACTUAL AREA VOLUME AREA VOLUME SHOTCRETE REPAIRS SF CF SF CF 3**.**5 1.8 COLUMN 0.0 0.0 0.0 STRUT 0.0 0.0 0.0 FOOTER

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

> B-5941 PROJECT NO.____ BERTIE COUNTY BRIDGE NO.

SHEET 16 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 15

> > SHEET NO.

S-22

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT / S.T.SANDOR R.N.WEISZ

END VIEW
WEST SIDE

NOTES:

END VIEW

EAST SIDE

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.


FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE								
REPAIRS BENT 16 QUANTITIES								
REPAIRS DENT TO	ESTI	MATE	ACTUAL					
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF				
CAP	10.0	5.0	-					
COLUMN	0.0	0.0						
STRUT	0.0	0.0						
FOOTER	0.0	0.0						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

SPAN 17 SPAN 16


> PLAN TOP OF CAP



ELEVATION SOUTH SIDE

SPAN 17 SPAN 16

> PLAN BOTTOM OF CAP



ELEVATION NORTH SIDE

- SHOTCRETE REPAIR

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 17 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 16

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS S-23 DATE:

__ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u>

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ



REPAIR QUANTITY TABLE						
REPAIRS BENT 17 QUANTITIES						
NEFAINS DENT IT	ESTI	ESTIMATE		UAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP	34.9	17 . 5	-			
COLUMN	0.0	0.0				
STRUT	0.0 0.0					
FOOTER	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND

> B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 18 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 17

> > S-24

REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u>

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 18 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 14.3 REPAIR QUANTITY TABLE. COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN STRUT & GIRDER REPAIR DETAILS" SHEET. 0.0 FOOTER FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. SEE REPAIR DETAILS. SPAN 19 • • • • SPAN 18 PLAN TOP OF CAP PROJECT NO.____ BERTIE END VIEW

EAST SIDE ELEVATION END VIEW ELEVATION WEST SIDE SOUTH SIDE NORTH SIDE BRIDGE NO. SHEET 19 OF 96 - SHOTCRETE REPAIR SPAN 19 SPAN 18 PLAN Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 BOTTOM OF CAP

REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL VOLUME AREA VOLUME CF SF CF 7.2 0.0 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT.

> STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
> RALEIGH

> > SUBSTRUCTURE BENT 18

B-5941

_ COUNTY

REVISIONS S-25 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT / S.T.SANDOR R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 19 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE ESTIMATE AREA VOLUME SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 60.6 30.3 REPAIR QUANTITY TABLE. COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN STRUT 0.0 & GIRDER REPAIR DETAILS" SHEET. 0.0 FOOTER FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 20 SPAN 19 PLAN TOP OF CAP PROJECT NO.____ END VIEW ELEVATION END VIEW ELEVATION BERTIE EAST SIDE WEST SIDE SOUTH SIDE NORTH SIDE BRIDGE NO. SHEET 20 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH - SHOTCRETE REPAIR SPAN 20 SPAN 19 SUBSTRUCTURE BENT 19 PLAN BOTTOM OF CAP Robbie Weisz CEA153463B6D43D...
6/5/2017 REVISIONS

ACTUAL

VOLUME

CF

AREA

SF

B-5941

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ COUNTY

S-26

DATE : 09/2016
DATE : 10/2016

P.D.BRYANT / S.T.SANDOR R.N.WEISZ

END VIEW WEST SIDE

P.D.BRYANT / S.T.SANDOR

CHECKED BY : R.N. WEISZ

NOTES:


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE						
REPAIRS BENT 20 QUANTITIES						
REPAIRS DENI 20	ESTI	MATE	ACT	UAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP	4.0	2.0				
COLUMN	0.0	0.0				
STRUT	0.0	0.0				
FOOTER	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



SPAN 21

SPAN 20

SPAN 21 SPAN 20

PLAN

TOP OF CAP

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 21 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 20

Robbie Weisz

- SHOTCRETE REPAIR

CEA153463B6D43D								
6/5/2017		REVISIONS						
CUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	D.A		
FINAL UNLESS ALL	1			3				
IGNATURES COMPLETED	2			A				

DATE : 09/2016
DATE : 10/2016

PLAN

BOTTOM OF CAP


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE						
REPAIRS BENT 21 QUANTITIES						
MERAINS DENI ZI	ESTI	MATE	ACT	UAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP	17.6	8.8				
COLUMN	9.2	4.6				
STRUT	0.0	0.0				
FOOTER	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



SPAN 22 SPAN 21

SPAN 22

SPAN 21

PLAN

TOP OF CAP

PLAN

BOTTOM OF CAP

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 22 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 21

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

- SHOTCRETE REPAIR

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 SHEET NO. REVISIONS S-28 DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT / S.T.SANDOR CHECKED BY: R.N. WEISZ

PLAN TOP OF CAP

NOTES:

SPAN 23 SPAN 22

SPAN 23 SPAN 22

_7.5 SF


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE						
DEDATES QUANTITIES						
REPAIRS BENT 22	ESTI	MATE	ACT	UAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP	7.5	3.8				
COLUMN	0.0	0.0				
STRUT	0.0	0.0				
FOOTER	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 23 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 22

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

- SHOTCRETE REPAIR

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 REVISIONS SHEET NO. S-29 DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT / S.T.SANDOR R.N.WEISZ CHECKED BY : _____

END VIEW
WEST SIDE

ELEVATION SOUTH SIDE

PLAN

BOTTOM OF CAP


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE						
DEDATES QUANTITIES						
REPAIRS BENT 23	ESTI	MATE	ACT	UAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP	9.0	4.5				
COLUMN	0.0	0.0				
STRUT	32.1	16.0				
FOOTER	0.0	0.0				


VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



PLAN TOP OF CAP

PLAN

BOTTOM OF CAP



SPAN 24 SPAN 23

- SHOTCRETE REPAIR

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 24 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 23

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET NO. REVISIONS S-30 DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT / S.T.SANDOR R.N.WEISZ CHECKED BY : _____

END VIEW
WEST SIDE


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.


FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE						
REPAIRS BENT 24 QUANTITIES						
NEFAINS DENT 24	ESTI	MATE	ACT	UAL		
SHOTCRETE REPAIRS	AREA SF			VOLUME CF		
CAP	57.9	29.0	-			
COLUMN	11.9	6.0				
STRUT	0.0	0.0				
FOOTER	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.




PLAN TOP OF CAP



PLAN

BOTTOM OF CAP

SPAN 25 SPAN 24



ELEVATION NORTH SIDE

- SHOTCRETE REPAIR

PROJECT NO. 15B.13.38 BERTIE _ COUNTY BRIDGE NO.

SHEET 25 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 24

6/5/2017			
OCUMENT NOT CONSIDERED	NO.	BY:	DA
FINAL UNLESS ALL	1		
SIGNATURES COMPLETED	2		

Robbic Weisg

			SHEET NO.					
<u>-</u>	NO.	BY:	DATE:	NO.	BY:	DATE:	S-31	
ا ا	1			3			TOTAL SHEETS	
	2			4				

__ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u> P.D.BRYANT / S.T.SANDOR R.N.WEISZ CHECKED BY : _____

END VIEW

WEST SIDE

SPAN 26 SPAN 25

PLAN

TOP OF CAP

NOTES:


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE						
REPAIRS BENT 25						
REPAIRS DENT 25	ESTI	MATE	ACT	UAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP	41.3	20.7				
COLUMN	0.0	0.0				
STRUT	0.0	0.0				
FOOTER	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 26 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> SUBSTRUCTURE BENT 25

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

- SHOTCRETE REPAIR

Pocusigned by:

Robbic Weish

CEA153463B6D43D...
6/5/2017 SHEET NO. REVISIONS DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT / S.T.SANDOR CHECKED BY: R.N. WEISZ

END VIEW WEST SIDE

05-JUN-2017 13:13 R:\Structures\DGN\400_043._B5941_SMU_S9 THRU S44_BENTS1thru34.DGN gdickey

PLAN

BOTTOM OF CAP


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.


FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE						
REPAIRS BENT 26 QUANTITIES						
REPAIRS DENI 20	ESTI	MATE	ACTUAL			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
CAP	48.6	24.3				
COLUMN	0.0	0.0				
STRUT	0.0	0.0				
FOOTER	0.0	0.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.









__26.0 SF

PLAN

BOTTOM OF CAP

SPAN 27 SPAN 26





ELEVATION NORTH SIDE

- SHOTCRETE REPAIR

B-5941 PROJECT NO.____ BERTIE COUNTY BRIDGE NO.

SHEET 27 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 26

6/5/2017	
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	140
ETNIAL LINEECC ALL	I٤
	L
SIGNATURES COMPLETED	2

Robbie Weisz							
6/5/2017			REVI:	1012	NS		SHEET
NT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-3
NAL UNLESS ALL	1			3			TOTA SHEE

__ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u> P.D.BRYANT / S.T.SANDOR

05-JUN-2017 13:13 R:\Structures\DGN\400_043._B5941_SMU_S9 THRU S44_BENTS1thru34.DGN gdickey

R.N.WEISZ CHECKED BY : _____

_16.2 SF

NOTES:

SPAN 28

SPAN 27

PLAN

TOP OF CAP


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE							
REPAIRS BENT 27	QUANTITIES						
REPAIRS DENI ZI	ESTIMATE		ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP	30.4	15.2					
COLUMN	0.0	0.0					
STRUT	0.0	0.0					
FOOTER	0.0	0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



PROJECT NO. B-5941

BERTIE COUNTY

BRIDGE NO. 7

SHEET 28 OF 96

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE BENT 27

Pocusigned by:
Robbic Weisty

CEA153463B6D43D...

6/5/2017

REVISIONS

SHEET NO.
BY:
DATE:
NO. BY:
DATE:
S-34

TOTAL
SHEETS

SIGNATURES COMPLETED

4

- SHOTCRETE REPAIR

SPAN 28
SPAN 27

DRAWN BY: P.D.BRYANT/ S.T.SANDOR DATE: 09/2016
CHECKED BY: R.N.WEISZ DATE: 10/2016

END VIEW

WEST SIDE

05-JUN-2017 13:13 R:\Structures\DGN\400_043._B5941_SMU_S9 THRU S44_BENTS1thru34.DGN gdickey

1.5 SF —

ELEVATION

SOUTH SIDE


PLAN

BOTTOM OF CAP

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. SPAN 29 SPAN 28 PLAN TOP OF CAP _15.2 SF END VIEW
EAST SIDE END VIEW ELEVATION WEST SIDE SOUTH SIDE _26.0 SF SPAN 29 SPAN 28 - SHOTCRETE REPAIR PLAN BOTTOM OF CAP

REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 28 ESTIMATE ACTUAL AREA VOLUME AREA VOLUME SHOTCRETE REPAIRS SF CF CF 53.0 26.5 COLUMN 0.0 0.0 0.0 STRUT 0.0 FOOTER 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



ELEVATION NORTH SIDE

B-5941 PROJECT NO. ____ BERTIE COUNTY

BRIDGE NO.

SHEET 29 OF 96

Robbic Weisy


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 28

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

CEA153463B6D43D... SHEET NO. REVISIONS S-35 DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT/ S.T.SANDOR R.N.WEISZ CHECKED BY : _____



ACTUAL

COUNTY

S-36

VOLUME

CF

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 30 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA VOLUME SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 26.6 REPAIR QUANTITY TABLE. COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN 0.0 & GIRDER REPAIR DETAILS" SHEET. STRUT 0.0 FOOTER 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 31 SPAN 30 PLAN TOP OF CAP 9.1 SF-ELEVATION END VIEW ELEVATION END VIEW WEST SIDE EAST SIDE NORTH SIDE SOUTH SIDE PROJECT NO.____ BERTIE BRIDGE NO. 8.4 SF— SHEET 31 OF 96 SPAN 31 SPAN 30 STATE OF NORTH CAROLINA - SHOTCRETE REPAIR DEPARTMENT OF TRANSPORTATION
RALEIGH PLAN SUBSTRUCTURE BOTTOM OF CAP BENT 30 Robbic Weisy CEA153463B6D43D...
6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED DATE : 09/2016
DATE : 10/2016 P.D.BRYANT/ S.T.SANDOR

QUANTITIES

CF

13.3

0.0

ACTUAL

VOLUME

CF

AREA

B-5941

COUNTY

S-37

R.N.WEISZ

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 31 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. COLUMN FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. STRUT FOOTER FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. SPAN 32 SPAN 31 PLAN TOP OF CAP 2.9 SF-/ ELEVATION END VIEW ELEVATION END VIEW WEST SIDE EAST SIDE NORTH SIDE SOUTH SIDE PROJECT NO.____ 3.8 SF— BRIDGE NO. SHEET 32 OF 96 SPAN 32 SPAN 31 - SHOTCRETE REPAIR PLAN BOTTOM OF CAP Robbic Weisy

REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL AREA AREA VOLUME VOLUME SF CF CF 21.9 11.0 0.0 0.0 2.9 1**.**5 0.0 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

> STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
> RALEIGH

BERTIE

B-5941

COUNTY

SUBSTRUCTURE BENT 31

CEA153463B6D43D... REVISIONS S-38 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT/ S.T.SANDOR R.N.WEISZ

CHECKED BY : _____

DATE : 09/2016
DATE : 10/2016

NOTES: SPAN 33 SPAN 32 PLAN TOP OF CAP ELEVATION END VIEW END VIEW WEST SIDE EAST SIDE SOUTH SIDE

1.5 SF ¬ _3.8 SF SPAN 33 SPAN 32 PLAN BOTTOM OF CAP


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

REPAIR QUANTITY TABLE							
REPAIRS BENT 32	QUANTITIES						
REPAIRS DENI 32	ESTIMATE		ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
CAP	25.4	12.7					
COLUMN	0.0	0.0					
STRUT	0.0	0.0					
FOOTER	0.0	0.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



NORTH SIDE B-5941 PROJECT NO.____ BERTIE _ COUNTY

BRIDGE NO.

SHEET 33 OF 96

- SHOTCRETE REPAIR

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 32

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

Pocusigned by:

Robbic Weisz

CEA153463B6D43D...
6/5/2017 REVISIONS

SHEET NO. S-39 DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT/ S.T.SANDOR R.N.WEISZ CHECKED BY : _____

SPAN 34 SPAN 33 PLAN TOP OF CAP _14.2 SF 10.3 SF-/ END VIEW

ELEVATION END VIEW EAST SIDE SOUTH SIDE

SPAN 34 SPAN 33 PLAN BOTTOM OF CAP

NOTES:


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

	REPAIR QUANTITY TABLE					
	REPAIRS BENT 33	QUANTITIES				
		ESTIMATE		ACTUAL		
	SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
	CAP	36.2	18.1			
	COLUMN	0.0	0.0			
	STRUT	0.0	0.0			
	FOOTER	0.0	0.0	_		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



NORTH SIDE B-5941 PROJECT NO.____

BERTIE _ COUNTY BRIDGE NO.

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

SHEET 34 OF 96

- SHOTCRETE REPAIR

Robbic Weisz

SUBSTRUCTURE BENT 33

CEA153463B6D43D...
6/5/2017 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS S-40 DATE:

DATE : 09/2016
DATE : 10/2016 P.D.BRYANT/ S.T.SANDOR R.N.WEISZ CHECKED BY : _____

WEST SIDE

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 34 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE AREA SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 28.9 REPAIR QUANTITY TABLE. COLUMN 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. STRUT 0.0 FOOTER 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. SPAN 35 SPAN 34 PLAN TOP OF CAP _13**.**5 SF ELEVATION END VIEW ELEVATION END VIEW WEST SIDE EAST SIDE NORTH SIDE SOUTH SIDE PROJECT NO.____ BERTIE BRIDGE NO. SHEET 35 OF 96 SPAN 35 SPAN 34 STATE OF NORTH CAROLINA - SHOTCRETE REPAIR DEPARTMENT OF TRANSPORTATION
RALEIGH PLAN BOTTOM OF CAP SUBSTRUCTURE BENT 34 Robbie Weisz CEA153463B6D43D...
6/5/2017 REVISIONS

QUANTITIES

VOLUME

CF

14.5

0.0

0.0

0.0

ACTUAL

VOLUME

CF

AREA

SF

B-5941

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

P.D.BRYANT/ S.T.SANDOR R.N.WEISZ

CHECKED BY : _____

__ DATE : <u>09/2016</u> __ DATE : <u>10/2016</u>

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 35 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. END VIEW ELEVATION WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE COUNTY ELEVATION END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 36 OF 96 - SHOTCRETE REPAIR STATE OF NORTH CAROLINA NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE BENT 35 Robbie Weisz CEA153463B6D43D... 6/5/2017 SHEET NO. **REVISIONS** DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P.D.BRYANT / S.T.SANDOR _ DATE : <u>10/2016</u>

_ DATE : <u>11/2016</u>

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 36 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 6.2 3.1 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE _6.2 SF B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW _ COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 37 OF 96 STATE OF NORTH CAROLINA - SHOTCRETE REPAIR DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 36 Robbie Weisz 6/5/2017 REVISIONS S-43 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P.D.BRYANT / S.T.SANDOR _ DATE : <u>10/2016</u>

DATE : 11/2016

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 37 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 12.7 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. END VIEW ELEVATION WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 38 OF 96 STATE OF NORTH CAROLINA - SHOTCRETE REPAIR DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 37 Robbie Weisz 6/5/2017 REVISIONS S-44 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P.D.BRYANT / S.T.SANDOR _ DATE : <u>10/2016</u>


DATE : 11/2016

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 38 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME CF AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 12.6 6.3 PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. _ 4.4 SF <u> 5.3 SF</u> ELEVATION SOUTH FACE B-5941 PROJECT NO._ BERTIE END VIEW ELEVATION COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 39 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 38 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS S-45 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P.D.BRYANT / S.T.SANDOR _ DATE : <u>10/2016</u>

DATE : 11/2016

R.N.WEISZ



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 40 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 15.2 7.6 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE 2.7 SF_→ B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 41 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 40 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P.D.BRYANT / S.T.SANDOR _ DATE : <u>10/2016</u>

DATE : 11/2016

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 41 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME CF AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 17.9 9.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 6.7 SF— ELEVATION END VIEW WEST FACE SOUTH FACE 4.0 SF-\ B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 42 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 41 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P.D.BRYANT / S.T.SANDOR _ DATE : <u>10/2016</u>

DATE : 11/2016

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 42 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE AREA SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 15.6 PILES FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 3.3 SF— ELEVATION END VIEW WEST FACE SOUTH FACE 4.2 SF-PROJECT NO._ BERTIE END VIEW ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 43 OF 96 - SHOTCRETE REPAIR

> _ DATE : 11/2016 05-JUN-2017 13:13 R:\Structures\DGN\400_055_B5941_SMU_S45 THRU S102_BENTS35thru94.DGN gdickey

_ DATE : <u>10/2016</u>

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

B-5941

COUNTY

SHEET NO.

S-49

QUANTITIES

VOLUME CF

7.8

0.0

ACTUAL

VOLUME

AREA

SF

1.5 SF ─

SUBSTRUCTURE BENT 42

Robbie Weisz 6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS DATE:

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 43 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 44 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 43 Robbie Weisz 6/5/2017 REVISIONS S-50 DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

05-JUN-2017 13:13 R:\Structures\DGN\400_055_B5941_SMU_S45 THRU S102_BENTS35thru94.DGN gdickey

_ DATE : <u>10/2016</u>

DATE : 11/2016

P.D.BRYANT / S.T.SANDOR

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 44 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME CF AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.9 1.8 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO.__ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 45 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 44 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

_ DATE : <u>10/2016</u> DATE : 11/2016

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 45 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 46 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 45 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS


DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>10/2016</u>

DATE : 11/2016

P.D.BRYANT / S.T.SANDOR



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 47 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 35.6 17.8 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 11.4 SF⊸ ELEVATION END VIEW WEST FACE SOUTH FACE 6.8 SF → 5.8 SF-6.0 SF— B-5941 PROJECT NO.__ BERTIE ELEVATION _ COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 48 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 47 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

DATE : 11/2016

DRAWN BY : P.D. BRYANT / S. T. SANDOR DATE : 10/2016

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 48 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 18.6 9.3 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 5.3 SF-/ ELEVATION END VIEW WEST FACE SOUTH FACE 7.3 SF— 6.0 SF-B-5941 PROJECT NO.___ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 49 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 48 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS S-55

DATE:


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>10/2016</u> DATE : 11/2016

DRAWN BY : P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

05-JUN-2017 13:13 R:\Structures\DGN\400_055_B5941_SMU_S45 THRU S102_BENTS35thru94.DGN gdickey



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 50 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 0.0 0.0 PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION PROJECT NO. B-5941 BERTIE END VIEW COUNTY ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 51 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 50 - SHOTCRETE REPAIR 6/5/2017 REVISIONS S-57 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED DRAWN BY : P.D.BRYANT / S.T.SANDOR __ DATE : <u>10/2016</u>

DATE : 11/2016

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 51 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 8.3 CAP (VERTICAL FACE) 4.2 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 2.0 SF-\ <u>_6.3</u> SF END VIEW ELEVATION WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 52 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 51 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u>

DATE : 11/2016

P.D.BRYANT / S.T.SANDOR


REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 52 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO.____ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 53 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 52 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>10/2016</u> DATE : 11/2016

P.D.BRYANT / S.T.SANDOR



REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 54 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE VOLUME AREA SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 18.9 PILES FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 4.3 SF⊸ 4.2 SF-END VIEW ELEVATION WEST FACE SOUTH FACE 6.3 SF-/ PROJECT NO._ BERTIE END VIEW ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 55 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 54 - SHOTCRETE REPAIR Robbie Weisz

QUANTITIES

9.5

0.0

ACTUAL

VOLUME

AREA

SF

B-5941

REVISIONS

DATE:

6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

05-JUN-2017 13:14 R:\Structures\DGN\400_055_B5941_SMU_S45 THRU S102_BENTS35thru94.DGN gdickey

_ DATE : <u>10/2016</u> DATE : 11/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 55 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 14.9 7.5 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 10.0 SF-\ ELEVATION END VIEW WEST FACE SOUTH FACE 4.9 SF—— B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 56 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 55 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS

S-62

DATE:


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> DATE : 11/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY :



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 57 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 10.0 5.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 8.8 SF_ ELEVATION END VIEW WEST FACE SOUTH FACE 1.2 SF → B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 58 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 57 6/5/2017 REVISIONS S-64 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P.D.BRYANT / S.T.SANDOR __ DATE : <u>4/2016</u> DATE : 11/2016 R.N.WEISZ CHECKED BY : _____

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 58 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 0.0 0.0 PILES 0.0 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION SOUTH FACE B-5941 PROJECT NO._ BERTIE END VIEW ELEVATION COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 59 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 58 6/5/2017 REVISIONS

S-65

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> DATE : 11/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 59 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME CF AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. END VIEW ELEVATION WEST FACE SOUTH FACE 12.2 SF— B-5941 PROJECT NO.____ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 60 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 59 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS S-66 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>10/2016</u>

_ DATE : 11/2016

P.D.BRYANT / S.T.SANDOR

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 60 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 8.6 4.3 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE 8.6 SF-B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 61 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 60 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS S-67 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

05-JUN-2017 13:14 R:\Structures\DGN\400_055_B5941_SMU_S45 THRU S102_BENTS35thru94.DGN gdickey

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

_ DATE : <u>10/2016</u> DATE : 12/2016

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 61 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 5.6 2.8 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 5.6 SF— ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 62 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 61 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u>

_ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 62 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE AREA SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 8.9 PILES FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 2.6 SF-\ 6.3 SF ─ ELEVATION SOUTH FACE PROJECT NO._ BERTIE ELEVATION END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 63 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 62 - SHOTCRETE REPAIR Robbie Weisz

05-JUN-2017 13:14 R:\Structures\DGN\400_055_B5941_SMU_S45 THRU S102_BENTS35thru94.DGN gdickey

_ DATE : <u>10/2016</u> DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

6/5/2017

REVISIONS S-69 DATE:

B-5941

COUNTY

QUANTITIES

VOLUME CF

4.5

0.0

ACTUAL

VOLUME

AREA

SF

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 63 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 8.6 4.3 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE 4.3 SF ─ 4.3 SF— B-5941 PROJECT NO.___ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 64 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 63 - SHOTCRETE REPAIR Robbie Weisz 6/5/2017 REVISIONS

S-70

DATE:


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

__ DATE : <u>10/2016</u> __ DATE : <u>12/2016</u>



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 65 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE ACTUAL VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 10.5 5.3 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW SOUTH FACE WEST FACE 4.2 SF-6.3 SF—

√ B-5941 PROJECT NO.____ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 66 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 65 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>10/2016</u> _ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 66 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE AREA SHOTCRETE REPAIRS REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 8.7 PILES FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 1.0 SF ─ ELEVATION SOUTH FACE 7.7 SF— PROJECT NO._ BERTIE END VIEW ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 67 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR

REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL VOLUME CF AREA VOLUME SF 4.4 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND

SUBSTRUCTURE BENT 66

6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET NO. REVISIONS DATE:

B-5941

COUNTY

_ DATE : <u>10/2016</u> DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 67 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 25.1 12.6 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 4.3 SF-6.3 SF-ELEVATION END VIEW SOUTH FACE WEST FACE 9.2 SF-\ 5.3 SF—\ B-5941 PROJECT NO.____ BERTIE ELEVATION END VIEW _ COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 68 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 67 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

__ DATE : <u>10/2016</u> _ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 68 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 18.5 9.3 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 12.4 SF-\ 6.1 SF→ ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO.___ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 69 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 68 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> _ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 69 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 9.1 4.6 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 9.1 SF— ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 70 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 69 Robbie Weisz

05-JUN-2017 13:14 R:\Structures\DGN\400_055_B5941_SMU_S45 THRU S102_BENTS35thru94.DGN gdickey

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

_ DATE : <u>10/2016</u> _ DATE : 12/2016

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

6/5/2017

REVISIONS DATE:

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 70 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE VOLUME CF AREA SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 2.5 PILES FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION SOUTH FACE PROJECT NO._ BERTIE END VIEW ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 71 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 70 6/5/2017 REVISIONS

QUANTITIES

1.3

0.0

ACTUAL

VOLUME

AREA

SF

B-5941

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

_ DATE : <u>10/2016</u> DATE : 12/2016


REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 71 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 7.5 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. ELEVATION END VIEW WEST FACE SOUTH FACE 5.1 SF ─ 6.2 SF_→ 3.6 SF ─ B-5941 PROJECT NO._ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 72 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 71 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

_ DATE : <u>10/2016</u> DATE : 12/2016




REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 73 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 23.9 12.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 16.3 SF⊸ ELEVATION END VIEW WEST FACE SOUTH FACE 7.6 SF— B-5941 PROJECT NO._ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 74 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 73 6/5/2017 REVISIONS S-80 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 75 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 76 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 75 SHEET NO. 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

__ DATE : <u>10/2016</u> DATE : 12/2016

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 76 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 18.0 9.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE 16.8 SF─ B-5941 PROJECT NO._ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 77 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR BENT 76 Robbie Weisz 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> DATE : 12/2016

DRAWN BY : P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 77 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 17.4 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS" SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE 5.9 SF → 11**.**5 SF─ B-5941 PROJECT NO._ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 78 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 77 Robbie Weisz 6/5/2017 REVISIONS S-84 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

_ DATE : <u>10/2016</u> DATE : 12/2016

REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 78 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE VOLUME CF AREA SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 11.5 PILES FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 8.6 SF-ELEVATION SOUTH FACE ____1.8 SF 1.1 SF— PROJECT NO._ BERTIE END VIEW ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 79 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 78 CEA153463B6D43D... REVISIONS

QUANTITIES

5.8

0.0

ACTUAL

VOLUME

AREA

SF

B-5941

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ COUNTY

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

__ DATE : <u>10/2016</u> DATE : 12/2016

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 79 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO.____ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 80 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH - SHOTCRETE REPAIR SUBSTRUCTURE BENT 79 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 80 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 21.8 10.9 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE 8.2 SF¬ 5.6 SF-8.0 SF-B-5941 PROJECT NO.____ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 81 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 80 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ


REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 81 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 6.8 3.4 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. ELEVATION END VIEW WEST FACE SOUTH FACE 6.8 SF-B-5941 PROJECT NO._ BERTIE ELEVATION COUNTY END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 82 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 81 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

_ DATE : <u>10/2016</u> DATE : 12/2016



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 83 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 21.0 10.5 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 21.0 SF-ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO.____ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 84 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 83 SHEET NO. 6/5/2017 REVISIONS S-90 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u>

DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 84 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO.___ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 85 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 84 SHEET NO. 6/5/2017 REVISIONS

DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

__ DATE : <u>10/2016</u> __ DATE : <u>12/2016</u>

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 85 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION BY STRUCTURES FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 86 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR SUBSTRUCTURE BENT 85 SHEET NO. 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u> DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 86 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE AREA SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 21.4 PILES FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 2.1 SF ─\ 8.9 SF— END VIEW ELEVATION SOUTH FACE 3.6 SF ─\ PROJECT NO.____ BERTIE ELEVATION END VIEW EAST FACE NORTH FACE BRIDGE NO. SHEET 87 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION - SHOTCRETE REPAIR Robbie Weisz

REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL VOLUME CF AREA VOLUME SF 10.7 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND

SUBSTRUCTURE BENT 86

6/5/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET NO. REVISIONS S-93 DATE:

B-5941

COUNTY

_ DATE : <u>10/2016</u> DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ


REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 87 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 14.3 7.2 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 14.3 SF— ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 88 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH - SHOTCRETE REPAIR SUBSTRUCTURE BENT 87 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u>

_ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 89 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE SF SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 0.0 0.0 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. NO REPAIRS NOTED DURING INSPECTION. THE CONTRACTOR FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 90 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 89 Robbie Weisz 6/5/2017 REVISIONS

DATE:


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u>

_ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

CHECKED BY: R.N. WEISZ



REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 91 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME CF AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 6.4 3.2 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 6.4 SF_{\\\} ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO.___ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 92 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 91 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u>

_ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 92 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME CF AREA AREA VOLUME SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 4.5 2.3 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 4.5 SF-ELEVATION END VIEW WEST FACE SOUTH FACE B-5941 PROJECT NO._ BERTIE ELEVATION END VIEW COUNTY EAST FACE NORTH FACE BRIDGE NO. SHEET 93 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 92 SHEET NO. 6/5/2017 REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

_ DATE : <u>10/2016</u>

_ DATE : 12/2016

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 93 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE ESTIMATE VOLUME CF AREA SHOTCRETE REPAIRS SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. 13.4 PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 8.4 SF_→ 3.9 SF ─\ END VIEW ELEVATION WEST FACE SOUTH FACE PROJECT NO._ BERTIE END VIEW ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 94 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE - SHOTCRETE REPAIR BENT 93 Robbie Weisz CEA153463B6D43D...
6/5/2017 REVISIONS DATE:

ACTUAL

VOLUME

AREA

SF

B-5941

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

COUNTY

SHEET NO.

S-100

P.D.BRYANT / S.T.SANDOR

R.N.WEISZ

CHECKED BY : _____

__ DATE : <u>10/2016</u> DATE : 12/2016

REPAIR QUANTITY TABLE NOTES: QUANTITIES REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN REPAIRS BENT 94 WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ESTIMATE ACTUAL INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE VOLUME AREA AREA VOLUME SHOTCRETE REPAIRS SĒ SF REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE 27.3 13.7 REPAIR QUANTITY TABLE. PILES 0.0 FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS"SHEET. VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 10.6 SF-END VIEW ELEVATION SOUTH FACE WEST FACE _12.6 SF 4.1 SF---B-5941 PROJECT NO.____ BERTIE COUNTY END VIEW ELEVATION EAST FACE NORTH FACE BRIDGE NO. SHEET 95 OF 96 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION SUBSTRUCTURE BENT 94 - SHOTCRETE REPAIR Robbie Weisz CEA153463B6D43D...
6/5/2017

REVISIONS

DATE:


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P. D. BRYANT / S. T. SANDOR DATE : 10/2016

R.N.WEISZ

CHECKED BY : _____

_ DATE : 12/2016



REPAIR QUANTITY TABLE QUANTITIES REPAIRS END BENT 2 ESTIMATE ACTUAL AREA VOLUME AREA VOLUME SHOTCRETE REPAIRS SF CAP (VERTICAL FACE) 13.3 CAP (HORIZONTAL, CORNER) 0.0 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP AND COLUMN REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.

FOR "EPOXY COATING", SEE SPECIAL PROVISIONS.



- SHOTCRETE REPAIR

B-5941 PROJECT NO.____ BERTIE _ COUNTY BRIDGE NO.

SHEET 96 OF 96

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUBSTRUCTURE END BENT 2

Robbie Weisz 6/5/2017

SHEET NO. REVISIONS S-102 DATE:


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED


DATE : 3/2017 DATE : 4/2017

M.A.LEE

R.WEISZ

DRAWN BY :





SECTION B-B (IF MORE THAN HALF THE CIRCUMFERENCE OF REINFORCING BAR IS EXPOSED DURING THIS PROCESS, REMOVE ADDITIONAL CONCRETE BEHIND THE BAR. THIS DOES NOT APPLY TO PRESTRESSED STRANDS.)

SAW CUT 1/2" DEEP -AROUND PERIMETER GIRDER REPAIR (TYP.)

NOTES

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL OR PRESTRESSED TENDONS.

CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL AND PRESTRESSED TENDONS SHALL NOT BE DAMAGED.

CONTRACTOR SHALL SAW CUT THE REPAIR AREAS SO THAT THE CORNERS ARE SQUARE AS INDICATED ON THE DETAILS.

FOR REPAIRS TO PRESTRESSED GIRDERS, SEE SPECIAL PROVISIONS.

FOR SHOTCRETE REPAIRS. SEE SPECIAL PROVISIONS.


GIRDER REPAIR MATERIAL MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.



DAMAGED AREA

SECTION C-C

(ALL UNSOUND CONCRETE MUST BE REMOVED. HOWEVER, PRESTRESSED STRANDS SHOULD NOT BE DISTURBED UNLESS ABSOLUTELY NECESSARY. USE EXTREME CARE TO NOT DAMAGE STRANDS. PRESTRESSED STRANDS NOT SHOWN FOR CLARITY.)



BENT CAP REPAIRS

CAP REPAIR

CONCRETE GIRDER REPAIR DETAIL

B-5941 PROJECT NO. ____ BERTIE COUNTY BRIDGE NO.

SHEET 1 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

TYPICAL CAP & COLUMN & GIRDER REPAIR DETAILS


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

6/5/2017

039163

			SHEET NO.				
)	NO.	BY:	DATE:	NO.	BY:	DATE:	S-103
1	1			3			TOTAL SHEETS
	2			4			

R.N.WEISZ DATE : 12/2016 DRAWN BY DATE : 3/2017 G.DICKEY CHECKED BY : ___



SECTION D-D

— REMOVE 1"(MIN.) BEHIND ANY EXPOSED REBAR SHOTCRETE REPAIR — (TYP.)

SECTION E-E

INTERIOR DIAPHRAGM REPAIR DETAILS

NOTES

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL OR PRESTRESSED TENDONS.

CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF $\frac{1}{2}$ " BUT REINFORCING STEEL AND PRESTRESSED TENDONS SHALL NOT BE DAMAGED.


CONTRACTOR SHALL SAW CUT THE REPAIR AREAS SO THAT THE CORNERS ARE SQUARE AS INDICATED ON THE DETAILS.

GIRDER REPAIR MATERIAL MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.



DAMAGED AREA



BRIDGE NO.

BERTIE

PROJECT NO.____

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

B-5941

_ COUNTY

TYPICAL UNDERDECK & DIAPHRAGM REPAIR DETAILS

6/5/2017

Robbie Weisz

SEAL 039163


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS S-104 DATE:

UNDERDECK DETAILS

* REFER TO REPAIR TABLE ON SHT'S S-5 & S-6 FOR SPECIFIED REPAIR MATERIAL. IF EPOXY COATING IS SPECIFIED REFER TO EPOXY COATING SPECIAL PROVISION.


R.WEISZ DATE : 12/2016 DRAWN BY DATE : 3/2017 G.DICKEY CHECKED BY : ___




EXISTING GIRDER AND EXPANSION BEARING

(SEE NOTES)

EACH 752



(SEE NOTES)



SECTION A-A

B-5941 PROJECT NO.____ BERTIE _ COUNTY

BRIDGE NO.

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

CLEANING AND

Robbic Weisz

N. W. T.	PAINTING	ŌF	BEARINGS
ocuSigned by:			


6/5/2017			REVI:	SIO	NS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-105
FINAL UNLESS ALL	١IJ١			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			


__ DATE : <u>3/2017</u> __ DATE : <u>4/2017</u> M.A.LEE DRAWN BY : R.WEISZ CHECKED BY : __


PILE ENCAPSULATION						
		REPAIR	LENGTH			
BENT	PILE	EST. LF	ACTUAL LF			
1	9	3				
3	3	3				
4	1	3				
7	1	3				
7	2	3				
7	3	3				
7	4	3				
7	5	3				
7	6	3				
7	7	3				
7	8	3				
7	9	3				
7	10	3				
7	11	3				
7	12	3				
11	1	5				
11	2	5				
12						
	1	6				
12	2	6				
12	3	6				
12	4	6				
12	5	6				
12	6	6				
12	7	6				
12	8	6				
12	9	6				
12	10	6				
12	11	6				
12	12	6				
14	2	7				
16	6	7				
16	7	7				
18	1	7				
18	2	7				
18	3	7				
18	4	7				
18	5	7				
18	6	7				
18	7	7				
18	8	7				
18	9	7				
18	10	7				
18	11	7				
18	12	7				
18	13	7				

PILE ENCAPSULATION							
<u> </u>	TILE ENG						
55			LENGTH				
BENT	PILE	EST. LF	ACTUAL LF				
18	14	7					
18	15	7					
18	16	7					
18	17	7					
18	18	7					
18	19	7					
18	20	7					
18	21	7					
19	6	3					
19	7	3					
21	1	4					
23	1	5					
23	2	5					
23	3	5					
23	4	5					
23	6	5					
27	4	7					
27	11	7					
28	1	7					
29	1	7					
29	5	7					
30	4	7					
30	6	7					
30	7	7					
31	4	7					
36	1	6					
36	2	6					
36	3	6					
36	4	6					
36	5	6					
36	6	6					
39	1	6					
44	1	7					
44	2	7					
44	3	7					
44	4	7					
44	5	7					
44	6	7					
46	2	6					
46	4	6					
48	3	5					
48	6	5					
59	6	7					
60	2	7					
66		7	l l				


P.	ILE ENC	APSULATI	ON
		REPAIR	LENGTH
BENT	PILE	EST.	ACTUAL
		LF	LF
66	6	7	
67	1	7	
67	2	7	
67	3	7	
67	4	7	
67	5	7	
69	3	6	
69	4	6	
69	5	6	
78	3	6	
78	7	6	
80	2	7	
80	3	7	
80	4	7	
82	4	7	
82	5	7	
82	6	7	
82	7	7	
85	1	7	
85	6	7	
86		7	
86	1	7	
86	5 6	7	
88	1	7	
88		7	
88	2	7	
90	3	7	
90			
91	6	7	
93		7	
93	6	7	
94	1	5	
J-1	1	<u>, , , , , , , , , , , , , , , , , , , </u>	








FOR BT'S 17&18



FOR BT'S 35-37,39-41,43-45, 47-49,51-53,55-57,59-61,63-65, 67-69,71-73,75-77,79-81, 83-85,87-89,91-92,94



FOR BT'S 38,42,46,50,54,58,62,66,70,74,78,82,86,90,93

TYPICAL PILE LAYOUT

SUMMAR	Y OF QUANT	TITIES			
	QUANTITIES				
	ESTIMATE	ACTUAL			
BENTS 1 - 94	LF	LF			
PILE ENCAPSULATION	736				

SEE SHT S-107 & S-108 FOR PILE ENCAPSULATION.
FOR PILE ENCAPSULATION, SEE SPECIAL PROVISIONS.

PROJECT NO. B-5941

BERTIE COUNTY

BRIDGE NO. 7

DEPARTMENT OF TRANSPORTATION
RALEIGH

PILE ENCAPSULATION REPAIR TABLES

SHEET NO.


Robbic Weisz CEA153463B6D43D...

SEAL * 039163

CHICINEER

CEA153463B6D43D						_
6/5/2017			REVI	SIO	NS	
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	Ī
FINAL UNLESS ALL	1			3		Ī
SIGNATURES COMPLETED	2			4		Ī

DRAWN BY: R.WEISZ DATE: 12/16
CHECKED BY: G.DICKEY DATE: 04/17



NOTES:

ALL EXISTING PILES ARE 22"OCTOGONAL PRESTRESSED CONCRETE PILES.

SEE PILE ENCAPSULATION TABLE FOR ESTIMATED ENCAPSULATION LENGTH.

FOR PILE ENCAPSULATION AT BENTS 1-34, PILE ENCAPSULATION SHALL START AT THE BOTTOM OF THE PILE FOOTING AND EXTEND 5 FEET BELOW MEAN WATER ELEVATION OR 1 FOOT BELOW MUDLINE, WHICHEVER COMES FIRST.

FOR PILE ENCAPSULATION AT BENTS 35-94, PILE ENCAPSULATION SHALL START 2 FEET ABOVE MEAN WATER ELEVATION AND EXTEND 5 FEET BELOW MEAN WATER ELEVATION OR 1 FOOT BELOW MUDLINE, WHICHEVER COMES FIRST.

REPAIR SEQUENCES

22"

JACKET

SECTION A-A

1. AFTER SURFACE PREPARATION, PLACE JACKET IN PROPER LOCATION AROUND PILE AND SEAL LONGITUDINAL SEAMS (SEE DETAIL "A"). INSTALL TEMPORARY BRACING.

— VERTICAL SEAMS

-SEE DETAIL "A"-

TRANSLUCENT FIBERGLASS JACKET

1/2"FIXED STANDOFF PER DETAIL OR USE

ADJUSTABLE STANDOFF

MAINTAIN MINIMUM GROUT THICKNESS OF 1/2". DISTANCE

BETWEEN STANDOFFS NOT TO

LONGITUDINAL DIRECTION

AND 12" IN THE VERTICAL

PER DETAIL "B"

LOCATE STANDOFFS

EXCEED 18" IN THE

DIRECTION.

AS REQUIRED TO

- 2. CONFIRM SPACING BETWEEN JACKET AND PILE. INSTALL BOTTOM SEAL (SEE DETAIL "D"). ALLOW BOTTOM SEAL TO CURE APPX. 4 HOURS.
- 3. ATTACH GROUT HOSE TO LOWERMOST INJECTION PORT AND PUMP A-P-E GROUT FOR 30-sec. CHECK FOR LEAKS ALONG SEAMS AND BOTTOM SEAL. (OPTIONALLY ALLOW THIS GROUT TO CURE AND PROCEED WITH GROUT INJECTION FROM 2nD PORT.)
- 4. PLUG UPPER INJECTION PORTS AND PUMP GROUT INTO LOWER PORT UNTIL GROUT REACHES TOP OF JACKET. ONLY USE UPPER PORTS IF INJECTION BECOMES DIFFICULT.


PROJECT NO. B-5941

BERTIE COUNTY

BRIDGE NO. 7

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION



CEA153463B6D43D...


PILE ENCAPSULATION


DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

6/5/2017

			SHEET NO.					
<u>- D</u>	NO.	BY:	DATE:	NO.	BY:	DATE:	S-107	
ַ	1			3			TOTAL SHEETS	
	2			<u>a</u>				

DRAWN BY: R.WEISZ DATE: 01/17
CHECKED BY: G. DICKEY DATE: 04/17







05-JUN-2017 13:38
R:\Structures\DGN\BERTIE_7_FENDER.dgn


CHECKED BY : __

FINAL UNLESS ALL SIGNATURES COMPLETED





05-JUN-2017 13:38 R:\Structures\DGN\BERTIE_7_FENDER.dgn gdickey



B-5941 PROJECT NO._ BERTIE COUNTY_ BRIDGE NO.

- 15"TIMBER PILES (TYP.)

−6 X 19-5⁄8″Ø GALVANIZED CABLE

___78″Ø × 1′-3″ DOME HEAD SPIKE

(TYP)

SHEET 1 OF 2

OF ESSION

21271

3 CHOINEES

6/5/2017

VIEW Y-Y

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

FENDER SYSTEM

FENDER SYSTEM DETAILS

Greg Dickey -- 884E46B8CE5B4B6... SHEET NO. **REVISIONS** F-4 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

PILE CLUSTERS CONTAINING THREE PILES SHALL BE WRAPPED WITH THREE TURNS OF 6 X 19-5/8" Ø GALVANIZED CABLE AT 1'-1" AND 3'-9" FROM TOP OF CLUSTER. CABLE SHALL BE SECURED WITH 5/8" X 4"
GALVANIZED STAPLES AND TWO WIRECLAMPS AT EACH END.

VIEW X-X


DATE : 10/2014 M.A.LEE DRAWN BY : W.M.CLARKE DATE : 10/2014 CHECKED BY : .

WALE. (FIELD VERIFY.)

15" VERT. TIMBER PILE ——)

SECTION A-A

 $\frac{7}{8}$ "Ø × 2'-0" DOME HEAD BOLT (TYP.)





DETAIL OF 7-PILE CLUSTER (DOLPHINS)

PILES 15' FROM ENDS OF FENDER SYSTEM

SIX (6) OUTSIDE PILES TO BE EQUALLY SPACED ON A 6 FT. CIRCLE AT TOP AND BATTERED AT 11/2:12.

DRAW THE PILES TOGETHER AT THE TOP AND WRAP WITH 3 TURNS OF 6 X 19-5/8" Ø GALVANIZED CABLE AT 1'-6" AND 5'-6" FROM THE TOP OF THE CLUSTER. CABLE SHALL BE SECURED WITH 5/8" X 4" GALVANIZED STAPLES AND THREE WIRE ROPE CLAMPS AT EACH END.





ALL DRIVE SPIKE HEADS MUST BE IN FULL CONTACT WITH THE SURFACE OF THE TIMBER PILES OR WALES.

STRUCTURAL TIMBER							
ITEM UNIT LENGTH SIZE NO. TOTAL							
15"TREATED TIMBER PILE	LIN.FT.	60'-0"	15"	122	7,320′-0″		
10"× 6"TREATED LUMBER	LIN.FT.	16′-0"	6" X 10"	96	1,536′-0″		

STRUCTURAL HARDWARE							
(GALVANIZED)							
ITEM	UNIT	NO.	TOTAL				
6 X 19 - 5⁄8″Ø GALVANIZED CABLE	LIN.FT.		2,350′-0″				
5% "CABLE CLAMPS	LBS.	130	130 LBS				
%"X 4"STAPLES	83 LBS/100	820	681 LBS				
7_8 " Ø X 15" DOME HEAD DRIVE SPIKE	240 LBS/100	108	260 LBS				
6d COMMON NAIL	BOX	1	1 LBS.				
7_8 " \varnothing X 24"DOME HEAD TIMBER BOLT	427 LBS/100	308	1,315 LBS				
O.G. WASHER	150 LBS/100	308	462 LBS.				
₹ HEAVY HEX NUT	30 LBS/100	308	93 LBS.				

PROJECT NO. B-5941

COUNTY BERTIE

BRIDGE NO. 7

SHEET 2 OF 2

SEAL 21271

COPY W. DICKERTON DOCUSION DE LA COMPANIA DEL COMPANIA DEL COMPANIA DE LA COMPANIA DE LA COMPANIA DE LA COMPANIA DEL COMPANI

DEPARTMENT OF TRANSPORTATION
RALEIGH
FENDER SYSTEM

FENDER SYSTEM DETAILS

REVISIONS

BY: DATE: NO. BY: DATE: NO. BY: DATE: SHEET NO. SHEET S

 DRAWN BY :
 M.A.LEE
 DATE :
 10/2014

 CHECKED BY :
 W.M.CLARKE
 DATE :
 10/2014