# This electronic collection of documents is provided for the convenience of the user and is Not a Certified Document –

The documents contained herein were originally issued and sealed by the individuals whose names and license numbers appear on each page, on the dates appearing with their signature on that page.

This file or an individual page shall not be considered a certified document.



### STATE OF NORTH CAROLINA


### DIVISION OF HIGHWAYS

# HYDE COUNTY

SHEET TOTAL NO. SHEETS N.C. B-5942 46481.1.1 46481.3.1 CONST.

BRIDGE #20 ON US264 OVER INTERCOASTAL WATERWAY LOCATION:

TYPE OF WORK: BRIDGE PRESERVATION - GIRDER AND SUBSTRUCTURE REPAIRS







DESIGN DATA HYDE COUNTY ADT 2013 = 2,200

PROJECT LENGTH HYDE COUNTY BRIDGE #20 = 0.29 MILE

Prepared in the Office of: STRUCTURES MANAGEMENT UNIT NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

2012 STANDARD SPECIFICATIONS

LETTING DATE: JULY 19, 2017

TIMOTHY M. SHERRILL, P.E.





# STATE OF NORTH CAROLINA DIVISION OF HIGHWAYS

### HYDE COUNTY

STATE	STA	TE PROJECT REPERENCE NO.		SHEET NO.	TOTAL SHEETS
N.C.	B-5942			1A	
STAT	E PROJ. NO.	F. A. PROJ. NO.		DESCRIPT	NOF
46	481.1.1			P.E	
464	481.3.1			CON	ST.
				· ·	Ü
l			Г		

LOCATION: BRIDGE #20 ON US264 OVER INTERCOASTAL WATERWAY

TYPE OF WORK: BRIDGE PRESERVATION - GIRDER AND SUBSTRUCTURE REPAIRS


### INDEX OF SHEETS


1 TITLE SHEET


1A INDEX OF SHEETS

S-1 THRU S-30 STRUCTURAL PLANS - BRIDGE NO. 20

SN STANDARD NOTES







### NOTES

EXISTING DIMENSIONS AND BRIDGE CONDITION ARE FROM BEST INFORMATION AVAILABLE. THE CONTRACTOR SHALL FIELD VERIFY THE INFORMATION SHOWN ON THE PLANS AND NOTIFY THE ENGINEER IF ACTUAL DIMENSIONS AND CONDITIONS DIFFER.

FOR SUBMITTAL OF WORKING DRAWINGS, SEE SPECIAL PROVISIONS.

FOR FALSEWORK AND FORMWORK, SEE SPECIAL PROVISIONS.

FOR CRANE SAFETY, SEE SPECIAL PROVISIONS.

FOR GROUT FOR STRUCTURES, SEE SPECIAL PROVISIONS.

FOR UNDER STRUCTURE WORK PLATFORM, SEE SPECIAL PROVISIONS.

IT IS THE CONTRACTORS RESPONSIBILITY TO FOLLOW ALL STATE AND FEDERAL SAFETY REQUIREMENTS.

FOR CONTROL OF TRAFFIC AND LIMITS ON PHASING OF CONSTRUCTION, SEE TRANSPORTATION MANAGEMENT PLANS.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR REPAIRS TO PRESTRESSED CONCRETE GIRDERS, SEE SPECIAL PROVISIONS.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR EPOXY COATING POPOUTS, SEE SPECIAL PROVISIONS.

FOR SPLICING OF PRESTRESSING STRANDS, SEE SPECIAL PROVISIONS.

	TOTAL BILL OF MATERIAL									
SHOTCRETE REPAIRS	EPOXY RESIN INJECTION	REPAIRS TO PRESTRESSED CONCRETE GIRDERS	EPOXY COATING	EPOXY COATING POPOUTS	TEXTURED COATING	△ SPLICING OF PRESTRESSING STRANDS				
CU.FT.	LIN.FT.	CU.FT.	SQ.FT.	EA.	SO.FT.	EACH				
139.2	84.5	192.5	9,130	285	1,072	10				

<sup>^</sup> A QUANTITY IS NOT ANTICIPATED. A TOKEN PAY ITEM IS INDICATED FOR PRICING PURPOSES, IN CASE UNANTICIPATED REPAIRS ARE ENCOUNTERED.

B-5942 PROJECT NO. \_ \_ COUNTY 20 BRIDGE NO.

Brandon Grun

I HEREBY CERTIFY THESE PLANS ARE THE AS-BUILT PLANS

6/7/2017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

GENERAL DRAWING FOR BRIDGE ON U.S. 264 OVER INTRACOASTAL WATERWAY

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION


REVISIONS S-3


R.W. WRIGHT DATE : 10/15 DATE : 10/15 DRAWN BY : \_ P.C.BREWER CHECKED BY :

DATE : \_

DESIGN ENGINEER OF RECORD:

02-JUN-2017 13:00 A:\TIPProjects-B\B5942\Structures\B5942\_SMU\_ FinalPlans.dgn





GIRDER REPAIR LOCATIONS REPAIR SIZE LABEL DISTANCE ALONG SPAN SPAN GIRDER LOCATION BTM. OF GDR. 11" X 1'-4" 0'-0"

NOTE: FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY BRIDGE NO.\_

SHEET 2 OF 11

Brandon Green SEAL 7 037403


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 2

3/7/2017

REVISIONS SHEET NO. S-5 DATE: DATE: NO. BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_ DATE : <u>10-16</u> B. L. GREEN CHECKED BY : .



	GIRDER REPAIR LOCATIONS									
				REPAIR SIZE	LABEL					
3	4	28′-10″	BTM. OF GDR.	13'-0" X 2'-2"	А					
3	4	40′-7″	BTM. OF GDR.	6" X 6"	В					
3	4	42′-7"	BTM.OF GDR.	2'-0" X 10"	С					
3	4	44'-7"	BTM. OF GDR.	8" X 6"	D					
3	4	46′-7"	BTM. OF GDR.	1'-4" X 2'-2"	E					
3	4	48′-7″	BTM. OF GDR.	1'-0" X 6"	F					
3	4	51′-7″	BTM. OF GDR.	9″ X 6″	G					

GIRDER POPOUT LOCATIONS									
SPAN	GIRDER	BAY	LOCATION	REPAIR NUMBER/SIZE					
3	1	1	WEB	6 @ 3" X 3"					
3	2	1	WEB	14 @ 3" X 3"					
3	3	2	WEB	10 @ 3" X 3"					
3	3	3	WEB	1 @ 3" X 3"					
3	4	3	WEB	2 @ 3" X 3"					
3	4	4	WEB	5 @ 3" X 3"					
3	5	4	WEB	1 @ 3" X 1'-0"					
3	5	5	WEB	19 @ 3" X 3"					
3	6	5	WEB	7 @ 3" X 3"					

(FOR CLARITY, POPOUTS ARE NOT SHOWN IN PLAN VIEW )

NOTE:

FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

FOR EPOXY COATING POPOUTS, SEE SPECIAL PROVISION.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY BRIDGE NO.\_

SHEET 3 OF 11

Brandon Grun SEAL 7 037403


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 3

3/7/2017

		REVISIONS				SHEET NO.	
DCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-6
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			30

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_\_ DATE : \_\_10-16 B. L. GREEN CHECKED BY : .



GIRDER REPAIR LOCATIONS										
SPAN	GIRDER	DISTANCE ALONG SPAN	LOCATION	REPAIR SIZE	LABEL					
4	1	0'-0"	BTM. OF GDR.	4" X 6"	Α					
4	1	54'-2"	BTM. OF GDR.	7" X 1'-3"	В					
4	1	92'-0"	BTM. OF GDR.	3" X 5"	С					
4	2	0'-0"	BTM. OF GDR.	4" X 1'-0"	D					
4	2	42′-7″	BTM. OF GDR.	5" X 6"	E					
4	2	92'-0"	BTM. OF GDR.	4" X 1'-4"	F					
4	3	42'-7"	BTM. OF GDR.	1'-0" X 1'-0"	G					
4	3	48'-7"	BTM. OF GDR.	1'-1" X 1'-6"	Н					
4	5	0'-0"	BTM.OF GDR.	1'-0" X 1'-0"	I					
4	5	41'-0"	BTM. OF GDR.	3" X 3"	J					
4	5	43'-0"	BTM. OF GDR.	1'-1" X 9"	K					
4	5	49′-0″	BTM. OF GDR.	8'-6" X 1'-8"	L					
4	6	6′-0″	BTM. OF GDR.	1'-8" X 2'-3"	М					
4	6	40′-0″	BTM. OF GDR.	1'-0" X 1'-0"	N					
4	6	41'-0"	BTM. OF GDR.	6" X 6"	0					
4	6	46′-0"	BTM. OF GDR.	2'-8" X 1'-0"	Р					

GIRDER POPOUT LOCATIONS								
SPAN	GIRDER	BAY	LOCATION	REPAIR NUMBER/SIZE				
4	1	1	WEB	3 @ 3" X 3"				
4	2	1	WEB	9 @ 3" X 3"				
4	3	2	WEB	3 @ 3" X 3"				
4	6	5	WEB	7 @ 3" X 3"				
4	6	EXT.	WEB	2 @ 3" X 3"				

(FOR CLARITY, POPOUTS ARE NOT SHOWN IN PLAN VIEW )

NOTE:

FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

FOR EPOXY COATING POPOUTS, SEE SPECIAL PROVISION.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY BRIDGE NO.\_

SHEET 4 OF 11

Brandon Green SEAL 7 037403


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 4

3/7/2017

REVISIONS SHEET NO. S-7 DATE: NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_\_ DATE : \_\_10-16 B. L. GREEN CHECKED BY : .



GIRDER REPAIR LOCATIONS								
SPAN	GIRDER	DISTANCE ALONG SPAN	LOCATION	REPAIR SIZE	LABEL			
5	1	40′-7"	BTM. OF GDR.	5'-6" X 1'-4"	Α			
5	1	50′-7″	BTM. OF GDR.	2'-3" X 1'-4"	В			
5	1	62′-2″	BTM. OF GDR.	1'-10" X 1'-2"	С			
5	1	71'-2"	BTM. OF GDR.	3'-4" X 1'-1"	D			
5	1	73′-7"	BTM. OF GDR.	2'-0" X 1'-2"	E			
5	2	88′-0″	BTM. OF GDR.	1′-6″ X 5″	F			
5	2	90′-0″	BTM. OF GDR.	6" X 4"	G			
5	2	92′-0″	BTM. OF GDR.	4" X 4"	Н			
5	3	12'-0"	BTM. OF GDR.	3'-6" X 1'-0"	I			
5	3	13'-0"	BTM. OF GDR.	6" X 5"	J			
5	3	16'-0"	BTM. OF GDR.	6" X 5"	K			
5	3	30′-7″	BTM. OF GDR.	4'-0" X 1'-0"	L			
5	4	92′-0″	BTM. OF GDR.	6" X 6"	М			
5	5	89′-0″	BTM. OF GDR.	6" X 6"	N			
5	5	92′-0″	BTM. OF GDR.	6" X 6"	0			
5	6	6′-0″	BTM. OF GDR.	4'-0" X 1'-0"	Р			
5	6	12'-0"	BTM. OF GDR.	4" X 4"	Q			
5	6	16'-0"	BTM. OF GDR.	10'-6" X 1'-3"	R			
5	6	48′-7″	BTM. OF GDR.	32'-0" X 1'-6"	S			
5	6	92'-0"	BTM. OF GDR.	6" X 3"	Т			

GIRDER POPOUT LOCATIONS								
SPAN	GIRDER	BAY	LOCATION	REPAIR NUMBER/SIZE				
5	1	EXT.	WEB	12 @ 3" X 6"				
5	1	1	WEB	16 @ 3" X 6"				
5	2	1	WEB	9 @ 3" X 6"				
5	2	2	WEB	23 @ 3" X 3"				
5	3	2	WEB	8 @ 3" X 6"				
5	3	3	WEB	22 @ 3" X 3"				
5	4	3	WEB	3 @ 3" X 3"				
5	4	4	WEB	13 @ 3" X 3"				
5	5	5	WEB	1 @ 3" X 3"				
(EOR CI	ARTTY PO	POLITS	ARE NOT SHO	WN TN				

(FOR CLARITY, POPOUTS ARE NOT SHOWN IN PLAN VIEW )

NOTE:

FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

FOR EPOXY COATING POPOUTS, SEE SPECIAL PROVISION.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY BRIDGE NO.\_

SHEET 5 OF 11

Brandon Green SEAL 7 037403


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 5

3/7/2017

SHEET NO. REVISIONS S-8 DATE: NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_\_ DATE : \_\_10-16 B. L. GREEN CHECKED BY : .



GIRDER REPAIR LOCATIONS									
SPAN	GIRDER	DISTANCE ALONG SPAN	LOCATION	REPAIR SIZE	LABEL				
6	1	2'-0"	BTM. OF GDR.	9" X 10"	Α				
6	1	6′-0″	BTM. OF GDR.	1'-4" X 1'-4"	В				
6	1	9'-0"	BTM. OF GDR.	9'-0" X 1'-6"	С				
6	1	46′-0″	BTM. OF GDR.	26'-0" X 1'-8"	D				
6	2	92′-1″	BTM.FLG.	3" X 9"	E				
6	3	0'-0"	BTM. OF GDR.	6" X 1'-8"	F				
6	3	90′-1″	BTM. OF GDR.	4" X 4"	G				
6	4	24'-7"	BTM. OF GDR.	4" X 4"	Н				
6	4	28′-7″	BTM. OF GDR.	3'-4" X 1'-7"	I				
6	5	0'-0"	BTM. OF GDR.	8" X 1'-0"	J				
6	5	11'-0"	BTM. OF GDR.	1'-3" X 9"	K				
6	5	29'-7"	BTM. OF GDR.	9" X 1'-0"	L				
6	5	31'-7"	BTM. OF GDR.	11" X 7"	М				
6	6	0'-0"	BTM. OF GDR.	6" X 6"	N				
6	6	11'-6"	BTM. OF GDR.	12'-0" X 1'-4"	0				
6	6	35′-7"	BTM. OF GDR.	12'-0" X 2'-2"	Р				
6	6	61'-2"	BTM. OF GDR.	8'-0" X 1'-4"	Q				

GIRDER POPOUT LOCATIONS								
SPAN	GIRDER	BAY	LOCATION	REPAIR NUMBER/SIZE				
6	1	1	WEB	2 @ 3" X 3"				
6	2	2	WEB	2 @ 3" X 3"				
6	3	2	WEB	12 @ 3" X 3"				
6	3	3	WEB	12 @ 3" X 3"				
6	4	3	WEB	39 @ 3" X 3"				
6	5	4	WEB	11 @ 3" X 3"				
6	5	5	WEB	7 @ 3" X 3"				
6	6	5	WEB	4 @ 3" X 3"				
COD CL	ADTTV DO	DOLLTS	ADE NOT SHO	WNI TNI				

(FOR CLARITY, POPOUTS ARE NOT SHOWN IN PLAN VIEW )

NOTE:

FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

FOR EPOXY COATING POPOUTS, SEE SPECIAL PROVISION.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY BRIDGE NO.\_

SHEET 6 OF 11

—Docusigned by: Brandon Grun SEAL 7 037403


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 6

3/7/2017

SHEET NO. REVISIONS S-9 DATE: NO. BY: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_\_ DATE : \_\_10-16 B. L. GREEN CHECKED BY : .



	GIRDER REPAIR LOCATIONS										
SPAN	GIRDER	DISTANCE ALONG SPAN	REPAIR SIZE	LABEL							
10	1	0'-0"	BTM. OF GDR.	4" X 6"	А						
10	1	34'-1"	BTM. OF GDR.	56'-2" X 2'-2"	В						
10	3	56′-2″	BTM.OF GDR.	6" X 6"	С						
10	3	61'-2"	BTM. OF GDR.	6" X 6"	D						
10	4	0'-0"	BTM. OF GDR.	6" X 1'-8"	Е						
10	5	92′-1″	BTM. OF GDR.	3" X 1'-4"	F						
10	6	92'-1"	BTM. OF GDR.	3" X 2'-0"	G						

NOTE: FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

> B-5942 PROJECT NO.\_ HYDE \_ COUNTY 20 BRIDGE NO.\_

SHEET 7 OF 11

Brandon Grun


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 10

3/7/2017

REVISIONS SHEET NO. S-10 DATE: DATE: NO. BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_ DATE : <u>10-16</u> B. L. GREEN CHECKED BY : .



GIRDER REPAIR LOCATIONS							
SPAN	GIRDER	DISTANCE ALONG SPAN	LOCATION	REPAIR SIZE	LABEL		
11	3	29'-7"	BTM. OF GDR.	1'-4" X 2'-2"	Α		
11	3	33'-7"	BTM. OF GDR.	7" X 2'-2"	В		
11	3	49'-2"	BTM. OF GDR.	1'-0" X 4"	С		
11	6	20′-7″	BTM. OF GDR.	2'-8" X 1'-1"	D		
11	6	33'-7"	BTM. OF GDR.	1'-8" X 6"	Е		
11	6	36′-7″	BTM. OF GDR.	3'-9" X 1'-1"	F		
11	6	42'-7"	BTM. OF GDR.	6" X 6"	G		
11	6	43′-7″	BTM. OF GDR.	11" X 7"	Н		
11	6	51'-2"	BTM. OF GDR.	2'-4" X 1'-2"	I		

NOTE:

FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY 20 BRIDGE NO.\_

SHEET 8 OF 11

Brandon Grun


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 11

3/7/2017

REVISIONS SHEET NO. S-11 DATE: DATE: NO. BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_\_ DATE : \_\_10-16\_ B. L. GREEN CHECKED BY : \_



GIRDER REPAIR LOCATIONS							
SPAN	GIRDER	DISTANCE ALONG SPAN	LOCATION	REPAIR SIZE (L X W )	LABEL		
12	1	13'-6"	BTM. OF GDR.	7" X 1'-2"	Α		
12	1	39'-7"	BTM. OF GDR.	1'-2" X 11"	В		
12	1	55′-2″	BTM. OF GDR.	5'-0" X 1'-2"	С		
12	1	59′-2″	BTM. OF GDR.	1'-4" X 11"	D		
12	1	66′-2″	BTM. OF GDR.	1'-4" X 11"	Е		
12	2	29′-7″	BTM.OF GDR.	6" X 4"	F		
12	2	92'-0"	BTM. OF GDR.	3" X 3"	G		
12	5	3'-0"	BTM. OF GDR.	4" X 6"	Н		
12	6	30′-7″	BTM. OF GDR.	43'-2" X 2'-2"	I		
12	6	92′-0"	BTM. OF GDR.	5" X 1'-0"	J		

NOTE:

FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY 20 BRIDGE NO.\_

SHEET 9 OF 11

—Docusigned by: Brandon Grun


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> PRESTRESSED GIRDER REPAIR SPAN 12

3/7/2017

REVISIONS SHEET NO. S-12 DATE: DATE: NO. BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_ DATE : <u>10-16</u> B. L. GREEN CHECKED BY : .



GIRDER REPAIR LOCATIONS							
SPAN	GIRDER	DISTANCE ALONG SPAN	LOCATION	REPAIR SIZE	LABEL		
13	1	46′-10″	BTM. OF GDR.	28'-7" X 1'-8"	Α		
13	3	1'-0"	BTM. OF GDR.	5" X 6"	В		
13	3	86′-0″	BTM. OF GDR.	1'-4" X 6"	С		
13	4	0'-0"	BTM. OF GDR.	4" X 4"	D		
13	6	0'-0"	BTM. OF GDR.	2'-0" X 10"	E		
13	6	27′-7"	BTM. OF GDR.	1'-10" X 11"	F		
13	6	31′-7"	BTM. OF GDR.	1'-0" X 1'-0"	G		

GIRDER POPOUT LOCATIONS								
SPAN GIRDER BAY LOCATION REPAIR NUMBER/SIZE								
13 2 2 WEB 8 @ 3" X 3"								
(FOR CLARITY, POPOUTS ARE NOT SHOWN IN								

PLAN VIEW )

NOTE:

FOR GIRDER REPAIR DETAILS AND SEQUENCE, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

FOR EPOXY COATING POPOUTS, SEE SPECIAL PROVISION.

B-5942 PROJECT NO.\_ HYDE \_ COUNTY BRIDGE NO.\_

SHEET 10 OF 11

Brandon Grun SEAL 037403


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PRESTRESSED GIRDER REPAIR SPAN 13


3/7/2017

REVISIONS SHEET NO. S-13 DATE: DATE: NO. BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

P.C. BREWER \_\_ DATE : <u>10-16</u> DRAWN BY : \_\_ DATE : \_\_10-16 B. L. GREEN CHECKED BY : .



# GIRDER WEB REPAIR



ELEVATION

SECTION

## GIRDER FLANGE REPAIR

### PRESTRESSED GIRDER REPAIR SEQUENCE:

- . SOUND CONCRETE TO DETERMINE EXTENTS OF REPAIR LOCATION.
- 2. REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL. SAW CUT AROUND REPAIR AREA TO A NOMINAL DEPTH OF  $\frac{1}{2}$ .
- 3. REMOVE CONCRETE WITHIN SAW CUT AREA TO MINIMUM 1/2" DEPTH. IF CONCRETE IS DAMAGED BEYOND THE ORIGINAL SAW CUT, A NEW SAW CUT IS REQUIRED.
- 4. ▲ IF MORE THAN HALF THE CIRCUMFERENCE OF A REINFORCING BAR IS EXPOSED DURING THIS PROCESS, REMOVE ADDITIONAL CONCRETE TO 1"BEHIND THE BAR. THIS DOES NOT APPLY TO PRESTRESSED STRANDS.
- 5. ALL UNSOUND CONCRETE MUST BE REMOVED, HOWEVER, PRESTRESSED STRANDS SHOULD NOT BE DISTURBED UNLESS ABSOLUTELY NECESSARY. USE EXTREME CARE TO NOT DAMAGE STRANDS.
- O. USE A WIRE BRUSH TO CLEAN ALL EXPOSED REINFORCING BARS AND PRESTRESSED STRANDS. FOR BARS WITH MORE THAN 10% SECTION LOSS, SPLICE AND SECURELY TIE SUPPLEMENTAL REINFORCING BARS AS NEEDED. NOTE AND PROVIDE DETAILED DOCUMENTATION, INCLUDING LOCATION AND SEVERITY, OF ALL DAMAGE TO PRESTRESSED STRANDS THAT EXCEEDS 10% SECTION LOSS. IF FIVE OR MORE STRANDS ARE DAMAGED, NOTIFY THE ENGINEER PRIOR TO PLACEMENT OF REPAIR MATERIAL.
- 7. REMOVE ALL LOOSE OR WEAKENED MATERIAL THEN CLEAN THE REPAIR AREA OF DIRT, GREASE, OIL, AND FOREIGN MATTER.
- 8. PREPARE SURFACE AND PLACE APPROVED REPAIR MATERIAL ACCORDING TO MANUFACTURER'S RECOMMENDATIONS. MAXIMUM AGGREGATE SIZE FOR REPAIR MATERIAL SHALL NOT EXCEED 2/3 THE MINIMUM REPAIR DEPTH.

GIRDER REPAIR QUANTITIES			GIRDER POPOUT QUANTITIES								
		QUANT	ITIES					QUANTITIES			
	ESTI	ESTIMATE ACTUAL			ESTIMATE		ACTUAL				
	AREA SF	VOLUME CF	AREA SF	DEPTH FT	VOLUME CF		NUMBER OF REPAIR LOCATIONS	AREA SF	NUMBER OF REPAIR LOCATIONS	AREA SF	
SPAN 1	0.6	0.2				SPAN 1	0	0.0			
SPAN 2	1.2	0.4				SPAN 2	0	0.0			
SPAN 3	34.2	11.4				SPAN 3	65	4.3			
SPAN 4	28.5	9.5				SPAN 4	24	1 <b>.</b> 5			
SPAN 5	93.6	31.2				SPAN 5	107	9.5			
SPAN 6	121.8	40.6				SPAN 6	89	5.6			
SPAN 10	124.2	41.4				SPAN 10	0	0.0			
SPAN 11	15.9	5.3				SPAN 11	0	0.0			
SPAN 12	104.4	34.8				SPAN 12	0	0.0			
SPAN 13	53.1	17.7				SPAN 13	8	0.5			
SPAN 14	0.0	0.0				SPAN 14	0	0.0			
SPAN 15	0.0	0.0				SPAN 15	0	0.0			
TOTAL	577 <b>.</b> 5	192.5				TOTAL	285	21.4			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.

PROJECT NO. \_\_\_\_\_B-5942 \_\_\_\_\_HYDE \_\_\_\_county BRIDGE NO. \_\_\_\_\_20

SHEET 11 OF 11

Brandon Grun
2C7028B6BB61448

CAROLLINIAN
SEAL
037403

3/7/2017

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION


RALEIGH


PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY

REVISIONS SHEET NO.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 4 30

DRAWN BY: B.L.GREEN DATE: 10-16
CHECKED BY: P.C.BREWER DATE: 10-16





REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 1 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 COLUMN 0 LN. FT EPOXY RESIN INJECTION 21.0 COLUMN 0 AREA EPOXY COATING SF 166 TOP OF CAP FOOTINGS 714

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

PROJECT NO. B-5942

HYDE COUNTY

BRIDGE NO. 20

SHEET 1 OF 15

Brandon Grun

2C7028B6BB61448...

2C7028B6BB61448...

QCFESSION

SEAL

037403

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE BENT 1


DOCUMENT NOT CONSIDERED NO. BY:
FINAL UNLESS ALL
SIGNATURES COMPLETED 2

3/7/2017

REVISIONS

NO. BY: DATE: NO. BY: DATE: S-16

1 3 TOTAL SHEETS
2 4 30



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 2 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 COLUMN 0 LN. FT EPOXY RESIN INJECTION CAP 0 COLUMN 0 AREA EPOXY COATING SF TOP OF CAP 166 714 FOOTINGS

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

PROJECT NO. B-5942

HYDE COUNTY

BRIDGE NO. 20

SHEET 2 OF 15

Brandon Grun

2C7028B6BB61448...

THE CAROLLES SEAL

037403

SEAL

037403

3/7/2017

STATE OF WEST CAROLINA


DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE BENT 2

REVISIONS SHEET NO.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 4 30



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 3 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 COLUMN 0 LN. FT EPOXY RESIN INJECTION CAP 0 COLUMN 0 AREA EPOXY COATING SF TOP OF CAP 166 733 FOOTINGS

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

> B-5942 PROJECT NO.\_ HYDE COUNTY BRIDGE NO.\_

SHEET 3 OF 15


Brandon Green

STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 3

3/7/2017

REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 4 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 COLUMN 0 LN. FT EPOXY RESIN INJECTION CAP 3.0 COLUMN 0 AREA EPOXY COATING SF TOP OF CAP 166 733 FOOTINGS

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

> B-5942 PROJECT NO.\_ HYDE COUNTY BRIDGE NO.\_

SHEET 4 OF 15




3/7/2017

STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE BENT 4

REVISIONS DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 5 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 COLUMN 0 LN. FT EPOXY RESIN INJECTION 6.0 COLUMN 0 AREA SF EPOXY COATING FOUNDATIONS TOP OF CAP 166 733 FOOTINGS

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

PROJECT NO. B-5942

HYDE COUNTY

BRIDGE NO. 20

SHEET 5 OF 15

Brandon Grun

2C7028B6BB61448

CARO

SEAL

037403

STATE OF WEST CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE BENT 5

3/7/2017


REVISIONS SHEET NO.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 A 30

02-MAR-2017 10:08 R:\Structures\Plans\B5942\_SMU\_ FinalPlans.dgn bgreen

DATE : \_\_\_\_\_

DESIGN ENGINEER OF RECORD: \_\_\_\_




ACTUAL

COUNTY

SHEET NO.

S-21



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 7 ESTIMATE ACTUAL AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 COLUMN 0 LN. FT EPOXY RESIN INJECTION 0 COLUMN 0 AREA EPOXY COATING SF TOP OF CAP 186 TOP OF BASE 177 AREA TEXTURED COATING SF SIDE FACES OF BASE 536

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

B-5942 PROJECT NO.\_ HYDE COUNTY

BRIDGE NO.\_ SHEET 7 OF 15

Docusigned by:
Brandon Grun

STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 7

3/7/2017

REVISIONS S-22 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

02-MAR-2017 10:08
R:\Structures\Plans\B5942\_SMU\_ FinalPlans.dgn
bgreen

\_ DATE : \_\_\_\_ DESIGN ENGINEER OF RECORD: \_\_\_\_


\_ DATE : <u>10/15</u>

R.W. WRIGHT

B. L. GREEN

DRAWN BY :

CHECKED BY : \_\_\_



BOTTOM OF CAP

REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 8 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS SF CF CAP (VERTICAL FACE) 9.7 4.1 CAP (HORIZONTAL, CORNER) 1.3 3.0 COLUMN 0 LN. FT EPOXY RESIN INJECTION CAP 0 0 COLUMN AREA EPOXY COATING SF 186 TOP OF CAP TOP OF BASE 177 AREA TEXTURED COATING SF SIDE FACES OF BASE 536

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

\* IF DEMO OF CAP EXTENDS TO AREA UNDER THE SOLE PLATE, BETWEEN THE ANCHOR BOLTS, STOP ALL WORK TO THIS AREA. CONTRACTOR SHALL SUBMIT FOR APPROVAL PLANS FOR NECESSARY SHORING. TRAFFIC CONTROL, AND/OR JACKING SHALL NOT CONTINUE UNTIL SUCH PLANS ARE APPROVED.

> B-5942 PROJECT NO.\_ HYDE COUNTY 20 BRIDGE NO.

SHEET 8 OF 15

—Docusigned by: Brandon Grun


3/7/2017


STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH


> SUBSTRUCTURE BENT 8

SHEET NO. REVISIONS S-23 DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

R.W. WRIGHT \_ DATE : <u>10/15</u> DRAWN BY : \_ DATE : <u>11/15</u> B. L. GREEN CHECKED BY : \_\_ \_ DATE : \_\_\_\_\_ DESIGN ENGINEER OF RECORD: \_\_\_\_







VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

> B-5942 PROJECT NO.\_ HYDE COUNTY BRIDGE NO.\_

SHEET 10 OF 15


Brandon Green SEAL 037403

STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 10

3/7/2017

REVISIONS S-25 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 11 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 COLUMN 0 LN. FT EPOXY RESIN INJECTION 8.0 COLUMN 0 AREA EPOXY COATING SF TOP OF CAP 166 308 FOOTINGS

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

PROJECT NO. B-5942

HYDE county

BRIDGE NO. 20

SHEET 11 OF 15

Brandon Grun
2C7028B6BB61448...

1 CAROLLING
SEAL
037403

STATE OF WEST CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH


SUBSTRUCTURE BENT 11

3/7/2017

REVISIONS SHEET NO.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 SHEET NO. BY: DATE: SHEETS

30



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 12 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS SF CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 10.9 COLUMN 4.6 LN. FT EPOXY RESIN INJECTION CAP 0 COLUMN 0 AREA EPOXY COATING SF TOP OF CAP 166 308 FOOTINGS

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:


REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

> B-5942 PROJECT NO.\_ HYDE COUNTY BRIDGE NO.\_


SHEET 12 OF 15



STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 12

REVISIONS S-27 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED



REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 13 ACTUAL ESTIMATE AREA DEPTH VOLUME SF FT CF AREA VOLUME SHOTCRETE REPAIRS CF CAP (VERTICAL FACE) 0 0 CAP (HORIZONTAL, CORNER) 0 0 2.7 COLUMN 1.2 LN. FT EPOXY RESIN INJECTION CAP 0 COLUMN 0 AREA EPOXY COATING SF TOP OF CAP 166 297 FOOTINGS

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

### NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

FOR SUBSTRUCTURE REPAIR DETAIL, SEE "SUBSTRUCTURE REPAIR DETAIL" SHEET.

> B-5942 PROJECT NO.\_ HYDE COUNTY BRIDGE NO.\_

SHEET 13 OF 15


Brandon Green SEAL 9

3/7/2017

STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE BENT 13

REVISIONS S-28 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED



02-MAR-2017 10:08 R:\Structures\Plans\B5942\_SMU\_ FinalPlans.dgn

B-5942 COUNTY

ACTUAL

FT

CF

STATE OF WEST CAROLINA DEPARTMENT OF TRANSPORTATION

SUBSTRUCTURE

SHEET NO S-29

### NOTES:

BENT DIAPHRAGMS AND OTHER CONCRETE COMPONENTS MY BE REPAIRED UNDER SHOTCRETE REPAIRS OR CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED.


CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT BE DAMAGE EXISTING REINFORCING STEEL.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.





FACE REPAIR

SUBSTRUCTURE REPAIR DETAIL

B-5942 PROJECT NO.\_\_ HYDE COUNTY 20 BRIDGE NO.\_

SHEET 15 OF 15

Brandon Grun

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

> SUBSTRUCTURE REPAIR DETAIL

> > S-30

3/7/2017

	REVISIONS					
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:
FINAL UNLESS ALL	1			<b></b>		
SIGNATURES COMPLETED	2			4		

B. L. GREEN \_\_ DATE : \_\_10/15\_ DRAWN BY : \_ DATE : <u>11/15</u> R.W.WRIGHT CHECKED BY : .

## STANDARD NOTES

### DESIGN DATA:

SPECIFICATIONS	A.A.S.H.T.O. (CURRENT)
LIVE LOAD	SEE PLANS
IMPACT ALLOWANCE	SEE A.A.S.H.T.O.
STRESS IN EXTREME FIBER OF	
STRUCTURAL STEEL - AASHTO M270 GRADE 36 -	20,000 LBS. PER SQ. IN.
- AASHTO M270 GRADE 50W -	27,000 LBS.PER SQ.IN.
- AASHTO M270 GRADE 50 -	27,000 LBS. PER SQ. IN.
REINFORCING STEEL IN TENSION	
GRADE 60	24,000 LBS. PER SQ. IN.
CONCRETE IN COMPRESSION	1,200 LBS. PER SQ. IN.
CONCRETE IN SHEAR	SEE A.A.S.H.T.O.
STRUCTURAL TIMBER - TREATED OR	
UNTREATED - EXTREME FIBER STRESS	1,800 LBS. PER SQ. IN.
COMPRESSION PERPENDICULAR TO GRAIN OF TIMBER	375 LBS. PER SQ. IN.
EQUIVALENT FLUID PRESSURE OF EARTH	30 LBS.PER CU.FT.

### MATERIAL AND WORKMANSHIP:

EXCEPT AS MAY OTHERWISE BE SPECIFIED ON PLANS OR IN THE SPECIAL PROVISIONS, ALL MATERIAL AND WORKMANSHIP SHALL BE IN ACCORDANCE WITH THE 2012 "STANDARD SPECIFICATIONS FOR ROADS AND STRUCTURES" OF THE N. C. DEPARTMENT OF TRANSPORTATION.

STEEL SHEET PILING FOR PERMANENT OR TEMPORARY APPLICATIONS SHALL BE HOT ROLLED.

### CONCRETE:

UNLESS OTHERWISE REQUIRED ON PLANS, CLASS A CONCRETE SHALL BE USED FOR ALL PORTIONS OF ALL STRUCTURES WITH THE EXCEPTION THAT: CLASS AA CONCRETE SHALL BE USED IN BRIDGE SUPERSTRUCTURES, ABUTMENT BACKWALLS, AND APPROACH SLABS; AND CLASS B CONCRETE SHALL BE USED FOR SLOPE PROTECTION AND RIP RAP.

### CONCRETE CHAMFERS:

UNLESS OTHERWISE NOTED ON THE PLANS, ALL EXPOSED CORNERS ON STRUCTURES SHALL BE CHAMFERED 3/4" WITH THE FOLLOWING EXCEPTIONS: TOP CORNERS OF CURBS MAY BE ROUNDED TO 1-1/2" RADIUS WHICH IS BUILT INTO CURB FORMS: CORNERS OF TRANSVERSE FLOOR EXPANSION JOINTS SHALL BE ROUNDED WITH A 1/4"FINISHING TOOL UNLESS OTHERWISE REQUIRED ON PLANS: AND CORNERS OF EXPANSION JOINTS IN THE ROADWAY FACES AND TOPS OF CURBS AND SIDEWALKS SHALL BE ROUNDED TO A 1/4"RADIUS WITH A FINISHING STONE OR TOOL UNLESS OTHERWISE REQUIRED ON PLANS.

### DOWELS:

DOWELS WHEN INDICATED ON PLANS AS FOR CULVERT EXTENSIONS, SHALL BE EMBEDDED AT LEAST 12" INTO THE OLD CONCRETE AND GROUTED INTO PLACE WITH 1:2 CEMENT MORTAR.

### ALLOWANCE FOR DEAD LOAD DEFLECTION, SETTLEMENT, ETC. IN CASTING SUPERSTRUCTURES:

BRIDGES SHALL BE BUILT ON THE GRADE OR VERTICAL CURVE SHOWN ON PLANS. SLABS, CURBS AND PARAPETS SHALL CONFORM TO THE GRADE OR CURVE. ALL DIMENSIONS WHICH ARE GIVEN IN SECTION AND ARE AFFECTED BY DEAD LOAD DEFLECTIONS ARE DIMENSIONS AT CENTER LINE OF BEARING UNLESS OTHERWISE NOTED ON PLANS. IN SETTING FORMS FOR STEEL BEAM BRIDGES AND PRESTRESSED CONCRETE GIRDER BRIDGES, ADJUSTMENTS SHALL BE MADE DUE TO THE DEAD LOAD DEFLECTIONS FOR THE ELEVATIONS SHOWN. WHERE BLOCKS ARE SHOWN OVER BEAMS FOR BUILDING UP TO THE SLAB, THE VERTICAL DIMENSIONS OF THE BLOCKS SHALL BE ADJUSTED BETWEEN BEARINGS TO COMPENSATE FOR DEAD LOAD DEFLECTIONS, VERTICAL CURVE ORDINATE, AND ACTUAL BEAM CAMBER. WHERE BOTTOM OF SLAB IS IN LINE WITH BOTTOM OF TOP FLANGES, DEPTH OF SLAB BETWEEN BEARINGS SHALL BE ADJUSTED TO COMPENSATE FOR DEAD LOAD DEFLECTION, VERTICAL CURVE ORDINATE, AND ACTUAL BEAM CAMBER.

IN SETTING FALSEWORK AND FORMS FOR REINFORCED CONCRETE SPANS, AN ALLOWANCE SHALL BE MADE FOR DEAD LOAD DEFLECTIONS. SETTLEMENT OF FALSEWORK. AND PERMANENT CAMBER WHICH SHALL BE PROVIDED FOR IN ADDITION TO THE ELEVATIONS SHOWN. AFTER REMOVAL OF THE FALSEWORK, THE FINISHED STRUCTURES SHALL CONFORM TO THE PROFILE AND ELEVATIONS SHOWN ON THE PLANS AND CONSTRUCTION ELEVATIONS FURNISHED BY THE ENGINEER.

DETAILED DRAWINGS FOR FALSEWORK OR FORMS FOR BRIDGE SUPERSTRUCTURE AND ANY STRUCTURE OR PARTS OF A STRUCTURE AS NOTED ON THE PLANS SHALL BE SUBMITTED TO THE ENGINEER FOR APPROVAL BEFORE CONSTRUCTION OF THE FALSEWORK OR FORMS IS STARTED.

### REINFORCING STEEL:

ALL REINFORCING STEEL SHALL BE DEFORMED. DIMENSIONS RELATIVE TO PLACEMENT OF REINFORCING ARE TO CENTERS OF BARS UNLESS OTHERWISE INDICATED IN THE PLANS. DIMENSIONS ON BAR DETAILS ARE TO CENTERS OF BARS OR ARE OUT TO OUT AS INDICATED ON PLANS.

WIRE BAR SUPPORTS SHALL BE PROVIDED FOR REINFORCING STEEL WHERE INDICATED ON THE PLANS. WHEN BAR SUPPORT PIECES ARE PLACED IN CONTINUOUS LINES, THEY SHALL BE SO PLACED THAT THE ENDS OF THE SUPPORTING WIRES SHALL BE LAPPED TO LOCK LEGS ON ADJOINING PIECES.

### STRUCTURAL STEEL:

AT THE CONTRACTOR'S OPTION, HE MAY SUBSTITUTE 7/8" Ø SHEAR STUDS FOR THE  $rac{3}{4}$   $^{\prime\prime}$  arphi STUDS SPECIFIED ON THE PLANS. THIS SUBSTITUTION SHALL BE MADE AT THE RATE OF 3 - 7/8" Ø STUDS FOR 4 - 3/4" Ø STUDS, AND STUD SPACING CHANGES SHALL BE MADE AS NECESSARY TO PROVIDE THE SAME EQUIVALENT NUMBER OF 7/8" Ø STUDS ALONG THE BEAM AS SHOWN FOR 3/4" Ø STUDS BASED ON THE RATIO OF 3 - 7/8" Ø STUDS FOR 4 - 3/4" Ø STUDS. STUDS OF THE LENGTH SPECIFIED ON THE PLANS MUST BE PROVIDED. THE MAXIMUM SPACING SHALL BE 2'-0".

EXCEPT AT THE INTERIOR SUPPORTS OF CONTINUOUS BEAMS WHERE THE COVER PLATE IS IN CONTACT WITH BEARING PLATE, THE CONTRACTOR MAY, AT HIS OPTION, SUBSTITUTE FOR THE COVER PLATES DESIGNATED ON THE PLANS COVER PLATES OF THE EQUIVALENT AREA PROVIDED THESE PLATES ARE AT LEAST 5/16" IN THICKNESS AND DO NOT EXCEED A WIDTH EQUAL TO THE FLANGE WIDTH LESS 2"OR A THICKNESS EQUAL TO 2 TIMES THE FLANGE THICKNESS. THE SIZE OF FILLET WELDS SHALL CONFORM TO THE REQUIREMENTS OF THE CURRENT ANSI/AASHTO/AWS "BRIDGE WELDING CODE". ELECTROSLAG WELDING WILL NOT BE PERMITTED.

WITH THE SOLE EXCEPTION OF EDGES AT SURFACES WHICH BEAR ON OTHER SURFACES.ALL SHARP EDGES AND ENDS OF SHAPES AND PLATES SHALL BE SLIGHTLY ROUNDED BY SUITABLE MEANS TO A RADIUS OF APPROXIMATELY 1/16 INCH OR EQUIVALENT FLAT SURFACE AT A SUITABLE ANGLE PRIOR TO PAINTING, GALVANIZING, OR METALLIZING.

### HANDRAILS AND POSTS:

METAL STANDARDS AND FACES OF THE CONCRETE END POSTS FOR THE METAL RAIL SHALL BE SET NORMAL TO THE GRADE OF THE CURB. UNLESS OTHERWISE SHOWN ON PLANS. THE METAL RAIL AND TOPS OF CONCRETE POSTS USED WITH THE ALUMINUM RAIL SHALL BE BUILT PARALLEL TO THE GRADE OF THE CURB.

METAL HANDRAILS SHALL BE IN ACCORDANCE WITH THE PLANS. RAILS SHALL BE AS MANUFACTURED FOR BRIDGE RAILING. CASTINGS SHALL BE OF A UNIFORM APPEARANCE. FINS AND OTHER DEFORMATIONS RESULTING FROM CASTING OR OTHERWISE SHALL BE REMOVED IN A MANNER SO THAT A UNIFORM COLORING OF THE COMPLETED CASTING SHALL BE OBTAINED. CASTINGS WITH DISCOLORATIONS OR OF NON-UNIFORM COLORING WILL NOT BE ACCEPTED. CERTIFIED MILL REPORTS ARE REQUIRED FOR METAL RAILS AND POSTS.

### SPECIAL NOTES:

GENERALLY, IN CASE OF DISCREPANCY, THIS STANDARD SHEET OF NOTES SHALL GOVERN OVER THE SPECIFICATIONS, BUT THE REMAINDER OF THE PLANS SHALL GOVERN OVER NOTES HEREON, AND SPECIAL PROVISIONS SHALL GOVERN OVER ALL. SEE SPECIFICATIONS ARTICLE 105-4.

ENGLISH

JANUARY, 1990