



NC DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS  
BRIDGE MANAGEMENT UNIT

ATTENTION

IMPACT DAMAGE REPORT ON SPAN 3  
RATINGS ON SPAN 3 ITEMS ONLY  
PRIORITY MAINTENANCE REQUESTED

# BRIDGE INSPECTION REPORT

INSPECTION TYPE: Damage Inspection Report

COUNTY CATAWBA BRIDGE NUMBER 170142 INSPECTION CYCLE 0 YRS  
ROUTE SR1692 ACROSS US321 M.P. 0

LOCATION 0.1 MI. N. JCT. SR2231

SUPERSTRUCTURE REINFORCED CONCRETE DECK ON I-BEAMS

SUBSTRUCTURE END BENTS:RC CAP ON TIMBER PILES,INT.BTS:RCP&B ON PILE FTGS.

SPANS 1@45'0, 2@47'6, 1@45'0

LONGITUDE 81° 21' 50.59"

LATITUDE 35° 43' 47.16"

PRESENT CONDITION POOR

INVENTORY RATING

INSPECTION DATE 08/06/2012

OPERATING RATING

PRESENT POSTING Not Posted

PROPOSED POSTING

COMPUTER UPDATE

ANALYSIS DATE

POSTING LETTER DATE

SUFFICIENCY RATING

OTHER SIGNS PRESENT NONE



LOOKING NORTH

SIGN NOTICE ISSUED FOR		NUMBERED REQUIRED
<u>No</u>	WEIGHT LIMIT	<u></u>
<u>No</u>	DELINEATORS	<u></u>
<u>No</u>	NARROW BRIDGE	<u></u>
<u>No</u>	ONE LANE BRIDGE	<u></u>
<u>No</u>	LOW CLEARANCE	<u></u>

## NATIONAL BRIDGE INVENTORY----- STRUCTURE INVENTORY AND APPRAISAL

Run Date: 11/29/2012

IDENTIFICATION			
(1) STATE NAME -NORTH CAROLINA	BRIDGE	170142	SUFFICIENCY RATING = 76
(8) STRUCTURE NUMBER(FEDERAL)	00000000350142		STATUS = Functionally Obsolete
(5) INVENTORY ROUTE (ON/UNDER) - ON	31016920		
(2) STATE HIGHWAY DEPARTMENT DISTRICT	3		
(3) COUNTY CODE 35 (4) PLACE CODE	31060		
(6) FEATURE INTERSECTED - US321			
(7) FACILITY CARRIED SR1692			
(9) LOCATION 0.1 MI. N. JCT. SR2231			
(11) MILEPOINT	0		
(16) LAT 35° 43' 47.16" (17) LONG 81° 21' 50.59"			
(98) BORDER BRIDGE STATE CODE	PCT SHARE		
(99) BORDER BRIDGE STRUCTURE NO			

STRUCTURE TYPE AND MATERIAL			
(43) STRUCTURE TYPE MAIN: Steel			
TYPE - Stringer Multibeam or Girder	CODE	302	
(44) STRUCTURE TYPE APPR :			
TYPE -	CODE	000	
(45) NUMBER OF SPANS IN MAIN UNIT		4	
(46) NUMBER OF APPROACH SPANS			
(107) DECK STRUCTURE TYPE - 1	CODE		
(108) WEARING SURFACE / PROTECTIVE SYSTEM :			
(A) TYPE OF WEARING SURFACE -	CODE		
(B) TYPE OF MEMBRANE -	CODE		
(C) TYPE OF DECK PROTECTION -	CODE		

AGE AND SERVICE			
(27) YEAR BUILT		1955	
(106) YEAR RECONSTRUCTED			
(42) TYPE OF SERVICE : ON - Highway - Pedestrian			
UNDER - Highway	CODE	51	
(28) LANES: ON STRUCTURE 2 UNDER STRUCTURE		4	
(29) AVERAGE DAILY TRAFFIC		4400	
(30) YEAR OF ADT 2009 (109) TRUCK ADT PCT		6%	
(19) BYPASS OR DETOUR LENGTH		0 MI	

GEOMETRIC DATA			
(48) LENGTH OF MAXIMUM SPAN		48 FT	
(49) STRUCTURE LENGTH		185 FT	
(50) CURB OR SIDEWALK: LEFT 5.1 FT RIGHT		5.1 FT	
(51) BRIDGE ROADWAY WIDTH CURB TO CURB		28 FT	
(52) DECK WIDTH OUT TO OUT		40 FT	
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)		24 FT	
(33) BRIDGE MEDIAN - No Median	CODE	0	
(34) SKEW 22° (35) STRUCTURE FLARED		0	
(10) INVENTORY ROUTE MIN VERT CLEAR		999.9 FT	
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR		28 FT	
(53) MIN VERT CLEAR OVER BRIDGE RDWY		999.9 FT	
(54) MIN VERT UNDERCLEAR REF Highway		15.333 FT	
(55) MIN LAT UNDERCLEAR RT REF Highway		.5 FT	
(56) MIN LAT UNDERCLEAR LT REF -		.5 FT	

NAVIGATION DATA			
(38) NAVIGATION CONTROL - Not Applicable	CODE	N	
(111) PIER PROTECTION -	CODE		
(39) NAVIGATION VERTICAL CLEARANCE		0	
(116) VERT - LIFT BRIDGE NAV MIN VERT CLEAR		FT	
(40) NAVIGATION HORIZONTAL CLEARANCE		0 FT	

CLASSIFICATION			
(112) NBIS BRIDGE SYSTEM -			YES
(104) HIGHWAY SYSTEM Is not on NHS			0
(26) FUNCTIONAL CLASS - Minor Arterial			16
(100) STRAHNET HIGHWAY - Not a STRAHNET Route			0
(101) PARALLEL STRUCTURE - No Parallel Structure			N
(102) DIRECTION OF TRAFFIC - 1-way Traffic			1
(103) TEMPORARY STRUCTURE -			
(110) DESIGNATED NATIONAL NETWORK - Not on the National Network			0
(20) TOLL On Free Road			3
(31) MAINTAIN - State Highway Agency			01
(22) OWNER - State Highway Agency			01
(37) HISTORICAL SIGNIFICANCE - Not Eligible			5

CONDITION			
(58) DECK			6
(59) SUPERSTRUCTURE			6
(60) SUBSTRUCTURE			6
(61) CHANNEL & CHANNEL PROTECTION			N
(62) CULVERTS			N

LOAD RATING AND POSTING			
(31) DESIGN LOAD HS 20 + MOD			6
(63) OPERATING RATING METHOD - Load Factor			
(64) OPERATING RATING - HS-36			164
(65) INVENTORY RATING METHOD - Load Factor			
(66) INVENTORY RATING - HS-21			138
(70) BRIDGE POSTING - No Posting Required			5
(41) STRUCTURE OPEN, POSTED ,OR CLOSED DESCRIPTION - Open, No Restriction			A

APPRAISAL			
(67) STRUCTURAL EVALUATION			6
(68) DECK GEOMETRY			4
(69) UNDERCLEARANCES, VERTI & HORIZ			3
(71) WATERWAY ADEQUACY			N
(72) APPROACH ROADWAY ALIGNMENT			7
(36) TRAFFIC SAFETY FEATURES			0000
(113) SCOUR CRITICAL BRIDGES			N

PROPOSED IMPROVEMENTS			
(75) TYPE OF WORK -			CODE
(76) LENGTH OF STRUCTURE IMPROVEMENT			
(94) BRIDGE IMPROVEMENT COST			
(95) ROADWAY IMPROVEMENT COST			
(96) TOTAL PROJECT COST			
(97) YEAR OF IMPROVEMENT COST ESTIMATE			
(114) FUTURE ADT 10200 (115) YEAR FUTURE ADT			2025

INSPECTIONS			
(90) INSPECTION DATE			01/24/2011
(92) CRITICAL FEATURE INSPECTION :			(93) CFI DATE
A) FRACTURE CRIT DETAIL - NO			A)
B) UNDERWATER INSP - NO			B)
C) OTHER SPECIAL INSP NO			C)
SCOUR			

Structure No: 170142

County: CATAWBA

Run Date:

Span Number	Feature Intersected	Inventory Route	Minimum Maximum Vertical Clearance	Milepoint	Base Highway Network	LRS Inventory Route	Toll	Functional Classification	Nuner of Lanes	Average Daily Traffic	Year of Average Daily Traffic	Total Horizontal Clearance	See Note 1					STRAHNET Highway	Designator	Direction of Traffic	Highway System of Route	
													Reference Feature	Minimum Vertical Underclearance	Right Lateral Underclearance	Left Lateral Underclearance	Underclearance					Appraisal Grade
2	US 321 SBL	21003210	15.42	01	12	13	20	26	28	29	30	47	54A	54	55	56	69	69	100	102	102	104
3	US 321 NBL	21003210	15.33	01	01	20321		12	2	17500	2009	35H	15.25	15.33	.5	.5	.5	0	1	1	1	

Note 1: Items 54, 55, and 56 are not reported FHWA under route data points but are collected for each under route to determine the minimum value for Underclearance Appraisal Item 69. The under route that generates the lowest Underclearance Appraisal value will be reported on the Facility Carried record.

## BRIDGE MANAGEMENT UNIT

## DATA ON EXISTING STRUCTURE

Run Date: 11/29/2012

COUNTY : CATAWBA      DIVISION : 12      DISTRICT : 3      STRUCTURE NUMBER : 170142      LENGTH : 185 FEET

ROUTE CARRIED : SR1692      FEATURE INTERSECTED : US321

LOCATED : 0.1 MI. N. JCT. SR2231      BRIDGE NAME :      CITY : HICKORY

FUNC. CLASS : 16      SYST.ON : FA      SYST.UNDER : NFA      ADT & YR : 4400 2009      RAIL TYPE : LT 311 RT 311

BUILT : 1955      BY : SHPWC      PROJ : 6264      FED.AID PROJ : U-186(7)      DESIGN LOAD : HS 20 + MOD

REHAB :      BY :      PROJ :      ALIGNMENT : TAN      SKEW : 68      LANES : ON 2 UNDER 4

NAVIGATION : VC 0 FT HC 0 FT      HT. CRN. TO BED : 0 FT      WATER DEPTH : 0 FT

SUPERSTRUCTURE : REINFORCED CONCRETE DECK ON I-BEAMS

SUBSTRUCTURE : END BENTS:RC CAP ON TIMBER PILES,INT.BTS:RCP&B ON PILE FTGS.

SPANS : 1@45'0, 2@47'6, 1@45'0

BEAMS OR GIRDERS : 6 LINES I-BEAMS @ 6'0 CTS, SP#1&4:W33X130,SP#2&3:W33X141

FLOOR : 6.75 RC,2.5 AWS      ENCROACHMENT : WATER MAIN      DECK (OUT TO OUT) : 40 FT

CLEAR ROADWAY : 28 FT      BETWEEN RAILS : 38.3 FT      SIDEWALK OR CURB : LT 5.1 FT RT 5.1 FT

VERT.CL.OVER : 999.9 FT

INV.RTG. : HS-21      OPE.RTG. : HS-36      CONTR.MEMBER : int bm b      POSTED : SV TTST      DATE

SYSTEM : Primary S.R. Route      GREEN LINE ROUTE : N

## UNDER ROUTES AND CLEARANCES

Span	Route Description	Vertical Clearances		Horizontal Clearances		
		MMVC	MVC	Total	Left	Right
2	US 321 SBL	15.4170	15.25	35	0.50	0.50
3	US 321 NBL	15.3330	15.3330	35	0.50	0.50

Note: All measurements are in feet.

REMARKS :



# BRIDGE INSPECTION RECORD AND SUMMARY

INSPECTION TYPE Damage Inspection Report  
 BRIDGE NO. 170142 COUNTY CATAWBA ROUTE SR1692 OVER US321  
 STRUCTURE TYPE REINFORCED CONCRETE DECK ON I-BEAMS  
 ROUTE ORIENTATION SPANS 1@45'0, 2@47'6, 1@45'0

EVALUATION CODES: CRITICAL (C, 0 - 3); POOR (P, 4); FAIR (F, 5, 6); GOOD (G, 7 - 9)

INSPECTION ITEM			ITEM 61		
DECK ITEMS		GRADES			
1. WEARING SURFACE			45. CHANNEL & CHANNEL PROT.	a. WATERWAY	
				b. ALIGNMENT	
				c. SCOUR	
				d. SLOPE PROT., RIP-RAP, DIKES, ETC.	
2. DECK NO. OF EA TYPE SPN GRADE RATES SI & A ITEM 58	a. CONCRETE		50. APPROACH ROADWAY CONDITION		
	b. TIMBER		51. APPROACH SLABS		
	c. STEEL PLANK		52. PAINT SYSTEM CODE		
	d. OPEN GRID		53. UTILITIES		
3. RAILING	a. CONCRETE		54. RESPONSE TO LIVE LOAD		
	b. TIMBER		55. ESTIMATED REMAINING LIFE		
	c. ALUMINUM		20		
	d. STEEL				
4. CURBS, WHEELGUARDS, PARAPETS, MEDIANS					
5. WALKWAYS (ON OR ATTACHED TO STRUCTURE)			60. REGULATORY SIGN NOTICE ISSUED		
			NO		
6. DECK EXP JTS. OR DEVICES. NO. OF EACH	a. STEEL PL OR FINGER		61. PROMPT-ACTION NOTICE ISSUED		
	b. MISC PREFAB		NO		
	c. COMPRESSION SEAL		62. PRESENTLY POSTED		
	d. STANDARD JOINTS		NO		
	e. OPEN JOINTS		63. TOT. FIELD INSP TIME (INCLUDE WRITE UP)(MAN HR)		
7. DECK DEBRIS (INCLUDES EXCESS SAND/GRAVEL)			14		
			64. TOTAL SNOOPER INSP. TIME (HRS)		
			0		
			65. TOTAL TRAFFIC CONTROL TIME (MAN HRS)		
			7		
70. SI&A GENERAL CONDITION RATINGS					
SUPER STR. (FM. 1 (90)B TRUSS) ITEM 59			a. DECK	ITEM 58	
10. LONGITUDINAL BEAMS OR GIRDERS	P		b. SUPERSTRUCTURE	ITEM 59	
11. LONGITUDINAL JOIST OR STRINGERS			c. SUBSTRUCTURE	ITEM 60	
12. INT. DIAP'S, X-FRAMES, BRACING & CONN'S	G		d. CHANNEL & CHANNEL PROT.	ITEM 61	
13. END DIAP'S, CURTAIN WALLS, & CONN'S					
14. FLOOR BEAMS AND CONNECTIONS			71. SI&A FIELD APPRAISAL RATINGS		
15. BEARING ASSEMBLIES (INCLUDING MISALIGN)	G		a. WATERWAY ADAQUACY		
16. DRAINAGE SYSTEM (ON STRUCTURE)			b. APPR. RDWY. ALIGNMENT		
17. MOVABLE SPAN MACHINERY					
SUB STR. ITEMS. ITEM 60 (INCLUDE SCOUR)			72. FIELD SCOUR EVALUATION		
35. TIM SUB STR.	a. ABUT. & INT. BENT CAPS & RISERS		USE OF INSP. ACCESSIBILITY EQUIPMENT		
	b. PILES, POST, SILLS, & BRACING		SNOOPER (CODE S, 4, OR N)	HRS	NO
	c. BULKHEADS, WING'S, & TIE BACKS		LADDER		NO
36. CONC SUB STR.	a. ABUT. & INT. BENT CAPS		BUCKET TRUCK		
	b. ABUT. & BENT COL'S BREASTWALLS		BOAT		
	c. ABUT. & INT. BENT PILES		OTHER		
	d. BACKWALLS, WING'S, RETAIN. WALLS				
	e. ABUT. & BENT FOOTINGS & SILLS				
37. STEEL SUB STR.	a. ABUT. & INT. BENT CAPS & RISERS		SPECIAL INSPECTION REQUESTED FOR		
	b. PILES, BRACING, AND BULKHEADS				
38. FOUNDATION PILES TYPE MATERIAL			NOTE		
39. SLOPE PROT., RIP-RAP (INCLUDE DRAINAGE)					
40. FENDER SYSTEMS			80. INSPECTED BY:	D.A. Oshon	
41. DRIFT			81. REVIEWED BY:		

Bridge I&A Form 1(82)H <b>State of North Carolina</b> <b>Dept. of Transportation</b> <b>Division of Highways</b>		<h1 style="text-align: center;">FIELD INSPECTION REPORT</h1> <p style="text-align: center;"><u>Bridge Inspection &amp; Analysis</u></p>	
Team Leader <b>MD OSBORNE</b>			
Assisted By <b>A KING</b>			
<b>Item No.</b>	<b>Grade</b>		
<b>10</b>	<b>P</b>	<p>IMPACT DAMAGE INSPECTION WAS REQUESTED BY DIVISION BRIDGE MAINTENANCE ENGINEER FOR SPAN 3 OVER US 321 NB</p> <p>BEAM 6: POINT OF IMPACT ON BEAM 6 WAS 14'-1" FROM FACE OF BENT 3, FLANGE IS BENT UPWARD 2 3/4" WITH A GOUGE 7" X 1 1/2" X 1/16" +/- DEEP, INDENTIONS IN FLANGE 1" X 1/4" A 3 1/2" X 1/16", A 1" X 1/16" ALL IN THE DAMAGED AREA (DAMAGED AREA IS 3'-0" +/-). LIGHT GOUGES 1" X 12" X 1/64 &amp; 1 1/2" X 12" X 1/64 AT 14'-5". BEAM 6 IS OUT OF PLUMB 3 1/2" +/- TO THE NORTH AT 14'-1" FROM FACE OF BENT 3. INDENTIONS IN FLANGE 1 1/2" X 1/16" AT 15'-1" FROM FACE OF BENT 3. THE NORTH SIDE OF BEAM 6, THE FLANGE IS BENT DOWNWARD 1 1/4" AT 14'-1" FROM FACE OF BENT 3. INDENTIONS IN FLANGE 2" X 1/16" AT 18'-3", A 9" X 1/16" AT 17'-10", A 1" X 1/16" AT 17'-5" FROM FACE OF BENT 2. (SEE PHOTOS)</p> <p>BEAM 4: POINT OF IMPACT ON BEAM 4 WAS 14'-6" FROM FACE OF BENT 3, GOUGES 12" X 1 1/4" X 1/64" +/- DEEP, AND 12" X 1/4" X 1/16" +/- DEEP AT POINT OF IMPACT, A INDENTION 1 1/4" X 1/16" ALL AT POINT OF IMPACT. LIGHT SCRAPES ARE ALONG THE BOTTOM OF FLANGE. (SEE PHOTO).</p> <p>BEAM 3: POINT OF IMPACT ON BEAM 3 WAS 14'-4" FROM FACE OF BENT 3, INDENTIONS IN FLANGE 1" X 1/32" AT POINT OF IMPACT.</p>	
<b>12</b>	<b>G</b>	CONNECTION PLATE OF INTERMEDIATE DIAPHRAGMS IN SPAN 3 DID NOT SHOW ANY DAMAGE DUE TO THE IMPACT.	
<b>15</b>	<b>G</b>	BEARINGS & ANCHOR BOLTS IN SPAN 3 DID NOT SHOW ANY INDICATION OF DAMAGE DUE TO THE IMPACT.	
<b>73f</b>	<b>YES</b>	UT MACHINE,	


## BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 170142

County CATAWBA

Date: 08/06/2012

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	42	DAMAGE TO BEAM 6 DAMAGE TO BEAM 6 AT 14'-1" GOUGE IN BEAM 6 AT 14'-1" BEAM 6 OUT OF PLUMB LOOKING AT BEAM 6	
3314	Maintain Steel Superstructure Components	LF	42	DAMAGE TO BEAM 6 AT 14'-1"	

### Key



Priority Maintenance Item



Critical Finding Item



Priority Maintenance Level Not Determined

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 170142                      County CATAWBA

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	42              LF
Location:		
Beams and Girders	Bent/Span No.    3              BEAM	
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/09/2012	MD OSBORNE	A KING
Details		
DAMAGE TO BEAM 6 DAMAGE TO BEAM 6 AT 14'-1" GOUGE IN BEAM 6 AT 14'-1" BEAM 6 OUT OF PLUMB LOOKING AT BEAM 6		



DAMAGE TO BEAM 6 AT 14'-1"



GOUGE IN BEAM 6 AT 14'-1"





BEAM 6 OUT OF PLUMB



LOOKING AT BEAM 6




FLANGE ON BEAM 6 BENT DOWN



DAMAGE TO BEAM 4 AT 14'-6"

# Bridge Inspection Field Sketch

VERIFIED 1/24/11 R.A. PIERCE, M. FORD



Measurements for Span #	1		
Deck Thickness	0.562	Left Overhang	5
Top of Rail to Bottom of Beam	7	Right Overhang	5

Beam No	Beam Type	Spacing	Comments
1	Steel I Beam	6ft	ALL SPANS SIMILAR
2	Steel I Beam	6ft	
3	Steel I Beam	6ft	
4	Steel I Beam	6ft	
5	Steel I Beam	6ft	
6	Steel I Beam		

UTILITIES: 1 - 10" PIPE IN BAY # 4; 1 - 4" PIPE IN BAY # 5

## Title

SUPER.

## Description

DECK SECTION

Bridge No: 170142

Drawn By: RAP


Date: 03/27/2007

File Name: S0138002220



# Bridge Inspection Field Sketch

VERIFIED 1/24/11 R.A. PIERCE, M. FORD



LOOKING EAST

## Title

APPR. RDWY.

## Description

APPR. RDWY.

Bridge No: 170142

Drawn By: RAP

Date: 03/27/2007


File Name: S0138002221

# Bridge Inspection Field Sketch

VERIFIED 1/24/11 R.A. PIERCE, M. FORD  
MIN. & MAX. MIN. SAME FULL WIDTH: NO 10' BOX

S.R. 1692

SPAN # 3



Roadway 1	Distance to Left Guardrail
	Distance to Right Guardrail
	Distance to Left Toe of Slope
	Distance to Left Bent or Columns 3 FT
	Distance to Right Toe of Slope
	Distance to Right Bent or Columns 3.25 FT
	Maximum Minimum Vertical Clearance 15.333 FT @ 17.5 Measured From RT. CURB AT C.L. on Beam No 6
	Minimum Vertical Clearance 15.333 FT @ 17.5 Measured From LT. CURB AT C.L. on Beam No 6

## Title

CLEARANCE 1

## Description

CLR. FOR SPAN # 3

Bridge No: 170142

Drawn By: RAP

Date: 03/27/2007


File Name: S0138002222

# Bridge Inspection Field Sketch

VERIFIED 1/24/11 R.A. PIERCE, M. FORD

S.R. 1692

SPAN # 2



U.S. 321 S.B.L.

LOOKING SOUTH

Roadway 1	Distance to Left Guardrail
	Distance to Right Guardrail
	Distance to Left Toe of Slope
	Distance to Left Bent or Columns 3 FT
	Distance to Right Toe of Slope
	Distance to Right Bent or Columns 4.083 FT
	Maximum Minimum Vertical Clearance 15.417 FT @ 10 Measured From RT. CURB on Beam No 6
	Minimum Vertical Clearance 15.25 FT @ 10 Measured From LT. CURB on Beam No 6

## Title

CLEARANCE 2

## Description

CLR. FOR SPAN # 2

Bridge No: 170142

Drawn By: RAP

Date: 03/27/2007

File Name: S0138002223



LOOKING NORTH



NC DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS  
BRIDGE MANAGEMENT UNIT

ATTENTION

IMPACT DAMAGE REPORT ON SPAN 2  
RATINGS FOR SPAN 2 ITEMS ONLY  
PRIORITY MAINTENANCE REQUESTED

# BRIDGE INSPECTION REPORT

INSPECTION TYPE: Damage Inspection Report

COUNTY GASTON BRIDGE NUMBER 350149 INSPECTION CYCLE 0 YRS  
ROUTE SR2093 ACROSS I85 M.P. 0

LOCATION 1.0 MI. N. JCT. NC273

SUPERSTRUCTURE REINFORCED CONCRETE DECK ON I-BEAMS

SUBSTRUCTURE E.BTS:RC CAP ON ROCK FOUNDATION,INT.BTS:RCP&B W/SPREAD FTGS.

SPANS 1@65'0, 2@75'0, 1@74'6 COMPOSITE

LONGITUDE 81° 2' 39.1"

LATITUDE 35° 15' 28.9"

PRESENT CONDITION POOR

INVENTORY RATING

INSPECTION DATE 05/21/2012

OPERATING RATING

PRESENT POSTING Not Posted

PROPOSED POSTING

COMPUTER UPDATE

ANALYSIS DATE

POSTING LETTER DATE

SUFFICIENCY RATING

OTHER SIGNS PRESENT



LOOKING SOUTH

SIGN NOTICE ISSUED FOR		NUMBERED REQUIRED
No	WEIGHT LIMIT	<u></u>
No	DELINEATORS	<u></u>
No	NARROW BRIDGE	<u></u>
No	ONE LANE BRIDGE	<u></u>
No	LOW CLEARANCE	<u></u>

## NATIONAL BRIDGE INVENTORY----- STRUCTURE INVENTORY AND APPRAISAL

Run Date: 06/07/2012

IDENTIFICATION					
(1) STATE NAME -NORTH CAROLINA	BRIDGE	350149	SUFFICIENCY RATING =	79	
(8) STRUCTURE NUMBER(FEDERAL)	00000000710149		STATUS =	Functionally Obsolete	
(5) INVENTORY ROUTE (ON/UNDER) - ON	31020930				
(2) STATE HIGHWAY DEPARTMENT DISTRICT	1		CLASSIFICATION	CODE	
(3) COUNTY CODE 71 (4) PLACE CODE	4840		(112)NBIS BRIDGE SYSTEM -	YES	
(6) FEATURE INTERSECTED - I85			(104)HIGHWAY SYSTEM Is not on NHS	0	
(7) FACILITY CARRIED SR2093			(26) FUNCTIONAL CLASS - Other Principal Arterial	14	
(9) LOCATION 1.0 MI. N. JCT. NC273			(100)STRAHNET HIGHWAY - Not a STRAHNET Route	0	
(11)MILEPOINT	0		(101)PARALLEL STRUCTURE - No Parallel Structure	N	
(16)LAT 35° 15' 26.1" (17)LONG 81° 2' 37.5"			(102)DIRECTION OF TRAFFIC - 2-way Traffic	2	
(98)BORDER BRIDGE STATE CODE	PCT SHARE		(103)TEMPORARY STRUCTURE -		
(99)BORDER BRIDGE STRUCTURE NO			(110)DESIGNATED NATIONAL NETWORK - Not on the National Network	0	
			(20) TOLL On Free Road	3	
			(31) MAINTAIN - State Highway Agency	01	
			(22) OWNER - State Highway Agency	01	
			(37) HISTORICAL SIGNIFICANCE - Not Eligible	5	
STRUCTURE TYPE AND MATERIAL					
(43) STRUCTURE TYPE MAIN: Steel					
TYPE - Stringer Multibeam or Girder	CODE	302			
(44) STRUCTURE TYPE APPR :			CONDITION	CODE	
TYPE -	CODE	000			
(45) NUMBER OF SPANS IN MAIN UNIT	4		(58) DECK	7	
(46) NUMBER OF APPROACH SPANS			(59) SUPERSTRUCTURE	7	
(107)DECK STRUCTURE TYPE - 1	CODE		(60) SUBSTRUCTURE	6	
(108)WEARING SURFACE / PROTECTIVE SYSTEM :			(61) CHANNEL & CHANNEL PROTECTION	N	
(A) TYPE OF WEARING SURFACE -	CODE		(62) CULVERTS	N	
(B) TYPE OF MEMBRANE -	CODE				
(C) TYPE OF DECK PROTECTION -	CODE		LOAD RATING AND POSTING	CODE	
			(31) DESIGN LOAD HS 20+MOD	6	
			(63) OPERATING RATING METHOD - Load Factor		
			(64) OPERATING RATING - HS-24	143	
			(65) INVENTORY RATING METHOD - Load Factor		
			(66) INVENTORY RATING - HS-14	126	
			(70) BRIDGE POSTING - Posting Required	4	
			(41) STRUCTURE OPEN, POSTED ,OR CLOSED	P	
			DESCRIPTION - Posted for Load		
AGE AND SERVICE				APPRAISAL	
(27) YEAR BUILT	1961		(67) STRUCTURAL EVALUATION	6	
(106)YEAR RECONSTRUCTED			(68) DECK GEOMETRY	9	
(42) TYPE OF SERVICE : ON - Highway - Pedestrian			(69) UNDERCLEARANCES,VERTI & HORIZ	2	
UNDER - Highway	CODE	51	(71) WATERWAY ADEQUACY	N	
(28) LANES: ON STRUCTURE 4 UNDER STRUCTURE	6		(72) APPROACH ROADWAY ALIGNMENT	8	
(29) AVERAGE DAILY TRAFFIC	20000		(36) TRAFFIC SAFETY FEATURES	0010	
(30) YEAR OF ADT 2010 (109) TRUCK ADT PCT	12%		(113)SCOUR CRITICAL BRIDGES	N	
(19) BYPASS OR DETOUR LENGTH	0 MI				
GEOMETRIC DATA					
(48) LENGTH OF MAXIMUM SPAN	75 FT				
(49) STRUCTURE LENGTH	290 FT				
(50)CURB OR SIDEWALK: LEFT 5.1 FT RIGHT	5.1 FT				
(51) BRIDGE ROADWAY WIDTH CURB TO CURB	52 FT				
(52) DECK WIDTH OUT TO OUT	64.3 FT				
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)	48 FT				
(33) BRIDGE MEDIAN - No Median	CODE	0			
(34) SKEW 43° (35) STRUCTURE FLARED	0				
(10) INVENTORY ROUTE MIN VERT CLEAR	999.9 FT				
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR	52 FT				
(53) MIN VERT CLEAR OVER BRIDGE RDWY	999.9 FT				
(54) MIN VERT UNDERCLEAR REF Not a Highway or Railroad	0 FT				
(55) MIN LAT UNDERCLEAR RT REF Not a Highway or Railroad	000 FT				
(56) MIN LAT UNDERCLEAR LT REF -	000 FT				
NAVIGATION DATA				PROPOSED IMPROVEMENTS	
(38) NAVIGATION CONTROL - Not Applicable	CODE	N	(75) TYPE OF WORK -	CODE	
(111)PIER PROTECTION -	CODE		(76) LENGTH OF STRUCTURE IMPROVEMENT		
(39) NAVIGATION VERTICAL CLEARANCE	0		(94) BRIDGE IMPROVEMENT COST		
(116)VERT - LIFT BRIDGE NAV MIN VERT CLEAR	FT		(95) ROADWAY IMPROVEMENT COST		
(40) NAVIGATION HORIZONTAL CLEARANCE	0 FT		(96) TOTAL PROJECT COST		
			(97) YEAR OF IMPROVEMENT COST ESTIMATE		
			(114)FUTURE ADT 40000 (115) YEAR FUTURE ADT	2025	
				INSPECTIONS	
			(90) INSPECTION DATE	08/24/2010	
			(92) CRITICAL FEATURE INSPECTION :	(93) CFI DATE	
			A) FRACTURE CRIT DETAIL - NO	A)	
			B) UNDERWATER INSP - NO	B)	
			C) OTHER SPECIAL INSP NO	C)	
			SCOUR		

Structure No:

County:

Run Date:

Span Number	6	Inventory Route	Minimum Maximum Vertical Clearance	Milepoint	Base Highway Network	LRS Inventory Route	Toll	Functional Classification	Numer of Lanes	Average Daily Traffic	Year of Average Daily Traffic	Total Horizontal Clearance	See Note 1						Reference Feature	Minimum Vertical Underclearance	Right Lateral Underclearance	Left Lateral Underclearance	Underclearance Appraisal Grade	STRAHNET Highway Designator	Direction of Traffic	Highway System of Route
		5	10	11	12	13	20	26	28	29	30	47	54A	54	55	56	69	100	102	104						

Note 1: Items 54, 55, and 56 are not reported FHWA under route data points but are collected for each under route to determine the minimum value for Underclearance Appraisal Item 69. The under route that generates the lowest Underclearance Appraisal value will be reported on the Facility Carried record.

## BRIDGE MANAGEMENT UNIT

## DATA ON EXISTING STRUCTURE

Run Date: 06/07/2012

COUNTY : DIVISION : DISTRICT: STRUCTURE NUMBER : LENGTH :  
GASTON 12 1 350149 290 FEET

ROUTE CARRIED : FEATURE INTERSECTED :  
SR2093 I85

LOCATED : BRIDGE NAME : CITY :  
1.0 MI. N. JCT. NC273

FUNC. CLASS : SYST.ON : SYST.UNDER : ADT & YR : RAIL TYPE :  
14 FA NFA 20000 2010 LT 139 RT 139

BUILT : BY : PROJ : FED.AID PROJ : DESIGN LOAD :  
1961 SHC 8.16318 BP-5300K HS 20+MOD

REHAB : BY : PROJ : ALIGNMENT : SKEW : LANES :  
TAN 47 ON 4 UNDER 6

NAVIGATION : HT. CRN. TO BED : WATER DEPTH :  
VC 0 FT HC 0 FT 0 FT 0 FT

SUPERSTRUCTURE : REINFORCED CONCRETE DECK ON I-BEAMS

SUBSTRUCTURE : E.BTS:RC CAP ON ROCK FOUNDATION,INT.BTS:RCP&B W/SPREAD FTGS.

SPANS : 1@65'0, 2@75'0, 1@74'6 COMPOSITE

BEAMS OR GIRDERS : 10LN@6'1 CT,SP1:W36X150EX,W33X130IN,#2-4:W36X170EX,W36X150IN

FLOOR : ENCROACHMENT : DECK (OUT TO OUT) :  
6.75 RC,1.5 AWS 64.3 FT

CLEAR ROADWAY : BETWEEN RAILS : SIDEWALK OR CURB :  
52 FT 62.2 FT LT 5.1 FT RT 5.1 FT

VERT.CL.OVER :  
999.9 FT

INV.RTG. : OPE.RTG. : CONTR.MEMBER : POSTED :  
HS-14 HS-24 Entbm10(B) SV 41 TTST 41 DATE 05/10/2012

SYSTEM : GREEN LINE ROUTE :  
Primary S.R. Route Y

## UNDER ROUTES AND CLEARANCES

Span	Route Description	Vertical Clearances		Horizontal Clearances		
		MMVC	MVC	Total	Left	Right

Note: All measurements are in feet.

REMARKS :



# BRIDGE INSPECTION RECORD AND SUMMARY

INSPECTION TYPE Damage Inspection Report

BRIDGE NO. 350149

COUNTY GASTON

ROUTE SR2093

OVER I85

STRUCTURE TYPE REINFORCED CONCRETE DECK ON I-BEAMS

ROUTE ORIENTATION

SPANS 1 @65'0, 2 @75'0, 1 @74'6 COMPOSITE

EVALUATION CODES: CRITICAL (C, 0 - 3); POOR (P, 4); FAIR (F, 5, 6); GOOD (G, 7 - 9)

INSPECTION ITEM			ITEM 61		
DECK ITEMS		GRADES			
1. WEARING SURFACE			45. CHANNEL & CHANNEL PROT.	a. WATERWAY	
				b. ALIGNMENT	
				c. SCOUR	
				d. SLOPE PROT., RIP-RAP, DIKES, ETC.	
2. DECK NO. OF EA TYPE SPN GRADE RATES SI & A ITEM 58	a. CONCRETE		50. APPROACH ROADWAY CONDITION		
	b. TIMBER		51. APPROACH SLABS		
	c. STEEL PLANK		52. PAINT SYSTEM CODE		
	d. OPEN GRID		53. UTILITIES		
3. RAILING	a. CONCRETE		54. RESPONSE TO LIVE LOAD		
	b. TIMBER		55. ESTIMATED REMAINING LIFE		
	c. ALUMINUM		12		
	d. STEEL				
4. CURBS, WHEELGUARDS, PARAPETS, MEDIANS					
5. WALKWAYS (ON OR ATTACHED TO STRUCTURE)			60. REGULATORY SIGN NOTICE ISSUED		
			NO		
6. DECK EXP JTS. OR DEVICES. NO. OF EACH	a. STEEL PL OR FINGER		61. PROMPT-ACTION NOTICE ISSUED		
	b. MISC PREFAB		YES		
	c. COMPRESSION SEAL		62. PRESENTLY POSTED		
	d. STANDARD JOINTS		NO		
	e. OPEN JOINTS		63. TOT. FIELD INSP TIME (INCLUDE WRITE UP)(MAN HR)		
			24		
			64. TOTAL SNOOPER INSP. TIME (HRS)		
			0		
			65. TOTAL TRAFFIC CONTROL TIME (MAN HRS)		
			8		
7. DECK DEBRIS (INCLUDES EXCESS SAND/GRAVEL)					
			70. SI&A GENERAL CONDITION RATINGS		
SUPER STR. (FM. 1 (90)B TRUSS) ITEM 59			a. DECK ITEM 58		
10. LONGITUDINAL BEAMS OR GIRDERS			P		
11. LONGITUDINAL JOIST OR STRINGERS			b. SUPERSTRUCTURE ITEM 59		
12. INT. DIAP'S, X-FRAMES, BRACING & CONN'S			c. SUBSTRUCTURE ITEM 60		
13. END DIAP'S, CURTAIN WALLS, & CONN'S			d. CHANNEL & CHANNEL PROT. ITEM 61		
14. FLOOR BEAMS AND CONNECTIONS					
15. BEARING ASSEMBLIES (INCLUDING MISALIGN)			71. SI&A FIELD APPRAISAL RATINGS		
16. DRAINAGE SYSTEM (ON STRUCTURE)			a. WATERWAY ADAQUACY		
17. MOVABLE SPAN MACHINERY			b. APPR. RDWY. ALIGNMENT		
			72. FIELD SCOUR EVALUATION		
SUB STR. ITEMS. ITEM 60 (INCLUDE SCOUR)					
35. TIM SUB STR.	a. ABUT. & INT. BENT CAPS & RISERS		USE OF INSP. ACCESSIBILITY EQUIPMENT		
	b. PILES, POST, SILLS, & BRACING		SNOOPER (CODE S, 4, OR N) HRS		
	c. BULKHEADS, WING'S, & TIE BACKS		NO		
36. CONC SUB STR.	a. ABUT. & INT. BENT CAPS		LADDER		
	b. ABUT. & BENT COL'S BREASTWALLS		NO		
	c. ABUT. & INT. BENT PILES		BUCKET TRUCK		
	d. BACKWALLS, WING'S, RETAIN. WALLS		YES		
	e. ABUT. & BENT FOOTINGS & SILLS		BOAT		
37. STEEL SUB STR.	a. ABUT. & INT. BENT CAPS & RISERS		OTHER		
	b. PILES, BRACING, AND BULKHEADS		YES		
38. FOUNDATION PILES TYPE MATERIAL			SPECIAL INSPECTION REQUESTED FOR		
39. SLOPE PROT., RIP-RAP (INCLUDE DRAINAGE)					
40. FENDER SYSTEMS			NOTE		
41. DRIFT			80. INSPECTED BY:		
			81. REVIEWED BY:		

Bridge I&A Form 1(82)H State of North Carolina Dept. of Transportation Division of Highways		<h1 style="text-align: center;">FIELD INSPECTION REPORT</h1> <p style="text-align: center;"><u>Bridge Inspection &amp; Analysis</u></p>	
Team Leader MD OSBORNE			
Assisted By A KING			
Item No.	Grade		
10	P	<p>IMPACT DAMAGE INSPECTION WAS REQUESTED BY DIVISION BRIDGE MAINTENANCE FOR SPAN 2 OVER I 85 SOUTH GIRDERS HAVE BEEN PAINTED SINCE THE IMPACT.</p> <p>GIRDER #10: POINT OF IMPACT ON GIRDER #10 WAS 19'-11" FROM FACE OF BENT 1, THE FLANGE AND FLANGE COVER PLATE ARE BENT OUT OF SHAPE 1 7/8" TO THE SOUTH AT 19'-11" FROM BENT 1., A CRACK 1' -0" IN THE COVER PLATE TO FLANGE WELD, A 7" CRACK ACROSS THE COVER PLATE ONLY LEAVING 3 3/4"+/- NOT BEING CRACKED, A GOUGE IN THE COVER PLATE 8" X 1 1/4" X 1/4"+/- DEEP ALL AT 19'-11" FROM BENT 1. THE FLANGE AND COVER PLATE ARE BENT UPWARD 1/2", WITH AN INDENTION IN COVER PLATE 12"X 1/16" AT 21'-10" FROM FACE OF BENT 1. A 8" CRACK IN THE FLANGE TO COVER PLATE WELD AT 21'-2" FROM FACE OF BENT 1. INDENTIONS IN FLANGE COVER PLATE 5" X 1/16" AT 25'-9", A 2 1/2" X 1/2" AT 24'-6", A 6 1/2" X 1/4" AT 23'-11", A 3" X 1/16" AT 23'-7", 2 1/2" X 1/4" AT 23'-3", A 5 1/2" X 1/4" AT 18'-4", A 3'-4" X 1/16" AT 16'-2" ALL FROM FACE OF BENT 1. INDENTIONS IN FLANGE 2 1/2" X 1/2" AT 24'-6", A 4" X 1/4" AT 23'-11", A 1 1/2" X 1/4" AT 22'-8", A 12" X 1/4" AT 16'-2" ALL FROM FACE OF BENT 1. GIRDER IS OUT OF PLUMB 1 7/8" IN THE DIRECTION OF TRAFFIC AT 20'-2" FROM BENT 1. INDENTION IN FLANGE COVER PLATE 17" X 1/2" AND IN FLANGE 2'-0" X 5/8" AT 38'-2" FROM FACE OF BENT 1. INDENTION IN FLANGE COVER PLATE 7" X 5/8" AT 35'-7" FROM FACE OF BENT 1. GIRDER 10 IS 4 1/4" OUT OF PLUMB AT 37'-5" FROM FACE OF BENT 1. INDENTION IN FLANGE COVER PLATE 7" X 1/16" AND IN FLANGE 2'-10" X 1/4" AT 43'-1" FROM FACE OF BENT 1. (SEE PHOTOS)</p> <p>GIRDER #9: POINT OF IMPACT ON GIRDER #9 WAS 18'-0" FROM FACE OF BENT 1, INDENTION IN FLANGE COVER PLATE 1'-6" X 1/4". INDENTIONS IN FLANGE COVER PLATE 2 1/2" X 1/16" AT 19'-9", A 3" X 1/16" AT 16'-10" FROM FACE OF BENT 1. INDENTION IN FLANGE 1" X 1/16" AT 16'-10" FROM FACE OF BENT 1. A INDENTION IN FLANGE COVER PLATE 5" X 1/16" AT 36'-6" FROM FACE OF BENT 1. INDENTION IN FLANGE COVER PLATE 3" X 1/16" AT 42'-9" FROM FACE OF BENT 1. (SEE PHOTOS)</p> <p>GIRDER #8: POINT OF IMPACT ON GIRDER #8 WAS 21'-6" FROM FACE OF BENT 1, INDENTION IN FLANGE COVER PLATE 2" X 1/16" &amp; 5 1/2" X 1/16", A INDENTION IN FLANGE 1 1/2" X 1/16" ALL IN THE DAMAGED AREA. INDENTION IN FLANGE COVER PLATE 1'-7" X 1/16" AT 19'-4", 1 1/2" X 1/16 AT 18'-3" FROM FACE OF BENT 1. THE TOP WELD ON THE STIFFNER AT THE WEST END OF GIRDER #8 HAS RUSTED AWAY . (SEE PHOTOS)</p> <p>GIRDER 7: POINT OF IMPACT ON GIRDER #7 WAS 23'-11" FROM FACE OF BENT 1, INDENTION IN FLANGE COVER PLATE 3 3/4" X 1/2" AND IN FLANGE 5" X 1/4" AT DAMAGED AREA. INDENTIONS IN FLANGE COVER PLATE 6" X 1/16" AT 22'-10", A 4" X 1/16" AT 21'-9" FROM FACE OF BENT 1. (SEE PHOTOS)</p> <p>GIRDER #6: POINT OF IMPACT ON GIRDER #6 WAS 23'-6" FROM FACE OF BENT 1, INDENTION IN FLANGE COVER PLATE 2 1/2" X 1/16" AND A 4" X 1/16" IN THE DAMAGED AREA (SEE PHOTO)</p>	

Bridge I&A Form 1(82)H State of North Carolina Dept. of Transportation Division of Highways		<b>FIELD INSPECTION REPORT</b> <u>Bridge Inspection &amp; Analysis</u>	
Team Leader MD OSBORNE			
Assisted By A KING			
Item No.	Grade		
12	P	CONNECTION PLATE OF INTERMEDIATE DIAPHRAGMS: ON GIRDER #10 AT 19'-4" FROM FACE OF BENT 1 HAS 4 LOOSE DIAPHRAGM BOLTS AND 4 DIAPHRAGMS BOLTS WITHOUT WASHERS. SPACERS/WAHERS HAVE BEEN ADDED BEHIND THE DIAPHRAGM TO THE LOWER DIAPHRAGM BOLTS TO FILL THE SPACE BETWEEN DIAPHRAGM AND WEB. BOTTOM OF DIAPHRAGM AT 39'-11" IS 2 1/2" FROM WEB. THE DIAPHRAGM BRACE ON GIRDER 10 IS BENT TO THE WEST 1 1/4" AT 39'-11" FROM FACE OF BENT 1. WASHERS HAVE BEEN ADDED TO THE LOWER HALF OF DIAPHRAGM TO MAKE UP 2 1/2" AT 39'-11" FROM FACE OF BENT 1. ON GIRDER 10 THE 22 DIAPHRAGM BOLTS 14 ARE WITHOUT WASHERS AND 8 HAVE WASHERS AT 39'-11" FROM BENT 1. AT THE TOP OF DIAPHRAGM ON GIRDER #8 AT 13'-11" FROM BENT 1 IS PULLED AWAY FROM WEB 1/8". THE SECOND BOLT DOWN ON THE RIGHT SIDE OF DIAPHRAGM ON GIRDER #9 AT 16'-6" FROM FACE OF BENT 1 IS NOT FULLY THREADED. DIAPHRAGM BOLT ON GIRDER 9 AT 34'-7" IS NOT PULLED UP TIGHT .REPAIRS HAVE BEEN MADE TO THE DIAPHRAGM ON GIRDER #9 AT 16'-6" FROM FACE OF BENT 1. ALL GIRDERS HAVE BEEN PAINTED SINCE DAMAGE. (SEE PHOTOS)	
15	F	BEARINGS AND ANCHOR BOLTS IN SPAN 2 DID NOT SHOW ANY DAMAGE DUE TO THE IMPACT.	
61	YES	GIRDER #1 AND DIAPHRAGMS	
73f	YES	UT MACHINE	





# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 350149

County GASTON

Date: 05/21/2012

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
3314	Maintain Steel Superstructure Components	LF	1	CRACK ( 8" LONG ) IN WELD OF COVER PLATE TO FLANGE @ 21'-2"	
3314	Maintain Steel Superstructure Components	LF	1	CRACK IN BOTTOM OF COVER PLATE IS 7" LONG. 3 3/4" REMAINS NOT CRACKED.	
3314	Maintain Steel Superstructure Components	LF	1	CRACK IN WELD IN COVER PLATE TO FLANGE IS 1 FOOT LONG @ 19'-11" FROM THE FACE OF BENT 3. GIRDER # 1, SPAN 3	
 3314	Maintain Steel Superstructure Components	LF	1	DIAPHRAGM BOLT OD GIRDER 9 DIAPHRAGM BOLT ON RIGHT SIDE OF GIRDER 9 IS NOT PULLED UP TIGHT @ 34'-7" FROM THE FACE OF BENT 1	
3314	Maintain Steel Superstructure Components	LF	1	DIAPHRAGM BOLT ON GIRDER NOT FULL THREAD BOLT # 2 ON LEFT SIDE OF DIAPHRAGM @ 16'-6" IS NOT FULLY THREADED. GIRDER # 2, SPAN 3	
 3314	Maintain Steel Superstructure Components	LF	3	CRACK IN GIRDER #1 COVER PLATE POINT OF IMPACT ON GIRDER # 1 WAS 19'-11" FROM THE FACE OF BENT 3. FLANGE AND COVER PLATE IS OUT OF PLACE. GIRDER # 1, SPAN 3 CRACK IN WELD IN COVER PLATE TO FLANGE IS 1 FOOT LONG @ 19'-11" FROM THE FACE OF BENT 3. GIRDER # 1, SPAN 3 CRACK IN BOTTOM OF COVER PLATE IS 7" LONG. 3 3/4" REMAINS NOT CRACKED. CRACK ( 8" LONG ) IN WELD OF COVER PLATE TO FLANGE @ 21'-2"	
 3314	Maintain Steel Superstructure Components	LF	3	STIFFNER ON GIRDER #3 NO WELD CONDITIONS FOUND IN GIRDER # 3, SPAN 3	
 3314	Maintain Steel Superstructure Components	LF	4	DIAPHRAGM BOLTS ON GIRDER #1 ARE LOOSE BOTTOM OF WEB IS BENT TO THE SOUTH ( 7/8" ) AT DIAPHRAGM @ 19'-4" FROM THE FACE OF BENT 3. GIRDER # 1, SPAN 3 FOUR DIAPHRAGM BOLTS ARE NOT TIGHT @ 19'-4" FROM THE FACE OF BENT 3. DIAPHRAGM BOLTS ARE LOOSE. FOUR HAVE NO WASHERS. GIRDER # 1, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	4	FOUR DIAPHRAGM BOLTS ARE NOT TIGHT @ 19'-4" FROM THE FACE OF BENT 3.	

Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined




# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 350149

County GASTON

Date: 05/21/2012

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	5	DIAPHRAGM ON GIRDER 10 BOTTOM OF DIAPHRAGM ON GIRDER 10 IS 2 1/2" AWAY FROM THE WEB @ 39'-11" FROM THE FACE OF BENT 1 DIAPHRAGM BRACE IS BENT ( 1 1/4" ) TO THE WEST @ 39'-11" FROM THE FACE OF BENT 1. GIRDER 10 DIAPHRAGM BOLT DOES NOT HAVE A FULL THREAD @ 39'-11" FROM THE FACE OF BENT 1. GIRDER 10 WASHERS BEHIND DIAPHRAGM @ 39'-11" FROM THE FACE OF BENT 1, FOR A BUILD UP OF 2 1/2". GIRDER 10	
3314	Maintain Steel Superstructure Components	LF	6	FLANGE AND COVER PLATE IS BENT UPWARD ( 1/2" +/- ) @ 21'-10" INDENTION IS 12" LONG. GIRDER # 1	
 3314	Maintain Steel Superstructure Components	LF	74	GIRDER 10 IS OUT OF PLUMB 4 1/4" AT 37'-5" FROM BENT 1 GIRDER 10 IS OUT OF PLUMB ( 4 1/4" ) @ 37'-5" FROM THE FACE OF BENT 1 LOOKING EAST AT GIRDER 10	
3314	Maintain Steel Superstructure Components	LF	75	GIRDER # 1 IS OUT OF PLUMB ( 1 7/8" ) IN THE DIRECTION OF TRAFFIC @ 20'-2" FROM THE FACE OF BENT 3.	
 3314	Maintain Steel Superstructure Components	LF	75	GIRDER #1 IS OUT OF PLUMB GIRDER # 1 IS OUT OF PLUMB ( 1 7/8" ) IN THE DIRECTION OF TRAFFIC @ 20'-2" FROM THE FACE OF BENT 3. LOOKING AT GIRDER # 1 FROM BENT 3, SPAN 3	

## Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 350149

County GASTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	4 LF
Location:		
Beams and Girders	Bent/Span No. 3	DIAPHRAGM
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
05/08/2012	MD OSBORNE	A KING
Details		
<p>DIAPHRAGM BOLTS ON GIRDER #1 ARE LOOSE BOTTOM OF WEB IS BENT TO THE SOUTH ( 7/8" ) AT DIAPHRAGM @ 19'-4" FROM THE FACE OF BENT 3. GIRDER # 1, SPAN 3 FOUR DIAPHRAGM BOLTS ARE NOT TIGHT @ 19'-4" FROM THE FACE OF BENT 3. DIAPHRAGM BOLTS ARE LOOSE. FOUR HAVE NO WASHERS. GIRDER # 1, SPAN 3</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	75 LF
Location:		
Beams and Girders	Bent/Span No. 3	GIRDER
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
05/08/2012	MD OSBORNE	A KING
Details		
<p>GIRDER #1 IS OUT OF PLUMB GIRDER # 1 IS OUT OF PLUMB ( 1 7/8" ) IN THE DIRECTION OF TRAFFIC @ 20'-2" FROM THE FACE OF BENT 3. LOOKING AT GIRDER # 1 FROM BENT 3, SPAN 3</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 350149

County GASTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	3 LF
Location:		
Beams and Girders	Bent/Span No. 3	GIRDERS
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification Received	
Submitted Date:	Submitted By:	Assisted By:
05/08/2012	MD OSBORNE	A KING
Details		
CRACK IN GIRDER #1 COVER PLATE POINT OF IMPACT ON GIRDER # 1 WAS 19'-11" FROM THE FACE OF BENT 3. FLANGE AND COVER PLATE IS OUT OF PLACE. GIRDER # 1, SPAN 3 CRACK IN WELD IN COVER PLATE TO FLANGE IS 1 FOOT LONG @ 19'-11" FROM THE FACE OF BENT 3. GIRDER # 1, SPAN 3 CRACK IN BOTTOM OF COVER PLATE IS 7" LONG. 3 3/4" REMAINS NOT CRACKED. CRACK ( 8" LONG ) IN WELD OF COVER PLATE TO FLANGE @ 21'-2"		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	3 LF
Location:		
Beams and Girders	Bent/Span No. 3	GIRDER
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
05/08/2012	MD OSBORNE	A KING
Details		
STIFFNER ON GIRDER #3 NO WELD CONDITIONS FOUND IN GIRDER # 3, SPAN 3		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 350149

County GASTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1 LF
Location:		
Beams and Girders	Bent/Span No. 3	DIAPHRAGM
Priority Level	Status	
Recommended	Routine Maintenance	
Submitted Date:	Submitted By:	Assisted By:
05/08/2012	MD OSBORNE	A KING
Details		
<p>DIAPHRAGM BOLT ON GIRDER NOT FULL THREAD BOLT # 2 ON LEFT SIDE OF DIAPHRAGM @ 16'-6" IS NOT FULLY THREADED. GIRDER # 2, SPAN 3</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	5 LF
Location:		
Beams and Girders	Bent/Span No. 2	DIAPHRAGM
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
05/21/2012	MD OSBORNE	A KING
Details		
<p>DIAPHRAGM ON GIRDER 10 BOTTOM OF DIAPHRAGM ON GIRDER 10 IS 2 1/2" AWAY FROM THE WEB @ 39'-11" FROM THE FACE OF BENT 1 DIAPHRAGM BRACE IS BENT ( 1 1/4" ) TO THE WEST @ 39'-11" FROM THE FACE OF BENT 1. GIRDER 10 DIAPHRAGM BOLT DOES NOT HAVE A FULL THREAD @ 39'-11" FROM THE FACE OF BENT 1. GIRDER 10 WASHERS BEHIND DIAPHRAGM @ 39'-11" FROM THE FACE OF BENT 1, FOR A BUILD UP OF 2 1/2". GIRDER 10</p>		



## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 350149

County GASTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	74 LF
Location:		
Beams and Girders	Bent/Span No. 2	GIRDER
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
05/21/2012	MD OSBORNE	A KING
Details		
GIRDER 10 IS OUT OF PLUMB 4 1/4" AT 37'-5" FROM BENT 1 GIRDER 10 IS OUT OF PLUMB ( 4 1/4" ) @ 37'-5" FROM THE FACE OF BENT 1 LOOKING EAST AT GIRDER 10		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1 LF
Location:		
Beams and Girders	Bent/Span No. 2	DIAPHRAGM
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
05/21/2012	MD OSBORNE	A KING
Details		
DIAPHRAGM BOLT OD GIRDER 9 DIAPHRAGM BOLT ON RIGHT SIDE OF GIRDER 9 IS NOT PULLED UP TIGHT @ 34'-7" FROM THE FACE OF BENT 1		



IMPACT ON GIRDER # 6 WAS 23'-6" FROM THE FACE OF BENT 1. INDENTIONS 2 1/2" X 1/16" & 4" X 1/16"



IMPACT ON GIRDER # 7 WAS 23'-11" FROM THE FACE OF BENT 1



LADDER FOR PAINTERS IS AGAINST BENT # 1.



IMPACT ON GIRDER # 8 WAS 21'-6" FROM THE FACE OF BENT 1.



INDENTION ( 1'-7" X 1/16" ) IN COVER PLATE @ 19'-4" FROM THE FACE OF BENT 1. GIRDER 8




POINT OF IMPACT ON GIRDER 9 WAS 18'-0" FROM THE FACE OF BENT 1. INDENTIONS IN COVER PLATE





TOP OF DIAPHRAGM @ 13'-11" HAS PULLED AWAY FROM FLANGE 1/8". GIRDER 9



CONDITIONS FOUND IN GIRDER 8



REPAIRS MADE TO DIAPHRAGM @ 16'-6" ON SOUTH SIDE OF GIRDER 9



BOLT # 2 ON LEFT SIDE OF DIAPHRAGM @ 16'-6" IS NOT FULLY THREADED. GIRDER 9



IMPACT ON GIRDER 10 WAS 19'-11" FROM THE FACE OF BENT 1.




CRACK IN WELD IN COVER PLATE TO FLANGE IS 1 FOOT LONG @ 19'-11" FROM THE FACE OF BENT 1  
GIRDER 10





CRACK IN BOTTOM OF COVER PLATE IS 7" LONG. 3 3/4" REMAINS NOT CRACKED. GIRDER 10



FLANGE AND COVER PLATE IS BENT UPWARD ( 1/2" +/- ) @ 21'-10" INDENTATION IS 12" LONG. GIRDER # 10





CRACK 8" LONG IN WELD OF COVER PLATE TO FLANGE @ 21'-2" IN GIRDER 10



GIRDER 10 IS OUT OF PLUMB  $1\frac{7}{8}$ " IN THE DIRECTION OF TRAFFIC @ 20'-2" FROM THE FACE OF BENT 1.



BOTTOM OF WEB IS BENT TO THE SOUTH 7/8" AT DIAPHRAGM @ 19'-4" FROM THE FACE OF BENT 1.  
GIRDER 10



FOUR DIAPHRAGM BOLTS ARE NOT TIGHT @ 19'-4" FROM THE FACE OF BENT 1. GIRDER 10



DIAPHRAGM BOLTS ARE LOOSE. FOUR HAVE NO WASHERS. GIRDER 10



LOOKING AT GIRDER 10 FROM BENT 1






POINT OF IMPACT, IN MIDDLE LANE, ON GIRDER 9 IS 36'-6" FROM THE FACE OF BENT 1. INDENTATION IN COVER PLATE IS 5" X 1/16".




DIAPHRAGM BOLT ON RIGHT SIDE OF GIRDER 9 IS NOT PULLED UP TIGHT @ 34'-7" FROM THE FACE OF BENT 1



POINT OF IMPACT ON GIRDER 10 IS 38'-2" FROM THE FACE OF BENT 1. INDENTIONS IN COVER PLATE ( 17" X 1/2" ) & FLANGE ( 24" X 5/8" )



INDENTION ( 7" X 5/8" ) IN COVER PLATE @ 35'-7" FROM THE FACE OF BENT 1. GIRDER 10



BOTTOM OF DIAPHRAGM ON GIRDER 10 IS 2 1/2" AWAY FROM THE WEB @ 39'-11" FROM THE FACE OF BENT  
1




DIAPHRAGM BRACE IS BENT ( 1 1/4" ) TO THE WEST @ 39'-11" FROM THE FACE OF BENT 1. GIRDER 10





DIAPHRAGM BOLT DOES NOT HAVE A FULL THREAD @ 39'-11" FROM THE FACE OF BENT 1. GIRDER 10



WASHERS BEHIND DIAPHRAGM @ 39'-11" FROM THE FACE OF BENT 1, FOR A BUILD UP OF 2 1/2". GIRDER 10





BOTTOM OF DECK ABOVE DIAPHRAGM @ 39'-11" FROM THE FACE OF BENT 1. GIRDER 10



GIRDER 10 IS OUT OF PLUMB ( 4 1/4" ) @ 37'-5" FROM THE FACE OF BENT 1



INDENTION ( 2'-10" X 1/4" ) IN FLANGE OF GIRDER 10 @ 43'-1" FROM THE FACE OF BENT 1 AND COVER PLATE ( 7" X 1/16" )



1 1/2" BOW IN GIRDER 10 WEB @ 39'-11" FROM THE FACE OF BENT 1



14 DIAPHRAGM BOLTS WITHOUT WASHERS AND 8 WITH WASHERS @ 39'-11" FROM THE FACE OF BENT 1.  
GIRDER 10



LOOKING EAST AT GIRDER 10

## Bridge Inspection Field Sketch




Roadway	48.00ft Wide	4 Paved Lanes	Looking East
Left Shoulder	12ft Wide		12.00ft Unpaved
Right Shoulder	9ft Wide		9.00ft Unpaved
Left Guardrail			
Right Guardrail	9.00ft from road		

VERIFIED 8-24-2010 BY DELVIN ADAMS

<b>Title</b> APPROACH ROADWAY		<b>Description</b> APPROACH ROADWAY	
<b>Bridge No:</b> 350149	<b>Drawn By:</b> DJA	<b>Date:</b> 8/20/2008	<b>File Name:</b> S0298000778

# Bridge Inspection Field Sketch

Deck Width/Out to Out	64.33ft	Wearing Surface	0.13ft
Between Rails	62.17ft	Median Width	
Curb Height	0.75ft	Median Height	
Top Rail to Deck/Wearing Surface	3.17ft	Left Guardrail Width	
Clear Roadway	52.00ft	Right Guardrail Width	
Left Bridge Rail	Type 13	Right Bridge Rail	Type 13





Measurements for Span #	1		
Deck Thickness	0.56	Left Overhang	5.29
Top of Rail to Bottom of Beam		Right Overhang	5.29

Beam No	Beam Type	Spacing	Comments
1	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
2	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
3	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
4	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
5	Steel I Beam	5.00ft	SEE PLANS FOR BEAM SIZE
6	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
7	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
8	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
9	Steel I Beam	6.08ft	SEE PLANS FOR BEAM SIZE
10	Steel I Beam		SEE PLANS FOR BEAM SIZE

VERIFIED 8-24-2010 BY DELVIN ADAMS

<b>Title</b>		<b>Description</b>	
DECK DIMENSIONS		TYPICAL SECTION	
Bridge No:	350149	Drawn By:	DJA
Date:	8/20/2008	File Name:	S0298000779

# Bridge Inspection Field Sketch





Roadway 1	Distance to Left Guardrail 4.58 FT
	Distance to Right Guardrail 9 FT
	Distance to Left Toe of Slope
	Distance to Left Bent or Columns 6.08 FT
	Distance to Right Toe of Slope
	Distance to Right Bent or Columns 10.5 FT
	Maximum Minimum Vertical Clearance 16.92 FT @ 10 Measured From LEFT EDGE OF ROADWAY on Beam No 10
	Minimum Vertical Clearance 16.583 FT @ 0 Measured From RIGHT EDGE OF ROADWAY on Beam No 10

VERIFIED 8-24-2010 BY DELVIN ADAMS

<b>Title</b>		<b>Description</b>	
SPAN #2 OVER I-85 NORTHBOUND		SPAN #2 UNDERCLEARANCE	
<b>Bridge No:</b> 350149	<b>Drawn By:</b> DJA	<b>Date:</b> 8/20/2008	<b>File Name:</b> S0298000780

# Bridge Inspection Field Sketch



Roadway 1	Distance to Left Guardrail 4.5 FT
	Distance to Right Guardrail 9 FT
	Distance to Left Toe of Slope
	Distance to Left Bent or Columns 6 FT
	Distance to Right Toe of Slope
	Distance to Right Bent or Columns 10.5 FT
	Maximum Minimum Vertical Clearance 15.17 FT @ 10 Measured From RIGHT EDGE OF ROADWAY on Beam No 10
	Minimum Vertical Clearance 15 FT @ 0 Measured From LEFT EDGE OF ROADWAY on Beam No 10

VERIFIED 8-24-2010 BY DELVIN ADAMS

## Title

SPAN #3 OVER I-85 SOUTHBOUND

## Description

SPAN #3 UNDERCLEARANCE

Bridge No: 350149

Drawn By: DJA

Date: 8/20/2008

File Name: S0298000781





LOOKING SOUTH





NC DEPARTMENT OF TRANSPORTATION  
DIVISION OF HIGHWAYS  
BRIDGE MANAGEMENT UNIT

ATTENTION

IMPACT DAMAGE REPORT ON SPAN 3  
RATINGS FOR SPAN 3 ITEMS ONLY  
PRIORITY MAINTENANCE REQUESTED

# BRIDGE INSPECTION REPORT

INSPECTION TYPE: Damage Inspection Report

COUNTY IREDELL BRIDGE NUMBER 480104 INSPECTION CYCLE 0 YRS  
ROUTE 140 EBL ACROSS US64,NC90 M.P. 148000

LOCATION 0.1 MI. S. JCT. SR1006

SUPERSTRUCTURE REINFORCED CONCRETE DECK ON I-BEAMS, APPROACH SLABS

SUBSTRUCTURE EBTS:RC CAPS ON PPC PILES, INTBTS:RC POST&BEAM ON PILE FTGS

SPANS 1@56'0 , 1@70'0 , 1@64'0 , 1@50'0 , COMPOSITE

LONGITUDE 80° 56' 92.24"

LATITUDE 35° 47' 37.64"

PRESENT CONDITION POOR

INVENTORY RATING

INSPECTION DATE 07/25/2012

OPERATING RATING

PRESENT POSTING Not Posted

PROPOSED POSTING

COMPUTER UPDATE

ANALYSIS DATE

POSTING LETTER DATE

SUFFICIENCY RATING

OTHER SIGNS PRESENT LOW CLEARANCE



LOOKING NORTH

SIGN NOTICE ISSUED FOR		NUMBERED REQUIRED
<u>No</u>	WEIGHT LIMIT	<u></u>
<u>No</u>	DELINEATORS	<u></u>
<u>No</u>	NARROW BRIDGE	<u></u>
<u>No</u>	ONE LANE BRIDGE	<u></u>
<u>No</u>	LOW CLEARANCE	<u></u>

## NATIONAL BRIDGE INVENTORY----- STRUCTURE INVENTORY AND APPRAISAL

Run Date: 08/29/2012

IDENTIFICATION					
(1) STATE NAME -NORTH CAROLINA	BRIDGE	480104	SUFFICIENCY RATING =	63	
(8) STRUCTURE NUMBER(FEDERAL)	00000000970104		STATUS =	Functionally Obsolete	
(5) INVENTORY ROUTE (ON/UNDER) - ON	11000400				
(2) STATE HIGHWAY DEPARTMENT DISTRICT	2		CLASSIFICATION	CODE	
(3) COUNTY CODE 97 (4) PLACE CODE	64740		(112)NBIS BRIDGE SYSTEM -	YES	
(6) FEATURE INTERSECTED - US64,NC90			(104)HIGHWAY SYSTEM Is on the NHS	1	
(7) FACILITY CARRIED I40 EBL			(26) FUNCTIONAL CLASS - Arterial - Interstate	11	
(9) LOCATION 0.1 MI. S. JCT. SR1006			(100)STRAHNET HIGHWAY - Interstate STRAHNET Route	1	
(11)MILEPOINT	148		(101)PARALLEL STRUCTURE - Right Parallel Structure	R	
(16)LAT 35° 47' 37.64" (17)LONG 80° 56' 92.24"			(102)DIRECTION OF TRAFFIC - 1-way Traffic	1	
(98)BORDER BRIDGE STATE CODE	PCT SHARE		(103)TEMPORARY STRUCTURE -		
(99)BORDER BRIDGE STRUCTURE NO			(110)DESIGNATED NATIONAL NETWORK - On the National Network	1	
			(20) TOLL On Free Road	3	
			(31) MAINTAIN - State Highway Agency	01	
			(22) OWNER - State Highway Agency	01	
			(37) HISTORICAL SIGNIFICANCE - Not Eligible	5	
STRUCTURE TYPE AND MATERIAL					
(43) STRUCTURE TYPE MAIN: Steel					
TYPE - Stringer Multibeam or Girder	CODE	302			
(44) STRUCTURE TYPE APPR :			CONDITION	CODE	
TYPE -	CODE	000			
(45) NUMBER OF SPANS IN MAIN UNIT	4		(58) DECK	5	
(46) NUMBER OF APPROACH SPANS			(59) SUPERSTRUCTURE	5	
(107)DECK STRUCTURE TYPE - 1	CODE		(60) SUBSTRUCTURE	5	
(108)WEARING SURFACE / PROTECTIVE SYSTEM :			(61) CHANNEL & CHANNEL PROTECTION	N	
(A) TYPE OF WEARING SURFACE -	CODE		(62) CULVERTS	N	
(B) TYPE OF MEMBRANE -	CODE				
(C) TYPE OF DECK PROTECTION -	CODE		LOAD RATING AND POSTING	CODE	
			(31) DESIGN LOAD HS 20 + MOD	6	
			(63) OPERATING RATING METHOD - Load Factor		
			(64) OPERATING RATING - HS-35	163	
			(65) INVENTORY RATING METHOD - Load Factor		
			(66) INVENTORY RATING - HS-21	138	
			(70) BRIDGE POSTING - No Posting Required	5	
			(41) STRUCTURE OPEN, POSTED ,OR CLOSED	A	
			DESCRIPTION - Open, No Restriction		
AGE AND SERVICE				APPRAISAL	
(27) YEAR BUILT	1960		(67) STRUCTURAL EVALUATION	5	
(106)YEAR RECONSTRUCTED	1985		(68) DECK GEOMETRY	3	
(42) TYPE OF SERVICE : ON - Overpass - Interchange			(69) UNDERCLEARANCES,VERTI & HORIZ	3	
UNDER - Highway	CODE	61	(71) WATERWAY ADEQUACY	N	
(28) LANES: ON STRUCTURE 2 UNDER STRUCTURE	5		(72) APPROACH ROADWAY ALIGNMENT	7	
(29) AVERAGE DAILY TRAFFIC	21250		(36) TRAFFIC SAFETY FEATURES	1111	
(30) YEAR OF ADT 2011 (109) TRUCK ADT PCT	16%		(113)SCOUR CRITICAL BRIDGES	N	
(19) BYPASS OR DETOUR LENGTH	0 MI				
GEOMETRIC DATA					
(48) LENGTH OF MAXIMUM SPAN	69 FT				
(49) STRUCTURE LENGTH	240 FT				
(50)CURB OR SIDEWALK: LEFT 0 FT RIGHT	0 FT				
(51) BRIDGE ROADWAY WIDTH CURB TO CURB	28 FT				
(52) DECK WIDTH OUT TO OUT	31.5 FT				
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)	28 FT				
(33) BRIDGE MEDIAN - No Median	CODE	1			
(34) SKEW 44° (35) STRUCTURE FLARED	0				
(10) INVENTORY ROUTE MIN VERT CLEAR	999.9 FT				
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR	28 FT				
(53) MIN VERT CLEAR OVER BRIDGE RDWY	999.9 FT				
(54) MIN VERT UNDERCLEAR REF Highway	13.833 FT				
(55) MIN LAT UNDERCLEAR RT REF Highway	16 FT				
(56) MIN LAT UNDERCLEAR LT REF -	5 FT				
NAVIGATION DATA				PROPOSED IMPROVEMENTS	
(38) NAVIGATION CONTROL - Not Applicable	CODE	N	(75) TYPE OF WORK -	CODE	
(111)PIER PROTECTION -	CODE		(76) LENGTH OF STRUCTURE IMPROVEMENT		
(39) NAVIGATION VERTICAL CLEARANCE	0		(94) BRIDGE IMPROVEMENT COST		
(116)VERT - LIFT BRIDGE NAV MIN VERT CLEAR	FT		(95) ROADWAY IMPROVEMENT COST		
(40) NAVIGATION HORIZONTAL CLEARANCE	0 FT		(96) TOTAL PROJECT COST		
			(97) YEAR OF IMPROVEMENT COST ESTIMATE		
			(114)FUTURE ADT 46000 (115) YEAR FUTURE ADT	2025	
				INSPECTIONS	
				(90) INSPECTION DATE	04/10/2012
				(92) CRITICAL FEATURE INSPECTION :	(93) CFI DATE
				A) FRACTURE CRIT DETAIL - NO	A)
				B) UNDERWATER INSP - NO	B)
				C) OTHER SPECIAL INSP NO	C)
				SCOUR	

Structure No: 480104

County: IREDELL

Run Date:

Span Number	Feature Intersected	Inventory Route	Minimum Maximum Vertical Clearance	Milepoint	Base Highway Network	LRS Inventory Route	Toll	Functional Classification	Nuner of Lanes	Average Daily Traffic	Year of Average Daily Traffic	Total Horizontal Clearance	See Note 1					STRAHNET Highway Designator	Direction of Traffic	Highway System of Route
													Reference Feature	Minimum Vertical Underclearance	Right Lateral Underclearance	Left Lateral Underclearance	Underclearance Appraisal Grade			
2	US 64 EBL	5 21000640	10 14. 5830	11 1481	12 1	13 2	20	26 14	28 2	29 8750	30 2011	47 29H	54A H	54 14.50	55 5	56 6	69 9	100 1	102 1	104 1
3	US 64 WBL	21000640	13. 9170	1481				14	3	8750	2011	45H		13. 8330	16	5 9	1 1	1 1	1 1	

Note 1: Items 54, 55, and 56 are not reported FHWA under route data points but are collected for each under route to determine the minimum value for Underclearance Appraisal Item 69. The under route that generates the lowest Underclearance Appraisal value will be reported on the Facility Carried record.

## BRIDGE MANAGEMENT UNIT

## DATA ON EXISTING STRUCTURE

Run Date: 08/29/2012

COUNTY : IREDELL DIVISION : 12 DISTRICT : 2 STRUCTURE NUMBER : 480104 LENGTH : 240 FEET

ROUTE CARRIED : I40 EBL FEATURE INTERSECTED : US64,NC90

LOCATED : 0.1 MI. S. JCT. SR1006 BRIDGE NAME : CITY : STATESVILLE

FUNC. CLASS : 11 SYST.ON : FA SYST.UNDER : NFA ADT & YR : 21250 2011 RAIL TYPE : LT 333 RT 333

BUILT : 1960 BY : SHC PROJ : 8.16377 FED.AID PROJ : I-809 DESIGN LOAD : HS 20 + MOD

REHAB : 1985 BY : DOH PROJ : ALIGNMENT : TAN SKEW : 46 LANES : ON 2 UNDER 5

NAVIGATION : VC 0 FT HC 0 FT HT. CRN. TO BED : 0 FT WATER DEPTH : 0 FT

SUPERSTRUCTURE : REINFORCED CONCRETE DECK ON I-BEAMS, APPROACH SLABS

SUBSTRUCTURE : EBTS:RC CAPS ON PPC PILES, INTBTS:RC POST&BEAM ON PILE FTGS

SPANS : 1@56'0 , 1@70'0 , 1@64'0 , 1@50'0 , COMPOSITE

BEAMS OR GIRDERS : 4 LINES OF I-BEAMS @ 8'0 CTS,SP#1:36 EXT,33 INT,SP#2-4:36

FLOOR : 7 1/4 RC SLAB ENCROACHMENT : DECK (OUT TO OUT) : 31.5 FT

CLEAR ROADWAY : 28 FT BETWEEN RAILS : 28 FT SIDEWALK OR CURB : LT 0 FT RT 0 FT

VERT.CL.OVER : 999.9 FT

INV.RTG. : HS-21 OPE.RTG. : HS-35 CONTR.MEMBER : Intbm(D) POSTED : SV TTST DATE

SYSTEM : Primary Interstate GREEN LINE ROUTE : Y

## UNDER ROUTES AND CLEARANCES

Span	Route Description	Vertical Clearances		Horizontal Clearances		
		MMVC	MVC	Total	Left	Right
2	US 64 EBL	14.5830	14.50	29	6	5
3	US 64 WBL	13.9170	13.8330	45	5	16

Note: All measurements are in feet.

REMARKS :

# BRIDGE INSPECTION RECORD AND SUMMARY

INSPECTION TYPE Damage Inspection Report

BRIDGE NO. 480104

COUNTY IREDELL

ROUTE I40 EBL

OVER US64,NC90

STRUCTURE TYPE REINFORCED CONCRETE DECK ON I-BEAMS, APPROACH SLABS

ROUTE ORIENTATION

SPANS 1@56'0", 1@70'0", 1@64'0", 1@50'0", COMPOSITE

EVALUATION CODES: CRITICAL (C, 0 - 3); POOR (P, 4); FAIR (F, 5, 6); GOOD (G, 7 - 9)

INSPECTION ITEM			ITEM 61		
DECK ITEMS		GRADES			
1. WEARING SURFACE			45. CHANNEL & CHANNEL PROT.	a. WATERWAY	
				b. ALIGNMENT	
				c. SCOUR	
				d. SLOPE PROT., RIP-RAP, DIKES, ETC.	
2. DECK NO. OF EA TYPE SPN GRADE RATES SI & A ITEM 58	a. CONCRETE		50. APPROACH ROADWAY CONDITION		
	b. TIMBER		51. APPROACH SLABS		
	c. STEEL PLANK		52. PAINT SYSTEM CODE		
	d. OPEN GRID		53. UTILITIES		
3. RAILING	a. CONCRETE		54. RESPONSE TO LIVE LOAD		
	b. TIMBER		55. ESTIMATED REMAINING LIFE		
	c. ALUMINUM		30		
	d. STEEL				
4. CURBS, WHEELGUARDS, PARAPETS, MEDIANS					
5. WALKWAYS (ON OR ATTACHED TO STRUCTURE)			60. REGULATORY SIGN NOTICE ISSUED		
			NO		
6. DECK EXP JTS. OR DEVICES. NO. OF EACH	a. STEEL PL OR FINGER		61. PROMPT-ACTION NOTICE ISSUED		
	b. MISC PREFAB		YES		
	c. COMPRESSION SEAL		62. PRESENTLY POSTED		
	d. STANDARD JOINTS		NO		
	e. OPEN JOINTS		63. TOT. FIELD INSP TIME (INCLUDE WRITE UP)(MAN HR)		
7. DECK DEBRIS (INCLUDES EXCESS SAND/GRAVEL)			17		
			64. TOTAL SNOOPER INSP. TIME (HRS)		
			0		
			65. TOTAL TRAFFIC CONTROL TIME (MAN HRS)		
			7		
70. SI&A GENERAL CONDITION RATINGS					
SUPER STR. (FM. 1 (90)B TRUSS) ITEM 59			a. DECK ITEM 58		
10. LONGITUDINAL BEAMS OR GIRDERS			P		
11. LONGITUDINAL JOIST OR STRINGERS			b. SUPERSTRUCTURE ITEM 59		
12. INT. DIAP'S, X-FRAMES, BRACING & CONN'S			c. SUBSTRUCTURE ITEM 60		
13. END DIAP'S, CURTAIN WALLS, & CONN'S			P		
14. FLOOR BEAMS AND CONNECTIONS			d. CHANNEL & CHANNEL PROT. ITEM 61		
15. BEARING ASSEMBLIES (INCLUDING MISALIGN)			F		
16. DRAINAGE SYSTEM (ON STRUCTURE)			71. SI&A FIELD APPRAISAL RATINGS		
17. MOVABLE SPAN MACHINERY			a. WATERWAY ADAQUACY		
			b. APPR. RDWY. ALIGNMENT		
			72. FIELD SCOUR EVALUATION		
SUB STR. ITEMS. ITEM 60 (INCLUDE SCOUR)					
35. TIM SUB STR.	a. ABUT. & INT. BENT CAPS & RISERS		USE OF INSP. ACCESSIBILITY EQUIPMENT		
	b. PILES, POST, SILLS, & BRACING		SNOOPER (CODE S, 4, OR N)		
	c. BULKHEADS, WING'S, & TIE BACKS		HRS		
36. CONC SUB STR.	a. ABUT. & INT. BENT CAPS		NO		
	b. ABUT. & BENT COL'S BREASTWALLS		LADDER		
	c. ABUT. & INT. BENT PILES		NO		
	d. BACKWALLS, WING'S, RETAIN. WALLS		BUCKET TRUCK		
	e. ABUT. & BENT FOOTINGS & SILLS		BOAT		
37. STEEL SUB STR.	a. ABUT. & INT. BENT CAPS & RISERS		OTHER		
	b. PILES, BRACING, AND BULKHEADS		YES		
38. FOUNDATION PILES TYPE MATERIAL			SPECIAL INSPECTION REQUESTED FOR		
39. SLOPE PROT., RIP-RAP (INCLUDE DRAINAGE)					
40. FENDER SYSTEMS			NOTE		
41. DRIFT			80. INSPECTED BY:		
			81. REVIEWED BY:		

Bridge I&A Form 1(82)H State of North Carolina Dept. of Transportation Division of Highways		<h1 style="text-align: center;">FIELD INSPECTION REPORT</h1> <p style="text-align: center;"><u>Bridge Inspection &amp; Analysis</u></p>	
Team Leader MD OSBORNE			
Assisted By A KING			
Item No.	Grade		
10	P	<p>IMPACT DAMAGE INSPECTION WAS REQUESTED BY TOPSIDE BRIDGE INSPECTION FOR SPAN 3 OVER US 64</p> <p>BEAM 4:(NBL) POINT OF IMPACT ON BEAM 4 IN NBL WAS 33'-10" FROM FACE OF BENT 3, GOUGE IN FLANGE 1 1/2" X 1" X 1/2" AN INDENTION IN FLANGE 12" X 1/4" AND INDENTION IN COVER 12" X 1/2" ALL AT THE POINT OF IMPACT. INDENTIONS IN FLANGE FROM 33'-10" TO 24'-4". INDENTION IN COVER PLATE 8" X 1/16" AT 36'-3", 2" X 1/4" AT 36'-0", A 16" X 1/2" AT 32'-0", A 5'-0" X 1/2" AT 27'-2", A 48" X 3/4" AT 23'-0", A 1" X 1/4" AT 21'-8", A 3" X 1/16" AT 20'-10", A 2 1/2" X 1/16" AT 18'-7", A 1" X 1/16" AT 14'-7", A 3" X 1/16" AT 12'-9" 1 1/2" X 1/16" AT 34'-6", A 3" X 1/16" AT 35'-2", A 2 1/2" X 1/16" AT 35'-6", A 4" X 1/16" AT 35'-11", A3" X 1/16" AT 38'-5", ALL FROM FACE OF BENT 3. INDENTIONS IN FLANGE 13" X 1/4" AT 21'-2", A 5" X 1/2" AT 27'-2", A 2" X 1/4" AT 24'-9", A 1" X 1/4" AT 21'-11", A 1 1/2" X 1/16" AT 12'-9", A 2" X 1/16" AT 36'-2", A 1 1/2" X 1/16" AT 38'-3" ALL FROM FACE OF BENT 3. BEAM 4 IS 1 7/8" OUT OF PLUMB TO THE NORTH AT 30'-0" FROM BENT 3. THE WEB HAS A 17" X 11" AREA THAT IS BENT IN 1 1/2" AT 30'-4" AND A 9" X 16" AREA THAT IS BENT IN 1 1/4" AT 28'-6" BOTH FROM BENT 3. COVER PLATE AND FLANGE IS DAMAGED ON THE OUTSIDE FROM 22'-6" TO 34'-0" FROM FACE OF BENT 3. INDENTIONS IN COVER PLATE 2" X 1/16" AT 24'-2", A4" X 1/16" AT 20'-0", A 4" X 1/16" AT 19'-0", A 1" X 1/16" AT 18'-1", A 16" X 1/4" &amp; 2" X 3/4" AT 16'-2" ALL FROM FACE OF BENT 2. INDENTIONS IN FLANGE 25" X 1/4" AT 8'-0", A 35" X 1/16" AT 13'-10",A 14" X 1/16 AT 16'-2",A 1" X 1/16" AT 20'-0" ALL FROM FACE OF BENT 2</p> <p>(SBL) POINT OF IMPACT ON BEAM 4 IN SBL WAS 19'-1" FROM FACE OF BENT 2, INDENTION IN FLANGE 31" X 1/4" AND IN COVER PLATE 37" X 1/4" AT POINT OF IMPACT. BEAM 4 HAS IMPACT DAMAGE FROM 15'-6" TO 29'-8" FROM FACE OF BENT 2. BEAM 4 IS OUT OF PLUMB 1/2" AT 19'-1" IN THE DIRECTION OF TRAFFIC FROM BENT 2.INDENTIONS IN COVER PLATE 4" X 1/16" AT 29'-6", A 1 1/2" X 1/16" AT 28'-1", A 33" X 1/32" AT 25'-11", A 7" X 1/16" AT 25'-1", A 1 1/2" X 1/4" AT 22'-9", A 1 1/2" X 1/4" AT 21'-4", A 14" X 1/4" AT 21'-0", A 2" X 1/16"AT 16'-6", A 6" X 1/16" AT 16'-0", A 2 1/2" X 1/16" AT 10'-2"ALL FROM FACE OF BENT 2. INDENTIONS IN FLANGE 12" X 1/16" AT 29'-8", A2 1/2" X 1/32" AT 26'-10", A 6" X 1/16" AT 25'-2", A2" X 1/16" AT 22'-4", A 8" X 1/4" AT 21'-0", A 7" X 1/4" AT 17'-8", A 3" X 1/16" AT 8'-11" ALL FROM FACE OF BENT 2. INDENTIONS IN FLANGE COVER PLATE 14" X 1/4" AT 27'-6", A 14" X 1/16" AT 23'-3", A 1" X 1/4" AT 23'-0", A 2" X 1/4" AT 21'-11", A 3" X 1/4" AT 21'-6", A 6" X 1/4" AT 20'-2", A 14" X 1/32" AT 19'-3", A 9" X 1/4" AT 18'-5", A 1" X 1/16" AT 17'-4", A 2 1/2" X 1/16" AT 17'-0" ALL FROM FACE OF BENT 1. INDENTIONS IN FLANGE 5" X 1/32" AT 23'-0", A 2" X 1/16" AT 21'-9", A 6" X 1/4" AT 19'-7", A 2" X 1/2" AT 19'-4" ALL FROM FACE OF BENT 1.(SEE PHOTOS)</p> <p>Note: More details for this item are on attached sheets</p>	
12	P	<p>CONNECTION PLATE OF INTERMEDIATE DIAPHRAGMS DIAPHRAGM ON BEAM 4 HAS IMPACT DAMAGE AT 20'-4" FROM FACE OF BENT 3, A 11" CRACK IN THE BOTTOM, A 2 1/2" CRACK IN THE BOTTOM WELD TO BRACKET, A 4" CRACK IN THE TOP AND 3 1/2" CRACK ON THE BOTTOM AT 20'-4", DIAPHRAGM IS BENT 4 1/2" TO THE EAST. DIAPHRAGM AT 37'-4" FROM BENT 3 HAS A 6" CRACK IN THE BOTTOM, AND 3" CRACK IN THE TOP. AND 2" CRACK IN THE BOTTOM. DIAPHRAGM AT 37'-4" IS BENT 3/4" OUT OF PLUMB TO THE EAST. A CRACK IS IN THE BOTTOM WELD AND RUNS TO THE TOP PART. THERE IS A 3/4" BEND IN THE DIAPHRAGM 4'-0" FROM BEAM 4 (SEE PHOTOS)</p>	

Bridge I&A Form 1(82)H State of North Carolina Dept. of Transportation Division of Highways		<b>FIELD INSPECTION REPORT</b> <u>Bridge Inspeccion &amp; Analysis</u>	
Team Leader MD OSBORNE			
Assisted By A KING			
Item No.	Grade		
15	F	BEARINGS AND ANCHOR BOLTS IN SPAN 3 DID NOT SHOW ANY INDICATION OF DAMAGE DUE TO THE IMPACT.	
61	YES	DIAPHRAGMS ON BEAM 4 BEAM 4	
73f	YES	CLIMBING VEST UT MACHINE	

State of North Carolina Dept. of Transportation Division of Highways		FIELD INSPECTION REPORT		
Item No.		Extended Field Inspection Notes		
10		<p>           BEAM 3: (NBL) POINT OF IMPACT ON BEAM 3 WAS 33'-3" FROM FACE OF BENT 3, AN INDENTION IN FLANGE COVER PLATE 13" X 1/4" AT POINT OF IMPACT. INDENTION IN FLANGE COVER PLATE 4" X 1/4" &amp; 1/2" X 1/4" AT 35'-1", A 1" X 1/16" AT 29'-0", A 1" X 1/16" AT 29'-9", A 1" X 1/16" AT 22'-4" A 6" X 1/4" AT 23'-2" ALL FROM FACE OF BENT 3. INDENTION IN FLANGE 1 1/2" X 1/4" AT 36'-7" FROM FACE OF BENT 3. INDENTION IN FLANGE COVER PLATE 8" X 1/4" AT 15'-5", 12" X 1/16" AT 13'-0", A 5" X 1/16" AT 14'-5" ALL FROM FACE OF BENT 2. INDENTIONS IN FLANGE 8" X 1/4" AT 15'-5", A 6" X 1/16" AT 12'-4", A 4" X 1/16", A 4" X 1/16" AT 10'-0", 16" X 1/16" AT 8'-4", 6" X 1/16" AT 6'-11" ALL FROM FACE OF BENT 2. SCATTERED MARKS ON WEB OF BEAM. (SBL) POINT OF IMPACT ON BEAM 3 WAS 20'-2" FROM FACE OF BENT 2, AN INDENTION IN FLANGE COVER PLATE 7" X 1/4" INDENTION IN FLANGE 2 1/2" X 1/4" AND 1 1/2" X 1/4" ALL AT POINT OF IMPACT. INDENTIONS IN COVER PLATE 3" X 1/2" AT 21'-7", A 1" X 1/16" AT 22'-1", A 1 1/2" X 1/16" AT 21'-11", A 14" X 1/4" AT 34'-4" ALL FROM BENT 2. INDENTION IN FLANGE 8" X 1/16" AT 23'-6" FROM BENT 2. GOUGE IN COVER PLATE 8" X 1" X 1/32" AT 20'-4" FROM BENT 2. INDENTIONS IN FLANGE COVER PLATE 6" X 1/32" AT 21'-11", A 1 1/2" X 1/4" AT 21'-5", A 20" X 1/4" AT 16'-9" ALL FROM FACE OF BENT 1. (SEE PHOTOS)         </p> <p>           BEAM 2:(NBL) POINT OF IMPACT ON BEAM 2 WAS 34'-2" FROM FACE OF BENT 3, AN INDENTION IN FLANGE COVER PLATE 3" X 1/4" AND 4" X 1/2", INDENTIONS IN FLANGE 2 1/2" X 1/4" AND 1" X 1/16" ALL AT POINT OF IMPACT. INDENTIONS IN FLANGE 1" X 1/16" AT 28'-5" FROM FACE OF BENT 3. (SBL) POINT OF IMPACT ON BEAM 2 IN SBL WAS 21'-6" FROM FACE OF BENT 3, AN INDENTION IN FLANGE COVER PLATE 5 1/2" X 1/2" AND IN FLANGE 1 1/4" X 1/16" FROM FACE OF BENT 2. INDENTIONS IN COVER PLATE 2" X 1/4" AT 22'-6" FROM BENT 2. INDENTIONS IN COVER PLATE 1" X 1/16" AT 16'-3", A 2" X 1/4" AT 25'-7" FROM FACE OF BENT 1 (SEE PHOTOS)         </p>		



# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 480104

County IREDELL

Date: 07/25/2012

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
3314	Maintain Steel Superstructure Components	LF	1	BOTTOM OF DIAPHRAGM @ BEAM 4 HAS A 3 1/2" CRACK. BEAM 4,	
3314	Maintain Steel Superstructure Components	LF	1	BOTTOM WELD OF DIAPHRAGM HAS A 3" CRACK. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	1	CRACK 2 1/2" LONG IN BOTTOM WELD AT DIAPHRAGM TO BRACKET @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4,	
3314	Maintain Steel Superstructure Components	LF	1	CRACK ( 2" ) IN BOTTOM OF DIAPHRAGM. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	1	CRACK ( 3" ) IN TOP OF DIAPHRAGM. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	1	CRACK ( 6 1/2" ) IN BOTTOM OF DIAPHRAGM BRACKET. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	1	CRACK ( 6" ) IN BOTTOM OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	1	CRACK 11" LONG AT THE BOTTOM OF DIAPHRAGM BRACKET @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4,	
3314	Maintain Steel Superstructure Components	LF	1	CRACK IN BOTTOM WELD OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	1	DIAPHRAGM IS BENT 4 1/2" TO THE EAST @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4,	
3314	Maintain Steel Superstructure Components	LF	1	TOP OF DIAPHRAGM @ BEAM 4 HAS A 4" CRACK. BEAM 4,	

Key



Priority Maintenance Item



Critical Finding Item



Priority Maintenance Level Not Determined



# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 480104

County IREDELL

Date: 07/25/2012

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	8	CRACK IN DIAPHRAGM CRACK 11" LONG AT THE BOTTOM OF DIAPHRAGM BRACKET @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4, CRACK 2 1/2" LONG IN BOTTOM WELD AT DIAPHRAGM TO BRACKET @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4, DIAPHRAGM IS BENT 4 1/2" TO THE EAST @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4, TOP OF DIAPHRAGM @ BEAM 4 HAS A 4" CRACK. BEAM 4, BOTTOM OF DIAPHRAGM @ BEAM 4 HAS A 3 1/2" CRACK. BEAM 4, BOTTOM WELD OF DIAPHRAGM HAS A 3" CRACK. BEAM 4, SPAN 3 CRACK ( 6" ) IN BOTTOM OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3 CRACK ( 3" ) IN TOP OF DIAPHRAGM. BEAM 4, SPAN 3 CRACK ( 2" ) IN BOTTOM OF DIAPHRAGM. BEAM 4, SPAN 3 CRACK ( 6 1/2" ) IN BOTTOM OF DIAPHRAGM BRACKET. BEAM 4, SPAN 3 DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3, IS OUT OF PLUMB ( 3/4" ) TO THE EAST. BEAM 4, SPAN 3 CRACK IN BOTTOM WELD OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3 DIAPHRAGM IS BENT ( 3/4" ) UPWARD AT 4'-0" FROM BEAM 4 @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3 DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3, IS OUT OF PLUMB ( 3/4" ) TO THE EAST. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	8		
 3314	Maintain Steel Superstructure Components	LF	63	DAMAGE TO BEAM 4 BEAM 4 IS OUT OF PLUMB ( 1 7/8" ) TO THE NORTH @ 30'-0" FROM THE FACE OF BENT 3. BEAM 4, WEB OF BEAM 4 IS BENT ( 1 1/2" ) INWARD @ 30'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3 WEB OF BEAM 4 IS BENT ( 1 1/4" ) INWARD @ 28'-6" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	63	POINT OF IMPACT ON BEAM 2 IS 34'-2" FROM THE FACE OF BENT 3. BEAM 2, SPAN 3	

## Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined

## BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 480104

County IREDELL

Date: 07/25/2012

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
3314	Maintain Steel Superstructure Components	LF	63	POINT OF IMPACT ON BEAM 3 IS 33'-3" FROM THE FACE OF BENT 3. BEAM 3, SPAN 3	
3314	Maintain Steel Superstructure Components	LF	63	POINT OF IMPACT ON BEAM 4 IS 33'-10" FROM THE FACE OF BENT 3. GOUGE IN FLANGE ( 1 1/2" W X 1" L X 1/2" D ). INDENTION IN FLANGE ( 12" X 1/4" ).	

### Key



Priority Maintenance Item



Critical Finding Item



Priority Maintenance Level Not Determined

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 480104                      County IREDELL

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	8              LF
Location:		
Beams and Girders                      Bent/Span No.    3                      DIAPHRAGM		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification Received	
Submitted Date:	Submitted By:	Assisted By:
07/25/2012	MD OSBORNE	A KING
Details		
<p>CRACK IN DIAPHRAGM CRACK 11" LONG AT THE BOTTOM OF DIAPHRAGM BRACKET @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4, CRACK 2 1/2" LONG IN BOTTOM WELD AT DIAPHRAGM TO BRACKET @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4, DIAPHRAGM IS BENT 4 1/2" TO THE EAST @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4, TOP OF DIAPHRAGM @ BEAM 4 HAS A 4" CRACK. BEAM 4, BOTTOM OF DIAPHRAGM @ BEAM 4 HAS A 3 1/2" CRACK. BEAM 4, BOTTOM WELD OF DIAPHRAGM HAS A 3" CRACK. BEAM 4, SPAN 3 CRACK ( 6" ) IN BOTTOM OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3 CRACK ( 3" ) IN TOP OF DIAPHRAGM. BEAM 4, SPAN 3 CRACK ( 2" ) IN BOTTOM OF DIAPHRAGM. BEAM 4, SPAN 3 CRACK ( 6 1/2" ) IN BOTTOM OF DIAPHRAGM BRACKET. BEAM 4, SPAN 3 DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3, IS OUT OF PLUMB ( 3/4" ) TO THE EAST. BEAM 4, SPAN 3 CRACK IN BOTTOM WELD OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3 DIAPHRAGM IS BENT ( 3/4" ) UPWARD AT 4'-0" FROM BEAM 4 @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 480104

County IREDELL

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	63 LF
Location:		
Beams and Girders	Bent/Span No. 3	BEAM
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification Received	
Submitted Date:	Submitted By:	Assisted By:
07/25/2012	MD OSBORNE	A KING
Details		
DAMAGE TO BEAM 4 BEAM 4 IS OUT OF PLUMB ( 1 7/8" ) TO THE NORTH @ 30'-0" FROM THE FACE OF BENT 3. BEAM 4, WEB OF BEAM 4 IS BENT ( 1 1/2" ) INWARD @ 30'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3 WEB OF BEAM 4 IS BENT ( 1 1/4" ) INWARD @ 28'-6" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3		



POINT OF IMPACT ON BEAM 4 IS 33'-10" FROM THE FACE OF BENT 3.



AN INDENTION IN FLANGE FROM 33'-10" TO 24'-4" FROM THE FACE OF BENT 3. BEAM 4,





INDENTION ( 16" X 1/2" ) IN COVER PLATE @ 32'-0" FROM THE FACE OF BENT 3. BEAM 4,



INDENTION ( 48" X 3/4" ) IN COVER PLATE @ 23'-0" FROM THE FACE OF BENT 3. BEAM 4,



BEAM 4 IS OUT OF PLUMB (  $1 \frac{7}{8}$ " ) TO THE NORTH @ 30'-0" FROM THE FACE OF BENT 3. BEAM 4,



WEB OF BEAM 4 IS BENT (  $1 \frac{1}{2}$ " ) INWARD @ 30'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3





WEB OF BEAM 4 IS BENT ( 1 1/4" ) INWARD @ 28'-6" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3



LOOKING AT BEAM 4 FROM BENT 3. BEAM 4 FLANGE AND COVER IS DAMAGED



MARKS ON BOTTOM OF COVER PLATE ON BEAM 4 FROM 22'-6" TO 34'-0"



CRACK 11" LONG AT THE BOTTOM OF DIAPHRAGM BRACKET @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4,





CRACK 2 1/2" LONG IN BOTTOM WELD AT DIAPHRAGM TO BRACKET @ 20'-4" FROM THE FACE OF BENT 3.  
BEAM 4,



DIAPHRAGM IS BENT 4 1/2" TO THE EAST @ 20'-4" FROM THE FACE OF BENT 3. BEAM 4,



TOP OF DIAPHRAGM @ BEAM 4 HAS A 4" CRACK. BEAM 4,



BOTTOM OF DIAPHRAGM @ BEAM 4 HAS A 3 1/2" CRACK. BEAM 4,





BOTTOM WELD OF DIAPHRAGM HAS A 3" CRACK. BEAM 4, SPAN 3



CRACK ( 6" ) IN BOTTOM OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3





CRACK ( 3" ) IN TOP OF DIAPHRAGM. BEAM 4, SPAN 3



CRACK ( 2" ) IN BOTTOM OF DIAPHRAGM. BEAM 4, SPAN 3



CRACK ( 6 1/2" ) IN BOTTOM OF DIAPHRAGM BRACKET. BEAM 4, SPAN 3



DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3, IS OUT OF PLUMB ( 3/4" ) TO THE EAST. BEAM 4, SPAN 3





CRACK IN BOTTOM WELD OF DIAPHRAGM @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3



DIAPHRAGM IS BENT (  $\frac{3}{4}$ " ) UPWARD AT 4'-0" FROM BEAM 4 @ 37'-4" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3



INDENTIONS IN COVER PLATE ON NORTH SIDE OF BEAM 4 @ 36'-3" FROM THE FACE OF BENT 3. BEAM 4, SPAN 3



POINT OF IMPACT ON BEAM 3 IS 33'-3" FROM THE FACE OF BENT 3. BEAM 3, SPAN 3





INDENTATION ( 1/2" X 1/4" ) IN COVER PLATE @ 35'-1" FROM THE FACE OF BENT 3. BEAM 3, SPAN 3



INDENTATION ( 6" X 1/4" ) IN COVER PLATE @ 23'-2" FROM THE FACE OF BENT 3. BEAM 3, SPAN 3



POINT OF IMPACT ON BEAM 2 IS 34'-2" FROM THE FACE OF BENT 3. BEAM 2, SPAN 3



INDENTATION ( 13" X 1/4" ) IN FLANGE ON BEAM 4 @ 21'-2" FROM THE FACE OF BENT 2. BEAM 4, SPAN 3





MARKS ON WEB HAVE BEEN PAINTED OVER. BEAM 4, SPAN 3



INDENTIONS IN FLANGE AND COVER PLATE @ 16'-2" FROM THE FACE OF BENT 2. BEAM 4, SPAN 3



INDENTION ( 8" X 1/4" ) IN COVER PLATE @ 15'-5" FROM THE FACE OF BENT 2. BEAM 3, SPAN 3



INDENTION IN FLANGE ( 8" X 1/4" ) AND COVER PLATE ( 5" X 1/16" ) @ 14'-5" FROM THE FACE OF BENT 2.  
BEAM 3, SPAN 3





MARKS ON WEB @ 14'-0" FROM THE FACE OF BENT 2. BEAM 3, SPAN 3



POINT OF IMPACT ON BEAM 2 @ 21'-6" FROM THE FACE OF BENT 2. BEAM 2, SPAN 2



POINT OF IMPACT ON BEAM 3 @ 20'-2" FROM THE FACE OF BENT 2. BEAM 3, SPAN 2




POINT OF IMPACT ON BEAM 4 @ 19'-1" FROM THE FACE OF BENT 2. BEAM 4, SPAN 2





TOP AND BOTTOM OF DIAPHRAGM BRACKET IS BENT UP TO 2" TO THE EAST. OUT OF PLUMB @ 18'-2"  
FROM THE FACE OF BENT 2. BEAM 4, SPAN 2



LOOKING AT DIAPHRAGM AND BEAM 4, SPAN 2



MARKS AND SCRAPES ON COVER PLATE TO BEAM 4, SPAN 2



# Bridge Inspection Field Sketch

VERIFIED 4/10/12 R.A. PIERCE, M. FORD



I - 40 E.B.L.

LOOKING EAST

Roadway	24ft Wide	2 Paved Lanes	Looking East
Left Shoulder	2ft Wide	2ft Paved	
Right Shoulder	2ft Wide	2ft Paved	
Left Guardrail	2ft from road		
Right Guardrail	2ft from road		

## Title

APPR. RDWY.

## Description

APPR. RDWY.

Bridge No: 480104

Drawn By: RAP


Date: 08/29/2006

File Name: S0318000294

# Bridge Inspection Field Sketch


VERIFIED 4/10/12 R.A. PIERCE, M. FORD

Deck Width/Out to Out	31.5ft	Between Rails	28ft
Clear Roadway	28ft	Wearing Surface	
Median Width		Median Height	
Curb Height		Left .75ft	Right .75ft
Sidewalk Width		Left	Right
Clear Roadway (Rail to Median)		Left	Right
Guardrail Width		Left 2.667ft	Right 2.667ft
Top of Rail to Deck/Wearing Surface		Left 2.583ft	Right 2.583ft
Bridge Rail		Left Type 33	Right Type 33




Measurements for Span #	4		
Deck Thickness	.625	Left Overhang	3.75
Top of Rail to Bottom of Beam	6.208	Right Overhang	3.75

Beam Number	Beam Type	Spacing	Comments
1	Steel I Beam	8.0ft	
2	Steel I Beam	8.0ft	
3	Steel I Beam	8.0ft	
4	Steel I Beam	ft	



FLANGE THICKNESS: 7/8"  
WEB THICKNESS: 1/2"

BM. # 1 & 4



FLANGE THICKNESS: 3/4"  
WEB THICKNESS: 1/2"

BM. # 2 & 3

Title

SUPER.

Description

DECK SECTION

Bridge No: 480104

Drawn By: RAP

Date: 08/29/2006

File Name: S0318000295

## Bridge Inspection Field Sketch

VOID

**Title**

VOID

**Description**

VOID

**Bridge No:** 480104

**Drawn By:** CJS

**Date:** 08/29/2006

**File Name:** S0318000298

# Bridge Inspection Field Sketch

VERIFIED 4/10/12 R.A. PIERCE, M. FORD

EAST →

I - 40 E.B.L.

SPAN # 3




M.M.V.C.

5 FT

24 FT

12 FT

4 FT



U.S. 64 / N.C. 90 W.B.L.

RAMP

LOOKING WEST

Roadway 1		Direction of Traffic	West
Distance to Left Rail		Distance to Right Rail	16FT
Distance to Left Toe of Slope		Distance to Left Bent	5FT
Distance to Right Toe of Slope	20FT	Distance to Right Bent	18FT
MMVC	13.917 Ft at Beam 4, 10 FT from LT. EDGE OF RDWY.		
MVC	13.833 Ft at Beam 4, 0 FT from RT. EDGE OF RAMP		

## Title

CLEARANCE 2

## Description

CLR. FOR SPAN # 3

Bridge No: 480104


Drawn By: RAP

Date: 09/03/2006

File Name: S0318000317

# Bridge Inspection Field Sketch

VERIFIED 4/10/12 R.A. PIERCE, M. FORD



LOOKING EAST

Roadway 1		Direction of Traffic	East
Distance to Left Rail		Distance to Right Rail	5FT
Distance to Left Toe of Slope		Distance to Left Bent	6FT
Distance to Right Toe of Slope	9FT	Distance to Right Bent	7FT
MMVC	14.583 Ft at Beam 4, 10 FT from RT. EDGE OF RDWY.		
MVC	14.5 Ft at Beam 4, 0 FT from LT. EDGE OF RDWY.		

## Title

CLEARANCE 1

## Description

CLR. FOR SPAN # 2.

Bridge No: 480104

Drawn By: RAP

Date: 09/03/2006

File Name: S0318000318

# Bridge Inspection Field Sketch

VERIFIED 4/10/12 R.A. PIERCE, M. FORD



Cap Information			Material Cast-in-Place Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
37.000 ft.	2.500 ft.	2.500 ft.	4.000 ft.	4.000 ft.	1.859 ft.	1.859 ft.				
Subcap Information			Material							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
Sill Information			Material							
Length	Width	Height								
Pile #	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar?
1	Concrete	14.5 ft.	2.5 ft.			Vertical	No	No	No	No
2	Concrete	14.5 ft.	2.5 ft.			Vertical	No	No	No	No
3	Concrete		2.5 ft.			Vertical	No	No	No	No
ABUTS.: R.C. CAP ON P.P.C. PILES										
Bent/Abutment #: 1 Similar Bents: 2,3										

Title

PIERS

Description

PIERS

Bridge No: 480104

Drawn By: RAP

Date: 9/11/2008

File Name: S0230000020





LOOKING NORTH



LOOKING SOUTH