



NC DEPARTMENT OF TRANSPORTATION  
 DIVISION OF HIGHWAYS  
 STRUCTURE MANAGEMENT UNIT

ATTENTION: **prompt action request; sketches updated; new beam repairs**

# Structure Safety Report

## Routine Element Inspection - Contract

STRUCTURE NUMBER: 110173      SAP STRUCTURE NO: 0120173      FHWA STRUCTURE NO: 00000000230173

DIVISION: 13      COUNTY: BURKE      INSPECTION DATE: 10/25/2023      FREQUENCY: 24 MONTHS

FACILITY CARRIED: SR1002      MILE POST: \_\_\_\_\_

LOCATION: .2 MI.N.JCT.SR1780

FEATURE INTERSECTED: I-40

LATITUDE: 35° 42' 19.14"      LONGITUDE: 81° 25' 24.74"

SUPERSTRUCTURE: REINFORCED CONCRETE FLOOR ON I-BEAMS (WIDENED)

SUBSTRUCTURE: E.BTS:RC CAPS/TIM.PILES&H-PILES;INT.BTS:RC POST&BEAM

SPANS: 4 SPANS. SEE SPAN PROFILE SHEET FOR SPAN DETAILS

FRACTURE CRITICAL     TEMPORARY SHORING     SCOUR CRITICAL     SCOUR PLAN OF ACTION

GRADES: (Inspector/NBI Coding)    DECK 5 / 5    SUPERSTRUCTURE 4 / 4    SUBSTRUCTURE 4 / 4    CULVERT N / N

POSTED SV: Not Posted      POSTED TTST: Not Posted

OTHER SIGNS PRESENT: none



Sign noticed issued for	Number Required
<u>NO</u> <b>WEIGHT LIMIT</b>	<u>0</u>
<u>NO</u> <b>DELINEATORS</b>	<u>0</u>
<u>NO</u> <b>NARROW BRIDGE</b>	<u>0</u>
<u>NO</u> <b>ONE LANE BRIDGE</b>	<u>0</u>
<u>NO</u> <b>LOW CLEARANCE</b>	<u>0</u>

**DIRECTION OF INSPECTION**      S-N

**DIRECTION MATCHES PLANS**      \_\_\_\_\_

south approach looking north

INSPECTED BY Juan Rodriguez	SIGNATURE 	ASSISTED BY    Hector Bonilla
--------------------------------	---------------	-------------------------------

NATIONAL BRIDGE INVENTROY ----- STRUCTURE INVENTORY AND APPRAISAL

01/12/2024

**IDENTIFICATION**

(1) STATE NAME NORTH CAROLINA BRIDGE 110173  
 (8) STRUCTURE NUMBER (FEDERAL) 0230173  
 (5) INVENTORY ROUTE (ON/UNDER) ON 131010020  
 (2) STATE HIGHWAY DEPARTMENT DISTRICT 13  
 (3) COUNTY CODE (FEDERAL) 23 (4) PLACE CODE 31500  
 (6) FEATURE INTERSECTED I-40  
 (7) FACILITY CARRIED SR1002  
 (9) LOCATION .2 MI.N.JCT.SR1780  
 (11) MILEPOINT 0.0  
 (12) BASE HIGHWAY NETWORK 0  
 (13) LRS INVENTORY ROUTE & SUBROUTE  
 (16) LATITUDE 35° 42' 19.14" (17) LONGITUDE 81° 25' 24.74"  
 (98) BORDER BRIDGE STATE CODE PERCENT SHARED  
 (99) BORDER BRIDGE STRUCTURE NUMBER

SUFFICIENCY RATING 61.86  
 STATUS = Structurally Deficient

**CLASSIFICATION** **CODE**

(112) NBIS BRIDGE SYSTEM YES  
 (104) HIGHWAY SYSTEM Inventory Route not on NHS 0  
 (26) FUNCTIONAL CLASS Urban Collector 17  
 (100) STRAHNET HIGHWAY Not a STRAHNET Route 0  
 (101) PARALLEL STRUCTURE No parallel structure exists N  
 (102) DIRECTION OF TRAFFIC 2-way traffic 2  
 (103) TEMPORARY STRUCTURE  
 (110) DESIGNATED NATIONAL NETWORK - on national network for trucks 0  
 (20) TOLL On Free Road 3  
 (21) MAINT - 01  
 (22) OWNER - 01  
 (37) HISTORICAL SIGNIFICANCE - 5

**STRUCTURE TYPE AND MATERIAL**

(43) STRUCTURE TYPE MAIN Steel  
 TYPE Stringer/Multi-beam or girder CODE 302  
 (44) STRUCTURE TYPE APPROACH  
 TYPE CODE  
 (45) NUMBER OF SPANS IN MAIN UNIT 4  
 (46) NUMBER OF SPANS IN APPROACH 0  
 (107) DECK STRUCTURE TYPE CODE 1  
 (108)WEARING SURFACE/PROTECTIVE SYSTEM  
 (A) TYPE OF WEARING SURFACE CODE 6  
 (B) TYPE OF MEMBRANE CODE 0  
 (C) TYPE OF DECK PROTECTION CODE 0

**CONDITION** **CODE**

(58) DECK 5  
 (59) SUPERSTRUCTURE 4  
 (60) SUBSTRUCTURE 4  
 (61) CHANNEL & CHANNEL PROTECTION N  
 (62) CULVERTS N

**LOAD RATING AND POSTING** **CODE**

(31) DESIGN LOAD HS 15 3  
 (63) OPERATING RATING METHOD - Load Factor 1  
 (64) OPERATING RATING - HS-27 49  
 (65) INVENTORY RATING METHOD - 1  
 (66) INVENTORY RATING HS-16 29  
 (70) BRIDGE POSTING No Posting Required 5  
 (41) STRUCTURE OPEN, POSTED, OR CLOSED DESCRIPTION Open, no restriction A

**AGE AND SERVICE**

(27) YEAR BUILT 1956  
 (106) YEAR RECONSTRUCTED 1975  
 (42) TYPE OF SERVICE ON - Overpass Structure  
 OFF - Highway CODE 61  
 (28) LANES ON STRUCTURE 4 LANES UNDER STRUCTURE 4  
 (29) AVERAGE DAILY TRAFFIC 4100  
 (30) YEAR OF ADT 2021 (109) TRUCK ADT PCT 7  
 (19) BYPASS OR DETOUR LENGTH 0.0

**APPRAISAL** **CODE**

(67) STRUCTURAL EVALUATION 4  
 (68) DECK GEOMETRY 9  
 (69) UNDERCLEARANCES, VERT & HORIZ 3  
 (71) WATERWAY ADEQUACY N  
 (72) APPROACH ROADWAY ALIGNMENT 8  
 (36) TRAFFIC SAFETY FEATURES 0110  
 (113) SCOUR CRITICAL BRIDGES N

**GEOMETRIC DATA**

(48) LENGTH OF MAXIMUM SPAN 57.0  
 (49) STRUCTURE LENGTH 207.0  
 (50) CURB OR SIDEWALK: LEFT 0.0 RIGHT 0.0  
 (51) BRIDGE ROADWAY WIDTH, CURB TO CURB 67.4  
 (52) DECK WIDTH OUT TO OUT 70.0  
 (32) APPROACH ROADWAY WITH (W/ SHOULDERS) 58.0  
 (33) BRIDGE MEDIAN No median CODE 0  
 (34) SKEW 27 (35) STRUCTURE FLARED 0  
 (10) INVENTORY ROUTE MIN VERT CLEAR 999.9  
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 67.4  
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 999.9  
 (54) MIN VERT UNDERCLEAR: REFERENCE H 14.8  
 (55) MIN LAT UNDERCLEARANCE RT: REFERENCE H 8.7  
 (56) MIN LAT UNDERCLEARANCE LT: 13.3

**PROPOSED IMPROVEMENTS**

(75) TYPE OF WORK CODE  
 (76) LENGTH OF STRUCTURE IMPROVEMENT  
 (94) BRIDGE IMPROVEMENT COST  
 (95) ROADWAY IMPROVEMENT COST  
 (96) TOTAL PROJECT COST  
 (97) YEAR OF IMPROVEMENT COST ESTIMATE  
 (114) FUTURE ADT 8,200 YEAR OF FUTURE ADT 2040

**NAVIGATION DATA**

(38) NAVIGATION CONTROL - CODE N  
 (111) PIER PROTECTION CODE  
 (39) NAVIGATION VERTICAL CLEARANCE 0.0  
 (116) VERT - LIFT BRIDGE NAV MIN VERT CLEAR 0.0  
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0

**INSPECTION**

(90) INSPECTION DATE 10/23 (91) FREQUENCY 24  
 (92) CRITICAL FEATURE INSPECTION (93) CFI DATE  
 A) FRACTURE CRIT DETAIL A)  
 B) UNDERWATER INSP B)  
 C) OTHER SPECIAL INSP C)  
 SCOUR

Span Number	Facility Carried	Inventory Route	Maximum Minimum Vertical Clearance	Milepoint	Base Highway	LRS Inventory Route	Functional Classification	Number of Lanes	Average Daily Traffic	Year of Average Daily Traffic	Total Horizontal Clearance	See Note Below					STRAHNET Highway	Direction of Traffic	National Highway System	National Truck Network
												Reference Feature	Minimum Vertical Underclearance	Righth Lateral Underclearance	Left Lateral Underclearance	Underclearance Appraisal Grade				
	7	5	10	11	12	13	26	28	29	30	47	54A	54	55	56	69	100	102	104	110
2	I 40 EB - LIDAR 05/30/13	1100040	16.4	119.0	1	10040	11	2	22500	2015	42.7	H	16.1	11.6	12.3	5		1	<input type="checkbox"/>	<input type="checkbox"/>
3	I 40 WB - LIDAR 05/30/13	1100040	15.0	119.0	1	10040	11	2	22500	2015	43.3	H	14.8	8.7	13.3	3		1	<input type="checkbox"/>	<input type="checkbox"/>
3	I 40 W	1100040	15.0	119.0	1	10040	11	2	25750	2019	43.3	H	14.8	8.7	13.3	3	1	1	<input type="checkbox"/>	<input type="checkbox"/>

Note: Items 54, 55, and 56 are not reported FHWA under route data points but are collected for each under route to determine the minimum value for Underclearance Appraisal Item 69.

## Superstructure Build Details

Span Number 1

Span Length 49.000

Skew 63.000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Asphalt Wearing Surface	Wearing Surface	3332 Square Feet		
22	Other Bearing	Other Bearings	22 Each	Unknown	22
11	Plate Girder	Steel Open Girder/Beam	539 Feet	Inorganic Zinc Pimer with Acrylic Top Coat	5115
2	Concrete and Metal Railing	Other Bridge Railing	98 Feet		
1	Reinforced Concrete Deck	Reinforced Concrete Deck	3430 Square Feet		

Span Number 2

Span Length 57.500

Skew 63.000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
22	Other Bearing	Other Bearings	22 Each	Unknown	22
1	Standard Joint	Pourable Joint Seal	77 Feet		
2	Concrete and Metal Railing	Other Bridge Railing	116 Feet		
1	Asphalt Wearing Surface	Wearing Surface	3910 Square Feet		
11	Plate Girder	Steel Open Girder/Beam	638 Feet	Inorganic Zinc Pimer with Acrylic Top Coat	6017
1	Reinforced Concrete Deck	Reinforced Concrete Deck	4025 Square Feet		

Span Number 3

Span Length 57.500

Skew 63.000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Asphalt Wearing Surface	Wearing Surface	3910 Square Feet		
22	Other Bearing	Other Bearings	22 Each	Unknown	22
2	Concrete and Metal Railing	Other Bridge Railing	116 Feet		
11	Plate Girder	Steel Open Girder/Beam	638 Feet	Inorganic Zinc Pimer with Acrylic Top Coat	6017
1	Reinforced Concrete Deck	Reinforced Concrete Deck	4025 Square Feet		
1	Standard Joint	Pourable Joint Seal	77 Feet		

Span Number 4

Span Length 42.500

Skew 63.000

## Superstructure Build Details

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
22	Other Bearing	Other Bearings	22 Each	Unknown	22
2	Concrete and Metal Railing	Other Bridge Railing	86 Feet		
1	Asphalt Wearing Surface	Wearing Surface	2890 Square Feet		
1	Reinforced Concrete Deck	Reinforced Concrete Deck	2975 Square Feet		
11	Plate Girder	Steel Open Girder/Beam	473 Feet	Inorganic Zinc Pimer with Acrylic Top Coat	4455
1	Standard Joint	Pourable Joint Seal	77 Feet		

# Structure Element Scoring

Structure Number: 110173

Inspection Date 10/25/202  
3

Element Number	Parent Number	Element Name	Location	Total Quantity	Level 1 Quantity	Level 2 Quantity	Level 3 Quantity	Level 4 Quantity
12		Reinforced Concrete Deck	Deck	14,455	9,233	16	5,206	0
107		Steel Open Girder/Beam	Beam	2,288	2,180	22	3	83
515	107	Steel Protective Coating	Beam	21,604	21,519	0	62	23
205		Reinforced Concrete Column	Piles and Columns	21	12	2	4	3
215		Reinforced Concrete Abutment	Abutments	148	131	0	17	0
234		Reinforced Concrete Pier Cap	Caps	392	213	76	95	8
301		Pourable Joint Seal	Expansion Joints	231	211	0	20	0
316		Other Bearings	Bearing Device	88	55	6	26	1
515	316	Steel Protective Coating	Bearing Device	88	63	0	1	24
333		Other Bridge Railing	Bridge Rail	416	345	67	4	0
510		Wearing Surface	Wearing Surfaces	14,042	9,531	0	4,511	0

# Summary of Maintenance Needs

## Maintenance By Defect

Structure Number: **110173**

Inspection Date: **10/25/2023**

<b>MMS Code</b>	<b>Element Name</b>	<b>Defect Name</b>	<b>Recommended Quantity</b>
3326	Reinforced Concrete Deck	Delamination/Spall	20 Square Feet
3326	Reinforced Concrete Deck	Cracking (RC and Other)	5202 Square Feet
3314	Steel Open Girder/Beam	Corrosion	85 Feet
3314	Steel Open Girder/Beam	Damage	3 Feet
3348	Reinforced Concrete Column	Exposed Rebar	4 Each
3348	Reinforced Concrete Column	Cracking (RC and Other)	2 Each
3348	Reinforced Concrete Column	Delamination/Spall	13 Each
3350	Reinforced Concrete Abutment	Cracking (RC and Other)	6 Feet
3350	Reinforced Concrete Abutment	Delamination/Spall	11 Feet
3348	Reinforced Concrete Pier Cap	Exposed Rebar	26 Feet
3348	Reinforced Concrete Pier Cap	Cracking (RC and Other)	59 Feet
3348	Reinforced Concrete Pier Cap	Delamination/Spall	28 Feet
3310	Pourable Joint Seal	Seal Damage	14 Feet
3334	Other Bearings	Corrosion	26 Each
3334	Other Bearings	Connection	2 Each
3334	Other Bearings	Loss of Bearing Area	1 Each
3318	Other Bridge Railing	Delamination/Spall	2 Feet
3318	Other Bridge Railing	Distortion	1 Feet
2816	Wearing Surface	Crack (Wearing Surface)	4500 Square Feet
2816	Wearing Surface	Patched Area/Pothole (Wearing Surface)	11 Square Feet
3342	Steel Protective Coating	Effectiveness (Steel Protective Coatings)	110 Square Feet

## Element Structure Maintenance Quantities

Structure Number: 110173

Inspection Date 10/25/2023

Location	MMS Code	Description	Maint Quantity	Total Quantity	Severe Quantity	Poor Quantity	Fair Quantity	Good Quantity
Beam	3314	Maintenance Steel Superstructure Components	88	2288	83.000	3.000	22.000	2180.000
Beam	3342	Clean and Paint Steel	85	21604	23.000	62.000	0.000	21519.000
Bearing Device	3334	Bridge Bearing	29	88	1.000	26.000	6.000	55.000
Bearing Device	3342	Clean and Paint Steel	25	88	24.000	1.000	0.000	63.000
Bridge Rail	3318	Maintenance of Concrete Bridge Rail	3	416	0.000	4.000	67.000	345.000
Deck	3326	Maintenance of Concrete Deck	5222	14455	0.000	5206.000	16.000	9233.000
Expansion Joints	3310	Maintenance of Standard Bridge Expansion Joints	14	231	0.000	20.000	0.000	211.000
Wearing Surfaces	2816	Asphalt Surface Repair	4511	14042	0.000	4511.000	0.000	9531.000
Abutments	3350	Maintenance of Concrete Wings and Wall	17	148	0.000	17.000	0.000	131.000
Caps	3348	Maintenance of Concrete Substructure	113	392	8.000	95.000	76.000	213.000
Piles and Columns	3348	Maintenance of Concrete Substructure	19	21	3.000	4.000	2.000	12.000



# Priority Actions Request

Structure Number 110173

## Span1

3326	Deck	Reinforced Concrete Deck	
Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	3	Span 1 Deck: (PAR) 6 inch diameter x 1 inch deep spall with exposed reinforcement. no measurable section loss. 18 inch long x 12 inch wide area of delamination along beam 8 top flange, in bay 7, at midspan.
2	Delamination/Spall	1	Span 1 Deck: (PAR) 6 inch diameter x 1/2 inch deep spall with exposed reinforcement in bay 4 near end bent 1
3314	Beam 4	Plate Girder	
Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	1	Span 1 Beam 4: (PAR) 8 inch long x full flange width x 0.55 inch remaining thickness in bottom flange with corrosion reactivating at bent 1
3314	Beam 5	Plate Girder	
Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	1	Span 1 Beam 5: (PAR) 10 inch long x 3 inch high x 3/16 inch average remaining in the web with 3 inch long x 1.5 inch corrosion hole under the diaphragm at bent 1
3314	Beam 6	Plate Girder	
Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	3	Span 1 Beam 6: (PAR) at bent 1, corrosion with section loss: web (1/4 inch average remaining x 3 foot x 8 inch); bottom flange (0.42 inch average remaining x 20 inch)
3314	Beam 7	Plate Girder	
Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	1	Span 1 Beam 7: (PAR) at bent 1 active corrosion with section loss, web at diaphragm [10 inch x 2 inch x 3/16 inch average remaining] with 1/2 inch diameter corrosion hole
3314	Beam 8	Plate Girder	
Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	2	Span 1 Beam 8: (PAR) 18 inch long x up to 8 inch x 1/4 inch average remaining area of section loss in web at bent 1, spot rust present.
3318	Left Bridge Rail	Concrete and Metal Railing	
Priority Level	Defect Type	Quantity	Defect Description
2	Damage	1	Span 1 Left Bridge Rail: (PAR) impact damage to rail bracket of fourth post

? Priority Action Request (PAR)
 1 Assigned Routine Maintenance
 2 Assigned Priority Maintenance
 3 Assigned Critical Find

# Priority Actions Request

Structure Number 110173

## Span2

3314	Beam 3	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 2 Beam 3: (PAR) 10 inch long x up to 2 inch high x 5/16 inch section remaining in the web at beam end at bent 1, spot rust present	
3314	Beam 4	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	5	Span 2 Beam 4: (PAR) at bent 1, corrosion with section loss: web adjacent to diaphragm (1/4 inch average remaining x 12 inch x 2.5 inch) with corrosion hole (6 inch x 1 inch); lower web (5/16 inch average remaining x 52 inch x 2 inch); bottom flange (0.55 inch average remaining x 10 inch)	
2	Corrosion	3	Span 2 Beam 4: (PAR) at bent 2, corrosion with section loss: bottom flange (0.60 inch average remaining x 2.5 foot), lower web (5/16 inch average remaining x 27 inch x 2 inch), web adjacent to diaphragm (1/4 inch average remaining x 11 inch x 3 inch)	
2	Damage	0	Span 2 Beam 4: (PAR) 7 foot long x 4 inch high x 4 inch wide area of spall, delamination with exposed reinforcement in the concrete diaphragm between beams 4 and 5 at bent 1. 75 percent section remaining in the exposed reinforcement.	
3314	Beam 5	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 2 Beam 5: (PAR) active corrosion with section loss 10 inch long x 3 inch high x 1/4 inch average remaining in the web with 3 inch long x 1.25 inch high corrosion hole under the diaphragm at bent 1	
2	Corrosion	1	Span 2 Beam 5: (PAR) at bent 2, corrosion with section loss: bottom flange (0.50 inch average remaining x 8 inch); web adjacent to diaphragm (3/16 inch average remaining x 11 inch x 8 inch)	
2	Damage	0	Span 2 Beam 5: (PAR) 7 foot long x 10 inch high x 3 inch wide area of spall, delamination with exposed reinforcement in the concrete diaphragm between beams 5 and 6 at bent 1. 70 percent section remaining in the exposed reinforcement	
2	Damage	0	Span 2 Beam 5: (PAR) up to 4.5 foot long x 4 inch high x 3 inch deep spalls in south and bottom with exposed rusted reinforcement with up to 1/16 inch section loss, in the diaphragm between beams 4 and 5.	
3314	Beam 6	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	2	Span 2 Beam 6: (PAR) at bent 1, corrosion with section loss: web (1/4 inch average remaining x 54 inch x 13 inch); bottom flange (0.56 inch average remaining x 2 foot)	
2	Corrosion	1	Span 2 Beam 6: (PAR) at bent 2, corrosion with section loss: web adjacent to diaphragm (3/16 inch average remaining x 10.5 inch x 2.5 inch) with corrosion hole (1.5 inch x 1/2 inch); lower web (3/8 inch average remaining x 5.5 inch x 1 inch)	
2	Damage	0	Span 2 Beam 6: (PAR) 7 foot x 16 inch x up to 3 inch deep spall with exposed reinforcement in the underside and south face of the diaphragm between beams 6 and 7. 70 percent section remaining in exposed reinforcement.	
3314	Beam 7	Plate Girder		

? Priority Action Request (PAR)
 1 Assigned Routine Maintenance
 2 Assigned Priority Maintenance
 3 Assigned Critical Find

# Priority Actions Request

Structure Number 110173

Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	2	Span 2 Beam 7: (PAR) at bent 1 active corrosion with section loss, web at diaphragm [20 inch long x 13 inch high x 1/4 inch average remaining] with multiple corrosion holes up to [3 inch x 1 inch]
2	Corrosion	1	Span 2 Beam 7: (PAR) at bent 2, painted over section loss:: bottom flange (0.50 inch average remaining x 8 inch); lower web (3/8 inch average remaining x 5 inch x 1 inch); web adjacent to diaphragm (3/16 inch average remaining x 10 inch x 3 inch)
2	Damage	0	Span 2 Beam 7: (PAR) 2 foot x 4 inch x 3 inch deep spall with exposed rusted and debonded reinforcement on south face of end diaphragm, at bent 2
2	Damage	0	Span 2 Beam 7: (PAR) 7 foot long x 4 inch high x 4 inch wide area of spalling, delamination with the exposed reinforcement in the concrete diaphragm between beams 7 and 8 at bent 1. 70 percent section remaining in the exposed reinforcement.

3314 **Beam 8** Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	2	Span 2 Beam 8: (PAR) at bent 1, corrosion with section loss: web (1/4 inch average remaining x 24 inch x 12 inch) with corrosion hole (3 inch x 1 inch); bottom flange (0.56 inch average remaining x 12 inch)
2	Corrosion	2	Span 2 Beam 8: (PAR) at bent 2, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 14 inch x 8 inch); lower web (7/16 inch average remaining x 2 foot x 3 inch)
2	Connection	1	Span 2 Beam 8 - Far Bearing 8: [PAR] West face anchor bolt not visible within nut

3318 **Left Bridge Rail** Concrete and Metal Railing

Priority Level	Defect Type	Quantity	Defect Description
2	Distortion	1	Span 2 Left Bridge Rail: (PAR) impact damage to left bridge rail at 3rd vertical post from bent 1. base plate is broken off along the weld and spalls under the base plate with two of four anchor bolts exposed. impact damage is above eastbound I-40 right travel lane. rail and post are intact

## Span3

3314 **Beam 4** Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	6	Span 3 Beam 4: (PAR) at bent 2, corrosion with section loss: bottom flange (0.56 inch average remaining x 9 inch), lower web (3/16 inch average remaining x 6 foot x 2 inch), web adjacent to diaphragm (3/16 inch average remaining x 12 inch x 2 inch)
2	Corrosion	2	Span 3 Beam 4: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 15 inch x 9 inch)
2	Damage	0	Span 3 Beam 4: (PAR) 6 foot long x up to 3 inch high x 10 inch wide area of spall in the diaphragm between beams 4 and 5 at bent 2 with exposed reinforcement. 70 percent section remaining in the exposed reinforcement.

3314 **Beam 5** Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
----------------	-------------	----------	--------------------

# Priority Actions Request

Structure Number 110173

②	Corrosion	3	Span 3 Beam 5: (PAR) at bent 2, corrosion with section loss: bottom flange (0.60 inch average remaining x 3 foot); web (1/4 inch average remaining x 3 foot x 12 inch) with arrested hole (1.5 inch x 1 inch)
②	Corrosion	2	Span 3 Beam 5: (PAR) at bent 3, corrosion with section loss: bottom flange (0.45 inch average remaining x 1 foot); web (1/4 in average remaining x 2 foot x 9 inch)
②	Loss of Bearing Area	1	Span 3 Near Bearing 5: (PAR) loss of bearing area (up to 1/2 inch x 3 inch)
②	Damage	0	Span 3 Beam 5: (PAR) 7 foot long x up to 3 inch high x 10 inch wide area of spall in the diaphragm between beams 5 and 6 at bent 2 with exposed reinforcement. 70 percent section remaining in the exposed reinforcement.

**3314**      **Beam 6**      Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
②	Corrosion	1	Span 3 Beam 6: (PAR) at bent 2, corrosion with section loss: web (1/4 inch average remaining x 3 foot x 1 foot) with corrosion hole (5 inch x 2 inch); bottom flange (0.60 inch average remaining x 2.5 foot)
②	Corrosion	2	Span 3 Beam 6: (PAR) at bent 3, corrosion with section loss: web (1/4 inch average remaining x 20 inch x 10 inch); bottom flange (0.56 inch average remaining x 1 foot)

**3314**      **Beam 7**      Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
②	Corrosion	5	Span 3 Beam 7: (PAR) at bent 2, painted over section loss: web (1/4 inch average remaining x 4.5 foot x 16 inch)
②	Corrosion	1	Span 3 Beam 7: (PAR) at bent 3, corrosion with section loss: web adjacent to diaphragm (3/8 inch average remaining x 10 inch x 5 inch)
②	Connection	1	Span 3 Near Bearing 7: (PAR) east weld between sole and masonry plate, broken

**3314**      **Beam 8**      Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
②	Corrosion	1	Span 3 Beam 8: (PAR) at bent 2, corrosion with section loss: web adjacent to diaphragm (3/16 inch average remaining x 16 inch x 2.5 inch); lower web (1/4 inch average remaining x 20 inch x 2 inch); bottom flange (0.50 inch average remaining x 9 inch)
②	Corrosion	3	Span 3 Beam 8: (PAR) at bent 3, corrosion with section loss: web adjacent to diaphragm (1/4 inch average remaining x 1 foot x 8 inch); lower web (1/4 inch average remaining x 32 inch x 2 inch); bottom flange (0.50 inch average remaining x 18 inch)
②	Damage	1	Span 3 Beam 8: (PAR) 3 foot long x 6 inch wide x 3 inch high spall with exposed reinforcement in end diaphragm between beams 7 and 8 at bent 3. 70 percent section remaining in exposed reinforcement.

**Span4**

**3314**      **Beam 4**      Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
②	Corrosion	6	Span 4 Beam 4: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 5.5 foot x 10 inch) with corrosion holes (up to 1 inch x 1/2 inch); bottom flange (0.45 inch average remaining x 4 foot)

# Priority Actions Request

Structure Number 110173

3314	Beam 5	Plate Girder	Priority Level	Defect Type	Quantity	Defect Description
			2	Corrosion	5	Span 4 Beam 5: (PAR) at bent 3, corrosion with section loss: web (1/4 inch average remaining x 6 foot x 1 foot) with corrosion holes (6 inch x 1.5 inch); bottom flange (0.56 inch average remaining x 15 inch)

3314	Beam 6	Plate Girder	Priority Level	Defect Type	Quantity	Defect Description
			2	Corrosion	4	Span 4 Beam 6: (PAR) at bent 3, corrosion with section loss: web (1/4 inch average remaining x 32 inch x 12 inch)

3314	Beam 7	Plate Girder	Priority Level	Defect Type	Quantity	Defect Description
			2	Corrosion	8	Span 4 Beam 7: (PAR) at bent 3, corrosion with section loss: web (1/4 inch average remaining x 8 foot x 12 inch) with corrosion holes (up to 1/4 inch diameter); bottom flange (0.45 inch average remaining x 26 inch)

3314	Beam 8	Plate Girder	Priority Level	Defect Type	Quantity	Defect Description
			2	Corrosion	4	Span 4 Beam 8: (PAR) at bent 3, corrosion with section loss: web (1/4 inch average remaining x 34 inch x 12 inch) with corrosion hole (10 inch x 3 inch); bottom flange (0.50 inch average remaining x 34 inch)
			2	Damage	0	Span 4 Beam 8: (PAR) 7 foot long x 1.5 foot wide x 3 inch deep spall with exposed reinforcement in end diaphragm between beams 7 and 8 at bent 3. 60 percent section remaining in exposed reinforcement.

## Bent 1

3348	Cap 1	Reinforced Concrete Pier Cap	Priority Level	Defect Type	Quantity	Defect Description
			2	Exposed Rebar	9	Bent 1 Cap 1: (PAR) South and top face between beams 7 and 8, spall/delamination [4.5 foot x up to 3.5 foot x up to 4 inch deep] with 4 vertical and 1 horizontal exposed rusted reinforcing with up to 1/16 inch section loss. no loss of bearing area

3348	Pile 3	Reinforced Concrete Column	Priority Level	Defect Type	Quantity	Defect Description
			2	Delamination/Spall	1	Bent 1 Pile 3: (PAR) 34 inch high x 10 inch wide x up to 2 inch deep spall with exposed rusted reinforcement.

# Priority Actions Request

Structure Number 110173

## Bent 2

3348	Cap 1	Reinforced Concrete Pier Cap	
Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Rebar	2	Bent 2 Cap 1: (PAR) (3) up to 1.5 foot x 1 foot wide x 1/2 inch deep spall with exposed rusted reinforcement, 80 percent remaining on underside of cap between columns 5 and 6
2	Exposed Rebar	2	Bent 2 Cap 1: (PAR) south face, below beam 4, spall/delamination (18 inch x 38 inch x 1.5 inch deep) with exposed and debonded rebar
2	Exposed Rebar	8	Bent 2 Cap 1: (PAR) south face, in bay 6, spall/delamination (8 foot x 4 foot x 1.5 inch deep) with exposed rusted rebar (approximately 75 percent remaining) and cracks (up to 1/16 inch)
2	Exposed Rebar	5	Bent 2 Cap 1: [PAR] bottom face of cap between columns 4 and 5, spall/delamination [5 foot long x full width x up to 3 inch deep] with seven exposed rusted reinforcing with 80 percent remaining

3348	Pile 3	Reinforced Concrete Column	
Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Rebar	1	Bent 2 Pile 3: (PAR) Southeast corner 5 foot from the ground, delamination/spall [28 inch wide x 9.5 foot x up to 4 inch deep] with [1] primary exposed rusted reinforcing [75 percent remaining]

3348	Pile 4	Reinforced Concrete Column	
Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Rebar	1	Bent 2 Pile 4: (PAR) north face, at ground, spall/delamination (full width x 7.5 foot high x 3 inch deep) extends into east and west faces (up to 7 inch) with exposed rusted and debonded rebars

3348	Pile 5	Reinforced Concrete Column	
Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Rebar	1	Bent 2 Pile 5: (PAR) Southwest corner below cap, delamination/spall [7 foot high x up to full width x up to 3 inch deep] with two exposed rusted reinforcing, 70 percent section remaining in the exposed reinforcement.

## Bent 3

3348	Pile 3	Reinforced Concrete Column	
Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Rebar	1	Bent 3 Pile 3: (PAR) Southeast corner above barrier rail, spall/delamination [10 foot high x up to full width x up to 4 inch deep] with primary debonded exposed rusted reinforcing 75 percent remaining

3348	Pile 5	Reinforced Concrete Column	
------	--------	----------------------------	--

# Priority Actions Request

Structure Number 110173

Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Rebar	1	Bent 3 Pile 5: (PAR) 6.5 foot high x 20 inch wide x 3.5 inch deep spall and delaminated concrete with one debonded primary exposed reinforcement on south east corner of pile. 80 percent section remaining in exposed reinforcement.

## Approach Guardrail and Barriers

3120 Approach Guardrail and Barriers Approach Guardrail and Barriers

Priority Level	Defect Type	Quantity	Defect Description
2		1	(PAR) northwest guardrail attachment, improper lap
2		13	(PAR) northwest guardrail, 55 foot from end bent 2, impact damage (12.5 foot)
2		1	(PAR) southeast guardrail attachment, improper lap
2		9	(PAR) southeast guardrail, 3 foot from end bent 1, impact damage (9 foot)
2		50	(PAR) along end bent 1 slope protection, homeless debris (full length)
2		50	(PAR) along end bent 2 slope protection, homeless debris (full length)

## Element Condition and Maintenance Data

Structure Number: 110173

Inspection Date: 10/25/2023

**Span 1** **Deck**  
**Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	3,430	2,214	12	1,204	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random	3	1,200	1,200	Square Feet
<input checked="" type="checkbox"/> 12	Delamination/Spall	(PAR) 6 inch diameter x 1 inch deep spall with exposed reinforcement. no measurable section loss. 18 inch long x 12 inch wide area of delamination along beam 8 top flange, in bay 7, at midspan.	3	3	3	Square Feet
<input checked="" type="checkbox"/> 12	Delamination/Spall	(PAR) 6 inch diameter x 1/2 inch deep spall with exposed reinforcement in bay 4 near end bent 1	3	1	1	Square Feet
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	left overhang, at bent 1, delamination (2 foot x 6 inch)	2	2	2	Square Feet
<input checked="" type="checkbox"/> 12	Delamination/Spall	(2) up to 2 foot wide x 12 inch long areas of delamination in deck underside, bay 3, near midspan.	2	4	4	Square Feet
<input checked="" type="checkbox"/> 12	Delamination/Spall	underside of deck, bay 2, at end bent 1 and midspan, (2) delaminations (up to 3 foot x 1 foot)	2	6	6	Square Feet
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	(combined with other notes 2023) 2 - hairline full width transverse cracks in underside of deck in bay 4, scattered. typical for bay 5.	1			Square Feet
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	(combined with other notes 2023) 4 - up to 1/16 inch wide full width transverse cracks in underside of deck in bay 2, scattered.	1			Square Feet
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	(combined with other notes 2023) 7 - hairline full width transverse cracks in underside of deck in bay 3.	1			Square Feet
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	(combined with other notes 2023) 7 - up to 1/16 inch wide full width transverse cracks in underside of deck in bay 1, scattered.	1			Square Feet

**General Comments**

**Span 1** **Beam 4**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	49	48	0	0	1	Feet
515	Steel Protective Coating	465	464	0	1	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 107	Corrosion	(PAR) 8 inch long x full flange width x 0.55 inch remaining thickness in bottom flange with corrosion reactivating at bent 1	4	1	1	Feet
<input checked="" type="checkbox"/> 107	Damage	6 inch x 4 inch x full depth spall with exposed reinforcement and up to 1/8 inch wide x 7 foot long longitudinal crack along the south face of the diaphragm near the bottom between beams 4 and 5 at bent 1	3			Feet
<input checked="" type="checkbox"/> 107	Corrosion	at bent 1, painted over pitting up to 1/16 inch x 12 inch x 7 inch with corrosion reactivating	2			Feet
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust	3	1	1	Square Feet



**General Comments****Span 1****Beam 5****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	49	48	0	0	1 Feet
515	Steel Protective Coating	465	464	0	1	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 107	Corrosion	(PAR) 10 inch long x 3 inch high x 3/16 inch average remaining in the web with 3 inch long x 1.5 inch corrosion hole under the diaphragm at bent 1	4	1	1 Feet
<input checked="" type="checkbox"/> 107	Damage	multiple up to 1/8 inch wide x up to full length longitudinal cracks along the south face of the diaphragm near the bottom between beams 5 and 6 at bent 1	3		Feet
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust	3	1	1 Square Feet

**General Comments****Span 1****Beam 6****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	49	46	0	0	3 Feet
515	Steel Protective Coating	465	461	0	4	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 107	Corrosion	(PAR) at bent 1, painted over section loss: web (1/4 inch average remaining x 3 foot x 8 inch); bottom flange (0.42 inch average remaining x 20 inch) with corrosion reinitiated	4	3	3 Feet
<input checked="" type="checkbox"/> 107	Damage	up to 1/8 inch wide x 7 foot long longitudinal crack along the south face of the diaphragm near the bottom between beams 6 and 7 at bent 1	3		Feet
<input checked="" type="checkbox"/> 107	Corrosion	(combined with other notes 2023) bent 1 active corrosion with section loss, bottom flange [20 inch long x full flange width x 0.5 inch average remaining]	1		Feet
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust	3	4	4 Square Feet

**General Comments****Span 1****Beam 7****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	49	48	0	0	1 Feet
515	Steel Protective Coating	465	464	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 1 active corrosion with section loss, web at diaphragm [10 inch x 2 inch x 3/16 inch average remaining] with 1/2 inch diameter corrosion hole	4	1	1	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	diaphragm between beams 7 and 8 at bent 1, spall/delamination [full width x up to 6 inch high x up to 3 inch deep]	3			Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1	Square Feet

**General Comments**

**Span 1 Beam 8 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	49	47	0	0	2	Feet
515	Steel Protective Coating	465	463	0	2	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) 18 inch long x up to 8 inch x 1/4 inch average remaining area of section loss in web at bent 1, spot rust present.	4	2	2	Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	2	2	Square Feet

**General Comments**

**Span 1 Wearing Surface Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
510	Wearing Surface	3,332	2,324	0	1,008	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/16 inch x 8 foot)	3	1,000	1,000	Square Feet
<input checked="" type="checkbox"/>	<b>510</b>	Patched Area/Pothole (Wearing Surface)	7 foot long x 16 foot wide x 1 inch deep failed/depressed patch in center of southbound lane near end bent 1	3	7	7	Square Feet
<input checked="" type="checkbox"/>	<b>510</b>	Patched Area/Pothole (Wearing Surface)	left shoulder of asphalt over end bent 1, pothole/broken asphalt [6 foot x 8 inch x up to 1 inch deep]	3	1	1	Square Feet
<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	(combined with other notes 2023) 9 - up to 1/8 inch wide x 3 foot long transverse cracks, scattered, in southbound left lanes and left shoulder	1			Square Feet

**General Comments**

**Span 1 Left Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	49	38	10	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 333	Connection	(PAR) impact damage to rail bracket of fourth post	3	1	Feet
<input checked="" type="checkbox"/> 333	Damage	fourth post, impact damage	3		Feet
<input checked="" type="checkbox"/> 333	Cracking (RC and Other)	along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	10	Feet

General Comments

**Span 1 Right Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	49	44	5	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 333	Cracking	along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	5	Feet
<input checked="" type="checkbox"/> 333	Damage	(2023 moved to general notes) moderate to heavy impact damage and moderate to heavy corrosion for 11 foot starting at southeast guardrail transition	1		Feet

General Comments

**Span 1 Near Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	surface rust/rust scale	2	1	Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust/rust scale	4	1	1 Square Feet

General Comments

**Span 1 Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

Structure Number: 110173

Inspection Date: 10/25/2023

<input checked="" type="checkbox"/>	316	Corrosion	surface rust/rust scale	2	1	Each
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	surface rust/rust scale	4	1	1 Square Feet

**General Comments**

**Span 1 Far Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	1	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	316	Corrosion	arrested pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1 Each

**General Comments**

**Span 1 Far Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	1	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	316	Corrosion	surface rust	2	1	Each
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	surface rust	3	1	1 Square Feet

**General Comments**

**Span 1 Far Bearing 6**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining. west anchor bolt nut 60 percent remaining.	3	1	1 Each
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1 Square Feet

**General Comments**

**Span 1 Far Bearing 7**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	surface rust/rust scale	2	1		Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust/rust scale	4	1	1	Square Feet

**General Comments**

**Span 1 Far Bearing 8**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1	Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1	Square Feet

**General Comments**

**Span 1 Near Bearing 11**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	surface rust/rust scale	2	1		Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust/rust scale	4	1	1	Square Feet

**General Comments**

**Span 2 Deck**  
**Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	4,025	2,525	0	1,500	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random	3	1,500	1,500	Square Feet

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>12</b>	Cracking (RC and Other)	(combined with other notes 2023) 2 - hairline transverse full width cracks in deck underside, bay 1, at both interior diaphragms.	1			Square Feet
<input checked="" type="checkbox"/>	<b>12</b>	Cracking (RC and Other)	(combined with other notes 2023) 2 - hairline transverse full width cracks in deck underside, bay 3, at both interior diaphragms.	1			Square Feet
<input checked="" type="checkbox"/>	<b>12</b>	Cracking (RC and Other)	(Moved to wearing service 10/26/21) 5 - up to 1/8 inch wide x 3 foot long transverse cracks, scattered in southbound left lane.	1			Square Feet

**General Comments**

**Span 2** **Beam 3**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	58	57	0	0	1	Feet
515	Steel Protective Coating	547	545	0	2	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) 10 inch long x up to 2 inch high x 5/16 inch section remaining in the web at beam end at bent 1, spot rust present	4	1	1	Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	2	2	Square Feet

**General Comments**

**Span 2** **Beam 4**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	58	50	0	0	8	Feet
515	Steel Protective Coating	547	537	0	10	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 1, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 12 inch x 2.5 inch) with corrosion hole (6 inch x 1 inch); lower web (5/16 inch average remaining x 52 inch x 2 inch); bottom flange (0.55 inch average remaining x 10 inch) with corrosion reinitiated	4	5	5	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 2, painted over section loss: bottom flange (0.60 inch average remaining x 2.5 foot), lower web (5/16 inch average remaining x 27 inch x 2 inch), web adjacent to diaphragm (1/4 inch average remaining x 11 inch x 3 inch) with corrosion reinitiated	4	3	3	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	(PAR) 7 foot long x 4 inch high x 4 inch wide area of spall, delamination with exposed reinforcement in the concrete diaphragm between beams 4 and 5 at bent 1. 75 percent section remaining in the exposed reinforcement.	4			Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(combined with other notes 2023) active corrosion with section loss 8 inch long x full flange width x 0.55 inch section remaining in bottom flange at bent 1.	1			Feet

<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	10	10	Square Feet
-------------------------------------	------------	---	--------------	---	----	----	-------------

**General Comments**

**Span 2 Beam 5 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	56	0	0	2 Feet
515	Steel Protective Coating	547	545	0	0	2 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	107	Corrosion	(PAR) active corrosion with section loss 10 inch long x 3 inch high x 1/4 inch average remaining in the web with 3 inch long x 1.25 inch high corrosion hole under the diaphragm at bent 1	4	1	1 Feet
<input checked="" type="checkbox"/>	107	Corrosion	(PAR) at bent 2, painted over section loss: bottom flange (0.50 inch average remaining x 8 inch); web adjacent to diaphragm (3/16 inch average remaining x 11 inch x 8 inch) with corrosion reinitiated	4	1	1 Feet
<input checked="" type="checkbox"/>	107	Damage	(PAR) 7 foot long x 10 inch high x 3 inch wide area of spall, delamination with exposed reinforcement in the concrete diaphragm between beams 5 and 6 at bent 1. 70 percent section remaining in the exposed reinforcement	4		Feet
<input checked="" type="checkbox"/>	107	Damage	(PAR) up to 4.5 foot long x 4 inch high x 3 inch deep spalls in south and bottom with exposed rusted reinforcement with up to 1/16 inch section loss, in the diaphragm between beams 4 and 5.	3		Feet
<input checked="" type="checkbox"/>	107	Corrosion	(combined with other notes 2023) at bent 2 active corrosion with section loss, bottom flange at bearing [full width x 2 inch x average remaining 5/8 inch]	1		Feet
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	2	2 Square Feet
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	(combined with other notes 2023) substantially effective freckled corrosion initiated	1		Square Feet

**General Comments**

**Span 2 Beam 6 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	52	0	0	6 Feet
515	Steel Protective Coating	547	541	0	6	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	107	Corrosion	(PAR) at bent 1, painted over section loss: web (1/4 inch average remaining x 54 inch x 13 inch); bottom flange (0.56 inch average remaining x 2 foot) with corrosion reinitiated	4	5	5 Feet
<input checked="" type="checkbox"/>	107	Corrosion	(PAR) at bent 2, painted over section loss: web adjacent to diaphragm (3/16 inch average remaining x 10.5 inch x 2.5 inch) with corrosion hole (1.5 inch x 1/2 inch); lower web (3/8 inch average remaining x 5.5 inch x 1 inch) with corrosion reinitiated	4	1	1 Feet





**Span 2****Beam 8****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	54	0	0	4 Feet
515	Steel Protective Coating	547	543	0	4	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 107	Corrosion	(PAR) at bent 1, painted over section loss: web (1/4 inch average remaining x 24 inch x 12 inch) with corrosion hole (3 inch x 1 inch); bottom flange (0.56 inch average remaining x 12 inch) with corrosion reinitiated	4	2	2 Feet
<input checked="" type="checkbox"/> 107	Corrosion	(PAR) at bent 2, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 14 inch x 8 inch); lower web (7/16 inch average remaining x 2 foot x 3 inch)	4	2	2 Feet
<input checked="" type="checkbox"/> 107	Damage	(combined with beam 7 notes 2023) end diaphragm between beams 7 and 8, spall [full length x 14 inch x up to 3 inch deep] with exposed rusted reinforcing up to 1/16 inch section loss	1		Feet
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust	3	4	4 Square Feet

**General Comments****Span 2****Expansion Joint at Bent 1****Standard Joint**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
301	Pourable Joint Seal	77	75	0	2	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 301	Seal Damage	southbound turn lane, missing seal material (2 foot x 9 inch x full depth)	3	2	2 Feet

**General Comments****Span 2****Wearing Surface****Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
510	Wearing Surface	3,910	2,407	0	1,503	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 510	Crack (Wearing Surface)	throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/16 inch x 8 foot)	3	1,500	1,500 Square Feet
<input checked="" type="checkbox"/> 510	Patched Area/Pothole (Wearing Surface)	at right Southbound lane adjacent to joint over bent 2, unsound patch/pothole [32 inch x 10 inch x full depth]	3	3	3 Square Feet
<input checked="" type="checkbox"/> 510	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x 3 foot long transverse and longitudinal cracks, scattered in southbound left lane.	1		Square Feet

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x 3 foot long transverse and longitudinal cracks, scattered, in right shoulder.	1			Square Feet
<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x 5 foot long transverse and longitudinal cracks, scattered, in left shoulder.	1			Square Feet

**General Comments**

**Span 2 Left Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	58	47	10	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	333	Damage	3rd post from bent 1, impact damage	3		Feet
<input checked="" type="checkbox"/>	333	Distortion	(PAR) impact damage to left bridge rail at 3rd vertical post from bent 1. base plate is broken off along the weld and spalls under the base plate with two of four anchor bolts exposed. impact damage is above eastbound I-40 right travel lane. rail and post are intact	3	1	1 Feet
<input checked="" type="checkbox"/>	333	Cracking (RC and Other)	along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	10	Feet

**General Comments**

**Span 2 Right Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	58	52	6	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	333	Cracking	along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	6	Feet

**General Comments**

**Span 2 Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 75 percent section remaining	3	1	1 Each
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1 Square Feet

**General Comments**

**Span 2 Far Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 75 percent section remaining	3	1	1 Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1 Square Feet

General Comments

**Span 2 Near Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1 Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	pack rust/ corrosion with section loss	4	1	1 Square Feet

General Comments

**Span 2 Far Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	corrosion with section loss (up to 1/8 inch loss) on masonry plate and sole plate	3	1	1 Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1 Square Feet

General Comments

**Span 2 Near Bearing 6**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	rust scale	2	1	Each

<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	rust scale	4	1	1	Square Feet
-------------------------------------	------------	---	------------	---	---	---	-------------

**General Comments****Span 2 Far Bearing 6****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>316</b>	Corrosion				1 Each
		active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1		
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)				1 Square Feet
		corrosion with section loss	4	1		

**General Comments****Span 2 Near Bearing 7****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>316</b>	Corrosion				1 Each
		active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1		
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)				1 Square Feet
		corrosion with section loss	4	1		

**General Comments****Span 2 Far Bearing 7****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>316</b>	Corrosion				1 Each
		active pack rust arrested when painted. Section loss in masonry and sole plates with 75 percent remaining.	3	1		
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)				1 Square Feet
		corrosion with section loss	4	1		

**General Comments**

**Span 2 Near Bearing 8****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	1	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	arrested pack rust and section loss in masonry plate. 80 percent section remaining.	3	1	1	Each

**General Comments****Span 2 Far Bearing 8****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	1	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Connection	[PAR] West face anchor bolt not visible within nut	3	1	1	Each

**General Comments****Span 3 Deck****Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	4,025	2,521	4	1,500	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 12	Cracking (RC and Other)	throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random	3	1,500	1,500	Square Feet
<input checked="" type="checkbox"/> 12	Delamination/Spall	at bent 3, both overhangs, (2) delaminations (up to 1.5 foot x 6 inch)	2	4	4	Square Feet

**General Comments****Span 3 Beam 1****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	58	56	2	0	0	Feet
515	Steel Protective Coating	547	546	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 107	Corrosion	at bent 2, web, rust scale (10 inch)	2	1		Feet
<input checked="" type="checkbox"/> 107	Damage	impact damage	2			Feet

Structure Number: 110173

Inspection Date: 10/25/2023

<input checked="" type="checkbox"/>	107	Distortion	(2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021 :scattered scrapes	2	1	Feet
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	rust scale	4	1	1 Square Feet

**General Comments**

**Span 3 Beam 2**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	57	1	0	0 Feet
515	Steel Protective Coating	547	547	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	107	Damage		2	Feet
<input checked="" type="checkbox"/>	107	Distortion		2	1 Feet
		2023 new paint repair, previously noted as: SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021 :scattered scrapes			

**General Comments**

**Span 3 Beam 3**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	57	1	0	0 Feet
515	Steel Protective Coating	547	547	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	107	Damage		2	Feet
<input checked="" type="checkbox"/>	107	Distortion		2	1 Feet
		2023 new paint repair; previously noted as: SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021 :scattered scrapes			

**General Comments**

**Span 3 Beam 4**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	49	1	2	6 Feet
515	Steel Protective Coating	547	539	0	8	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	107	Corrosion		4	6 Feet
		(PAR) at bent 2, painted over section loss: bottom flange (0.56 inch average remaining x 9 inch), lower web (3/16 inch average remaining x 6 foot x 2 inch), web adjacent to diaphragm (3/16 inch average remaining x 12 inch x 2 inch) with corrosion reinitiated			

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>107</b>	Damage	(PAR) 6 foot long x up to 3 inch high x 10 inch wide area of spall in the diaphragm between beams 4 and 5 at bent 2 with exposed reinforcement. 70 percent section remaining in the exposed reinforcement.	4		Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 15 inch x 9 inch)	3	2	2 Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	impact damage	2		Feet
<input checked="" type="checkbox"/>	<b>107</b>	Distortion	(2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021: scattered scrapes	2	1	Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	8	8 Square Feet

**General Comments**

**Span 3 Beam 5**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	53	0	0	5 Feet
515	Steel Protective Coating	547	542	0	5	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion			
		(PAR) at bent 2, painted over section loss: bottom flange (0.60 inch average remaining x 3 foot); web (1/4 inch average remaining x 3 foot x 12 inch) with hole (1.5 inch x 1 inch) with corrosion reinitiated	4	3	3 Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion			
		(PAR) at bent 3, painted over section loss: bottom flange (0.45 inch average remaining x 1 foot); web (1/4 in average remaining x 2 foot x 9 inch) with corrosion reinitiated	4	2	2 Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage			
		(PAR) 7 foot long x up to 3 inch high x 10 inch wide area of spall in the diaphragm between beams 5 and 6 at bent 2 with exposed reinforcement. 70 percent section remaining in the exposed reinforcement.	4		Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage			
		7 foot x 4 inch delamination with cracks up to 1/8 inch in south face end diaphragm at bent 3	3		Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion			
		(combined with other notes 2023) active corrosion with section loss 22 inch long x full flange width x 0.34 inch section remaining in bottom flange, starting at beam end, bent 3.	1		Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)			
		surface rust	3	5	5 Square Feet

**General Comments**

**Span 3 Beam 6**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	55	0	0	3 Feet
515	Steel Protective Coating	547	544	0	3	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 2, painted over section loss: web (1/4 inch average remaining x 3 foot x 1 foot) with corrosion hole (5 inch x 2 inch); bottom flange (0.60 inch average remaining x 2.5 foot) with corrosion reinitiated	4	1	1	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 20 inch x 10 inch); bottom flange (0.56 inch average remaining x 1 foot) with corrosion reinitiated	4	2	2	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	spall/delamination 7 foot x 10 inch x 2 inch deep with exposed rusted rebar in north face of end diaphragm between beams 6 and 7 at bent 2	3			Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(combined with other notes 2023) active corrosion with section loss 20 inch long x full flange width x up to 0.33 inch section remaining in bottom flange, starting at beam end	1			Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	3	3	Square Feet

**General Comments**

**Span 3 Beam 7 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	49	3	0	6 Feet
515	Steel Protective Coating	547	541	0	1	5 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion			
		(PAR) at bent 2, painted over section loss: web (1/4 inch average remaining x 4.5 foot x 16 inch)	4	5	5 Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion			
		(PAR) at bent 3, painted over section loss: web adjacent to diaphragm (3/8 inch average remaining x 10 inch x 5 inch) with corrosion reinitiated	4	1	1 Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage			
		multiple up to 3 foot long horizontal 1/8 inch wide cracks in end diaphragm between beams 7 and 8 at bent 2 starting at beam 8	3		Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage			
		impact damage	2		Feet
<input checked="" type="checkbox"/>	<b>107</b>	Distortion			
		over right westbound lane, impact scrapes	2	3	Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)			
		over right westbound lane, impact scrapes	4	5	5 Square Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)			
		surface rust	3	1	1 Square Feet

**General Comments**

**Span 3 Beam 8 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	49	5	0	4 Feet
515	Steel Protective Coating	547	536	0	1	10 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------



Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 2, painted over section loss: web adjacent to diaphragm (3/16 inch average remaining x 16 inch x 2.5 inch); lower web (1/4 inch average remaining x 20 inch x 2 inch); bottom flange (0.50 inch average remaining x 9 inch) with corrosion reinitiated	4	1	1	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 3, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 1 foot x 8 inch); lower web (1/4 inch average remaining x 32 inch x 2 inch); bottom flange (0.50 inch average remaining x 18 inch)	4	3	3	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	(PAR) 3 foot long x 6 inch wide x 3 inch high spall with exposed reinforcement in end diaphragm between beams 7 and 8 at bent 3. 70 percent section remaining in exposed reinforcement.	4			Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	impact damage	2			Feet
<input checked="" type="checkbox"/>	<b>107</b>	Distortion	over right westbound lane, impact scrapes with distortion	2	5		Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	over right westbound lane, impact scrapes	4	10	10	Square Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	1	1	Square Feet

**General Comments**

**Span 3 Beam 9 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	57	1	0	0 Feet
515	Steel Protective Coating	547	547	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	<b>107</b>	Damage	impact damage	2	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Distortion	(2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021: 1 indentation 1 inch long x 1/4 inch deep at 18 foot-7 inch from interior. bent 3	2	1 Feet

**General Comments**

**Span 3 Beam 10 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	58	57	1	0	0 Feet
515	Steel Protective Coating	547	547	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	<b>107</b>	Damage	impact damage	2	Feet
<input checked="" type="checkbox"/>	<b>107</b>	Distortion	(2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021: 1 indentation 1 inch long x 1/2 inch deep at 18 foot-8 inch from interior. bent 3 . scattered scrapes along the web .	2	1 Feet

**General Comments**

**Span 3 Beam 11**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	58	51	7	0	0	Feet
515	Steel Protective Coating	547	546	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 107	Corrosion	at bent 3, top flange, surface rust/rust scale (1 foot)	2	1		Feet
<input checked="" type="checkbox"/> 107	Damage	repaired impact damage	2			Feet
<input checked="" type="checkbox"/> 107	Distortion	2023 new repair (beam heat straightened and coverplate rewelded); previously noted as: SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021 area of previous impact damage, distortion of bottom flange vertical up to 2 inch lateral up to 1/2 inch with broken cover plate weld [10 inch long]. new area of impact damage 6 inch long x 2 inch high at 13 foot-5 inch out from interior. bent 3 . with the bottom cover plate being broken loose from bottom flange 10 inch long x 2 inch deep . there are also two older 1/2 inch indentions in the same area . Beam 11 is swept westward up to 1 1/2 inch. (par) there is a 2 inch diameter torch cut hole at both ends of the 6 foot length .	2	6		Feet
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust/rust scale	4	1		1 Square Feet

**General Comments**

**Span 3 Expansion Joint at Bent 2**  
**Standard Joint**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
301	Pourable Joint Seal	77	71	0	6	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 301	Seal Adhesion	along the length of the joint, adhesion loss (up to 1/8 inch wide x 2.5 foot x 3/4 inch deep) at random	3	6		Feet

**General Comments**

**Span 3 Wearing Surface**  
**Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
510	Wearing Surface	3,910	2,910	0	1,000	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 510	Crack (Wearing Surface)	throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/16 inch x 8 foot)	3	1,000	1,000	Square Feet

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x 5 foot long transverse and longitudinal cracks, scattered, in left shoulder.	1			Square Feet
<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x 5 foot long transverse and longitudinal cracks, scattered, in right shoulder.	1			Square Feet

**General Comments**

**Span 3 Left Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
333	Other Bridge Railing	58	45	13	0	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
<input checked="" type="checkbox"/>	333	Cracking		along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	13	Feet

**General Comments**

**Span 3 Right Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
333	Other Bridge Railing	58	49	9	0	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
<input checked="" type="checkbox"/>	333	Cracking		adjacent to rail post 6, hairline map cracking	2	3	Feet
<input checked="" type="checkbox"/>	333	Cracking		along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	6	Feet

**General Comments**

**Span 3 Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
<input checked="" type="checkbox"/>	316	Corrosion		active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1 Each
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)		corrosion with section loss	4	1	1 Square Feet

**General Comments**

**Span 3 Far Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1 Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1 Square Feet

General Comments

**Span 3 Near Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining	3	1	1 Each
<input checked="" type="checkbox"/> 316	Loss of Bearing Area	(PAR) loss of bearing area (up to 1/2 inch x 3 inch)	2		1 Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1 Square Feet

General Comments

**Span 3 Far Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	1	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	corrosion has been arrested when painted, 75 percent section remaining in masonry and sole plate. west anchor bolt has 25 percent section remaining, no nut present	3	1	1 Each

General Comments

**Span 3 Near Bearing 6**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	active corrosion and section loss in sole and masonry plates. 80 percent section remaining.	3	1	1	Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1	Square Feet

**General Comments**

**Span 3 Far Bearing 6**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	1	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	corrosion has been arrested when painted, 75 percent section remaining in masonry and sole plate. west anchor bolt nut has 20 percent section remaining	3	1	1	Each

**General Comments**

**Span 3 Near Bearing 7**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	0	1	Each
515	Steel Protective Coating	1	1	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Connection	(PAR) east weld between sole and bottom flange plate, broken	4	1	1	Each
<input checked="" type="checkbox"/> 316	Corrosion	arrested pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3		1	Each

**General Comments**

**Span 3 Far Bearing 7**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

Structure Number: 110173

Inspection Date: 10/25/2023

<input checked="" type="checkbox"/>	316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1	Each
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1	Square Feet

**General Comments**

**Span 3 Near Bearing 8**

**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	316	Corrosion				1 Each
		active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1		
<input checked="" type="checkbox"/>	515	Effectiveness (Steel Protective Coatings)				1 Square Feet
		corrosion with section loss	4	1		

**General Comments**

**Span 3 Far Bearing 8**

**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	1	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	316	Corrosion				1 Each
		corrosion has been arrested when painted, up to 75 percent section remaining in masonry and sole plate. west anchor bolt nut has up to 80 percent section remaining.	3	1		

**General Comments**

**Span 4 Deck**

**Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	2,975	1,973	0	1,002	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	12	Cracking (RC and Other)				1,000 Square Feet
		throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) some with efflorescence at random	3	1,000		
<input checked="" type="checkbox"/>	12	Delamination/Spall				2 Square Feet
		2 foot long x 6 inch wide x up to 1/2 inch deep area of delamination/spall in deck underside of bay 10, 15 foot from end bent 2.	3	2		
<input checked="" type="checkbox"/>	12	Cracking (RC and Other)				Square Feet
		(combined with other notes 2023) three (3) up to 1/16 inch wide full width transverse cracks in underside of deck in bay 2, scattered.	1			

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>12</b>	Cracking (RC and Other)	(combined with other notes 2023) up to 1/16 inch wide full width transverse crack in deck underside, bay 6, at the intermediate diaphragm.	1			Square Feet
<input checked="" type="checkbox"/>	<b>12</b>	Cracking (RC and Other)	2 - up to 1/16 inch wide full width transverse cracks in underside of deck in bay 1, scattered.	1			Square Feet
<input checked="" type="checkbox"/>	<b>12</b>	Cracking (RC and Other)	multiple up to 1/16 inch wide full width transverse cracks in underside of deck in bay 3 scattered, some with efflorescence	1			Square Feet
<input checked="" type="checkbox"/>	<b>12</b>	Efflorescence/Rust Staining	(combined with other notes 2023) hairline full width transverse crack with light efflorescence in underside of deck in bay 8, 10 foot from end bent 2.	1			Square Feet

**General Comments**

**Span 4 Beam 4 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	43	37	0	0	6 Feet
515	Steel Protective Coating	405	405	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion		6	6 Feet
		(PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 5.5 foot x 10 inch) with corrosion holes (up to 1 inch x 1/2 inch); bottom flange (0.45 inch average remaining x 4 foot)	4		
<input checked="" type="checkbox"/>	<b>107</b>	Damage			1 Feet
		7 foot long x 8 inch wide x 4 inch along north face and 8 in along bottom face area of delamination and unsound concrete in end diaphragm at bent 3 between beams 4 and 5.	3		
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion			Feet
		(combined with other notes 2023) 2 foot long from beam end x full flange width x 0.24 inch remaining in bottom flange, at bent 3. no active corrosion present.	1		

**General Comments**

**Span 4 Beam 5 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	43	37	0	1	5 Feet
515	Steel Protective Coating	405	404	0	1	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion		5	5 Feet
		(PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 6 foot x 1 foot) with corrosion holes (6 inch x 1.5 inch); bottom flange (0.56 inch average remaining x 15 inch) with corrosion reinitiated	4		
<input checked="" type="checkbox"/>	<b>107</b>	Damage			1 Feet
		4 foot x 6 inch long x 8 inch wide x 5 inch along north and bottom faces area of delamination and unsound concrete in end diaphragm at bent 3 between beams 5 and 6.	3	1	

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(combined with other notes 2023) active corrosion with section loss 8 inch long from beam end x full flange width x 3/8 inch section remaining in bottom flange, at bent 3	1			1	Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	1		1	Square Feet

**General Comments**

**Span 4 Beam 6 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	43	39	0	0	4 Feet
515	Steel Protective Coating	405	404	0	1	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 32 inch x 12 inch) with corrosion reinitiated	4	4	4 Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	32 inch long x 10 inch wide x 5 inch along north and bottom faces area of delamination and unsound concrete in end diaphragm at bent 3 between beams 6 and 7.	3		1 Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	1	1 Square Feet

**General Comments**

**Span 4 Beam 7 Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	43	35	0	0	8 Feet
515	Steel Protective Coating	405	397	0	8	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 8 foot x 12 inch) with corrosion holes (up to 1/4 inch diameter); bottom flange (0.45 inch average remaining x 26 inch) with corrosion reinitiated	4	8	8 Feet
<input checked="" type="checkbox"/>	<b>107</b>	Corrosion	(combined with other notes 2023) active corrosion with section loss 28 inch long x full flange width x 0.34 inch remaining thickness in bottom flange, starting at beam end.	1		Feet
<input checked="" type="checkbox"/>	<b>107</b>	Damage	(combined with beam 8 notes 2023) 6 foot x 1 foot x 3 inch deep spall with exposed reinforcement, 75 percent remaining on north bottom corner of end diaphragm at bent 3	1		Feet
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)	surface rust	3	8	8 Square Feet

**General Comments**



**Span 4****Beam 8****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	43	39	0	0	4 Feet
515	Steel Protective Coating	405	401	0	4	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 107	Corrosion	(PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 34 inch x 12 inch) with corrosion hole (10 inch x 3 inch); bottom flange (0.50 inch average remaining x 34 inch) with corrosion reinitiated	4	4	4 Feet
<input checked="" type="checkbox"/> 107	Damage	(PAR) 7 foot long x 1.5 foot wide x 3 inch deep spall with exposed reinforcement in end diaphragm between beams 7 and 8 at bent 3. 60 percent section remaining in exposed reinforcement.	4		Feet
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	surface rust	3	4	4 Square Feet

**General Comments****Span 4****Expansion Joint at Bent 3****Standard Joint**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
301	Pourable Joint Seal	77	65	0	12	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 301	Seal Damage	along the length of the joint, adhesion loss (up to 3/4 inch wide x 7 foot x 1.5 inch deep) at random	3	12	12 Feet

**General Comments****Span 4****Wearing Surface****Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
510	Wearing Surface	2,890	1,890	0	1,000	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 510	Crack (Wearing Surface)	throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/8 inch x 40 foot)	3	1,000	1,000 Square Feet
<input checked="" type="checkbox"/> 510	Crack (Wearing Surface)	(combined with other notes 2023) at both shoulders at end bent 2, transverse cracks [up to 2 foot x up to 3/4 inch wide] with vegetation and debris accumulation	1		Square Feet
<input checked="" type="checkbox"/> 510	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x 5 foot long transverse and longitudinal cracks, scattered, in left shoulder.	1		Square Feet
<input checked="" type="checkbox"/> 510	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x 6 foot long transverse and longitudinal cracks, scattered, in right shoulder.	1		Square Feet

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch wide x up to 5 foot long transverse and longitudinal cracks, scattered, in southbound left lane.	1			Square Feet
<input checked="" type="checkbox"/>	<b>510</b>	Crack (Wearing Surface)	(combined with other notes 2023) multiple up to 1/8 inch x 2 foot long transverse and longitudinal cracks, scattered, in northbound left lane.	1			Square Feet

**General Comments**

**Span 4 Left Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
333	Other Bridge Railing	43	33	8	2	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>333</b>	Delamination/Spall				2 Feet
		at end bent 2, (2) spalls (up to 5 inch x 4 inch x 1.5 inch deep) exposed reinforcement. no measureable section loss.	3	2		
<input checked="" type="checkbox"/>	<b>333</b>	Cracking				Feet
		along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	8		
<input checked="" type="checkbox"/>	<b>333</b>	Damage				Feet
		(2023 moved to general notes) guardrail at northwest end terminal has been fixed since last inspection. wood posts and spacer blocks have been replaced	1			

**General Comments**

**Span 4 Right Bridge Rail**  
**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
333	Other Bridge Railing	43	37	6	0	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>333</b>	Cracking				Feet
		along the length of parapet, vertical cracks (up to 1/32 x full height) at random	2	6		

**General Comments**

**Span 4 Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>316</b>	Corrosion				1 Each
		active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1		
<input checked="" type="checkbox"/>	<b>515</b>	Effectiveness (Steel Protective Coatings)				1 Square Feet
		corrosion with section loss	4	1		

**General Comments**

**Span 4 Near Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1	Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1	Square Feet

**General Comments**

**Span 4 Near Bearing 6**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.	3	1	1	Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1	Square Feet

**General Comments**

**Span 4 Near Bearing 7**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 316	Corrosion	active corrosion and section loss in masonry plate and sole plate. 80 percent section remaining. both anchor bolt nuts have up to 40 percent section remaining	3	1	1	Each
<input checked="" type="checkbox"/> 515	Effectiveness (Steel Protective Coatings)	corrosion with section loss	4	1	1	Square Feet

**General Comments**

**Span 4****Near Bearing 8****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	1	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 316	Corrosion	corrosion has been arrested when painted, 75 percent section remaining in masonry plate and sole plate. both anchor bolt nuts have up to 50 percent section remaining.	3	1	1 Each

**General Comments****End Bent 1****Abutment****Reinforced Concrete Abutment**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
215	Reinforced Concrete Abutment	74	63	0	11	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 215	Delamination/Spall	along the length of the abutment, adjacent to beam bottom flanges, spall/delaminations (up to 9 inch x 4 inch x 4 inch deep) with cracks (up to 1/8 inch)	3	11	11 Feet
<input checked="" type="checkbox"/> 215	Cracking (RC and Other)	(combined with other notes 2023) up to 1/8 inch wide x 9 inch long crack in backwall at beam 4, bay 3.	1		Feet
<input checked="" type="checkbox"/> 215	Cracking (RC and Other)	(combined with other notes 2023) up to 1/8 inch wide x 9 inch long crack in backwall at beam 5, bay 4.	1		Feet
<input checked="" type="checkbox"/> 215	Cracking (RC and Other)	(combined with other notes 2023) up to 1/8 inch wide x 9 inch long crack in backwall at beam 6, bay 5.	1		Feet
<input checked="" type="checkbox"/> 215	Delamination/Spall	(combined with other notes 2023) 16 inch long x 4 inch high x up to 4 inch deep spall in backwall at beam 7, bay 6.	1		Feet

**General Comments****End Bent 1****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	82	59	22	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 234	Delamination/Spall	11 inch high x 7 inch wide x up to 1 inch deep spall with exposed rusted rebar in north face of cap at beam 4.	3	1	1 Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	scattered along length of cap, multiple vertical cracks [15 inch long x up to 1/32 inch]	2	20	Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	west end, map cracks (hairline x 1.5 foot x full height)	2	2	Feet

**General Comments**

**Bent 1****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	76	34	0	42	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	15 foot long x 12 inch delamination with cracks up to 1/8 inch between beams 5 and 7 on south face of the cap.	3	15	15 Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	5 foot long x 21 inch high area of delaminated concrete with cracks up to 1/16 inch between beams 7 and 8 in the north face of cap near top.	3	5	5 Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	5 foot x full width delamination with cracks up to 1/16 inch in the underside of the cap between columns 4 and 5. 1/16 inch wide vertical crack in the north face of the cap between columns 4 and 5.	3	5	5 Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	north face, below beam 5, delamination/spall [4 foot x 1 foot x 1/2 inch]	3	4	4 Feet
<input checked="" type="checkbox"/> 234	Delamination/Spall	1 foot long x full width of cap area of delaminated concrete with cracks up to 1/8 inch extends 1 foot into north face between columns 5 and 6.	3	1	1 Feet
<input checked="" type="checkbox"/> 234	Delamination/Spall	35 inch long x 16 inch high x up to 1.5 inch deep area of delamination and spall in north face at beam 4 with exposed reinforcement. no measurable section loss.	3	3	3 Feet
<input checked="" type="checkbox"/> 234	Exposed Rebar	(PAR) South and top face between beams 7 and 8, spall/delamination [4.5 foot x up to 3.5 foot x up to 4 inch deep] with 4 vertical and 1 horizontal exposed rusted reinforcing with up to 1/16 inch section loss. no loss of bearing area	3	9	9 Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	north face, under beam 6, horizontal crack [19 inch x 1/32 inch]	2		Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	(combined with other notes 2023) up to 1/2 inch wide crack on underside of cap at the construction joint	1		Feet

**General Comments**

**Bent 1****Pile 3****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 205	Delamination/Spall	(PAR) 34 inch high x 10 inch wide x up to 2 inch deep spall with exposed rusted reinforcement.	3	1	1 Each

**General Comments**

**Bent 1****Pile 4****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 205	Cracking (RC and Other)	North face at top of the column, delamination [31 inch x 10 inch wide] with cracks [up to 1/8 inch]	3	1	1 Each

General Comments

**End Bent 2****Abutment****Reinforced Concrete Abutment**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
215	Reinforced Concrete Abutment	74	68	0	6	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 215	Cracking (RC and Other)	(2023 unable to verify due to homeless encampment) up to 1/8 inch wide x 9 inch long crack in backwall at beam 3, bay 2. similar condition at beam 4-8.	3	6	6 Feet

General Comments

**End Bent 2****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	82	42	40	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	(2023 unable to verify due to homeless encampment) multiple vertical cracks [up to 15 inch x up to 1/32 inch wide] scattered along cap	2	25	Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	(2023 unable to verify due to homeless encampment) scattered areas of hairline map cracking along face of cap	2	15	Feet

General Comments

**Bent 2****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	76	32	8	28	8 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
<input checked="" type="checkbox"/> 234	Exposed Rebar	(PAR) south face, in bay 6, spall/delamination (8 foot x 4 foot x 1.5 inch deep) with exposed rusted rebar (approximately 75 percent remaining) and cracks (up to 1/16 inch)	4	8	8 Feet
<input checked="" type="checkbox"/> 234	Cracking (RC and Other)	10 foot x 1/16 inch horizontal crack in north face of cap under bays 5 and 6	3	10	10 Feet

Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	4 foot long x 18 inch x 1 inch high spall/delamination concrete in south face near the top between beams 7 and 8.	3	4	4	Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	4 foot x up to 20 inch x 1 inch deep high area of delaminated concrete in south face between beams 4 and 5.	3	4	4	Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	under beam 5, spall [14 inch x 4 inch x 1 inch deep] with coarse aggregate exposed, undermining bearing 1/2 inch	3	1	1	Feet
<input checked="" type="checkbox"/>	<b>234</b>	Exposed Rebar	(PAR) (3) up to 1.5 foot x 1 foot wide x 1/2 inch deep spall with exposed rusted reinforcement, 80 percent remaining on underside of cap between columns 5 and 6	3	2	2	Feet
<input checked="" type="checkbox"/>	<b>234</b>	Exposed Rebar	(PAR) south face, below beam 4, spall/delamination (18 inch x 38 inch x 1.5 inch deep) with exposed and debonded rebar	3	2	2	Feet
<input checked="" type="checkbox"/>	<b>234</b>	Exposed Rebar	[PAR] bottom face of cap between columns 4 and 5, spall/delamination [5 foot long x full width x up to 3 inch deep] with seven exposed rusted reinforcing with 80 percent remaining	3	5	5	Feet
<input checked="" type="checkbox"/>	<b>234</b>	Cracking (RC and Other)	4 foot long x 1/32 inch wide horizontal crack on north face of cap under beam 7	2	4		Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	between columns 3 and 4, 4 foot long x full width delamination in the bottom face extending into vertical faces of concrete	2	4	4	Feet
<input checked="" type="checkbox"/>	<b>234</b>	Cracking (RC and Other)	(combined with other notes 2023) 4 foot long longitudinal hairline cracks in south face near top of cap between beams 6 and 7.	1			Feet
<input checked="" type="checkbox"/>	<b>234</b>	Exposed Rebar	(combined with other notes 2023) 1 foot long x 2 foot wide area of delaminated concrete with exposed reinforcement. no measurable section loss in the exposed reinforcement.	1			Feet

**General Comments**

**Bent 2 Pile 3**

**Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>205</b>	Exposed Rebar	(PAR) Southeast corner 5 foot from the ground, delamination/spall [28 inch wide x 9.5 foot x up to 4 inch deep] with [1] primary exposed rusted reinforcing [75 percent remaining]	4	1	1 Each
<input checked="" type="checkbox"/>	<b>205</b>	Delamination/Spall	southwest corner, below cap, spall/delamination (36 inch x 10 inch x 1 inch deep)	3		1 Each

**General Comments**

**Bent 2 Pile 4**  
**Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
205	Reinforced Concrete Column	1	0	0	1	0	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 205	Cracking (RC and Other)	below cap, northeast and southeast corners, (2) delaminations (up to 3.5 foot x 10 inch) with cracks (1/4 inch)	3		1	Each
<input checked="" type="checkbox"/> 205	Delamination/Spall	(PAR) north face, at ground, spall/delamination (full width x 7.5 foot high x 3 inch deep) extends into east and west faces (up to 7 inch) with exposed rusted and debonded rebars	3	1	1	Each

General Comments

**Bent 2 Pile 5**  
**Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
205	Reinforced Concrete Column	1	0	0	0	1	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 205	Exposed Rebar	(PAR) Southwest corner below cap, delamination/spall [7 foot high x up to full width x up to 3 inch deep] with two exposed rusted reinforcing, 70 percent section remaining in the exposed reinforcement.	4	1	1	Each
<input checked="" type="checkbox"/> 205	Delamination/Spall	3 foot from ground, west and south faces, (2) spalls/delaminations (up to 1 foot x 19 inch x 1.5 inch deep) with exposed rusted rebar	3		1	Each

General Comments

**Bent 2 Pile 7**  
**Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
205	Reinforced Concrete Column	1	0	1	0	0	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 205	Cracking (RC and Other)	north and west faces, map cracks (hairline x 1 foot x full width)	2	1		Each

General Comments

**Bent 3 Cap 1**  
**Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
234	Reinforced Concrete Pier Cap	76	46	6	24	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--



Structure Number: **110173**

Inspection Date: **10/25/2023**

<input checked="" type="checkbox"/>	<b>234</b>	Cracking (RC and Other)	4 foot long x 8 inch high area of up to 1/16 inch wide cracks and delamination on north face under bay 5	3	4	4 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Cracking (RC and Other)	North face under bay 7, delamination 6 foot long x up to 1 foot x 4 inch x 1 inch deep in and has up to 1/8 inch wide cracks	3	6	6 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Cracking (RC and Other)	south face, in bays 4 and 5, multiple spalls/delaminations (up to 5 foot x 2 foot x 1.5 inch deep) with exposed rusted rebar	3	10	10 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	10 inch x 5 inch x 1 inch deep spall with exposed reinforcement in south face between beams 6 and 7. 90 percent section remaining in exposed reinforcement.	3	1	1 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	12 inch high x 9 inch wide x 1.5 inch deep with exposed reinforcement under beam 7, south face. 90 percent section remaining in exposed reinforcement.	3	1	1 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	12 inch x 4 inch x 1/2 inch deep spall with exposed reinforcement on east face of top radius at pile 5	3	1	1 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	North face under beam 4, spall [1 foot x 6 inch x 1/2 inch deep] no undermining	3	1	1 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	5 foot x up to full height area of cracked delamination on south face of cap below beam 8	2	6	6 Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	(combined with other notes 2023) 3 foot long x 1 foot high area of delaminated concrete in south face between beams 5 and 6.	1		Feet
<input checked="" type="checkbox"/>	<b>234</b>	Delamination/Spall	(combined with other notes 2023) bottom of South face below bay 5, spall [14 inch x 10 inch x up to 1 inch deep] with exposed rusted reinforcing 90 percent remaining	1		Feet

**General Comments**

**Bent 3**

**Pile 3**

**Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/>	<b>205</b>	Exposed Rebar	(PAR) Southeast corner above barrier rail, spall/delamination [10 foot high x up to full width x up to 4 inch deep] with primary debonded exposed rusted reinforcing 75 percent remaining	4	1	1 Each
<input checked="" type="checkbox"/>	<b>205</b>	Delamination/Spall	east face 12 inch high x 6 inch wide x 1 inch deep spall with exposed reinforcement	3		1 Each
<input checked="" type="checkbox"/>	<b>205</b>	Delamination/Spall	3 foot high x 10 inch wide area of delamination and unsound concrete in north face. up to 43 inch high x 19 inch wide area of delamination and unsound concrete in east face.	2		1 Each
<input checked="" type="checkbox"/>	<b>205</b>	Delamination/Spall	4 foot high x 12 inch wide area of delamination and unsound concrete in north face. similar condition in west face.	2		1 Each

**General Comments**

**Bent 3****Pile 4****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
205	Reinforced Concrete Column	1	0	1	0	0	Each

---

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 205	Delamination/Spall	29 inch wide x height varying from 18 inch to 45 inch area of delamination on west face. 3 foot high x 12 inch wide area of delamination in south face. 3 foot high x 12 inch wide area of delamination in north face.	2		3	Each
<input checked="" type="checkbox"/> 205	Delamination/Spall	3 foot high x 10 inch wide area of delamination and unsound concrete at southeast corner.	2		1	Each
<input checked="" type="checkbox"/> 205	Delamination/Spall	3 foot high x 12 inch wide area of delamination and unsound concrete at northeast corner.	2	1	1	Each

**General Comments****Bent 3****Pile 5****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
205	Reinforced Concrete Column	1	0	0	1	0	Each

---

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
<input checked="" type="checkbox"/> 205	Delamination/Spall	4 foot high x 16 inch wide area of delamination/spall and unsound concrete at northeast corner.	3		1	Each
<input checked="" type="checkbox"/> 205	Exposed Rebar	(PAR) 6.5 foot high x 20 inch wide x 3.5 inch deep spall and delaminated concrete with one debonded primary exposed reinforcement on south east corner of pile. 80 percent section remaining in exposed reinforcement.	3	1	1	Each
<input checked="" type="checkbox"/> 205	Exposed Rebar	(combined with other notes 2023) underside of corbel, 12 inch long x 3 inch wide x 1/2 inch deep spall with exposed reinforcement. 90 percent section remaining in exposed reinforcement.	1			Each

**General Comments**

## Elements Verified

Location	Name	Component	Element Name	Amount
Span 1	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	3430
Span 1	Beam 1	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 2	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 3	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 4	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 5	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 6	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 7	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 8	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 9	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 10	Plate Girder	Steel Open Girder/Beam	49
Span 1	Beam 11	Plate Girder	Steel Open Girder/Beam	49
Span 1	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	49
Span 1	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	49
Span 1	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	3332
Span 1	Near Bearing 1	Other Bearing	Other Bearings	1
Span 1	Far Bearing 1	Other Bearing	Other Bearings	1
Span 1	Near Bearing 2	Other Bearing	Other Bearings	1
Span 1	Far Bearing 2	Other Bearing	Other Bearings	1
Span 1	Far Bearing 3	Other Bearing	Other Bearings	1
Span 1	Near Bearing 3	Other Bearing	Other Bearings	1
Span 1	Near Bearing 4	Other Bearing	Other Bearings	1
Span 1	Far Bearing 4	Other Bearing	Other Bearings	1
Span 1	Far Bearing 5	Other Bearing	Other Bearings	1
Span 1	Near Bearing 5	Other Bearing	Other Bearings	1
Span 1	Near Bearing 6	Other Bearing	Other Bearings	1
Span 1	Far Bearing 6	Other Bearing	Other Bearings	1
Span 1	Far Bearing 7	Other Bearing	Other Bearings	1
Span 1	Near Bearing 7	Other Bearing	Other Bearings	1
Span 1	Near Bearing 8	Other Bearing	Other Bearings	1
Span 1	Far Bearing 8	Other Bearing	Other Bearings	1
Span 1	Far Bearing 9	Other Bearing	Other Bearings	1
Span 1	Near Bearing 9	Other Bearing	Other Bearings	1
Span 1	Far Bearing 10	Other Bearing	Other Bearings	1
Span 1	Near Bearing 10	Other Bearing	Other Bearings	1
Span 1	Near Bearing 11	Other Bearing	Other Bearings	1
Span 1	Far Bearing 11	Other Bearing	Other Bearings	1
Span 2	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	4025
Span 2	Beam 1	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 2	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 3	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 4	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 5	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 6	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 7	Plate Girder	Steel Open Girder/Beam	58

## Elements Verified

Location	Name	Component	Element Name	Amount
Span 2	Beam 8	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 9	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 10	Plate Girder	Steel Open Girder/Beam	58
Span 2	Beam 11	Plate Girder	Steel Open Girder/Beam	58
Span 2	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	58
Span 2	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	58
Span 2	Expansion Joint at Bent 1	Standard Joint	Pourable Joint Seal	77
Span 2	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	3910
Span 2	Near Bearing 1	Other Bearing	Other Bearings	1
Span 2	Far Bearing 1	Other Bearing	Other Bearings	1
Span 2	Far Bearing 2	Other Bearing	Other Bearings	1
Span 2	Near Bearing 2	Other Bearing	Other Bearings	1
Span 2	Near Bearing 3	Other Bearing	Other Bearings	1
Span 2	Far Bearing 3	Other Bearing	Other Bearings	1
Span 2	Far Bearing 4	Other Bearing	Other Bearings	1
Span 2	Near Bearing 4	Other Bearing	Other Bearings	1
Span 2	Near Bearing 5	Other Bearing	Other Bearings	1
Span 2	Far Bearing 5	Other Bearing	Other Bearings	1
Span 2	Far Bearing 6	Other Bearing	Other Bearings	1
Span 2	Near Bearing 6	Other Bearing	Other Bearings	1
Span 2	Near Bearing 7	Other Bearing	Other Bearings	1
Span 2	Far Bearing 7	Other Bearing	Other Bearings	1
Span 2	Far Bearing 8	Other Bearing	Other Bearings	1
Span 2	Near Bearing 8	Other Bearing	Other Bearings	1
Span 2	Near Bearing 9	Other Bearing	Other Bearings	1
Span 2	Far Bearing 9	Other Bearing	Other Bearings	1
Span 2	Far Bearing 10	Other Bearing	Other Bearings	1
Span 2	Near Bearing 10	Other Bearing	Other Bearings	1
Span 2	Near Bearing 11	Other Bearing	Other Bearings	1
Span 2	Far Bearing 11	Other Bearing	Other Bearings	1
Span 3	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	4025
Span 3	Beam 1	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 2	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 3	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 4	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 5	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 6	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 7	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 8	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 9	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 10	Plate Girder	Steel Open Girder/Beam	58
Span 3	Beam 11	Plate Girder	Steel Open Girder/Beam	58
Span 3	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	58
Span 3	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	58
Span 3	Expansion Joint at Bent 2	Standard Joint	Pourable Joint Seal	77

## Elements Verified

Location	Name	Component	Element Name	Amount
Span 3	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	3910
Span 3	Far Bearing 1	Other Bearing	Other Bearings	1
Span 3	Near Bearing 1	Other Bearing	Other Bearings	1
Span 3	Far Bearing 2	Other Bearing	Other Bearings	1
Span 3	Near Bearing 2	Other Bearing	Other Bearings	1
Span 3	Near Bearing 3	Other Bearing	Other Bearings	1
Span 3	Far Bearing 3	Other Bearing	Other Bearings	1
Span 3	Far Bearing 4	Other Bearing	Other Bearings	1
Span 3	Near Bearing 4	Other Bearing	Other Bearings	1
Span 3	Near Bearing 5	Other Bearing	Other Bearings	1
Span 3	Far Bearing 5	Other Bearing	Other Bearings	1
Span 3	Far Bearing 6	Other Bearing	Other Bearings	1
Span 3	Near Bearing 6	Other Bearing	Other Bearings	1
Span 3	Near Bearing 7	Other Bearing	Other Bearings	1
Span 3	Far Bearing 7	Other Bearing	Other Bearings	1
Span 3	Far Bearing 8	Other Bearing	Other Bearings	1
Span 3	Near Bearing 8	Other Bearing	Other Bearings	1
Span 3	Near Bearing 9	Other Bearing	Other Bearings	1
Span 3	Far Bearing 9	Other Bearing	Other Bearings	1
Span 3	Near Bearing 10	Other Bearing	Other Bearings	1
Span 3	Far Bearing 10	Other Bearing	Other Bearings	1
Span 3	Far Bearing 11	Other Bearing	Other Bearings	1
Span 3	Near Bearing 11	Other Bearing	Other Bearings	1
Span 4	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	2975
Span 4	Beam 1	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 2	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 3	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 4	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 5	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 6	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 7	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 8	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 9	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 10	Plate Girder	Steel Open Girder/Beam	43
Span 4	Beam 11	Plate Girder	Steel Open Girder/Beam	43
Span 4	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	43
Span 4	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	43
Span 4	Expansion Joint at Bent 3	Standard Joint	Pourable Joint Seal	77
Span 4	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	2890
Span 4	Near Bearing 1	Other Bearing	Other Bearings	1
Span 4	Far Bearing 1	Other Bearing	Other Bearings	1
Span 4	Far Bearing 2	Other Bearing	Other Bearings	1
Span 4	Near Bearing 2	Other Bearing	Other Bearings	1
Span 4	Near Bearing 3	Other Bearing	Other Bearings	1
Span 4	Far Bearing 3	Other Bearing	Other Bearings	1

## Elements Verified

Location	Name	Component	Element Name	Amount
Span 4	Far Bearing 4	Other Bearing	Other Bearings	1
Span 4	Near Bearing 4	Other Bearing	Other Bearings	1
Span 4	Near Bearing 5	Other Bearing	Other Bearings	1
Span 4	Far Bearing 5	Other Bearing	Other Bearings	1
Span 4	Far Bearing 6	Other Bearing	Other Bearings	1
Span 4	Near Bearing 6	Other Bearing	Other Bearings	1
Span 4	Near Bearing 7	Other Bearing	Other Bearings	1
Span 4	Far Bearing 7	Other Bearing	Other Bearings	1
Span 4	Far Bearing 8	Other Bearing	Other Bearings	1
Span 4	Near Bearing 8	Other Bearing	Other Bearings	1
Span 4	Near Bearin 9	Other Bearing	Other Bearings	1
Span 4	Far Bearing 9	Other Bearing	Other Bearings	1
Span 4	Far Bearing 10	Other Bearing	Other Bearings	1
Span 4	Near Bearing 10	Other Bearing	Other Bearings	1
Span 4	Near Bearing 11	Other Bearing	Other Bearings	1
Span 4	Far Bearing 11	Other Bearing	Other Bearings	1
Bent 1	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	76
Bent 1	Pile 1	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 1	Pile 2	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 1	Pile 3	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 1	Pile 4	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 1	Pile 5	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 1	Pile 6	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 1	Pile 7	Reinforced Concrete Column	Reinforced Concrete Column	1
End Bent 1	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	82
End Bent 1	Abutment	Reinforced Concrete Abutment	Reinforced Concrete Abutment	74
Bent 2	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	76
Bent 2	Pile 1	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 2	Pile 2	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 2	Pile 3	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 2	Pile 4	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 2	Pile 5	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 2	Pile 6	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 2	Pile 7	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	76
Bent 3	Pile 1	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Pile 2	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Pile 3	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Pile 4	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Pile 5	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Pile 6	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Pile 7	Reinforced Concrete Column	Reinforced Concrete Column	1

# General Inspection Notes

# National Bridge and NC Inspection Items

Structure Number: 110173

Inspection Date: 10/25/2023

## National Bridge Inventory Items

Item	Grade Scale	Grade
Item 58: Deck	0 - 9 , N	5
Item 59: Superstructure	0 - 9 , N	4
Item 60: Substructure	0 - 9 , N	4
Item 61: Channel and Channel Protection	0 - 9 , N	N
Item 62: Culvert	0 - 9 , N	N
Item 71: Waterway Adequacy	0 - 9 , N	N
Item 72: Approach Roadway Alignment	0 - 9 , N	8

**Note:**  
Items 58,59,60,62 reflect this inspection only.  
  
For overall NBI coding grade, see cover sheet.

Note: If NBI Inspection Item is not present, code NBI item with "N"

## NC SMU Inspection Items

Item	Grade Scale	Grade	Maint. Qty.	Maint. Code
Deck Debris	G, F, P, or C	P	14455	3376
Drainage System	G, F, P, or C	P	0	3332
Utilities	G, F, P, or C			
Slope Protection	G, F, P, or C	G	0	3352
Scour	G, F, P, or C			
Wingwall	G, F, P, or C	G	0	3350
Field Scour Evaluation				
Drift	G, F, P, or C		0	3366
Fender System	G, F, P, or C		0	3364
Movable Span Machinery	G, F, P, or C			
Response to Live Load	G, F, P, or C	G		
Superstructure Paint Code		I		

Note: If NC SMU Inspection Item is not present, leave NC SMU item blank

## Inspection Information

Item	Grade Scale	Grade
Sign Noticed Issued	YES/NO	N
Priority Maintenance Request Submitted	YES/NO	Y
Inspection Time	Hours	16
Traffic Control Time	Hours	
Snooper Time	Hours	
Ladder Used	YES/NO	Y
Bucket Truck Used	YES/NO	N
Boat Used	YES/NO	N
Other Equipment Used	YES/NO	N
Portion of Structure in > 3' of water	YES/NO	N



# National Bridge and NC SMU Inspection Item Details

**Structure Number:** 110173

**Inspection Date:** 10/25/2023

<b>Item</b>	Superstructure - Item 59	<b>Grade</b>	4	<b>Maint Code</b>		<b>Qty.</b>	0
<b>Details</b>	superstructure rated 4 due to advanced corrosion with section loss with some corrosion holes at beam ends in all spans						
<b>Item</b>	Substructure - Item 60	<b>Grade</b>	4	<b>Maint Code</b>		<b>Qty.</b>	0
<b>Details</b>	substructure rated 4 due to delaminations and spalls with exposed rebar (rebar has up to 30 percent section loss)						
<b>Item</b>	Deck Debris	<b>Grade</b>	P	<b>Maint Code</b>	3376	<b>Qty.</b>	14455
<b>Details</b>	along both curblines, debris accumulation (1 foot wide x full length); partially obstructing deck drainage						
<b>Item</b>	Drainage System	<b>Grade</b>	P	<b>Maint Code</b>	3332	<b>Qty.</b>	0
<b>Details</b>	see deck debris						
<b>Item</b>	General Comments and Misc Items	<b>Grade</b>		<b>Maint Code</b>		<b>Qty.</b>	0
<b>Details</b>	(PAR) southeast guardrail, 3 foot from end bent 1, impact damage (9 foot) (PAR) southeast guardrail attachment, improper lap (PAR) northwest guardrail attachment, improper lap (PAR) northwest guardrail, 55 foot from end bent 2, impact damage (12.5 foot) (PAR) along end bent 1 slope protection, homeless debris (full length) inhibiting inspection access (PAR) along end bent 2 slope protection, homeless debris with inhabitants (full length) inhibiting inspection access guardrail at northwest end terminal has been fixed since last inspection. wood posts and spacer blocks have been replaced						



(PAR) southeast guardrail, 3 foot from end bent 1, impact damage (9 foot)



(PAR) southeast guardrail attachment, improper lap



Span 1 Wearing Surface: throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/16 inch x 8 foot)



Span 1 Wearing Surface: throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/16 inch x 8 foot)



Span 1 Wearing Surface: left shoulder of asphalt over end bent 1, pothole/broken asphalt [6 foot x 8 inch x up to 1 inch deep]



Span 1 Wearing Surface: 7 foot long x 16 foot wide x 1 inch deep failed/depresed patch in center of southbound lane near end bent 1



Span 1 Left Bridge Rail: (PAR) impact damage to rail bracket of fourth post



Span 2 Expansion Joint at Bent 1: southbound turn lane, missing seal material (2 foot x 9 inch x full depth)



Span 1 Left Bridge Rail: along the length of parapet, vertical cracks (up to 1/32 x full height) at random



along both curblines, debris accumulation (1 foot wide x full length); partially obstructing deck drainage



Span 2 Left Bridge Rail: (PAR) impact damage to left bridge rail at 3rd vertical post from bent 1. base plate is broken off along the weld and spalls under the base plate with two of four anchor bolts exposed. impact damage is above eastbound I-40 right travel lane. rail and post are intact



Span 2 Left Bridge Rail: (PAR) impact damage to left bridge rail at 3rd vertical post from bent 1. base plate is broken off along the weld and spalls under the base plate with two of four anchor bolts exposed. impact damage is above eastbound I-40 right travel lane. rail and post are intact





Span 2 Wearing Surface: throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/16 inch x 8 foot)



Span 2 Wearing Surface: at right Southbound lane adjacent to joint over bent 2, unsound patch/pothole [32 inch x 10 inch x full depth]



Span 3 Expansion Joint at Bent 2: along the length of the joint, adhesion loss (up to 1/8 inch wide x 2.5 foot x 3/4 inch deep) at random



Span 3 Expansion Joint at Bent 2: along the length of the joint, adhesion loss (up to 1/8 inch wide x 2.5 foot x 3/4 inch deep) at random



Span 3 Left Bridge Rail: along the length of parapet, vertical cracks (up to 1/32 x full height) at random



Span 3 Right Bridge Rail: adjacent to rail post 6, hairline map cracking



Span 4 Expansion Joint at Bent 3: along the length of the joint, adhesion loss (up to 3/4 inch wide x 7 foot x 1.5 inch deep) at random



Span 4 Expansion Joint at Bent 3: along the length of the joint, adhesion loss (up to 3/4 inch wide x 7 foot x 1.5 inch deep) at random



Span 4 Wearing Surface: throughout asphalt wearing surface, partially sealed transverse and longitudinal cracks (up to 1/8 inch x 40 foot)



Span 4 Left Bridge Rail: at end bent 2, (2) spalls (up to 5 inch x 4 inch x 1.5 inch deep) exposed reinforcement. no measureable section loss.



(PAR) northwest guardrail attachment, improper lap



(PAR) northwest guardrail, 55 foot from end bent 2, impact damage (12.5 foot)



(PAR) along end bent 2 slope protection, homeless debris with inhabitants (full length) inhibiting inspection access



End Bent 1 Cap 1: scattered along length of cap, multiple vertical cracks [15 inch long x up to 1/32 inch]



End Bent 1 Cap 1: 11 inch high x 7 inch wide x up to 1 inch deep spall with exposed rusted rebar in north face of cap at beam 4.



End Bent 1 Cap 1: west end, map cracks (hairline x 1.5 foot x full height)





Span 1 Near Bearing 2: surface rust/rust scale



End Bent 1 Abutment: along the length of the abutment, adjacent to beam bottom flanges, spall/delaminations (up to 9 inch x 4 inch x 4 inch deep) with cracks (up to 1/8 inch)



End Bent 1 Abutment: along the length of the abutment, adjacent to beam bottom flanges, spall/delaminations (up to 9 inch x 4 inch x 4 inch deep) with cracks (up to 1/8 inch)



Span 1 Deck: throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random



Span 1 Deck: throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random



Span 1 Deck: throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random



Span 1 Deck: (PAR) 6 inch diameter x 1/2 inch deep spall with exposed reinforcement in bay 4 near end bent 1



Span 1 Deck: (2) up to 2 foot wide x 12 inch long areas of delamination in deck underside, bay 3, near midspan.



Span 1 Deck: (2) up to 2 foot wide x 12 inch long areas of delamination in deck underside, bay 3, near midspan.



Span 1 Deck: (PAR) 6 inch diameter x 1 inch deep spall with exposed reinforcement. no measurable section loss. 18 inch long x 12 inch wide area of delamination along beam 8 top flange, in bay 7, at midspan.



Span 1 Deck: left overhang, at bent 1, delamination (2 foot x 6 inch)



Span 1 Deck: underside of deck, bay 2, at end bent 1 and midspan, (2) delaminations (up to 3 foot x 1 foot)



Span 1 Deck: underside of deck, bay 2, at end bent 1 and midspan, (2) delaminations (up to 3 foot x 1 foot)



(PAR) along end bent 1 slope protection, homeless debris (full length) inhibiting inspection access



Span 2 Beam 3: (PAR) 10 inch long x up to 2 inch high x 5/16 inch section remaining in the web at beam end at bent 1, spot rust present



Span 1 Beam 4: (PAR) 8 inch long x full flange width x 0.55 inch remaining thickness in bottom flange with corrosion reactivating at bent 1





Span 1 Beam 4: at bent 1, painted over pitting up to 1/16 inch x 12 inch x 7 inch with corrosion reactivating



Span 1 Beam 4 - Far Bearing 4: arrested pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.



Span 2 Beam 4: (PAR) at bent 1, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 12 inch x 2.5 inch) with corrosion hole (6 inch x 1 inch); lower web (5/16 inch average remaining x 52 inch x 2 inch); bottom flange (0.55 inch average remaining x 10 inch) with corrosion reinitiated



Span 2 Beam 4: (PAR) at bent 1, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 12 inch x 2.5 inch) with corrosion hole (6 inch x 1 inch); lower web (5/16 inch average remaining x 52 inch x 2 inch); bottom flange (0.55 inch average remaining x 10 inch) with corrosion reinitiated



Span 2 Beam 4 - Near Bearing 4: active pack rust and section loss in masonry plate and sole plate. 75 percent section remaining



Bent 1 Cap 1: 35 inch long x 16 inch high x up to 1.5 inch deep area of delamination and spall in north face at beam 4 with exposed reinforcement. no measurable section loss.



Span 2 Beam 4: (PAR) 7 foot long x 4 inch high x 4 inch wide area of spall, delamination with exposed reinforcement in the concrete diaphragm between beams 4 and 5 at bent 1. 75 percent section remaining in the exposed reinforcement.



Span 1 Beam 5: (PAR) 10 inch long x 3 inch high x 3/16 inch average remaining in the web with 3 inch long x 1.5 inch corrosion hole under the diaphragm at bent 1



Span 2 Beam 5: (PAR) active corrosion with section loss 10 inch long x 3 inch high x 1/4 inch average remaining in the web with 3 inch long x 1.25 inch high corrosion hole under the diaphragm at bent 1



Bent 1 Cap 1: north face, below beam 5, delamination/spall [4 foot x 1 foot x 1/2 inch]



Span 2 Beam 5: (PAR) 7 foot long x 10 inch high x 3 inch wide area of spall, delamination with exposed reinforcement in the concrete diaphragm between beams 5 and 6 at bent 1. 70 percent section remaining in the exposed reinforcement



Span 2 Beam 6: (PAR) at bent 1, painted over section loss: web (1/4 inch average remaining x 54 inch x 13 inch); bottom flange (0.56 inch average remaining x 2 foot) with corrosion reinitiated



Span 1 Beam 6: (PAR) at bent 1, painted over section loss: web (1/4 inch average remaining x 3 foot x 8 inch); bottom flange (0.42 inch average remaining x 20 inch) with corrosion reinitiated





Span 1 Beam 6 - Far Bearing 6: active pack rust and section loss in masonry plate and sole plate. 80 percent section remaining. west anchor bolt nut 60 percent remaining.



Span 2 Beam 7: (PAR) at bent 1 active corrosion with section loss, web at diaphragm [20 inch long x 13 inch high x 1/4 inch average remaining] with multiple corrosion holes up to [3 inch x 1 inch]



Span 2 Beam 7: (PAR) 7 foot long x 4 inch high x 4 inch wide area of spalling, delamination with the exposed reinforcement in the concrete diaphragm between beams 7 and 8 at bent 1. 70 percent section remaining in the exposed reinforcement.



Span 1 Beam 7: (PAR) at bent 1 active corrosion with section loss, web at diaphragm [10 inch x 2 inch x 3/16 inch average remaining] with 1/2 inch diameter corrosion hole



Span 1 Beam 8: (PAR) 18 inch long x up to 8 inch x 1/4 inch average remaining area of section loss in web at bent 1, spot rust present.



Bent 1 Cap 1: 5 foot long x 21 inch high area of delaminated concrete with cracks up to 1/16 inch between beams 7 and 8 in the north face of cap near top.



Span 2 Beam 8: (PAR) at bent 1, painted over section loss: web (1/4 inch average remaining x 24 inch x 12 inch) with corrosion hole (3 inch x 1 inch); bottom flange (0.56 inch average remaining x 12 inch) with corrosion reinitiated



Span 2 Beam 8: (PAR) at bent 1, painted over section loss: web (1/4 inch average remaining x 24 inch x 12 inch) with corrosion hole (3 inch x 1 inch); bottom flange (0.56 inch average remaining x 12 inch) with corrosion reinitiated



Bent 1 Cap 1: 1 foot long x full width of cap area of delaminated concrete with cracks up to 1/8 inch extends 1 foot into north face between columns 5 and 6.



Bent 1 Pile 4: North face at top of the column, delamination [31 inch x 10 inch wide] with cracks [up to 1/8 inch]



Bent 1 Pile 3: (PAR) 34 inch high x 10 inch wide x up to 2 inch deep spall with exposed rusted reinforcement.



Bent 1 Cap 1: (PAR) South and top face between beams 7 and 8, spall/delamination [4.5 foot x up to 3.5 foot x up to 4 inch deep] with 4 vertical and 1 horizontal exposed rusted reinforcing with up to 1/16 inch section loss. no loss of bearing area



Bent 1 Cap 1: 5 foot x full width delamination with cracks up to 1/16 inch in the underside of the cap between columns 4 and 5. 1/16 inch wide vertical crack in the north face of the cap between columns 4 and 5.



Bent 1 Cap 1: 15 foot long x 12 inch delamination with cracks up to 1/8 inch between beams 5 and 7 on south face of the cap.





Span 2 Deck: throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random



Span 2 Deck: throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) at random



Bent 2 Pile 7: north and west faces, map cracks (hairline x 1 foot x full width)



Bent 2 Pile 5: 3 foot from ground, west and south faces, (2) spalls/delaminations (up to 1 foot x 19 inch x 1.5 inch deep) with exposed rusted rebar



Bent 2 Pile 5: (PAR) Southwest corner below cap, delamination/spall [7 foot high x up to full width x up to 3 inch deep] with two exposed rusted reinforcing, 70 percent section remaining in the exposed reinforcement.



Bent 2 Pile 4: below cap, northeast and southeast corners, (2) delaminations (up to 3.5 foot x 10 inch) with cracks (1/4 inch)



Bent 2 Pile 4: below cap, northeast and southeast corners, (2) delaminations (up to 3.5 foot x 10 inch) with cracks (1/4 inch)



Bent 2 Pile 4: (PAR) north face, at ground, spall/delamination (full width x 7.5 foot high x 3 inch deep) extends into east and west faces (up to 7 inch) with exposed rusted and debonded rebar



Bent 2 Pile 4: (PAR) north face, at ground, spall/delamination (full width x 7.5 foot high x 3 inch deep) extends into east and west faces (up to 7 inch) with exposed rusted and debonded rebars



Bent 2 Pile 3: southwest corner, below cap, spall/delamination (36 inch x 10 inch x 1 inch deep)



Bent 2 Pile 3: (PAR) Southeast corner 5 foot from the ground, delamination/spall [28 inch wide x 9.5 foot x up to 4 inch deep] with [1] primary exposed rusted reinforcing [75 percent remaining]



Span 3 Beam 1: at bent 2, web, rust scale (10 inch)



Span 2 Beam 4: (PAR) at bent 2, painted over section loss: bottom flange (0.60 inch average remaining x 2.5 foot), lower web (5/16 inch average remaining x 27 inch x 2 inch), web adjacent to diaphragm (1/4 inch average remaining x 11 inch x 3 inch) with corrosion reinitiated



Span 3 Beam 4: (PAR) at bent 2, painted over section loss: bottom flange (0.56 inch average remaining x 9 inch), lower web (3/16 inch average remaining x 6 foot x 2 inch), web adjacent to diaphragm (3/16 inch average remaining x 12 inch x 2 inch) with corrosion reinitiated





Bent 2 Cap 1: (PAR) south face, below beam 4, spall/delamination (18 inch x 38 inch x 1.5 inch deep) with exposed and debonded rebar



Span 2 Beam 5: (PAR) up to 4.5 foot long x 4 inch high x 3 inch deep spalls in south and bottom with exposed rusted reinforcement with up to 1/16 inch section loss, in the diaphragm between beams 4 and 5.



Span 2 Beam 5: (PAR) at bent 2, painted over section loss: bottom flange (0.50 inch average remaining x 8 inch); web adjacent to diaphragm (3/16 inch average remaining x 11 inch x 8 inch) with corrosion reinitiated



Span 2 Beam 5 - Far Bearing 5: painted over section loss (up to 1/8 inch loss) on masonry plate and sole plate



Span 3 Beam 5: (PAR) at bent 2, painted over section loss: bottom flange (0.60 inch average remaining x 3 foot); web (1/4 inch average remaining x 3 foot x 12 inch) with hole (1.5 inch x 1 inch) with corrosion reinitiated



Span 3 Beam 5: (PAR) at bent 2, painted over section loss: bottom flange (0.60 inch average remaining x 3 foot); web (1/4 inch average remaining x 3 foot x 12 inch) with hole (1.5 inch x 1 inch) with corrosion reinitiated



Bent 2 Cap 1: 4 foot x up to 20 inch x 1 inch deep high area of delaminated concrete in south face between beams 4 and 5.



Span 2 Beam 6: (PAR) at bent 2, painted over section loss: web adjacent to diaphragm (3/16 inch average remaining x 10.5 inch x 2.5 inch) with corrosion hole (1.5 inch x 1/2 inch); lower web (3/8 inch average remaining x 5.5 inch x 1 inch) with corrosion reinitiated




Span 2 Beam 6: (PAR) 7 foot x 16 inch x up to 3 inch deep spall with exposed reinforcement in the underside and south face of the diaphragm between beams 6 and 7. 70 percent section remaining in exposed reinforcement.



Span 3 Beam 6: (PAR) at bent 2, painted over section loss: web (1/4 inch average remaining x 3 foot x 1 foot) with corrosion hole (5 inch x 2 inch); bottom flange (0.60 inch average remaining x 2.5 foot) with corrosion reinitiated



Bent 2 Cap 1: (PAR) south face, in bay 6, spall/delamination (8 foot x 4 foot x 1.5 inch deep) with exposed rusted rebar (approximately 75 percent remaining) and cracks (up to 1/16 inch)



Span 2 Beam 7: (PAR) at bent 2, painted over section loss: bottom flange (0.50 inch average remaining x 8 inch); lower web (3/8 inch average remaining x 5 inch x 1 inch); web adjacent to diaphragm (3/16 inch average remaining x 10 inch x 3 inch)





Span 2 Beam 7: (PAR) 2 foot x 4 inch x 3 inch deep spall with exposed rusted and debonded reinforcement on south face of end diaphragm, at bent 2



Span 3 Beam 7: (PAR) at bent 2, painted over section loss: web (1/4 inch average remaining x 4.5 foot x 16 inch)



Span 3 Near Bearing 7: (PAR) east weld between sole and bottom flange, broken




Bent 2 Cap 1: 4 foot long x 18 inch x 1 inch high spall/delamination concrete in south face near the top between beams 7 and 8.



Span 2 Beam 8: (PAR) at bent 2, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 14 inch x 8 inch); lower web (7/16 inch average remaining x 2 foot x 3 inch)



Span 2 Beam 8 - Far Bearing 8: [PAR] West face anchor bolt not visible within nut



Span 3 Beam 8: (PAR) at bent 2, painted over section loss: web adjacent to diaphragm (3/16 inch average remaining x 16 inch x 2.5 inch); lower web (1/4 inch average remaining x 20 inch x 2 inch); bottom flange (0.50 inch average remaining x 9 inch) with corrosion reinitiated



Bent 2 Cap 1: [PAR] bottom face of cap between columns 4 and 5, spall/delamination [5 foot long x full width x up to 3 inch deep] with seven exposed rusted reinforcing with 80 percent remaining



Bent 2 Cap 1: between columns 3 and 4, 4 foot long x full width delamination in the bottom face extending into vertical faces of concrete



Bent 2 Cap 1: (PAR) (3) up to 1.5 foot x 1 foot wide x 1/2 inch deep spall with exposed rusted reinforcement, 80 percent remaining on underside of cap between columns 5 and 6



Bent 2 Cap 1: 10 foot x 1/16 inch horizontal crack in north face of cap under bays 5 and 6



Bent 2 Cap 1: under beam 5, spall [14 inch x 4 inch x 1 inch deep] with coarse aggregate exposed, undermining bearing 1/2 inch



Span 3 Near Bearing 5: (PAR) loss of bearing area (up to 1/2 inch x 3 inch)



Span 3 Beam 4: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 15 inch x 9 inch)



Span 4 Beam 4: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 5.5 foot x 10 inch) with corrosion holes (up to 1 inch x 1/2 inch); bottom flange (0.45 inch average remaining x 4 foot)





Span 3 Beam 5: (PAR) at bent 3, painted over section loss: bottom flange (0.45 inch average remaining x 1 foot); web (1/4 in average remaining x 2 foot x 9 inch) with corrosion reinitiated



Span 3 Beam 5: 7 foot x 4 inch delamination with cracks up to 1/8 inch in south face end diaphragm at bent 3



Span 4 Beam 5: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 6 foot x 1 foot) with corrosion holes (6 inch x 1.5 inch); bottom flange (0.56 inch average remaining x 15 inch) with corrosion reinitiated



Span 3 Beam 6: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 20 inch x 10 inch); bottom flange (0.56 inch average remaining x 1 foot) with corrosion reinitiated



Span 3 Beam 6 - Far Bearing 6: corrosion has been arrested when painted, 75 percent section remaining in masonry and sole plate. west anchor bolt nut has 20 percent section remaining



Span 4 Beam 6: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 32 inch x 12 inch) with corrosion reinitiated



Span 3 Beam 7: (PAR) at bent 3, painted over section loss: web adjacent to diaphragm (3/8 inch average remaining x 10 inch x 5 inch) with corrosion reinitiated



Span 3 Far Bearing 7: arrested pack rust and section loss in masonry plate and sole plate. 80 percent section remaining.



Span 4 Beam 7 - Near Bearing 7: arrested corrosion and section loss in masonry plate and sole plate. 80 percent section remaining. both anchor bolt nuts have up to 40 percent section remaining



Span 4 Beam 7: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 8 foot x 12 inch) with corrosion holes (up to 1/4 inch diameter); bottom flange (0.45 inch average remaining x 26 inch) with corrosion reinitiated



Span 4 Beam 7: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 8 foot x 12 inch) with corrosion holes (up to 1/4 inch diameter); bottom flange (0.45 inch average remaining x 26 inch) with corrosion reinitiated



Span 3 Beam 8: (PAR) at bent 3, painted over section loss: web adjacent to diaphragm (1/4 inch average remaining x 1 foot x 8 inch); lower web (1/4 inch average remaining x 32 inch x 2 inch); bottom flange (0.50 inch average remaining x 18 inch) with corrosion reinitiated





Span 3 Beam 8 - Far Bearing 8: corrosion has been arrested when painted, up to 75 percent section remaining in masonry and sole plate. west anchor bolt nut has up to 80 percent section remaining.



Span 3 Beam 8: (PAR) 3 foot long x 6 inch wide x 3 inch high spall with exposed reinforcement in end diaphragm between beams 7 and 8 at bent 3. 70 percent section remaining in exposed reinforcement.



Span 4 Beam 8: (PAR) at bent 3, painted over section loss: web (1/4 inch average remaining x 34 inch x 12 inch) with corrosion hole (10 inch x 3 inch); bottom flange (0.50 inch average remaining x 34 inch) with corrosion reinitiated



Span 4 Beam 8 - Near Bearing 8: corrosion has been arrested when painted, 75 percent section remaining in masonry plate and sole plate. both anchor bolt nuts have up to 50 percent section remaining.



Span 3 Beam 11: 2023 new repair (beam heat straightened and coverplate rewelded); previously noted as: SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021 area of previous impact damage, distortion of bottom flange vertical up to 2 inch lateral up to 1/2 inch with broken cover plate weld [10 inch long]. new area of impact damage 6 inch long x 2 inch high at 13 foot-5 inch out from interior. bent 3 . with the bottom cover plate being broken loose from bottom flange 10 inch long x 2 inch deep . there are also two older 1/2 inch indentions in the same area . Beam 11 is swept westward up to 1 1/2 inch. (par) there is a 2 inch diameter torch cut hole at both ends of of the 6 foot length .



Span 3 Beam 10: (2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021: 1 indentation 1 inch long x 1/2 inch deep at 18 foot-8 inch from interior. bent 3 . scattered scrapes along the web .



Span 3 Beam 9: (2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021: 1 indentation 1 inch long x 1/4 inch deep at 18 foot-7 inch from interior. bent 3



Span 3 Beam 8: over right westbound lane, impact scrapes with distortion



Span 3 Beam 7: over right westbound lane, impact scrapes



Span 3 Beam 7: multiple up to 3 foot long horizontal 1/8 inch wide cracks in end diaphragm between beams 7 and 8 at bent 2 starting at beam 8



Span 3 Deck: at bent 3, both overhangs, (2) delaminations (up to 1.5 foot x 6 inch)



Span 3 Beam 11: at bent 3, top flange, surface rust/rust scale (1 foot)



Span 3 Beam 6: spall/delamination 7 foot x 10 inch x 2 inch deep with exposed rusted rebar in north face of end diaphragm between beams 6 and 7 at bent 2



Span 3 Beam 5: (PAR) 7 foot long x up to 3 inch high x 10 inch wide area of spall in the diaphragm between beams 5 and 6 at bent 2 with exposed reinforcement. 70 percent section remaining in the exposed reinforcement.





Span 3 Beam 4: (PAR) 6 foot long x up to 3 inch high x 10 inch wide area of spall in the diaphragm between beams 4 and 5 at bent 2 with exposed reinforcement. 70 percent section remaining in the exposed reinforcement.



Span 3 Beam 4: (2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021: scattered scrapes



Span 3 Beam 3: 2023 new paint repair; previously noted as: SUPPLEMENTAL INSPECTION IMPACT DAMAGE  
2021 :scattered scrapes



Span 3 Beam 2: 2023 new paint repair, previously noted as: SUPPLEMENTAL INSPECTION IMPACT DAMAGE  
2021 :scattered scrapes



Span 3 Beam 1: (2023 no apparent change since previous inspection) SUPPLEMENTAL INSPECTION IMPACT DAMAGE 2021 :scattered scrapes



Span 4 Beam 4: 7 foot long x 8 inch wide x 4 inch along north face and 8 in along bottom face area of delamination and unsound concrete in end diaphragm at bent 3 between beams 4 and 5.



Span 4 Beam 5: 4 foot x 6 inch long x 8 inch wide x 5 inch along north and bottom faces area of delamination and unsound concrete in end diaphragm at bent 3 between beams 5 and 6.



Span 4 Beam 8: (PAR) 7 foot long x 1.5 foot wide x 3 inch deep spall with exposed reinforcement in end diaphragm between beams 7 and 8 at bent 3. 60 percent section remaining in exposed reinforcement.



Span 4 Deck: throughout underside of deck, transverse cracks (up to 1/16 inch x full bay width) and map cracks (1/32 inch) some with efflorescence at random



Span 4 Deck: 2 foot long x 6 inch wide x up to 1/2 inch deep area of delamination/spall in deck underside of bay 10, 15 foot from end bent 2.



Bent 3 Cap 1: 4 foot long x 8 inch high area of up to 1/16 inch wide cracks and delamination on north face under bay 5



Bent 3 Cap 1: North face under bay 7, delamination 6 foot long x up to 1 foot x 4 inch x 1 inch deep in and has up to 1/8 inch wide cracks



Bent 3 Cap 1: North face under beam 4, spall [1 foot x 6 inch x 1/2 inch deep] no undermining



Bent 3 Pile 3: 4 foot high x 12 inch wide area of delamination and unsound concrete in north face. similar condition in west face.



Bent 3 Pile 4: 3 foot high x 12 inch wide area of delamination and unsound concrete at northeast corner.



Bent 3 Pile 4: 29 inch wide x height varying from 18 inch to 45 inch area of delamination on west face. 3 foot high x 12 inch wide area of delamination in south face. 3 foot high x 12 inch wide area of delamination in north face.





Bent 3 Pile 5: 4 foot high x 16 inch wide area of delamination/spall and unsound concrete at northeast corner.



Bent 3 Cap 1: 5 foot x up to full height area of cracked delamination on south face of cap below beam 8



Bent 3 Cap 1: south face, in bays 4 and 5, multiple spalls/delaminations (up to 5 foot x 2 foot x 1.5 inch deep) with exposed rusted rebar



Bent 3 Cap 1: 12 inch high x 9 inch wide x 1.5 inch deep with exposed reinforcement under beam 7, south face. 90 percent section remaining in exposed reinforcement.



Bent 3 Cap 1: 10 inch x 5 inch x 1 inch deep spall with exposed reinforcement in south face between beams 6 and 7. 90 percent section remaining in exposed reinforcement.



Bent 3 Cap 1: 12 inch x 4 inch x 1/2 inch deep spall with exposed reinforcement on east face of top radius at pile 5



Bent 3 Pile 3: east face 12 inch high x 6 inch wide x 1 inch deep spall with exposed reinforcement



Bent 3 Pile 3: (PAR) Southeast corner above barrier rail, spall/delamination [10 foot high x up to full width x up to 4 inch deep] with primary debonded exposed rusted reinforcing 75 percent remaining




Bent 3 Pile 5: (PAR) 6.5 foot high x 20 inch wide x 3.5 inch deep spall and delaminated concrete with one debonded primary exposed reinforcement on south east corner of pile. 80 percent section remaining in exposed reinforcement.

# Structure Data Worksheet

## Span Profile

County: **BURKE**

Structure Number: **110173**



A: SPAN LENGTH  
 B: BEARING TO BEARING  
 C: DISTANCE FROM NEAR BEARING  
 D: DISTANCE TO FAR BEARING

Span Number	Span Length	Bearing to Bearing	Crutch/ Helper Bent	Distance to Near Bearing	Distance to Far Bearing
1	49.000	47.000			
2	57.500	56.500			
3	57.500	56.500			
4	42.500	41.000			

Structure Number: 110173

Span: 2

Route Name: I 40 EB - LIDAR 05/30/13



roadway under span 2, looking east

<b>Route Number:</b> 1100040		<b>Route Name:</b> I 40 EB - LIDAR 05/30/13			<b>Reference Feature:</b> H	
<b>Minimum Vertical Clearance</b> 16.060 feet		<b>Maximum Minimum Vertical Clearance</b> 16.360 feet				
<b>Total Horizontal Clearance</b> 42.650 feet		<b>Lateral Clearances: Left:</b> 12.250 feet <b>Right:</b> 11.580 feet				
<input checked="" type="checkbox"/> <b>Base Highway Network</b>		LRS Inventory Route, Sub Route Number 10040				
<b>Milepost:</b> 119.020	<b>Number of Lanes:</b> 2	<b>ADT:</b> 22500	<b>Year of ADT:</b> 2015	<b>Percentage of Trucks:</b> 16		
<input checked="" type="checkbox"/> <b>National Highway System</b>		<input type="checkbox"/> <b>STRAHNET Highway Designator</b>				
<b>Functional Classification</b> 11 Local Principal Arterial - Interstate		<b>Direction of Traffic:</b> 1 1 - way traffic				

Structure Number: 110173

Span: 3

Route Name: I 40 WB - LIDAR 05/30/13



roadway under span 3, looking west

<b>Route Number:</b> 1100040		<b>Route Name:</b> I 40 WB - LIDAR 05/30/13			<b>Reference Feature:</b> H	
<b>Minimum Vertical Clearance</b> 14.770 feet		<b>Maximum Minimum Vertical Clearance</b> 14.950 feet				
<b>Total Horizontal Clearance</b> 43.270 feet		<b>Lateral Clearances: Left:</b> 13.280 feet		<b>Right:</b> 8.670 feet		
<input checked="" type="checkbox"/> <b>Base Highway Network</b>		<b>LRS Inventory Route, Sub Route Number</b> 10040				
<b>Milepost:</b> 119.020	<b>Number of Lanes:</b> 2	<b>ADT:</b> 22500	<b>Year of ADT:</b> 2015	<b>Percentage of Trucks:</b> 16		
<input checked="" type="checkbox"/> <b>National Highway System</b>			<input type="checkbox"/> <b>STRAHNET Highway Designator</b>			
<b>Functional Classification</b> 11		Local Principal Arterial - Interstate		<b>Direction of Traffic:</b> 1 1 - way traffic		



# Bridge Inspection Field Sketch



Roadway	17ft Wide	2 Paved Lanes	Looking North
Left Shoulder	4ft Wide		4ft Unpaved
Right Shoulder	5ft Wide	1ft Paved	4ft Unpaved
Left Guardrail			
Right Guardrail			

measurements taken approximately 100 feet from end bent 1

Title  
APPROACH ROADWAY SKETCH

Description  
LOOKING NORTH

Structure No: 110173


Drawn By: HABonilla

Date: 10/25/2023

Filename: S000906000258.wes

# Bridge Inspection Field Sketch

Deck Width/Out to Out	70ft	Between Rails	68ft	
Clear Roadway	67.44ft	Wearing Surface		
Median Width		Median Height		
Curb Height		Left		Right
Sidewalk Width		Left		Right
Clear Roadway (Rail to Median)		Left		Right
Guardrail Width		Left	12in	Right 12in
Top of Rail to Deck/Wearing Surface		Left	2.667ft	Right 2.667ft
Bridge Rail Type		Left	Type 1	Right Type 1




Measurements for Span #	1	ALL SPANS SIMILAR	
Deck Thickness	6.5in	Left Overhang	2.5ft
Top of Rail to Bottom of Beam (Avg)	5.959ft	Right Overhang	2.5ft

Beam #	Beam Type	Width	Height	Spacing	From
1	Plate Girder	11.5in	33in	2.5ft	Left Edge of Deck
2	Plate Girder	11.5in	33in	6.5ft	Beam 1
3	Plate Girder	11.5in	33in	6.5ft	Beam 2
4	Plate Girder	11.5in	33in	6.5ft	Beam 3
5	Plate Girder	11.5in	33in	6.5ft	Beam 4
6	Plate Girder	11.5in	33in	6.5ft	Beam 5
7	Plate Girder	11.5in	33in	6.5ft	Beam 6
8	Plate Girder	11.5in	33in	6.5ft	Beam 7
9	Plate Girder	11.5in	33in	6.5ft	Beam 8
10	Plate Girder	11.5in	33in	6.5ft	Beam 9
11	Plate Girder	11.5in	33in	6.5ft	Beam 10

BEAM DIMENSIONS: between flanges 31.5"; flanges 11.5" x 3/4" thick; web 1/2" thick  
span 2 and 3 coverplates could not be field measured; refer to structure plans for dimensions

Title TYPICAL SECTION SKETCH		Description LOOKING NORTH		
Structure No: 110173	Drawn By: HABonilla	Date: 10/25/2023	Filename: S000906000259.wes	

# Bridge Inspection Field Sketch



Caps							
#	Name	Type	Length	Width	Height	Left Beam to End of Cap	Right Beam to End of Cap
1	Cap 1	Reinforced Concrete Pier Cap	75.75ft	30in	30in	2ft	2ft
Piles							
#	Name	Type	Spacing	From	Height/Diam	Width	Length
1	Pile 1	Reinforced Concrete Column	4ft	Left End of Bent	30in	30in	16.25ft
2	Pile 2	Reinforced Concrete Column	12.5ft	Pile 1	30in	30in	16.25ft
3	Pile 3	Reinforced Concrete Column	9.5ft	Pile 2	30in	30in	16.25ft
4	Pile 4	Reinforced Concrete Column	12ft	Pile 3	30in	30in	16.25ft
5	Pile 5	Reinforced Concrete Column	12ft	Pile 4	30in	30in	16.25ft
6	Pile 6	Reinforced Concrete Column	9.5ft	Pile 5	30in	30in	16.25ft
7	Pile 7	Reinforced Concrete Column	12.25ft	Pile 6	30in	30in	16.25ft

Title BENT SKETCH		Description LOOKING NORTH	
Structure No: 110173	Drawn By: HABonilla	Date: 10/25/2023	Filename: S000906000260.wes



west profile looking east



roadway under span 2, looking east (I-40 eastbound)




bent 2



superstructure underside



intermediate diaphragm



typical coverplate termination (spans 2 and 3)



end bent 1 and slope protection



end bearing assembly



southwest wingwall



southeast wingwall





southeast guardrail attachment



southeast guardrail transition



southeast guardrail



southeast guardrail termination



south approach looking north



left bridge rail



right bridge rail



asphalt wearing surface



end bent 1 asphalt



bent 1 joint



south approach looking south



roadway looking east



bent 2 joint



bent 3 joint



end bent 2 asphalt



north approach looking south





northwest guardrail



northwest guardrail termination



northwest guardrail attachment



northwest guardrail transition



roadway looking west



north approach looking north



northwest wingwall



end bent 2 and slope protection



northeast wingwall



east profile looking west



roadway under span 3, looking west (I-40 westbound)



bent 3



bent 1



end diaphragm



bridge number



interior bearing assembly





beams over bent



ladder used