

Monitoring Data Record

Project Title: R-2568B (Site 4) COE Action ID: 200121280
Stream Name: UT to Rich Fork Creek DWQ Number: 3478
City, County and other Location Information: Davidson Co, NC 109 from North of I-85 Business to North of SR 1756 (Lexington Ave.) Sta. 46+60 to 47+80 -L-
Date Construction Completed: water was turned on 8/29/05, planted on 2/17/06
Monitoring Year: (2) of 5
Ecoregion: _____ 8 digit HUC unit 03040103
USGS Quad Name and Coordinates: _____

Rosgen Classification: _____

Length of Project: 315' Urban or Rural: Rural Watershed Size: _____
Monitoring DATA collected by: M. Green & J. Young Date: 2/28/07

Applicant Information:

Name: NCDOT Roadside Environmental Unit
Address: 1425 Rock Quarry Road Raleigh, NC 27610
Telephone Number: (919) 861-3772 Email address: mlgreen@dot.state.nc.us

Consultant Information:

Name: _____
Address: _____
Telephone Number: _____ Email address: _____

Project Status: Complete

Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.): Level 1 ~~2~~ ~~3~~

Monitoring Level 1 requires completion of *Section 1, Section 2 and Section 3*

Permit States: NCDOT shall perform the following components of Level I monitoring twice each year for the 5 year monitoring period (summer and winter): Reference photos, plant survival, and visual inspection of channel stability. If less than two bankfull events occur during the first 5 years, NCDOT shall continue monitoring until the second bankfull event is documented. The bankfull events must occur during separate monitoring years. In the event that the required bankfull events do not occur during the 5 year monitoring period, the USACE, in consultation with resource agencies, may determine that further monitoring is not required.

Section 1. PHOTO REFERENCE SITES

(Monitoring at all levels must complete this section)

Total number of reference photo locations at this site: 4 reference points, 2 photos at each
Dates reference photos have been taken at this site: 7/18/06, 2/28/07

Individual from whom additional photos can be obtained (name, address, phone):

Other Information relative to site photo reference: _____

If required to complete Level 3 monitoring only stop here; otherwise, complete section 2.

Section 2. PLANT SURVIVAL

Attach plan sheet indicating reference photos.

Identify specific problem areas (missing, stressed, damaged or dead plantings):

Estimated causes, and proposed/required remedial action:

ADDITIONAL COMMENTS: Vegetation is dormant at this time. Hardwood vegetation noted onsite includes: black willow and silky dogwood live stakes. Other vegetation noted onsite includes: goldenrod, sedge, cattail, mimosa, *Juncus* sp., rye grain, and various grasses. The streambank and floodplain were live staked with black willow and silky dogwood species.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The channel is stable throughout the entire onsite stream relocation project. There is evidence that another bankfull event has recently occurred onsite. Point bars have developed from sediment being deposited through the stream during the bankfull events. The slope failure noted last monitoring evaluation has been repaired and is stabilized.

Date Inspected	Station Number				
Structure Type					
Is water piping through or around structure?					
Head cut or down cut present?					
Bank or scour erosion present?					

NOTE: Attach separate narrative sheets to each monitoring report describing/discussing the overall monitoring results. Include the identification of specific problem areas/channel failures, estimated cause and proposed/required remedial action. This should include a brief discussion of any parameter that has changed significantly from as-built.

UT Rich Fork Creek



PP #1 (Upstream)



PP #1 (Downstream)



PP #2 (Upstream)



PP #2 (Downstream)



PP #3 (Upstream)



PP #3 (Downstream)

UT Rich Fork Creek



PP #4 (Upstream)



PP #4 (Downstream)