



NC DEPARTMENT OF TRANSPORTATION  
 DIVISION OF HIGHWAYS  
 STRUCTURE MANAGEMENT UNIT

ATTENTION: **PROMPT ACTION REQUEST**

# Structure Safety Report

## Routine Element Inspection - Contract

INSPECTION DATE: 11/16/2021

DIVISION: 4 COUNTY: JOHNSTON STRUCTURE NUMBER: 500037 FREQUENCY: 24 MONTHS

FACILITY CARRIED: US301, NC96 MILE POST: \_\_\_\_\_

LOCATION: 0.2 MI N JCT US701 & US301

FEATURE INTERSECTED: CSX RR

LATITUDE: 35° 27' 41.06" LONGITUDE: 78° 23' 21.72"

SUPERSTRUCTURE: REINFORCED CONCRETE DECK ON I-BEAMS

SUBSTRUCTURE: ABUTMENTS:RC SPILL THROUGH, INT. BENTS:RC POST & BEAM

SPANS: 5 SPANS. SEE SPAN PROFILE SHEET FOR SPAN DETAILS

FRACTURE CRITICAL     TEMPORARY SHORING     SCOUR CRITICAL     SCOUR PLAN OF ACTION

GRADES: (Inspector/NBI Coding) DECK 6/6 SUPERSTRUCTURE 5/5 SUBSTRUCTURE 5/5 CULVERT N/N

POSTED SV: \_\_\_\_\_ POSTED TTST: \_\_\_\_\_

OTHER SIGNS PRESENT: (4) DELINEATORS



Sign noticed issued for	Number Required
<u>NO</u> WEIGHT LIMIT	<u>0</u>
<u>NO</u> DELINEATORS	<u>0</u>
<u>NO</u> NARROW BRIDGE	<u>0</u>
<u>NO</u> ONE LANE BRIDGE	<u>0</u>
<u>NO</u> LOW CLEARANCE	<u>0</u>

DIRECTION OF INSPECTION S-N

DIRECTION MATCHES PLANS \_\_\_\_\_

SOUTH APPROACH LOOKING NORTH

INSPECTED BY ERIC A. PATTERSON	SIGNATURE 	ASSISTED BY KEITH PROCTOR
-----------------------------------	---------------	------------------------------

NATIONAL BRIDGE INVENTROY ----- STRUCTURE INVENTORY AND APPRAISAL

02/01/2022

**IDENTIFICATION**

(1) STATE NAME NORTH CAROLINA BRIDGE 500037  
 (8) STRUCTURE NUMBER (FEDERAL) 1010037  
 (5) INVENTORY ROUTE (ON/UNDER) ON 121003010  
 (2) STATE HIGHWAY DEPARTMENT DISTRICT 4  
 (3) COUNTY CODE (FEDERAL) 101 (4) PLACE CODE 24520  
 (6) FEATURE INTERSECTED CSX RR  
 (7) FACILITY CARRIED US301, NC96  
 (9) LOCATION 0.2 MI N JCT US701 &US301  
 (11) MILEPOINT 0.0  
 (12) BASE HIGHWAY NETWORK 1  
 (13) LRS INVENTORY ROUTE & SUBROUTE  
 (16) LATITUDE 35° 27' 41.06" (17) LONGITUDE 78° 23' 21.72"  
 (98) BORDER BRIDGE STATE CODE PERCENT SHARED  
 (99) BORDER BRIDGE STRUCTURE NUMBER

SUFFICIENCY RATING 35.49  
 STATUS = Functionally Obsolete

**CLASSIFICATION**

**CODE**

(112) NBIS BRIDGE SYSTEM YES  
 (104) HIGHWAY SYSTEM Inventory Route is on NHS 1  
 (26) FUNCTIONAL CLASS Urban Minor Collector 16  
 (100) STRAHNET HIGHWAY Not a STRAHNET Route 0  
 (101) PARALLEL STRUCTURE No parallel structure exists N  
 (102) DIRECTION OF TRAFFIC 2-way traffic 2  
 (103) TEMPORARY STRUCTURE  
 (110) DESIGNATED NATIONAL NETWORK - on national network for trucks 0  
 (20) TOLL On Free Road 3  
 (21) MAINT - 01  
 (22) OWNER - 01  
 (37) HISTORICAL SIGNIFICANCE - 5

**STRUCTURE TYPE AND MATERIAL**

(43) STRUCTURE TYPE MAIN Steel  
 TYPE Stringer/Multi-beam or girder CODE 302  
 (44) STRUCTURE TYPE APPROACH  
 TYPE CODE  
 (45) NUMBER OF SPANS IN MAIN UNIT 5  
 (46) NUMBER OF SPANS IN APPROACH 0  
 (107) DECK STRUCTURE TYPE CODE 1  
 (108)WEARING SURFACE/PROTECTIVE SYSTEM  
 (A) TYPE OF WEARING SURFACE CODE 6  
 (B) TYPE OF MEMBRANE CODE 0  
 (C) TYPE OF DECK PROTECTION CODE 0

**CONDITION**

**CODE**

(58) DECK 6  
 (59) SUPERSTRUCTURE 5  
 (60) SUBSTRUCTURE 5  
 (61) CHANNEL & CHANNEL PROTECTION N  
 (62) CULVERTS N

**LOAD RATING AND POSTING**

**CODE**

(31) DESIGN LOAD HS20 5  
 (63) OPERATING RATING METHOD - Load Factor 1  
 (64) OPERATING RATING - HS-13 23  
 (65) INVENTORY RATING METHOD - 1  
 (66) INVENTORY RATING HS-8 14  
 (70) BRIDGE POSTING Posting Required 0  
 (41) STRUCTURE OPEN, POSTED, OR CLOSED  
 DESCRIPTION Posted for Load P

**AGE AND SERVICE**

(27) YEAR BUILT 1926  
 (106) YEAR RECONSTRUCTED 1954  
 (42) TYPE OF SERVICE ON - Highway  
 OFF - Railroad CODE 12  
 (28) LANES ON STRUCTURE 2 LANES UNDER STRUCTURE 0  
 (29) AVERAGE DAILY TRAFFIC 8900  
 (30) YEAR OF ADT 2018 (109) TRUCK ADT PCT 6  
 (19) BYPASS OR DETOUR LENGTH 1.0

**APPRAISAL**

**CODE**

(67) STRUCTURAL EVALUATION 3  
 (68) DECK GEOMETRY 3  
 (69) UNDERCLEARANCES, VERT & HORIZ 5  
 (71) WATERWAY ADEQUACY N  
 (72) APPROACH ROADWAY ALIGNMENT 8  
 (36) TRAFFIC SAFETY FEATURES 0001  
 (113) SCOUR CRITICAL BRIDGES N

**GEOMETRIC DATA**

(48) LENGTH OF MAXIMUM SPAN 47.0  
 (49) STRUCTURE LENGTH 189.0  
 (50) CURB OR SIDEWALK: LEFT 1.6 RIGHT 1.6  
 (51) BRIDGE ROADWAY WIDTH, CURB TO CURB 30.1  
 (52) DECK WIDTH OUT TO OUT 35.4  
 (32) APPROACH ROADWAY WITH (W/ SHOULDERS) 31.0  
 (33) BRIDGE MEDIAN No median CODE 0  
 (34) SKEW 40 (35) STRUCTURE FLARED 0  
 (10) INVENTORY ROUTE MIN VERT CLEAR 999.9  
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 30.1  
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 999.9  
 (54) MIN VERT UNDERCLEAR: REFERENCE R 21.3  
 (55) MIN LAT UNDERCLEARANCE RT: REFERENCE R 11.8  
 (56) MIN LAT UNDERCLEARANCE LT: 0.0

**PROPOSED IMPROVEMENTS**

**CODE**

(75) TYPE OF WORK  
 (76) LENGTH OF STRUCTURE IMPROVEMENT  
 (94) BRIDGE IMPROVEMENT COST  
 (95) ROADWAY IMPROVEMENT COST  
 (96) TOTAL PROJECT COST  
 (97) YEAR OF IMPROVEMENT COST ESTIMATE  
 (114) FUTURE ADT 17,800 YEAR OF FUTURE ADT 2040

**NAVIGATION DATA**

(38) NAVIGATION CONTROL - CODE N  
 (111) PIER PROTECTION CODE  
 (39) NAVIGATION VERTICAL CLEARANCE 0.0  
 (116) VERT - LIFT BRIDGE NAV MIN VERT CLEAR 0.0  
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0

**INSPECTION**

(90) INSPECTION DATE 11/21 (91) FREQUENCY 24  
 (92) CRITICAL FEATURE INSPECTION (93) CFI DATE  
 A) FRACTURE CRIT DETAIL A)  
 B) UNDERWATER INSP B)  
 C) OTHER SPECIAL INSP C)

SCOUR

Span Number	Facility Carried	Inventory Route	Maximum Minimum Vertical Clearance	Milepoint	Base Highway	LRS Inventory Route	Functional Classification	Number of Lanes	Average Daily Traffic	Year of Average Daily Traffic	Total Horizontal Clearance	See Note Below					STRAHNET Highway	Direction of Traffic	National Highway System	National Truck Network
												Reference Feature	Minimum Vertical Underclearance	Righth Lateral Underclearance	Left Lateral Underclearance	Underclearance Appraisal Grade				
	7	5	10	11	12	13	26	28	29	30	47	54A	54	55	56	69	100	102	104	110
3	Railroad	80000000		0.0							33.3	R	21.3	11.8	21.5	5			<input type="checkbox"/>	<input type="checkbox"/>

Note: Items 54, 55, and 56 are not reported FHWA under route data points but are collected for each under route to determine the minimum value for Underclearance Appraisal Item 69.

## Superstructure Build Details

Span Number 1

Span Length 38.0000

Skew 50.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
2	Concrete Railing	Reinforced Concrete Bridge Railing	76 Feet		
1	Asphalt Wearing Surface	Wearing Surface	1140 Square Feet		
5	Plate Girder	Steel Open Girder/Beam	190 Feet	Legacy Red Lead Primer Systems with Various Topcoats	1560
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1273 Square Feet		
10	Other Bearing	Other Bearings	10 Each	Unknown	10

Span Number 2

Span Length 37.5000

Skew 50.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1257 Square Feet		
10	Other Bearing	Other Bearings	10 Each	Unknown	10
2	Concrete Railing	Reinforced Concrete Bridge Railing	76 Feet		
1	Standard Joint	Pourable Joint Seal	40 Feet		
5	Plate Girder	Steel Open Girder/Beam	190 Feet	Legacy Red Lead Primer Systems with Various Topcoats	1540
1	Asphalt Wearing Surface	Wearing Surface	1125 Square Feet		

Span Number 3

Span Length 47.5000

Skew 50.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
5	Plate Girder	Steel Open Girder/Beam	240 Feet	Legacy Red Lead Primer Systems with Various Topcoats	2300
2	Concrete Railing	Reinforced Concrete Bridge Railing	96 Feet		
1	Standard Joint	Pourable Joint Seal	40 Feet		
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1592 Square Feet		
10	Other Bearing	Other Bearings	10 Each	Unknown	10
1	Asphalt Wearing Surface	Wearing Surface	1425 Square Feet		

Span Number 4

Span Length 32.5000

Skew 50.0000

## Superstructure Build Details

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1089 Square Feet		
1	Asphalt Wearing Surface	Wearing Surface	975 Square Feet		
5	Plate Girder	Steel Open Girder/Beam	165 Feet	Legacy Red Lead Primer Systems with Various Topcoats	1230
10	Other Bearing	Other Bearings	10 Each	Unknown	10
1	Standard Joint	Pourable Joint Seal	40 Feet		
2	Concrete Railing	Reinforced Concrete Bridge Railing	66 Feet		

Span Number 5

Span Length 33.0000

Skew 50.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Concrete Railing	Reinforced Concrete Bridge Railing	33 Feet	Unknown	33
1	Asphalt Wearing Surface	Wearing Surface	990 Square Feet		
1	Standard Joint	Pourable Joint Seal	40 Feet		
10	Other Bearing	Other Bearings	10 Each	Unknown	10
1	Concrete Railing	Reinforced Concrete Bridge Railing	33 Feet		
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1106 Square Feet		
5	Plate Girder	Steel Open Girder/Beam	165 Feet	Legacy Red Lead Primer Systems with Various Topcoats	1285

# Structure Element Scoring

Structure Number: **500037**

Inspection Date **11/16/2021**

<b>Element Number</b>	<b>Parent Number</b>	<b>Element Name</b>	<b>Location</b>	<b>Total Quantity</b>	<b>Level 1 Quantity</b>	<b>Level 2 Quantity</b>	<b>Level 3 Quantity</b>	<b>Level 4 Quantity</b>
12	0	Reinforced Concrete Deck	Deck	6317	6300	10	7	0
107	0	Steel Open Girder/Beam	Beam	950	565	349	27	9
515	107	Steel Protective Coating	Beam	7915	6618	324	0	973
205	0	Reinforced Concrete Column	Piles and Columns	8	1	0	7	0
215	0	Reinforced Concrete Abutment	Abutments	120	116	2	2	0
234	0	Reinforced Concrete Pier Cap	Caps	256	206	15	35	0
301	0	Pourable Joint Seal	Expansion Joints	160	160	0	0	0
316	0	Other Bearings	Bearing Device	50	5	24	21	0
515	316	Steel Protective Coating	Bearing Device	50	5	1	0	44
331	0	Reinforced Concrete Bridge Railing	Bridge Rail	380	237	10	133	0
510	0	Wearing Surface	Wearing Surfaces	5655	4234	0	1421	0

# Summary of Maintenance Needs

## Maintenance By Defect

Structure Number: **500037**

Inspection Date: **11/16/2021**

<b>MMS Code</b>	<b>Element Name</b>	<b>Defect Name</b>	<b>Recommended Quantity</b>
3326	Reinforced Concrete Deck	Delamination/Spall	10 Square Feet
3314	Steel Open Girder/Beam	Damage	1 Feet
3314	Steel Open Girder/Beam	Corrosion	36 Feet
3348	Reinforced Concrete Column	Cracking (RC and Other)	63 Each
3348	Reinforced Concrete Column	Delamination/Spall	16 Each
3350	Reinforced Concrete Abutment	Delamination/Spall	3 Feet
3348	Reinforced Concrete Pier Cap	Cracking (RC and Other)	32 Feet
3348	Reinforced Concrete Pier Cap	Delamination/Spall	8 Feet
3334	Other Bearings	Corrosion	21 Each
3318	Reinforced Concrete Bridge Railing	Delamination/Spall	9 Feet
3318	Reinforced Concrete Bridge Railing	Exposed Rebar	1 Feet
3318	Reinforced Concrete Bridge Railing	Cracking (RC and Other)	133 Feet
2816	Wearing Surface	Crack (Wearing Surface)	1415 Square Feet
2816	Wearing Surface	Patched Area/Pothole (Wearing Surface)	6 Square Feet
3342	Steel Protective Coating	Peeling/Bubbling/Cracking (steel Protective Coatings)	750 Square Feet
3342	Steel Protective Coating	Effectiveness (Steel Protective Coatings)	592 Square Feet

## Element Structure Maintenance Quantities

Structure Number: **500037**

Inspection Date **11/16/2021**

Location	MMS Code	Description	Maint Quantity	Total Quantity	Severe Quantity	Poor Quantity	Fair Quantity	Good Quantity
Abutments	3350	Maintenance of Concrete Wings and Wall	3	120	0	2	2	116
Beam	3314	Maintenance Steel Superstructure Components	37	950	9	27	349	565
Beam	3342	Clean and Paint Steel	1297	7915	973	0	324	6618
Bearing Device	3334	Bridge Bearing	21	50	0	21	24	5
Bearing Device	3342	Clean and Paint Steel	45	50	44	0	1	5
Bridge Rail	3318	Maintenance of Concrete Bridge Rail	143	380	0	133	10	237
Caps	3348	Maintenance of Concrete Substructure	40	256	0	35	15	206
Deck	3326	Maintenance of Concrete Deck	10	6317	0	7	10	6300
Expansion Joints	3310	Maintenance of Standard Bridge Expansion Joints	0	160	0	0	0	160
Piles and Columns	3348	Maintenance of Concrete Substructure	79	8	0	7	0	1
Wearing Surfaces	2816	Asphalt Surface Repair	1421	5655	0	1421	0	4234



# Priority Actions Request

Structure Number 500037

## Span1

3314	Beam 1	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	6	Span 1 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE LOWER CORNER OF THE INTERFACE THERE IS A HOLE [APPROXIMATELY 1/2" DIAMETER]. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 7/16" REMAINS] FOR APPROXIMATELY 6' LONG. AT THE SAME END IN THE LOWER 3" OF THE WEB CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 6' LONG.	
3314	Beam 2	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 1 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
3314	Beam 3	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 1 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
3314	Beam 4	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 1 Beam 4: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
3314	Beam 5	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 1 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	

# Priority Actions Request

Structure Number 500037

## Span2

3314	Beam 1	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 2 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
3314	Beam 2	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 2 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
3314	Beam 3	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 2 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
3314	Beam 5	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 2 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	

## Span3

3314	Beam 1	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	4	Span 3 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 IN THE LEFT LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH EDGE HOLES UP TO 3/4" DIAMETER. AT THE SAME END IN THE LOWER 6" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH PERFORATIONS THROUGHOUT.	

# Priority Actions Request

Structure Number 500037

3314	Beam 5	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	5	Span 3 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER LEFT FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 5' LONG. AT 1.5' OUT FROM THE SAME END IN THE LOWER 5" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 3' LONG.	

## Span4

3314	Beam 1	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	3	Span 4 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 3' LONG.	

3314	Beam 2	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 4 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	

3314	Beam 3	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 4 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	

3314	Beam 5	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 4 Beam 5: PAR--SECTION LOSS UP TO 3/8" WITH 3/8" AVERAGE REMAINING FULL WIDTH OF BOTTOM FLANGE 1FT LONG ON BEAM END OVER PIER 3. BEAM END HAS BEEN CLEANED AND PAINTED WITH ACTIVE SURFACE CORROSION. PLATE REPAIR ADDED BUT DOES NOT EXTEND OUT TO DEFECT.	

# Priority Actions Request

Structure Number 500037

## Span5

3314	Beam 2	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	1	Span 5 Beam 2: PAR--1 FOOT LONG X 2" WIDE AREA OF PREVIOUS CORROSION WITH 1/4" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 AREA HAS BEEN PAINTED OVER AND ARRESTED.	
3314	Beam 5	Plate Girder		
Priority Level	Defect Type	Quantity	Defect Description	
2	Corrosion	4	Span 5 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/4" REMAINS] FOR APPROXIMATELY 4' LONG. AT THE SAME END IN THE LOWER 4" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 4' LONG.	

## Bent 1

3348	Cap 1	Reinforced Concrete Pier Cap		
Priority Level	Defect Type	Quantity	Defect Description	
2	Cracking (RC and	2	Bent 1 Cap 1: [PROMPT ACTION REQUEST] SOUTH FACE AT THE LEFT END, LOWER 10", SPALLING WITH EXPOSED REBAR [APPROXIMATELY 40" LONG X UP TO 2.5" DEEP]	
3348	Pile 1	Reinforced Concrete Column		
Priority Level	Defect Type	Quantity	Defect Description	
2	Delamination/Spall	5	Bent 1 Pile 1: [PROMPT ACTION REQUEST] 6 FOOT X 9" FOOT X 2" DEEP SPALL WITH EXPOSED RUSTED REBAR NO SECTION LOSS AT NORTHWEST CORNER	

## Bent 3

3348	Pile 2	Reinforced Concrete Column		
Priority Level	Defect Type	Quantity	Defect Description	
2	Cracking (RC and	4	Bent 3 Pile 2: [PROMPT ACTION REQUEST] NORTHEAST CORNER, SPALLING WITH EXPOSED REBAR [APPROXIMATELY 4' HIGH X UP TO 1.25' WIDE X UP TO 3" DEEP]	
2	Delamination/Spall	3	Bent 3 Pile 2: PAR--SPALL WITH EXPOSED REBAR AND BROKEN HORIZONTAL TIE 3 FOOT X 1 FOOT X 4" DEEP IN NORTHEAST CORNER MID HEIGHT WITH SECTION LOSS	

## Element Condition and Maintenance Data

Structure Number: 500037

Inspection Date: 11/16/2021

**Span 1 Deck**  
**Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	1,273	1,273	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
12	Cracking (RC and Other)	TRANSVERSE HAIRLINE CRACK IN UNDERSIDE RIGHT OVERHANG AT 12 FT FROM END BENT 1	1	2		Square Feet
<b>General Comments</b>						

**Span 1 Beam 1**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	38	0	32	6	0	Feet
515	Steel Protective Coating	312	261	0	0	51	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE LOWER CORNER OF THE INTERFACE THERE IS A HOLE [APPROXIMATELY 1/2" DIAMETER]. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 7/16" REMAINS] FOR APPROXIMATELY 6' LONG. AT THE SAME END IN THE LOWER 3" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 6' LONG.	3	6		6 Feet
107	Damage	4" X 3" X 18" SPALL WITH EXPOSED REBAR IN WEST OVERHANG AT BENT 1 END DIAPHRAGM AT BEAM 1	3			1 Feet
107	Corrosion	CORROSION ON BOTTOM FLANGE WITH NO MEASURABLE SECTION LOSS EXTENDING 4 FT FROM THE END AT BENT 1	2	4		Feet
107	Corrosion	SURFACE CORROSION BOTTOM FLANGE WEST FACE AT END BENT 1	2	1		Feet
107	Corrosion	SURFACE CORROSION ON BOTH EDGES OF TOP FLANGE FULL LENGTH	2	23		Feet
107	Corrosion	SURFACE CORROSION ON BOTTOM FLANGE EXTENDING UP TO 10 FOOT FROM BENT 1	2	4		Feet
515	Effectiveness (Steel Protective Coatings)	5 SF. OF INEFFECTIVE PROTECTIVE COATING ON BOTTOM FLANGE AND WEB AT BENT 1	4	5		5 Square Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS AT BOTTOM FLANGE AT END BENT 1	4	1		1 Square Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS BOTH EDGES OF TOP FLANGE FULL LENGTH	4	15		15 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB, MAINLY EAST FACE NEAR BENT 1 AND AT RANDOM	4	30		30 Square Feet
<b>General Comments</b>						

**Span 1** **Beam 2**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	38	37	0	1	0 Feet
515	Steel Protective Coating	312	282	0	0	30 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB WEST FACE AT RANDOM	4	30	30 Square Feet

General Comments

**Span 1** **Beam 3**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	38	31	6	1	0 Feet
515	Steel Protective Coating	312	276	0	0	36 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
107	Corrosion	SURFACE CORROSION BOTTOM OF BOTTOM FLANGE FROM 5 FT TO 10 FT FROM BENT 1	2	5	Feet
107	Corrosion	SURFACE CORROSION ON BOTTOM FLANGE AT BENT 1	2	1	Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS BOTTOM OF BOTTOM FLANGE FROM 5 FT TO 10 FT FROM BENT 1	4	5	5 Square Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS ON BOTTOM FLANGE AT BENT 1	4	1	1 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB AT RANDOM	4	30	30 Square Feet

General Comments

**Span 1** **Beam 4**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	38	37	0	1	0 Feet
515	Steel Protective Coating	312	282	0	0	30 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1	Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB AT RANDOM	4	30	30	Square Feet
General Comments						

**Span 1** **Beam 5**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	38	22	15	1	0 Feet
515	Steel Protective Coating	312	250	0	0	62 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
107	Corrosion	SURFACE CORROSION ON EDGES OF TOP FLANGE BOTH SIDES AT RANDOM WHERE PAINT HAS PEELED	2	15	Feet
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail.	4	32	32 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB AT RANDOM	4	30	30 Square Feet
General Comments					

**Span 1** **Wearing Surface**  
**Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
510	Wearing Surface	1,140	760	0	380	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
510	Crack (Wearing Surface)	Full length longitudinal/map cracking up to 1/4" wide in travel lanes	3	300	300 Square Feet
510	Crack (Wearing Surface)	FULL WIDTH TRANSVERSE/MAP CRACKING UP TO 1/2" WIDE OVER END BENT 1 AND BENT 1, BENT 1 SHOWN	3	80	80 Square Feet
General Comments					

**Span 1** **Left Bridge Rail**  
**Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	38	27	1	10	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	10	10 Feet

331 Delamination/Spall 4" DIAMETER X 1" DEEP SPALL WITH EXPOSED REBAR AT END POST AT SOUTHWEST CORNER 2 1 1 Feet

General Comments

**Span 1 Right Bridge Rail**

**Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	38	25	1	12	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	12	12 Feet
331	Delamination/Spall	3" X 1" X 1/2" DEEP SPALL WITH EXPOSED REBAR IN TOP OF CURB AT GUARDRAIL ATTACHMENT	2	1	1 Feet

General Comments

**Span 1 Near Bearing 1**

**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	CORROSION WITH NO MEASURABLE SECTION LOSS	2	1	Each
515	Effectiveness (Steel Protective Coatings)	COATING HAS FAILED	4	1	1 Square Feet

General Comments

**Span 1 Far Bearing 1**

**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	PAINT FAILED	4	1	1 Square Feet

General Comments



**Span 1 Far Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	SURFACE CORROSION	2	1		Each
515	Effectiveness (Steel Protective Coatings)	LIMITED EFFECTIVENESS OF PROTECTIVE COATING	4	1	1	Square Feet

General Comments

**Span 1 Far Bearing 3**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	PAINT FAILED	4	1	1	Square Feet

General Comments

**Span 1 Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	SURFACE CORROSION	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS	4	1	1	Square Feet

General Comments

**Span 1 Far Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	SURFACE CORROSION	2	1		Each

515	Effectiveness (Steel Protective Coatings)	LIMITED EFFECTIVENESS OF PROTECTIVE COATING	4	1	1	Square Feet
General Comments						

**Span 1** **Near Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	SURFACE CORROSION	2	1	Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS	4	1	1 Square Feet
General Comments					

**Span 1** **Far Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	PAINT FAILED	4	1	1 Square Feet
General Comments					

**Span 2** **Beam 1**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	38	31	6	1	0 Feet
515	Steel Protective Coating	308	273	0	0	35 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 1/2" REMAINING SECTION IN BOTTOM FLANGE AND 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 2 HAS BEEN PAINTED OVER AND ARRESTED.	2	1	Feet
107	Corrosion	5 FT. OF SURFACE CORROSION ON BOTTOM FLANGE NEAR BENT 2	2	5	Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS ON BOTTOM OF BOTTOM FLANGE AT BENT 2	4	5	5 Square Feet

515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30	Square Feet
-----	---	--	---	----	----	-------------

General Comments

### Span 2

### Beam 2

#### Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	38	21	16	1	0 Feet
515	Steel Protective Coating	308	263	0	0	45 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
107	Corrosion	1 FT. OF PITTING 1/16" DEEP ON WEB AROUND END DIAPHRAGM AT BENT 2 HAS BEEN PAINTED	2	1	Feet
107	Corrosion	SURFACE CORROSION ALONG BOTTOM FLANGE AT RANDOM	2	15	Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS ALONG BOTTOM FLANGE AT RANDOM	4	15	15 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet

General Comments

### Span 2

### Beam 3

#### Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	38	36	1	1	0 Feet
515	Steel Protective Coating	308	278	0	0	30 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 2 HAS BEEN PAINTED OVER	2	1	Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet

General Comments

**Span 2** **Beam 4**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	38	36	2	0	0	Feet
515	Steel Protective Coating	308	278	0	0	30	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
107	Corrosion	1 FT. OF PAINTED OVER PITTING UP TO 1/16" DEEP IN WEB AROUND BENT 1 END DIAPHRAGM	2	1		Feet
107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 2 HAS BEEN PAINTED	2	1		Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30	Square Feet

General Comments

**Span 2** **Beam 5**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	38	16	21	1	0	Feet
515	Steel Protective Coating	308	246	0	0	62	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1	Feet
107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 1/2" X FULL WIDTH REMAINING SECTION IN BOTTOM FLANGE AND 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 2 HAS BEEN PAINTED WITH ACTIVE SURFACE CORROSION.	2	1		Feet
107	Corrosion	SURFACE CORROSION ALONG TOP FLANGE BOTH EDGES AT RANDOM WHERE PAINT HAS PEELED	2	20		Feet
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail	4	32	32	Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30	Square Feet

General Comments

**Span 2** **Wearing Surface**  
**Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
510	Wearing Surface	1,125	785	0	340	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
510	Crack (Wearing Surface)	Full length longitudinal/map cracking up to 1/4" wide in travel lanes	3	300	300	Square Feet
510	Crack (Wearing Surface)	FULL WIDTH TRANSVERSE/MAP CRACKING UP TO 1/2" WIDE OVER BENT 2,	3	40	40	Square Feet

General Comments

**Span 2 Left Bridge Rail**  
**Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	38	28	0	10	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	10	10 Feet
General Comments					

**Span 2 Right Bridge Rail**  
**Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	38	26	0	12	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	12	12 Feet
General Comments					

**Span 2 Near Bearing 1**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	SURFACE CORROSION	2	1	Each
515	Effectiveness (Steel Protective Coatings)	LIMITED EFFECTIVENESS OF PROTECTIVE COATING	4	1	1 Square Feet
General Comments					

**Span 2 Far Bearing 1**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	PAINT FAILED	4	1	1 Square Feet
General Comments					

**Span 2 Near Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	SURFACE CORROSION	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS	4	1	1	Square Feet

General Comments

**Span 2 Far Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Surface rust present	2	1		Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail	4	1	1	Square Feet

General Comments

**Span 2 Near Bearing 3**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	SURFACE CORROSION	2	1		Each
515	Effectiveness (Steel Protective Coatings)	LIMITED EFFECTIVENESS OF PROTECTIVE COATING	4	1	1	Square Feet

General Comments

**Span 2 Far Bearing 3**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each

<b>515</b>	<b>Effectiveness (Steel Protective Coatings)</b>	<b>PAINT FAILED</b>	<b>4</b>	<b>1</b>	<b>1</b>	<b>Square Feet</b>
<b>General Comments</b>						

**Span 2** **Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	SURFACE CORROSION	2	1	Each
515	Effectiveness (Steel Protective Coatings)	LIMITED EFFECTIVENESS OF PROTECTIVE COATING	4	1	1 Square Feet
<b>General Comments</b>					

**Span 2** **Far Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	PAINT FAILED	4	1	1 Square Feet
<b>General Comments</b>					

**Span 2** **Near Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	SURFACE CORROSION	2	1	Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS	4	1	1 Square Feet
<b>General Comments</b>					

**Span 2****Far Bearing 5****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	PAINT FAILED	4	1	1	Square Feet

General Comments

**Span 3****Deck****Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	1,592	1,590	0	2	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
12	Delamination/Spall	18" X 12" X 2" DEEP SPALL WITH EXPOSED REBAR IN UNDERSIDE OF LEFT OVERHANG NEAR MID SPAN. MULTIPLE EXPOSED BARS TRANSVERSE AND LONGITUDINAL HAVE SECTION LOSS WITH 50% AREA REMAINING	3	2	2	Square Feet

General Comments

**Span 3****Beam 1****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	48	29	15	0	4	Feet
515	Steel Protective Coating	460	370	0	0	90	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 3 IN THE LEFT LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH EDGE HOLES UP TO 3/4" DIAMETER. AT THE SAME END IN THE LOWER 6" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH PERFORATIONS THROUGHOUT.	4	4	4	Feet
107	Corrosion	SURFACE RUST ON TOP AND BOTTOM FLANGES AT VARIOUS LOCATIONS ALONG BEAM.	2	15		Feet
107	Corrosion	DUPLICATE	1			Feet
515	Effectiveness (Steel Protective Coatings)	5 SF. OF INEFFECTIVE PROTECTIVE COATING ON BOTTOM FLANGE AND WEB AT BENT 2	4	5	5	Square Feet
515	Effectiveness (Steel Protective Coatings)	5 SF. OF INEFFECTIVE PROTECTIVE COATING ON BOTTOM FLANGE AND WEB AT BENT 3	4	5	5	Square Feet
515	Effectiveness (Steel Protective Coatings)	COATING STARTING TO FAIL	4	50	50	Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30	Square Feet



## General Comments

## Span 3

## Beam 2

## Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	48	20	28	0	0 Feet
515	Steel Protective Coating	460	424	0	0	36 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	1 FT. OF ACTIVE CORROSION WITH 9/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 2	2	1	Feet
107	Corrosion	FRECKLED RUST ON WEB AT RANDOM	2	10	Feet
107	Corrosion	SURFACE CORROSION OF WEB AND BOTTOM FLANGE AT BENT 3	2	5	Feet
107	Corrosion	SURFACE RUST ON TOP AND BOTTOM FLANGES AT VARIOUS LOCATIONS ALONG BEAM.	2	12	Feet
515	Effectiveness (Steel Protective Coatings)	1 SF. OF INEFFECTIVE PROTECTIVE COATING ON WEB AT BENT 2	4	1	1 Square Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS AT WEB AND BOTTOM FLANGE AT BENT 3	4	5	5 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet

## General Comments

## Span 3

## Beam 3

## Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	48	19	29	0	0 Feet
515	Steel Protective Coating	460	423	0	0	37 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	1 FT. OF ACTIVE CORROSION WITH 9/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 2	2	1	Feet
107	Corrosion	3 FT. OF ACTIVE CORROSION WITH 3/4" REMAINING SECTION IN BOTTOM FLANGE AND 9/16" REMAINING SECTION 1 FT LONG IN WEB AROUND END DIAPHRAGM AT BENT 3	2	3	Feet
107	Corrosion	5 FT. OF SURFACE CORROSION ON BOTTOM FLANGE AND LOWER WEB NO MEASURABLE SECTION LOSS AT BENT 3	2	5	Feet
107	Corrosion	SURFACE CORROSION OF BOTTOM FLANGE AT RANDOM WHERE PAINT HAS PEELED	2	20	Feet
515	Effectiveness (Steel Protective Coatings)	1 SF. OF INEFFECTIVE PROTECTIVE COATING ON BOTTOM FLANGE AND WEB AT BENT 3	4	1	1 Square Feet
515	Effectiveness (Steel Protective Coatings)	1 SF. OF INEFFECTIVE PROTECTIVE COATING ON WEB AT BENT 2	4	1	1 Square Feet
515	Effectiveness (Steel Protective Coatings)	5 SF. OF INEFFECTIVE PROTECTIVE COATING ON BOTTOM FLANGE AND WEB AT BENT 3	4	5	5 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet

## General Comments

**Span 3** **Beam 4**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	48	46	2	0	0 Feet
515	Steel Protective Coating	460	428	0	0	32 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	1 FT. OF ACTIVE CORROSION WITH 9/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 3	2	1	Feet
107	Corrosion	1 FT. OF SURFACE CORROSION ON WEB AROUND END DIAPHRAGM AT BENT 2	2	1	Feet
515	Effectiveness (Steel Protective Coatings)	1 SF. OF INEFFECTIVE PROTECTIVE COATING ON WEB AT BENT 2	4	1	1 Square Feet
515	Effectiveness (Steel Protective Coatings)	1 SF. OF INEFFECTIVE PROTECTIVE COATING ON WEB AT BENT 3	4	1	1 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet

General Comments

**Span 3** **Beam 5**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	48	43	0	5	0 Feet
515	Steel Protective Coating	460	419	0	0	41 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER LEFT FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 5' LONG. AT 1.5' OUT FROM THE SAME END IN THE LOWER 5" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 3' LONG.	3	5	5 Feet
107	Corrosion	DUPLICATE	1		Feet
515	Effectiveness (Steel Protective Coatings)	5 SF. OF INEFFECTIVE PROTECTIVE COATING ON WEB AT BENT 3	4	5	5 Square Feet
515	Effectiveness (Steel Protective Coatings)	6 SF. OF INEFFECTIVE PROTECTIVE COATING ON WEB AND BOTTOM FLANGE AT BENT 2	4	6	6 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet

General Comments

**Span 3** **Wearing Surface**  
**Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
510	Wearing Surface	1,425	1,182	0	243	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

Structure Number: **500037**Inspection Date: **11/16/2021**

510	Crack (Wearing Surface)	Full length longitudinal/map cracking up to 3/16" wide in travel lanes	3	200	200	Square Feet
510	Crack (Wearing Surface)	FULL WIDTH TRANSVERSE/MAP CRACK UP TO 2" WIDE WITH ASPHALT DETERIORATION WITH UP TO 3/4" DEEP POT HOLES UP TO 1' LONG X 2" WIDE OVER BENT 3	3	40	40	Square Feet
510	Patched Area/Pothole (Wearing Surface)	3' Long x 6" wide x 2 1/2" deep pothole at right shoulder at pier 3	3	3	3	Square Feet

General Comments

### Span 3 Left Bridge Rail

#### Concrete Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	48	27	1	20	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	20	20 Feet
331	Delamination/Spall	3" X 3/4" X 1/4" DEEP SPALL WITH EXPOSED REBAR IN TOP OF CURB AT 15 FT FROM BENT 2	2	1	1 Feet

General Comments

### Span 3 Right Bridge Rail

#### Concrete Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	48	32	1	15	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	15	15 Feet
331	Delamination/Spall	3" X 1" X 1/2" DEEP SPALL WITH EXPOSED REBAR IN FACE OF RAIL POST AT BENT 2	2	1	1 Feet

General Comments

### Span 3 Near Bearing 1

#### Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	LIGHT SURFACE RUST	2	1	Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1 Square Feet

General Comments

**Span 3 Far Bearing 1**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	LIGHT SURFACE RUST	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1	Square Feet

General Comments

**Span 3 Near Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	LIGHT SURFACE RUST	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1	Square Feet

General Comments

**Span 3 Far Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	LIGHT SURFACE RUST	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1	Square Feet

General Comments

**Span 3 Near Bearing 3**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	LIGHT SURFACE RUST	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1	Square Feet

**General Comments****Span 3 Far Bearing 3****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	LIGHT SURFACE RUST	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1	Square Feet

**General Comments****Span 3 Near Bearing 4****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	LIGHT SURFACE RUST	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1	Square Feet

**General Comments****Span 3 Far Bearing 4****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	LIGHT SURFACE RUST	2	1		Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1	Square Feet

**General Comments****Span 3 Near Bearing 5****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

316	Corrosion	LIGHT SURFACE RUST	2	1	Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1 Square Feet

**General Comments****Span 3 Far Bearing 5****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	LIGHT SURFACE RUST	2	1	Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING FAILING	4	1	1 Square Feet

**General Comments****Span 4 Beam 1****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	7	23	3	0 Feet
515	Steel Protective Coating	246	170	40	0	36 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 3' LONG.	3	3	3 Feet
107	Corrosion	2 FT. OF PREVIOUS CORROSION WITH UP TO 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AND BOTTOM 3" OF WEB 3' LONG AT BENT 4 AREA HAS BEEN CLEANED AND PAINTED OVER	2	3	Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	20	Feet
515	Effectiveness (Steel Protective Coatings)	Coating has failed.	4	6	6 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	40	40 Square Feet

**General Comments**

BOLTED PLATE REPAIR FULL HEIGHT X 1' LONG TO WEB AT BENT 3

**Span 4** **Beam 2**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	20	12	1	0 Feet
515	Steel Protective Coating	246	196	20	0	30 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
107	Corrosion	1 FT. OF CORROSION WITH 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 3 HAS BEEN PAINTED OVER	2	1	Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	10	Feet
107	Corrosion	Section loss up to 3/16" with 3/4" average remaining 1' long at beam end over pier 3. Beam end has been cleaned and painted.	2	1	Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	20	20 Square Feet

General Comments

**Span 4** **Beam 3**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	22	10	1	0 Feet
515	Steel Protective Coating	246	196	20	0	30 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	3	1	1 Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	10	Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	20	20 Square Feet

General Comments

BOLTED PLATE REPAIR TO WEB ON BEAM 3 SPAN 4 24" X 24" AT BENT 3 END BOTH FACES

**Span 4****Beam 4****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	33	11	22	0	0	Feet
515	Steel Protective Coating	246	175	40	0	31	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 3 HAS BEEN PAINTED	2	1		Feet
107	Corrosion	1 FT. OF SURFACE CORROSION ON BOTTOM FLANGE AND PITTING WEB AT BENT 4	2	1		Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	20		Feet
515	Effectiveness (Steel Protective Coatings)	1 SF. OF INEFFECTIVE PROTECTIVE COATING ON BOTTOM FLANGE AND WEB AT BENT 4	4	1	1	Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30	Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	40	40	Square Feet

**General Comments****Span 4****Beam 5****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	33	6	26	1	0	Feet
515	Steel Protective Coating	246	163	50	0	33	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
107	Corrosion	PAR--SECTION LOSS UP TO 3/8" WITH 3/8" AVERAGE REMAINING FULL WIDTH OF BOTTOM FLANGE 1FT LONG ON BEAM END OVER PIER 3. BEAM END HAS BEEN CLEANED AND PAINTED WITH ACTIVE SURFACE CORROSION. PLATE REPAIR ADDED BUT DOES NOT EXTEND OUT TO DEFECT.	3	1	1	Feet
107	Corrosion	1 FT. OF SURFACE CORROSION ON BOTTOM FLANGE AND WEB AT BENT 4	2	1		Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	25		Feet
515	Effectiveness (Steel Protective Coatings)	1 SF. OF INEFFECTIVE PROTECTIVE COATING ON BOTTOM FLANGE AND WEB AT BENT 4	4	1	1	Square Feet
515	Effectiveness (Steel Protective Coatings)	Coating has failed.	4	2	2	Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30	Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	50	50	Square Feet

**General Comments**

BOLTED PLATE REPAIR 24" X 24" TO WEB BOTH SIDES AND 24" BOTTOM FLANGE WEST SIDE BEAM 5 SPAN 4 AT BENT 3



**Span 4 Wearing Surface****Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
510	Wearing Surface	975	707	0	268	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
510	Crack (Wearing Surface)	Full length longitudinal/map cracking up to 1/8" wide in travel lanes	3	225	225 Square Feet
510	Crack (Wearing Surface)	FULL WIDTH TRANSVERSE/MAP CRACKING UP TO 1/2" WIDE OVER BENT 4,	3	40	40 Square Feet
510	Patched Area/Pothole (Wearing Surface)	3' Long x 6" wide x 2 1/2" deep pothole at left shoulder at pier 3	3	3	3 Square Feet

General Comments

**Span 4 Left Bridge Rail****Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	33	20	1	12	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	12	12 Feet
331	Delamination/Spall	3" X 1" X 1/2" DEEP SPALL WITH EXPOSED REBAR IN TOP OF CURB AT 10 FT FROM BENT 4	2	1	1 Feet

General Comments

**Span 4 Right Bridge Rail****Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
331	Reinforced Concrete Bridge Railing	33	18	0	15	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	15	15 Feet

General Comments

**Span 4 Near Bearing 1****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	COATING STARTING TO FAIL	4	1	1 Square Feet

General Comments

**Span 4 Far Bearing 1**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail.	4	1	1	Square Feet

General Comments

**Span 4 Near Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	COATING STARTING TO FAIL	4	1	1	Square Feet

General Comments

**Span 4 Far Bearing 2**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	1	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	FRECKLED CORROSION	2	1		Each
515	Effectiveness (Steel Protective Coatings)	FRECKLED CORROSION	2	1	1	Square Feet

General Comments

**Span 4 Near Bearing 3**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

Structure Number: 500037

Inspection Date: 11/16/2021

316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	COATING STARTING TO FAIL	4	1	1	Square Feet
<b>General Comments</b>						

**Span 4 Far Bearing 3**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with light rust staining present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail.	4	1	1 Square Feet
<b>General Comments</b>					

**Span 4 Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	COATING STARTING TO FAIL	4	1	1 Square Feet
<b>General Comments</b>					

**Span 4 Far Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with light rust staining present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS LIMITED EFFECTIVENESS	4	1	1 Square Feet
<b>General Comments</b>					

**Span 4 Near Bearing 5****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	COATING STARTING TO FAIL	4	1	1	Square Feet

General Comments

**Span 4 Far Bearing 5****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	FAILED COATING	4	1	1	Square Feet

General Comments

**Span 5 Deck****Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	1,106	1,091	10	5	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
12	Delamination/Spall	3 SPALLS WITH EXPOSED REBAR IN WEST EDGE OF DECK NEAR BENT 4 UP TO 3" DIAMETER X 1/2" DEEP	3	3	3	Square Feet
12	Delamination/Spall	TWO SPALL WITH EXPOSED REBAR IN EAST EDGE OF DECK 4" DIAMETER X 1" DEEP AT 10 FT FROM END BENT 2	3	2	2	Square Feet
12	Delamination/Spall	A FEW SMALL AREAS UP TO DELAMINATION 3" X 9" IN UNDERSIDE WEST/EAST OVERHANGS AT VARIOUS LOCATIONS	2	3	3	Square Feet
12	Efflorescence/Rust Staining	7' long hairline diagonal crack with minor efflo. in underside of deck bay 4 at abutment 2	2	7		Square Feet

General Comments

**Span 5****Beam 1****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	11	20	2	0 Feet
515	Steel Protective Coating	257	183	40	0	34 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	1/4" section loss with 3/8" average remaining full width of bottom flange. Beam end has been painted with active surface corrosion present. No PAR issued due to repair plate added at pier 4.	3	2	2 Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	20	Feet
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail	4	4	4 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	40	40 Square Feet

**General Comments**

BOLTED PLATE REPAIR TO BOTTOM FLANGE WEST AND BOTH FACES OF WEB AT BENT 4 BEAM END AT BENT 4 HAS BEEN PAINTED.

**Span 5****Beam 2****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	19	13	0	1 Feet
515	Steel Protective Coating	257	201	24	0	32 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	PAR--1 FT LONG X 2" WIDE AREA OF PREVIOUS CORROSION WITH 1/4" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 AREA HAS BEEN PAINTED OVER AND ARRESTED.	4	1	1 Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	12	Feet
107	Corrosion	Minor section loss less than 1/16" on bottom flange 1' long at pier 4. Beam end has been painted over with no active corrosion	2	1	Feet
515	Effectiveness (Steel Protective Coatings)	Coating has failed	4	2	2 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	24	24 Square Feet

**General Comments****Span 5****Beam 3****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	22	11	0	0 Feet
515	Steel Protective Coating	257	207	20	0	30 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

Structure Number: **500037**

Inspection Date: **11/16/2021**

107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 HAS BEEN PAINTED	2	1	Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	10	Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	20	20 Square Feet

General Comments

**Span 5** **Beam 4**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	16	17	0	0 Feet
515	Steel Protective Coating	257	195	30	0	32 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 HAS BEEN PAINTED	2	1	Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	15	Feet
107	Corrosion	Minor section loss less than 1/16" on bottom flange 1' long at pier 4. Beam end has been painted over with no active corrosion	2	1	Feet
515	Effectiveness (Steel Protective Coatings)	Coating has failed.	4	2	2 Square Feet
515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30 Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	30	30 Square Feet

General Comments

**Span 5** **Beam 5**  
**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	33	7	22	0	4 Feet
515	Steel Protective Coating	257	179	40	0	38 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	[PROMPT ACTION REQUEST] BEAM END AT BENT 4 IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/4" REMAINS] FOR APPROXIMATELY 4' LONG. AT THE SAME END IN THE LOWER 4" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 4' LONG.	4	4	4 Feet
107	Corrosion	1 FT. OF PREVIOUS CORROSION WITH 7/16" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 HAS BEEN PAINTED	2	1	Feet
107	Corrosion	Freckled rust present on top and bottom flanges and web at various locations along beam	2	20	Feet
107	Corrosion	SURFACE CORROSION ON BOTTOM FLANGE EAST FACE 10" LONG AT END BENT 2 NO SECTION LOSS	2	1	Feet
515	Effectiveness (Steel Protective Coatings)	PROTECTIVE COATING HAS FAILED	4	8	8 Square Feet

515	Peeling/Bubbling/Cracking (steel Protective Coatings)	30 SF. OF PEELING PAINT ON FLANGES AND WEB	4	30	30	Square Feet
515	Effectiveness (Steel Protective Coatings)	Substantially effective	2	40	40	Square Feet
<b>General Comments</b>						

**Span 5 Wearing Surface****Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
510	Wearing Surface	990	800	0	190	0	Square Feet
Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
510	Crack (Wearing Surface)	Full length longitudinal/map cracking up to 1/4" wide in travel lanes	3	150	150		Square Feet
510	Crack (Wearing Surface)	FULL WIDTH TRANSVERSE/MAP CRACKS UP TO 1/4" WIDE OVER END BENT 2	3	40	40		Square Feet
<b>General Comments</b>							

**Span 5 Left Bridge Rail****Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
331	Reinforced Concrete Bridge Railing	33	19	2	12	0	Feet
Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	12	12		Feet
331	Delamination/Spall	TWO SPALLS WITH EXPOSED REBAR 3" X 1" X 1/2" DEEP IN TOP OF CURB AT 12 FT AND 6 FT FROM END BENT 2	2	2	2		Feet
<b>General Comments</b>							

**Span 5 Right Bridge Rail****Concrete Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
331	Reinforced Concrete Bridge Railing	33	15	3	15	0	Feet
Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty		
331	Cracking (RC and Other)	Hairline to 1/16" wide transverse/map cracking in curb portion of rail	3	15	15		Feet
331	Delamination/Spall	TWO SPALLS WITH EXPOSED REBAR 3" X 1" X 1/2" DEEP IN TOP/FRONT FACE OF CURB 4 FT FROM END BENT 2	2	2	2		Feet
331	Exposed Rebar	FAR END ON THE TOP OF THE REINFORCED CONCRETE RAIL, EXPOSED REBAR [APPROXIMATELY 5" LONG X 1/2" WIDE] WITH NO MEASURABLE SECTION LOSS	2	1	1		Feet
<b>General Comments</b>							

**Span 5****Near Bearing 1****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail.	4	1	1	Square Feet

**General Comments****Span 5****Far Bearing 1****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Light surface rust	2	1		Each
515	Effectiveness (Steel Protective Coatings)	LIMITED EFFECTIVENESS	4	1	1	Square Feet

**General Comments****Span 5****Near Bearing 2****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with light rust staining present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail	4	1	1	Square Feet

**General Comments****Span 5****Near Bearing 3****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	1	0	0	0	1	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--



Structure Number: 500037

Inspection Date: 11/16/2021

316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with light rust staining present.	3	1	1	Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail	4	1	1	Square Feet
<b>General Comments</b>						

**Span 5 Near Bearing 4**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with light rust staining present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail.	4	1	1 Square Feet
<b>General Comments</b>					

**Span 5 Near Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Section loss on outer edges with greater than 75% remaining. Bearing has previously been painted with active surface corrosion present.	3	1	1 Each
515	Effectiveness (Steel Protective Coatings)	Coating starting to fail.	4	1	1 Square Feet
<b>General Comments</b>					

**Span 5 Far Bearing 5**  
**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	1	0	0	0	1 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	Light surface rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	LIMITED EFFECTIVENESS	4	1	1 Square Feet
<b>General Comments</b>					

**Bent 1****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	40	29	0	11	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Cracking (RC and Other)	[PROMPT ACTION REQUEST] SOUTH FACE AT THE LEFT END, LOWER 10", SPALLING WITH EXPOSED REBAR [APPROXIMATELY 40" LONG X UP TO 2.5" DEEP]	3	2	2 Feet
234	Cracking (RC and Other)	6' LONG X 1/8" WIDE HORIZONTAL CRACK NORTH FACE UNDER BAY 1	3	6	6 Feet
234	Cracking (RC and Other)	HORIZONTAL CRACK 3 FT LONG UP TO 1/8" WIDE IN SOUTH FACE MID WAY BETWEEN COLUMNS 1 AND 2	3	3	3 Feet

General Comments

**Bent 1****Pile 1****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
205	Delamination/Spall	[PROMPT ACTION REQUEST] 6 FOOT X 9" X 2" DEEP SPALL WITH EXPOSED RUSTED REBAR NO SECTION LOSS AT NORTHWEST CORNER	3	1	5 Each
205	Delamination/Spall	3 FT X 9" X 1" DEEP SPALL AND DELAMINATION AT NORTHEAST CORNER	3		3 Each

General Comments

**Bent 1****Pile 2****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
205	Cracking (RC and Other)	SEVERAL AREAS OF DELAMINATIONS WITH CRACKING UP TO 1/16" WIDE ON NORTH FACE	3		6 Each
205	Cracking (RC and Other)	VERTICAL CRACKS UP TO 7 FT LONG AND 1/16" WIDE IN NORTH FACE	3		7 Each
205	Delamination/Spall	4 FT X 1 FT X 1/2" DEEP SPALL AND DELAMINATION WITH CRACKS UP TO 1/8" WIDE IN NORTH FACE	3	1	4 Each

General Comments

**End Bent 1****Abutment****Reinforced Concrete Abutment**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
215	Reinforced Concrete Abutment	60	57	1	2	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
215	Delamination/Spall	SPALL WITH EXPOSED REBAR 12" X 2" X 1/2" DEEP WITH CRACK WITH EFFLORESCENCE 12" LONG X UP TO 1/32" WIDE IN CURTAIN WALL AT WEST END	3	2	2 Feet

Structure Number: 500037Inspection Date: 11/16/2021

215	Cracking (RC and Other)	1' long vertical hairline to 1/32" crack abay 3	2	1	Feet
215	Cracking (RC and Other)	1' long horizontal hairline crack at east end	1	1	Feet

General Comments

**End Bent 1****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	48	38	2	8	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Cracking (RC and Other)	6 FT HORIZONTAL CRACK UP TO 1/16" WIDE UNDER BEAM 1	3	6	6 Feet
234	Delamination/Spall	8" DIAMETER X 1" DEEP SPALL WITH EXPOSED REBAR UNDER BAY 4	3	1	1 Feet
234	Delamination/Spall	8" X 2 FT X 1/2" DEEP SPALL WITH EXPOSED REBAR UNDER BAY 4	3	1	1 Feet
234	Cracking (RC and Other)	2 FT HORIZONTAL CRACK UP TO 1/32" WIDE UNDER BAY 4	2	2	Feet

General Comments

**Bent 2****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	40	19	10	11	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Cracking (RC and Other)	3 FT X 1.5 FT HIGH DELAMINATION WITH CRACK UP TO 1/4" WIDE IN SOUTH FACE UNDER BEAM 3	3	3	3 Feet
234	Cracking (RC and Other)	6FT LONG HORIZONTAL CRACK UP TO 1/4" WIDE UNDER BAYS 1 AND 2 NORTH FACE	3	6	6 Feet
234	Cracking (RC and Other)	DIAGONAL CRACK UP TO 1/16" WIDE BEAM 1 PEDESTAL SPAN 2 SIDE	3	1	1 Feet
234	Cracking (RC and Other)	DIAGONAL CRACK UP TO 1/16" WIDE IN EAST FACE OF PEDESTAL UNDER BEAM 2	3	1	1 Feet
234	Cracking (RC and Other)	2' LONG 1/32" HORIZONTAL CRACK NORTH FACE UNDER BEAM 4	2	2	Feet
234	Cracking (RC and Other)	DIAGONAL CRACK UP TO 1/32" WIDE IN BEAM 2 PEDESTAL EAST FACE	2	1	Feet
234	Cracking (RC and Other)	HORIZONTAL CRACK UP TO 1/32" WIDE ON SOUTH FACE UNDER BEAM 4	2	3	Feet
234	Delamination/Spall	3 FT X 1 FT X 6" DELAMINATION IN UNDERSIDE UNDER BEAM 5 IN FLUTED PORTION	2	3	3 Feet
234	Delamination/Spall	8" DIAMETER DELAMINATION AND 6" DIAMETER X 1/2" DEEP SPALL WITH EXPOSED REBAR NO LOSS IN NORTH FACE UNDER BEAM 1	2	1	1 Feet

General Comments

**Bent 2****Pile 1****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
205	Cracking (RC and Other)	VERTICAL THRU CRACK 7 FOOT LONG UP TO 1/2" WIDE IN MIDDLE OF CRASH WALL BOTH FACES	3	1	14 Each

General Comments

**End Bent 2****Abutment****Reinforced Concrete Abutment**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
215	Reinforced Concrete Abutment	60	59	1	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
215	Delamination/Spall	3" diameter x up to 3/4" deep spall in bay 1 at beam 1 with a 6" long hairline horizontal crack.	2	1	1 Feet

General Comments

**End Bent 2****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	48	44	0	4	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Cracking (RC and Other)	HORIZONTAL CRACK 4 FT LONG UP TO 1/8" WIDE IN FACE OF CAP UNDER BEAM 5	3	4	4 Feet

General Comments

**Bent 3****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	40	38	1	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Delamination/Spall	SPALL WITH EXPOSED REBAR 1 FT X 9" X 1" DEEP IN NORTH FACE UNDER BEAM 4	3	1	1 Feet
234	Delamination/Spall	9" DIAMETER DELAMINATION NORTH FACE UNDER BEAM 5	2	1	1 Feet

General Comments

**Bent 3****Pile 1****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
205	Cracking (RC and Other)	VERTICAL THRU CRACK 7 FOOT LONG X 1/8" WIDE IN MIDDLE OF CRASHWALL BOTH FACES	3		14 Each
205	Cracking (RC and Other)	VERTICAL THRU CRACK 7 FT LONG X 1/4" WIDE IN MIDDLE OF CRASHWALL BOTH FACES	3		7 Each
205	Delamination/Spall	9" X 6" X 1/2" DEEP SPALL WITH EXPOSED REBAR NO LOSS IN SOUTH FACE BELOW CAP	3	1	1 Each
205	Cracking (RC and Other)	AREA OF HAIRLINE MAP CRACKING 10' LONG ON SOUTH FACE OF CRASH WALL	1		Each

General Comments

**Bent 3****Pile 2****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
205	Cracking (RC and Other)	[PROMPT ACTION REQUEST] NORTHEAST CORNER, SPALLING WITH EXPOSED REBAR [APPROXIMATELY 4' HIGH X UP TO 1.25' WIDE X UP TO 3" DEEP]	3		4 Each
205	Delamination/Spall	PAR--SPALL WITH EXPOSED REBAR AND BROKEN HORIZONTAL TIE 3 FOOT X 1 FOOT X 4" DEEP IN NORTHEAST CORNER MID HEIGHT WITH SECTION LOSS	3	1	3 Each

General Comments

**Bent 4****Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	40	38	2	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Cracking (RC and Other)	2 hairline to 1/32" wide horizontal cracks on east face of cap that extend on to north face 1.5' long.	2	2	Feet

General Comments

**Bent 4****Pile 1****Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
205	Reinforced Concrete Column	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
205	Cracking (RC and Other)	VERTICAL CRACK 5 FT LONG UP TO 1/8" WIDE AT NORTHEAST CORNER	3	1	5 Each

General Comments

**Bent 4**

**Pile 2**

**Reinforced Concrete Column**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
205	Reinforced Concrete Column	1	0	0	1	0	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
205	Cracking (RC and Other)	6 FOOT X 9" AREA OF DELAMINATION WITH CRACKING UP TO 1/8" WIDE AT NORTHEAST CORNER	3	1	6	Each

General Comments

## Elements Verified

Location	Name	Component	Element Name	Amount
Span 1	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1273
Span 1	Beam 1	Plate Girder	Steel Open Girder/Beam	38
Span 1	Beam 2	Plate Girder	Steel Open Girder/Beam	38
Span 1	Beam 3	Plate Girder	Steel Open Girder/Beam	38
Span 1	Beam 4	Plate Girder	Steel Open Girder/Beam	38
Span 1	Beam 5	Plate Girder	Steel Open Girder/Beam	38
Span 1	Left Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	38
Span 1	Right Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	38
Span 1	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	1140
Span 1	Near Bearing 1	Other Bearing	Other Bearings	1
Span 1	Far Bearing 1	Other Bearing	Other Bearings	1
Span 1	Far Bearing 2	Other Bearing	Other Bearings	1
Span 1	Near Bearing 2	Other Bearing	Other Bearings	1
Span 1	Near Bearing 3	Other Bearing	Other Bearings	1
Span 1	Far Bearing 3	Other Bearing	Other Bearings	1
Span 1	Far Bearing 4	Other Bearing	Other Bearings	1
Span 1	Near Bearing 4	Other Bearing	Other Bearings	1
Span 1	Near Bearing 5	Other Bearing	Other Bearings	1
Span 1	Far Bearing 5	Other Bearing	Other Bearings	1
Span 2	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1257
Span 2	Beam 1	Plate Girder	Steel Open Girder/Beam	38
Span 2	Beam 2	Plate Girder	Steel Open Girder/Beam	38
Span 2	Beam 3	Plate Girder	Steel Open Girder/Beam	38
Span 2	Beam 4	Plate Girder	Steel Open Girder/Beam	38
Span 2	Beam 5	Plate Girder	Steel Open Girder/Beam	38
Span 2	Left Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	38
Span 2	Right Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	38
Span 2	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	1125
Span 2	Near Bearing 1	Other Bearing	Other Bearings	1
Span 2	Far Bearing 1	Other Bearing	Other Bearings	1
Span 2	Far Bearing 2	Other Bearing	Other Bearings	1
Span 2	Near Bearing 2	Other Bearing	Other Bearings	1
Span 2	Near Bearing 3	Other Bearing	Other Bearings	1
Span 2	Far Bearing 3	Other Bearing	Other Bearings	1
Span 2	Far Bearing 4	Other Bearing	Other Bearings	1
Span 2	Near Bearing 4	Other Bearing	Other Bearings	1
Span 2	Near Bearing 5	Other Bearing	Other Bearings	1
Span 2	Far Bearing 5	Other Bearing	Other Bearings	1
Span 3	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1592
Span 3	Beam 1	Plate Girder	Steel Open Girder/Beam	48
Span 3	Beam 2	Plate Girder	Steel Open Girder/Beam	48
Span 3	Beam 3	Plate Girder	Steel Open Girder/Beam	48
Span 3	Beam 4	Plate Girder	Steel Open Girder/Beam	48
Span 3	Beam 5	Plate Girder	Steel Open Girder/Beam	48
Span 3	Left Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	48

## Elements Verified

Location	Name	Component	Element Name	Amount
Span 3	Right Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	48
Span 3	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	1425
Span 3	Near Bearing 1	Other Bearing	Other Bearings	1
Span 3	Far Bearing 1	Other Bearing	Other Bearings	1
Span 3	Far Bearing 2	Other Bearing	Other Bearings	1
Span 3	Near Bearing 2	Other Bearing	Other Bearings	1
Span 3	Near Bearing 3	Other Bearing	Other Bearings	1
Span 3	Far Bearing 3	Other Bearing	Other Bearings	1
Span 3	Far Bearing 4	Other Bearing	Other Bearings	1
Span 3	Near Bearing 4	Other Bearing	Other Bearings	1
Span 3	Near Bearing 5	Other Bearing	Other Bearings	1
Span 3	Far Bearing 5	Other Bearing	Other Bearings	1
Span 4	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1089
Span 4	Beam 1	Plate Girder	Steel Open Girder/Beam	33
Span 4	Beam 2	Plate Girder	Steel Open Girder/Beam	33
Span 4	Beam 3	Plate Girder	Steel Open Girder/Beam	33
Span 4	Beam 4	Plate Girder	Steel Open Girder/Beam	33
Span 4	Beam 5	Plate Girder	Steel Open Girder/Beam	33
Span 4	Left Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	33
Span 4	Right Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	33
Span 4	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	975
Span 4	Near Bearing 1	Other Bearing	Other Bearings	1
Span 4	Far Bearing 1	Other Bearing	Other Bearings	1
Span 4	Far Bearing 2	Other Bearing	Other Bearings	1
Span 4	Near Bearing 2	Other Bearing	Other Bearings	1
Span 4	Near Bearing 3	Other Bearing	Other Bearings	1
Span 4	Far Bearing 3	Other Bearing	Other Bearings	1
Span 4	Far Bearing 4	Other Bearing	Other Bearings	1
Span 4	Near Bearing 4	Other Bearing	Other Bearings	1
Span 4	Near Bearing 5	Other Bearing	Other Bearings	1
Span 4	Far Bearing 5	Other Bearing	Other Bearings	1
Span 5	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1106
Span 5	Beam 1	Plate Girder	Steel Open Girder/Beam	33
Span 5	Beam 2	Plate Girder	Steel Open Girder/Beam	33
Span 5	Beam 3	Plate Girder	Steel Open Girder/Beam	33
Span 5	Beam 4	Plate Girder	Steel Open Girder/Beam	33
Span 5	Beam 5	Plate Girder	Steel Open Girder/Beam	33
Span 5	Left Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	33
Span 5	Right Bridge Rail	Concrete Railing	Reinforced Concrete Bridge Railing	33
Span 5	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	990
Span 5	Far Bearing 1	Other Bearing	Other Bearings	1
Span 5	Near Bearing 1	Other Bearing	Other Bearings	1
Span 5	Near Bearing 2	Other Bearing	Other Bearings	1
Span 5	Far Bearing 2	Other Bearing	Other Bearings	1
Span 5	Far Bearing 3	Other Bearing	Other Bearings	1



## Elements Verified

Location	Name	Component	Element Name	Amount
Span 5	Near Bearing 3	Other Bearing	Other Bearings	1
Span 5	Near Bearing 4	Other Bearing	Other Bearings	1
Span 5	Far Bearing 4	Other Bearing	Other Bearings	1
Span 5	Far Bearing 5	Other Bearing	Other Bearings	1
Span 5	Near Bearing 5	Other Bearing	Other Bearings	1
Bent 1	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	40
Bent 1	Pile 1	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 1	Pile 2	Reinforced Concrete Column	Reinforced Concrete Column	1
End Bent 1	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	48
End Bent 1	Abutment	Reinforced Concrete Abutment	Reinforced Concrete Abutment	60
Bent 2	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	40
Bent 2	Pile 1	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 2	Pile 2	Reinforced Concrete Column	Reinforced Concrete Column	1
End Bent 2	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	48
End Bent 2	Abutment	Reinforced Concrete Abutment	Reinforced Concrete Abutment	60
Bent 3	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	40
Bent 3	Pile 1	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 3	Pile 2	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 4	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	40
Bent 4	Pile 1	Reinforced Concrete Column	Reinforced Concrete Column	1
Bent 4	Pile 2	Reinforced Concrete Column	Reinforced Concrete Column	1

# General Inspection Notes

# National Bridge and NC Inspection Items

Structure Number: 500037

Inspection Date: 11/16/2021

## National Bridge Inventory Items

Item	Grade Scale	Grade
Item 58: Deck	0 - 9 , N	6
Item 59: Superstructure	0 - 9 , N	5
Item 60: Substructure	0 - 9 , N	5
Item 61: Channel and Channel Protection	0 - 9 , N	N
Item 62: Culvert	0 - 9 , N	N
Item 71: Waterway Adequacy	0 - 9 , N	N
Item 72: Approach Roadway Alignment	0 - 9 , N	8

**Note:**  
Items 58,59,60,62 reflect this inspection only.  
  
For overall NBI coding grade, see cover sheet.

Note: If NBI Inspection Item is not present, code NBI item with "N"

## NC SMU Inspection Items

Item	Grade Scale	Grade	Maint. Qty.	Maint. Code
Deck Debris	G, F, P, or C	F	6676	3376
Drainage System	G, F, P, or C	G	0	3332
Utilities	G, F, P, or C			
Slope Protection	G, F, P, or C		0	3352
Scour	G, F, P, or C			
Wingwall	G, F, P, or C	G	0	3350
Field Scour Evaluation				
Drift	G, F, P, or C		0	3366
Fender System	G, F, P, or C		0	3364
Movable Span Machinery	G, F, P, or C			
Response to Live Load	G, F, P, or C	G		
Superstructure Paint Code		A		

Note: If NC SMU Inspection Item is not present, leave NC SMU item blank

## Inspection Information

Item	Grade Scale	Grade
Sign Noticed Issued	YES/NO	N
Priority Maintenance Request Submitted	YES/NO	Y
Inspection Time	Hours	7
Traffic Control Time	Hours	
Snooper Time	Hours	
Ladder Used	YES/NO	Y
Bucket Truck Used	YES/NO	N
Boat Used	YES/NO	N
Other Equipment Used	YES/NO	N
Portion of Structure in > 3' of water	YES/NO	N

# National Bridge and NC SMU Inspection Item Details

Structure Number: 500037

Inspection Date: 11/16/2021

---

<b>Item</b>	Deck - Item 58	<b>Grade</b>	6	<b>Maint Code</b>		<b>Qty.</b>	0
-------------	----------------	--------------	---	-------------------	--	-------------	---

**Details** GRADING MAINTAINED

---

<b>Item</b>	Superstructure - Item 59	<b>Grade</b>	5	<b>Maint Code</b>		<b>Qty.</b>	0
-------------	--------------------------	--------------	---	-------------------	--	-------------	---

**Details** GRADING MAINTAINED

---

<b>Item</b>	Substructure - Item 60	<b>Grade</b>	5	<b>Maint Code</b>		<b>Qty.</b>	0
-------------	------------------------	--------------	---	-------------------	--	-------------	---

**Details** GRADING MAINTAINED

---

<b>Item</b>	Deck Debris	<b>Grade</b>	F	<b>Maint Code</b>	3376	<b>Qty.</b>	6676
-------------	-------------	--------------	---	-------------------	------	-------------	------

**Details** RIGHT AND LEFT GUTTERLINES, DEBRIS ACCUMULATION ALONG THE LENGTHS



Span 1 Left Bridge Rail: 4" DIAMETER X 1" DEEP SPALL WITH EXPOSED REBAR AT END POST AT SOUTHWEST CORNER



RIGHT AND LEFT GUTTERLINES, DEBRIS ACCUMULATION ALONG THE LENGTHS



Span 1 Wearing Surface: FULL WIDTH TRANSVERSE/MAP CRACKING UP TO 1/2" WIDE OVER END BENT 1 AND BENT 1, BENT 1 SHOWN



Span 1 Wearing Surface: FULL WIDTH TRANSVERSE/MAP CRACKING UP TO 1/2" WIDE OVER END BENT 1 AND BENT 1, BENT 1 SHOWN



Span 3 Wearing Surface: FULL WIDTH TRANSVERSE/MAP CRACK UP TO 2" WIDE WITH ASPHALT DETERIORATION WITH UP TO 3/4" DEEP POT HOLES UP TO 1' LONG X 2" WIDE OVER BENT 3



Span 3 Wearing Surface: FULL WIDTH TRANSVERSE/MAP CRACK UP TO 2" WIDE WITH ASPHALT DETERIORATION WITH UP TO 3/4" DEEP POT HOLES UP TO 1' LONG X 2" WIDE OVER BENT 3



Span 3 Wearing Surface: 3' Long x 6" wide x 2 1/2" deep pothole at right shoulder at pier 3



Span 5 Right Bridge Rail: FAR END ON THE TOP OF THE REINFORCED CONCRETE RAIL, EXPOSED REBAR [APPROXIMATELY 5" LONG X 1/2" WIDE] WITH NO MEASURABLE SECTION LOSS





Span 1 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE LOWER CORNER OF THE INTERFACE THERE IS A HOLE [APPROXIMATELY 1/2" DIAMETER]. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 7/16" REMAINS] FOR APPROXIMATELY 6' LONG. AT THE SAME END IN THE LOWER 3" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 6' LONG.



Span 1 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE LOWER CORNER OF THE INTERFACE THERE IS A HOLE [APPROXIMATELY 1/2" DIAMETER]. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 7/16" REMAINS] FOR APPROXIMATELY 6' LONG. AT THE SAME END IN THE LOWER 3" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 6' LONG.



Span 1 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 1 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 1 Beam 4: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 1 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 2 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 2 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.





Span 2 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 2 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 4 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 4 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.



Span 3 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER LEFT FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 5' LONG. AT 1.5' OUT FROM THE SAME END IN THE LOWER 5" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 3' LONG.



Span 3 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 IN THE LEFT LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH EDGE HOLES UP TO 3/4" DIAMETER. AT THE SAME END IN THE LOWER 6" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH PERFORATIONS THROUGHOUT.



Span 3 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 IN THE LEFT LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH EDGE HOLES UP TO 3/4" DIAMETER. AT THE SAME END IN THE LOWER 6" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH PERFORATIONS THROUGHOUT.



Span 4 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 3' LONG.





Span 4 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 3' LONG.



Span 4 Beam 5: PAR--SECTION LOSS UP TO 3/8" WITH 3/8" AVERAGE REMAINING FULL WIDTH OF BOTTOM FLANGE 1FT LONG ON BEAM END OVER PIER 3. BEAM END HAS BEEN CLEANED AND PAINTED WITH ACTIVE SURFACE CORROSION. PLATE REPAIR ADDED BUT DOES NOT EXTEND OUT TO DEFECT.



Span 5 Beam 2: PAR--1 FOOT LONG X 2" WIDE AREA OF PREVIOUS CORROSION WITH 1/4" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 AREA HAS BEEN PAINTED OVER AND ARRESTED.



Span 5 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/4" REMAINS] FOR APPROXIMATELY 4' LONG. AT THE SAME END IN THE LOWER 4" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 4' LONG.



Bent 3 Pile 2: PAR--SPALL WITH EXPOSED REBAR AND BROKEN HORIZONTAL TIE 3 FOOT X 1 FOOT X 4" DEEF IN NORTHEAST CORNER MID HEIGHT WITH SECTION LOSS



Bent 1 Cap 1: [PROMPT ACTION REQUEST] SOUTH FACE AT THE LEFT END, LOWER 10", SPALLING WITH EXPOSED REBAR [APPROXIMATELY 40" LONG X UP TO 2.5" DEEP]



Bent 1 Pile 1: 3 FOOT X 9" X 1" DEEP SPALL AND DELAMINATION AT NORTHEAST CORNER



Bent 1 Pile 1: [PROMPT ACTION REQUEST] 6 FOOT X 9" X 2" DEEP SPALL WITH EXPOSED RUSTED REBAR NO SECTION LOSS AT NORTHWEST CORNER




Bent 3 Pile 2: [PROMPT ACTION REQUEST] NORTHEAST CORNER, SPALLING WITH EXPOSED REBAR  
[APPROXIMATELY 4' HIGH X UP TO 1.25' WIDE X UP TO 3" DEEP]

# Structure Data Worksheet

## Span Profile

County: **JOHNSTON**

Structure Number: **500037**



A: SPAN LENGTH  
 B: BEARING TO BEARING  
 C: DISTANCE FROM NEAR BEARING  
 D: DISTANCE TO FAR BEARING

Span Number	Span Length	Bearing to Bearing	Crutch/ Helper Bent	Distance to Near Bearing	Distance to Far Bearing
1	38.000	36.000			
2	37.500	36.500			
3	47.500	46.500			
4	32.500	31.500			
5	33.000	31.000			



Structure Number: 500037

Span: 3

Route Name: Railroad



SPAN 3, LOOKING EAST AT THE RAIL LINE

<b>Route Number:</b> 80000000		<b>Route Name:</b> Railroad			<b>Reference Feature:</b> R	
<b>Minimum Vertical Clearance</b> 21.250 feet		<b>Maximum Minimum Vertical Clearance</b> feet				
<b>Total Horizontal Clearance</b> 33.250 feet		<b>Lateral Clearances: Left:</b> 21.500 feet		<b>Right:</b> 11.750 feet		
<input type="checkbox"/> <b>Base Highway Network</b>		<b>LRS Inventory Route, Sub Route Number</b>				
<b>Milepost:</b> 0.000	<b>Number of Lanes:</b>	<b>ADT:</b>	<b>Year of ADT:</b>	<b>Percentage of Trucks:</b> 0		
<input type="checkbox"/> <b>National Highway System</b>			<input type="checkbox"/> <b>STRAHNET Highway Designator</b>			
<b>Functional Classification</b>			<b>Direction of Traffic:</b>			



SOUTHWEST CORNER, GUARDRAIL END



SOUTHEAST CORNER, GUARDRAIL END



SOUTH APPROACH LOOKING NORTH



SOUTHWEST CORNER, GUARDRAIL TRANSITION



SOUTHWEST CORNER, GUARDRAIL NOT CONNECTED



SOUTHEAST CORNER, GUARDRAIL TRANSITION AND CONNECTION [SIMILAR AT THE NORTHEAST CORNER]



FROM THE DECK, LOOKING WEST AT THE RAIL LINE



FROM THE DECK, LOOKING EAST AT THE RAIL LINE



NORTHWEST CORNER, GUARDRAIL TRANSITION AND CONNECTION



NORTH APPROACH LOOKING SOUTH



NORTHWEST CORNER, GUARDRAIL END



NORTHEAST CORNER, GUARDRAIL END



FROM THE DECK, LOOKING NORTH



FROM THE DECK, LOOKING SOUTH





SOUTHWEST CORNER, REINFORCED CONCRETE WING [SIMILAR AT THE NORTHWEST CORNER, NORTHEAST CORNER, & SOUTHEAST CORNER]



SPAN 1 GIRDER 3 NEAR BEARING [TYPICAL BEARING AT THE ABUTMENTS]



ABUTMENT 1, LOOKING SOUTH



BENT 1, LOOKING SOUTH [BENT 4 SIMILAR]



BENT 2, LOOKING NORTH [BENT 3 SIMILAR]



SPAN 2 SUPERSTRUCTURE, LOOKING NORTH [ALL SPANS SIMILAR]



GIRDERS 2 BEARINGS AT BENT 4 [TYPICAL BEARINGS AT THE BENTS]



ABUTMENT 2, LOOKING NORTH



SPAN 3, LOOKING EAST AT THE RAIL LINE



SPAN 3, LOOKING WEST AT THE RAIL LINE



EAST PROFILE, LOOKING WEST





# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

Date:

**These Repairs Should Be Made Within Twelve Months From Date Of This Inspection**

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	6	Span 1 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE LOWER CORNER OF THE INTERFACE THERE IS A HOLE [APPROXIMATELY 1/2" DIAMETER]. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 7/16" REMAINS] FOR APPROXIMATELY 6' LONG. AT THE SAME END IN THE LOWER 3" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 6' LONG.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 1 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 1 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 1 Beam 4: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	

Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined






# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

Date:

**These Repairs Should Be Made Within Twelve Months From Date Of This Inspection**

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	1	Span 1 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 2 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 2 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 2 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 2 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	

**Key**

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined






# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

Date:

**These Repairs Should Be Made Within Twelve Months From Date Of This Inspection**

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	4	Span 3 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 IN THE LEFT LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH EDGE HOLES UP TO 3/4" DIAMETER. AT THE SAME END IN THE LOWER 6" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH PERFORATIONS THROUGHOUT.	
 3314	Maintain Steel Superstructure Components	LF	5	Span 3 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER LEFT FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 5' LONG. AT 1.5' OUT FROM THE SAME END IN THE LOWER 5" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 3' LONG.	
 3314	Maintain Steel Superstructure Components	LF	3	Span 4 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 3' LONG.	

**Key**

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined






# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

Date:

**These Repairs Should Be Made Within Twelve Months From Date Of This Inspection**

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	1	Span 4 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 4 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 4 Beam 5: PAR--SECTION LOSS UP TO 3/8" WITH 3/8" AVERAGE REMAINING FULL WIDTH OF BOTTOM FLANGE 1FT LONG ON BEAM END OVER PIER 3. BEAM END HAS BEEN CLEANED AND PAINTED WITH ACTIVE SURFACE CORROSION. PLATE REPAIR ADDED BUT DOES NOT EXTEND OUT TO DEFECT.	
 3314	Maintain Steel Superstructure Components	LF	1	Span 5 Beam 2: PAR--1 FOOT LONG X 2" WIDE AREA OF PREVIOUS CORROSION WITH 1/4" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 AREA HAS BEEN PAINTED OVER AND ARRESTED.	
 3314	Maintain Steel Superstructure Components	LF	4	Span 5 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/4" REMAINS] FOR APPROXIMATELY 4' LONG. AT THE SAME END IN THE LOWER 4" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 4' LONG.	

**Key**

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined





# BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

Date:

**These Repairs Should Be Made Within Twelve Months From Date Of This Inspection**

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3348	Maintain Concrete Substructure Components	LF	2	Bent 1 Cap 1: [PROMPT ACTION REQUEST] SOUTH FACE AT THE LEFT END, LOWER 10", SPALLING WITH EXPOSED REBAR [APPROXIMATELY 40" LONG X UP TO 2.5" DEEP]	
 3348	Maintain Concrete Substructure Components	LF	5	Bent 1 Pile 1: [PROMPT ACTION REQUEST] 6 FOOT X 9" FOOT X 2" DEEP SPALL WITH EXPOSED RUSTED REBAR NO SECTION LOSS AT NORTHWEST CORNER	
 3348	Maintain Concrete Substructure Components	LF	3	Bent 3 Pile 2: PAR--SPALL WITH EXPOSED REBAR AND BROKEN HORIZONTAL TIE 3 FOOT X 1 FOOT X 4" DEEP IN NORTHEAST CORNER MID HEIGHT WITH SECTION LOSS	
 3348	Maintain Concrete Substructure Components	LF	4	Bent 3 Pile 2: [PROMPT ACTION REQUEST] NORTHEAST CORNER, SPALLING WITH EXPOSED REBAR [APPROXIMATELY 4' HIGH X UP TO 1.25' WIDE X UP TO 3" DEEP]	

**Key**

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	6      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 1 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE LOWER CORNER OF THE INTERFACE THERE IS A HOLE [APPROXIMATELY 1/2" DIAMETER]. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 7/16" REMAINS] FOR APPROXIMATELY 6' LONG. AT THE SAME END IN THE LOWER 3" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 6' LONG.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 1 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 1 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 1 Beam 4: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 1 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 2 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 2 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level		Status
Priority Maintenance		Division Bridge Maintenance Notification
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 2 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level		Status
Priority Maintenance		Division Bridge Maintenance Notification
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 2 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 1 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 3" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		



## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	4      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 3 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 IN THE LEFT LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH EDGE HOLES UP TO 3/4" DIAMETER. AT THE SAME END IN THE LOWER 6" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/16" REMAINS] FOR APPROXIMATELY 4' LONG WITH PERFORATIONS THROUGHOUT.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	5      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 3 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 2" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER LEFT FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 5' LONG. AT 1.5' OUT FROM THE SAME END IN THE LOWER 5" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 1/8" REMAINS] FOR APPROXIMATELY 3' LONG.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	3 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 4 Beam 1: [PROMPT ACTION REQUEST] BEAM END AT BENT 3 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM. AT THE SAME END IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 3' LONG.</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 4 Beam 2: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 3/8" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 4 Beam 3: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 AT THE INTERFACE WITH THE REINFORCED CONCRETE DIAPHRAGM, THERE IS A BAND OF CORROSION UP TO 1" WIDE WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 1' LONG X UP TO THE FULL HEIGHT OF THE DIAPHRAGM.</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 4 Beam 5: PAR--SECTION LOSS UP TO 3/8" WITH 3/8" AVERAGE REMAINING FULL WIDTH OF BOTTOM FLANGE 1FT LONG ON BEAM END OVER PIER 3. BEAM END HAS BEEN CLEANED AND PAINTED WITH ACTIVE SURFACE CORROSION. PLATE REPAIR ADDED BUT DOES NOT EXTEND OUT TO DEFECT.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 5 Beam 2: PAR--1 FOOT LONG X 2" WIDE AREA OF PREVIOUS CORROSION WITH 1/4" REMAINING SECTION IN WEB AROUND END DIAPHRAGM AT BENT 4 AREA HAS BEEN PAINTED OVER AND ARRESTED.</p>		

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	4      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
<p>Span 5 Beam 5: [PROMPT ACTION REQUEST] BEAM END AT BENT 4 IN THE LOWER FLANGE, CORROSION WITH SECTION LOSS [AVERAGE 1/4" REMAINS] FOR APPROXIMATELY 4' LONG. AT THE SAME END IN THE LOWER 4" OF THE WEB, CORROSION WITH SECTION LOSS [AVERAGE 5/16" REMAINS] FOR APPROXIMATELY 4' LONG.</p>		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3348	Maintain Concrete Substructure Components	2 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
Bent 1 Cap 1: [PROMPT ACTION REQUEST] SOUTH FACE AT THE LEFT END, LOWER 10", SPALLING WITH EXPOSED REBAR [APPROXIMATELY 40" LONG X UP TO 2.5" DEEP]		

MMS Code	MMS Description	Quantity
3348	Maintain Concrete Substructure Components	5 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
Bent 1 Pile 1: [PROMPT ACTION REQUEST] 6 FOOT X 9" FOOT X 2" DEEP SPALL WITH EXPOSED RUSTED REBAR NO SECTION LOSS AT NORTHWEST CORNER		

## BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500037

County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3348	Maintain Concrete Substructure Components	3      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
Bent 3 Pile 2: PAR--SPALL WITH EXPOSED REBAR AND BROKEN HORIZONTAL TIE 3 FOOT X 1 FOOT X 4" DEEP IN NORTHEAST CORNER MID HEIGHT WITH SECTION LOSS		

MMS Code	MMS Description	Quantity
3348	Maintain Concrete Substructure Components	4      LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
11/17/2021	ERIC A. PATTERSON	
Details		
Bent 3 Pile 2: [PROMPT ACTION REQUEST] NORTHEAST CORNER, SPALLING WITH EXPOSED REBAR [APPROXIMATELY 4' HIGH X UP TO 1.25' WIDE X UP TO 3" DEEP]		

# Bridge Inspection Field Sketch



SOUTH APPROACH (LOOKING NORTH)  
MEASUREMENTS TAKEN AT 15 FT SOUTH OF END BENT 1


Roadway	23ft Wide	2 Paved Lanes	Looking North
Left Shoulder	5ft Wide	4ft Paved	1ft Unpaved
Right Shoulder	5ft Wide	4ft Paved	1ft Unpaved
Left Guardrail	5ft from road		
Right Guardrail	5ft from road		

NO CHANGE: KEITH PROCTOR ON 16-NOV-2021

<b>Title</b> SOUTH APPROACH ROADWAY		<b>Description</b> TYPICAL SECTION	
<b>Bridge No:</b> 500037	<b>Drawn By:</b> GGW	<b>Date:</b> 04/12/2006	<b>File Name:</b> S0214000199



# Bridge Inspection Field Sketch



<b>Cap Information</b>			<b>Material</b> Cast-in-Place Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
39.000 ft.	2.500 ft.	3.167 ft.	9.500 ft.	9.500 ft.	2.000 ft.	2.000 ft.				
<b>Subcap Information</b>			<b>Material</b>							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
<b>Sill Information</b>			<b>Material</b>							
Length	Width	Height								
<b>Pile #</b>	<b>Material</b>	<b>Spacing</b>	<b>Width/Dia.</b>	<b>Height</b>	<b>Length</b>	<b>Orientation</b>	<b>Driven?</b>	<b>Replacement?</b>	<b>Removed?</b>	<b>Collar?</b>
1	Concrete	20 ft.	3.75 ft.	2 ft.		Vertical	No	No	No	No
2	Concrete		3.75 ft.	2 ft.		Vertical	No	No	No	No
<b>Bent/Abutment #:</b> 1			<b>Similar Bents:</b> 2-4							


CRASH WALLS AT BENTS 2 AND 3

NO CHANGE: KEITH PROCTOR ON 16-NOV-2021

<b>Title</b>			<b>Description</b>			
SUBSTRUCTURE			TYPICAL BENT PROFILE			
<b>Bridge No:</b> 500037	<b>Drawn By:</b> DAVID WAGNER	<b>Date:</b> 3/13/2017	<b>File Name:</b> S0422000450			

# Bridge Inspection Field Sketch


Deck Width/Out to Out	35.417ft	Between Rails	33.333ft
Clear Roadway	30.083ft	Wearing Surface	0.333ft
Median Width		Median Height	
Curb Height		Left	0.625ft
		Right	0.625ft
Sidewalk Width		Left	
		Right	
Clear Roadway (Rail to Median)		Left	
		Right	
Guardrail Width		Left	1.042ft
		Right	1.042ft
Top of Rail to Deck/Wearing Surface		Left	2.25ft
		Right	2.25ft
Bridge Rail		Left	Type 14
		Right	Type 14



Measurements for Span #	1	ALL SPANS SIMILAR	
Deck Thickness	0.542	Left Overhang	4.041
Top of Rail to Bottom of Beam (A&B)	5.25	Right Overhang	4.041

5.75' (SPAN C) 5.00' (SPANS D&E)

Beam Number	Beam Type	Spacing	Comments
1	Steel I Beam	6.833ft	
2	Steel I Beam	6.833ft	
3	Steel I Beam	6.833ft	
4	Steel I Beam	6.833ft	
5	Steel I Beam	ft	



NO CHANGE: KEITH PROCTOR ON 16-NOV-2021

<b>Title</b> SUPERSTRUCTURE	<b>Description</b> TYPICAL SECTION
Bridge No: 500037	Drawn By: GGW
Date: 04/12/2006	File Name: S0214000200

# Bridge Inspection Field Sketch

THIS PAGE INTENTIONALLY BLANK

**Title**

DELETED

**Description**

DELETED

**Bridge No:** 500037

**Drawn By:** WTW

**Date:** 11/6/2013

**File Name:** S0214000201