



NC DEPARTMENT OF TRANSPORTATION
 DIVISION OF HIGHWAYS
 STRUCTURE MANAGEMENT UNIT

ATTENTION: **SNOOPER USED, NEW REPAIRS, NEW LMC OVERLAY, PAR SUBMITTED, CHANGE TO STRUCTURE DATA, NEWLY STRUCTURALLY DEFICIENT, CHANGE IN NBI RATING FOR ITEMS 60 AND 61.**

Structure Safety Report

Routine Element Inspection - Contract

INSPECTION DATE: 06/26/2019

DIVISION: 4 COUNTY: JOHNSTON STRUCTURE NUMBER: 500101 FREQUENCY: 24 MONTHS

FACILITY CARRIED: I95 SBL MILE POST: 91.5

LOCATION: 1.8 MI N. JCT 301/US

FEATURE INTERSECTED: NEUSE RIVER

LATITUDE: 35° 28' 39.74" LONGITUDE: 78° 22' 4.59"

SUPERSTRUCTURE: RC FLOOR/I-BEAMS

SUBSTRUCTURE: EBT:RC CAP/STL.PILES;IBTS:RC CAP/ENCASED STL.PILES

SPANS: 8 SPANS. SEE SPAN PROFILE SHEET FOR SPAN DETAILS

FRACTURE CRITICAL TEMPORARY SHORING SCOUR CRITICAL SCOUR PLAN OF ACTION

NBI GRADES: DECK 5 SUPERSTRUCTURE 6 SUBSTRUCTURE 4 CULVERT N

POSTED SV: Not Posted POSTED TTST: Not Posted

OTHER SIGNS PRESENT: (1) DELINEATOR, (1) NEUSE RIVER SIGN



Sign noticed issued for	Number Required
<u>NO</u> WEIGHT LIMIT	<u>0</u>
<u>NO</u> DELINEATORS	<u>0</u>
<u>NO</u> NARROW BRIDGE	<u>0</u>
<u>NO</u> ONE LANE BRIDGE	<u>0</u>
<u>NO</u> LOW CLEARANCE	<u>0</u>

DIRECTION OF INSPECTION: S-N

DIRECTION MATCHES PLANS: NO PLANS

LOOKING NORTH

INSPECTED BY RAGHUVVEER SURAPANENI	SIGNATURE <i>R. Surapaneni</i>	ASSISTED BY ANGELICA PILARSKI
---------------------------------------	-----------------------------------	----------------------------------

NATIONAL BRIDGE INVENTROY ----- STRUCTURE INVENTORY AND APPRAISAL

10/28/2019

IDENTIFICATION

(1) STATE NAME NORTH CAROLINA BRIDGE 500101
 (8) STRUCTURE NUMBER (FEDERAL) 1010101
 (5) INVENTORY ROUTE (ON/UNDER) ON 111000950
 (2) STATE HIGHWAY DEPARTMENT DISTRICT 4
 (3) COUNTY CODE (FEDERAL) 101 (4) PLACE CODE 62520
 (6) FEATURE INTERSECTED NEUSE RIVER
 (7) FACILITY CARRIED I95 SBL
 (9) LOCATION 1.8 MI N. JCT 301/US
 (11) MILEPOINT 91.5
 (12) BASE HIGHWAY NETWORK 1
 (13) LRS INVENTORY ROUTE & SUBROUTE 10095
 (16) LATITUDE 35° 28' 39.74" (17) LONGITUDE 78° 22' 4.59"
 (98) BORDER BRIDGE STATE CODE PERCENT SHARED
 (99) BORDER BRIDGE STRUCTURE NUMBER

SUFFICIENCY RATING 38.00000
 STATUS = Structurally Deficient

CLASSIFICATION

(112) NBIS BRIDGE SYSTEM YES
 (104) HIGHWAY SYSTEM Inventory Route is on NHS 1
 (26) FUNCTIONAL CLASS Urban Principal Arterial - Interstate 11
 (100) STRAHNET HIGHWAY Interstate STRAHNET Route 1
 (101) PARALLEL STRUCTURE The left structure of parallel bridges L
 (102) DIRECTION OF TRAFFIC 1-way traffic 1
 (103) TEMPORARY STRUCTURE
 (110) DESIGNATED NATIONAL NETWORK - on national network for trucks 1
 (20) TOLL On Free Road 3
 (21) MAINT - 01
 (22) OWNER - 01
 (37) HISTORICAL SIGNIFICANCE - 5

STRUCTURE TYPE AND MATERIAL

(43) STRUCTURE TYPE MAIN Steel
 TYPE Stringer/Multi-beam or girder CODE 302
 (44) STRUCTURE TYPE APPROACH
 TYPE CODE
 (45) NUMBER OF SPANS IN MAIN UNIT 8
 (46) NUMBER OF SPANS IN APPROACH 0
 (107) DECK STRUCTURE TYPE CODE 1
 (108) WEARING SURFACE/PROTECTIVE SYSTEM
 (A) TYPE OF WEARING SURFACE CODE 6
 (B) TYPE OF MEMBRANE CODE 0
 (C) TYPE OF DECK PROTECTION CODE 0

CONDITION

(58) DECK 5
 (59) SUPERSTRUCTURE 6
 (60) SUBSTRUCTURE 4
 (61) CHANNEL & CHANNEL PROTECTION 4
 (62) CULVERTS N

LOAD RATING AND POSTING

(31) DESIGN LOAD H 20 + Mod 6
 (63) OPERATING RATING METHOD - Load Factor 1
 (64) OPERATING RATING - HS-41 77
 (65) INVENTORY RATING METHOD - 1
 (66) INVENTORY RATING HS-24 46
 (70) BRIDGE POSTING No Posting Required 5
 (41) STRUCTURE OPEN, POSTED, OR CLOSED DESCRIPTION Open, no restriction A

AGE AND SERVICE

(27) YEAR BUILT 1955
 (106) YEAR RECONSTRUCTED 0.000000
 (42) TYPE OF SERVICE ON - Highway
 OFF - Waterway CODE 15
 (28) LANES ON STRUCTURE 2 LANES UNDER STRUCTURE 0
 (29) AVERAGE DAILY TRAFFIC 22750
 (30) YEAR OF ADT 2018 (109) TRUCK ADT PCT 16
 (19) BYPASS OR DETOUR LENGTH 4.0

APPRAISAL

(67) STRUCTURAL EVALUATION 4
 (68) DECK GEOMETRY 3
 (69) UNDERCLEARANCES, VERT & HORIZ N
 (71) WATERWAY ADEQUACY 4
 (72) APPROACH ROADWAY ALIGNMENT 3
 (36) TRAFFIC SAFETY FEATURES 1111
 (113) SCOUR CRITICAL BRIDGES 8

GEOMETRIC DATA

(48) LENGTH OF MAXIMUM SPAN 49.0
 (49) STRUCTURE LENGTH 401.0
 (50) CURB OR SIDEWALK: LEFT 0.0 RIGHT 0.0
 (51) BRIDGE ROADWAY WIDTH, CURB TO CURB 28.2
 (52) DECK WIDTH OUT TO OUT 35.3
 (32) APPROACH ROADWAY WITH (W/ SHOULDERS) 28.0
 (33) BRIDGE MEDIAN Open median CODE 1
 (34) SKEW 30 (35) STRUCTURE FLARED 0
 (10) INVENTORY ROUTE MIN VERT CLEAR 999.9
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 28.2
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 999.9
 (54) MIN VERT UNDERCLEAR: REFERENCE 0.0
 (55) MIN LAT UNDERCLEARANCE RT: REFERENCE N 0.0
 (56) MIN LAT UNDERCLEARANCE LT: 0.0

PROPOSED IMPROVEMENTS

(75) TYPE OF WORK CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 45,500 YEAR OF FUTURE ADT 2040

NAVIGATION DATA

(38) NAVIGATION CONTROL - CODE 0
 (111) PIER PROTECTION CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0
 (116) VERT - LIFT BRIDGE NAV MIN VERT CLEAR 0.0
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0

INSPECTION

(90) INSPECTION DATE 06/17 (91) FREQUENCY 24
 (92) CRITICAL FEATURE INSPECTION (93) CFI DATE
 A) FRACTURE CRIT DETAIL 0 A)
 B) UNDERWATER INSP 24 B) 09/17
 C) OTHER SPECIAL INSP 0 C)

SCOUR

Superstructure Build Details

Span Number 1

Span Length 50.2500

Skew 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Asphalt Wearing Surface	Wearing Surface	1416 Square Feet		
8	Other Bearing	Other Bearings	8 Each	Unknow	16
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836
1	Strip SEal	Strip Seal Expansion Joint	28 Feet		
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1587 Square Feet		
2	Concrete and Metal Railing	Other Bridge Railing	102 Feet	Unknow	102

Span Number 2

Span Length 50.0000

Skew 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
8	Other Bearing	Other Bearings	8 Each	Unknow	16
2	Concrete and Metal Railing	Other Bridge Railing	100 Feet	Unknow	100
1	Asphalt Wearing Surface	Wearing Surface	1409 Square Feet		
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836
1	Standard Joint	Pourable Joint Seal	28 Feet		
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1579 Square Feet		

Span Number 3

Span Length 50.0000

Skew 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
8	Other Bearing	Other Bearings	8 Each	Unknow	16
1	Asphalt Wearing Surface	Wearing Surface	1409 Square Feet		
2	Concrete and Metal Railing	Other Bridge Railing	100 Feet	Unknow	100
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836
1	Standard Joint	Pourable Joint Seal	28 Feet		

Superstructure Build Details

1	Reinforced Concrete Deck	Reinforced Concrete Deck	1558 Square Feet	
---	--------------------------	--------------------------	------------------	--

Span Number 4 **Span Length** 50.0000 **Skew** 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
8	Other Bearing	Other Bearings	8 Each	Unknow	16
2	Concrete and Metal Railing	Other Bridge Railing	100 Feet	Unknow	100
1	Asphalt Wearing Surface	Wearing Surface	1408 Square Feet		
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1579 Square Feet		
1	Standard Joint	Pourable Joint Seal	28 Feet		

Span Number 5 **Span Length** 50.0000 **Skew** 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Standard Joint	Pourable Joint Seal	28 Feet		
1	Asphalt Wearing Surface	Wearing Surface	1408 Square Feet		
2	Concrete and Metal Railing	Other Bridge Railing	100 Feet	Unknow	100
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1579 Square Feet		
8	Other Bearing	Other Bearings	8 Each	Unknow	16
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836

Span Number 6 **Span Length** 50.0000 **Skew** 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Asphalt Wearing Surface	Wearing Surface	1408 Square Feet		
1	Standard Joint	Pourable Joint Seal	28 Feet		
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1579 Square Feet		

Superstructure Build Details

8	Other Bearing	Other Bearings	8 Each	Unknow	16
2	Concrete and Metal Railing	Other Bridge Railing	100 Feet	Unknow	100

Span Number 7

Span Length 50.0000

Skew 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Asphalt Wearing Surface	Wearing Surface	1408 Square Feet		
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1579 Square Feet		
8	Other Bearing	Other Bearings	8 Each	Unknow	16
1	Standard Joint	Pourable Joint Seal	28 Feet		
2	Concrete and Metal Railing	Other Bridge Railing	100 Feet	Unknow	100

Span Number 8

Span Length 50.2500

Skew 120.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Asphalt Wearing Surface	Wearing Surface	1416 Square Feet		
2	Standard Joint	Pourable Joint Seal	56 Feet		
8	Other Bearing	Other Bearings	8 Each	Unknow	16
4	Plate Girder	Steel Open Girder/Beam	200 Feet	Unknow	1836
1	Reinforced Concrete Deck	Reinforced Concrete Deck	1587 Square Feet		
2	Concrete and Metal Railing	Other Bridge Railing	102 Feet	Unknow	102

Structure Element Scoring

Structure Number: **500101**

Inspection Date **6/26/2019**

Element Number	Parent Number	Element Name	Location	Total Quantity	Level 1 Quantity	Level 2 Quantity	Level 3 Quantity	Level 4 Quantity
12	0	Reinforced Concrete Deck	Deck	12627	9590	3008	29	0
107	0	Steel Open Girder/Beam	Beam	1600	1592	0	8	0
515	107	Steel Protective Coating	Beam	14688	14688	0	0	0
215	0	Reinforced Concrete Abutment	Abutments	66	33	33	0	0
229	0	Other Pile	Piles and Columns	49	17	12	5	15
234	0	Reinforced Concrete Pier Cap	Caps	290	287	2	1	0
301	0	Pourable Joint Seal	Expansion Joints	224	224	0	0	0
316	0	Other Bearings	Bearing Device	64	0	62	2	0
515	316	Steel Protective Coating	Bearing Device	128	128	0	0	0
321	0	Reinforced Concrete Approach Slabs	Approaches	312	312	0	0	0
333	0	Other Bridge Railing	Bridge Rail	804	718	51	35	0
515	333	Steel Protective Coating	Bridge Rail	804	804	0	0	0
510	0	Wearing Surface	Wearing Surfaces	11282	11282	0	0	0

Summary of Maintenance Needs

Maintenance By Defect

Structure Number: 500101

Inspection Date: 06/26/2019

MMS Code	Element Name	Defect Name	Recommended Quantity
3326	Reinforced Concrete Deck	Delamination/Spall	25 Square Feet
3326	Reinforced Concrete Deck	Exposed Rebar	23 Square Feet
3326	Reinforced Concrete Deck	Cracking (RC and Other)	2667 Square Feet
3314	Steel Open Girder/Beam	Corrosion	8 Feet
3348	Other Pile	Delamination/Spall	4 Each
3348	Other Pile	Damage	2 Each
3348	Other Pile	Deterioration (Other)	1 Each
3348	Other Pile	Scour	70 Each
3348	Reinforced Concrete Pier Cap	Cracking (RC and Other)	1 Feet
3334	Other Bearings	Corrosion	2 Each
3318	Other Bridge Railing	Connection	5 Feet
3318	Other Bridge Railing	Delamination/Spall	11 Feet
3318	Other Bridge Railing	Damage	20 Feet

Element Structure Maintenance Quantities

Structure Number: **500101**

Inspection Date **06/26/2019**

Location	MMS Code	Description	Maint Quantity	Total Quantity	Severe Quantity	Poor Quantity	Fair Quantity	Good Quantity
Abutments	3350	Maintenance of Concrete Wings and Wall	0	66	0	0	33	33
Approaches	3353	Maintenance of Concrete Bridge Approach Slabs	0	312	0	0	0	312
Beam	3314	Maintenance Steel Superstructure Components	8	1600	0	8	0	1592
Beam	3342	Clean and Paint Steel	0	14688	0	0	0	14688
Bearing Device	3334	Bridge Bearing	2	64	0	2	62	0
Bearing Device	3342	Clean and Paint Steel	0	128	0	0	0	128
Bridge Rail	3318	Maintenance of Concrete Bridge Rail	36	804	0	35	51	718
Bridge Rail	3342	Clean and Paint Steel	0	804	0	0	0	804
Caps	3348	Maintenance of Concrete Substructure	1	290	0	1	2	287
Deck	3326	Maintenance of Concrete Deck	2715	12627	0	29	3008	9590
Expansion Joints	3310	Maintenance of Standard Bridge Expansion Joints	0	224	0	0	0	224
Piles and Columns	3348	Maintenance of Concrete Substructure	77	49	15	5	12	17
Wearing Surfaces	2816	Asphalt Surface Repair	0	11282	0	0	0	11282

Priority Actions Request

Structure Number 500101

Span2

3314 **Beam 1** Plate Girder

Priority Level	Defect Type	Quantity	Defect Description
2	Corrosion	1	Span 2 Beam 1: 10 IN LONG X 5 IN WIDE AREA OF SECTION LOSS BENEATH THE PAINTED SURFACE ABOVE THE BEARING AT BENT 2. 0.60 IN SECTION REMAINING (PAR).

Bent 3

3348 **Pile 7** Other Pile

Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	1	Bent 3 Pile 7: 4 FT HIGH X 4 IN WIDE SPALL WITH EXPOSED REINFORCEMENT IN EAST FACE. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT (PAR).

Element Condition and Maintenance Data

Structure Number: 500101

Inspection Date: 06/26/2019

Span 1 Deck

Reinforced Concrete Deck

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
12	Reinforced Concrete Deck	1,587	1,100	480	7	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
12	Delamination/Spall	(2) 12 IN DIAMETER DELAMINATIONS, UNDERSIDE OF WEST OVERHANG, AT DRAIN 7.	3	2	2 Square Feet
12	Delamination/Spall	(2) 6 IN DIAMETER X 3/4 IN DEEP SPALLS, UNDERSIDE OF BAY 1 END DIAPHRAGM, AT BENT 1.	3	1	1 Square Feet
12	Delamination/Spall	12 IN DIAMETER AREA OF UNSOUND CONCRETE AT DRAIN 4 IN LEFT OVERHANG.	3	1	1 Square Feet
12	Delamination/Spall	5 IN DIAMETER X UP TO 1/2 IN DEEP SPALL IN WEST FACE AT MID SPAN.	3	1	1 Square Feet
12	Exposed Rebar	UP TO 1 FT WIDE X 9 IN LONG X UP TO 1 IN DEEP SPALL WITH EXPOSED REINFORCEMENT IN RIGHT OVERHANG, LOCATED AT THIRD DRAIN PIPE. 80% SECTION REMAINING IN EXPOSED REINFORCEMENT.	3	1	1 Square Feet
12	Exposed Rebar	UP TO 6 IN DIAMETER X UP TO 1 IN DEEP SPALL WITH EXPOSED REINFORCEMENT AT THIRD DRAIN PIPE IN LEFT OVERHANG. UP TO 90% SECTION REMAINING IN EXPOSED REINFORCEMENT.	3	1	1 Square Feet
12	Cracking (RC and Other)	2 FT HIGH X UP TO 0.03 IN WIDE VERTICAL CRACK IN DIAPHRAGM ABOVE BENT 1 CAP AT RIGHT END.	2	1	1 Square Feet
12	Cracking (RC and Other)	EIGHT (8) UP TO 0.03 IN WIDE X UP TO 3 FT LONG TRANSVERSE CRACKS IN RIGHT OVERHANG.	2	20	20 Square Feet
12	Cracking (RC and Other)	UP TO 0.02 IN WIDE RANDOM CRACKING IN DECK UNDERSIDE IN ALL BAYS, SCATTERED THROUGHOUT.	2	450	450 Square Feet
12	Patched Areas	4 FT LONG X 8 IN HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 1.	2	4	Square Feet
12	Patched Areas	5 FT WIDE X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 3 END DIAPHRAGM, AT BENT 1. PATCH EXHIBITS A HAIRLINE X 1 FT LONG CRACK IN BOTTOM RIGHT CORNER.	2	5	Square Feet

General Comments

Span 1 Beam 1

Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 1 **Beam 2**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 1 **Beam 3**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

2' OF RUST SCALE ALONG BOTTOM FLANGE, AT BENT 1. - - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 1 **Beam 4**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	49	0	1	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

107	Corrosion	5 IN LONG X 5 IN WIDE AREA OF HEAVY SURFACE CORROSION BENEATH THE PAINTED SURFACES IN BOTTOM FLANGE OF LEFT FLANGE ABOVE BEARING AT BENT 1. UP TO 0.8 IN SECTION REMAINING.	3	1	1 Feet
-----	-----------	---	---	---	--------

General Comments

3' OF RUST SCALE ALONG BOTTOM FLANGE, AT BENT 1. - - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

30% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 1 Left Bridge Rail
Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	51	31	15	5	0 Feet
515	Steel Protective Coating	51	51	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Connection	6 IN DIAMETER X 1 IN DEEP SPALLS IN EXTERIOR FACE AT ANCHOR BOLT CONNECTION TO SUPPLEMENTAL GUARDRAIL AT ISOLATED LOCATIONS.	3	5	5 Feet
333	Patched Area	15 FT LONG AREA OF SOUND CONCRETE PATCHING TO CONCRETE RAIL, BEGINNING AT 15 FT FROM END BENT 1. PREVIOUS REPAIR.	2	15	Feet

General Comments

Span 1 Right Bridge Rail
Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	51	26	20	5	0 Feet
515	Steel Protective Coating	51	51	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Delamination/Spall	6 IN DIAMETER X 1 IN DEEP SPALLS IN EXTERIOR FACE AT ANCHOR BOLT CONNECTION TO SUPPLEMENTAL GUARDRAIL AT ISOLATED LOCATIONS.	3	5	5 Feet
333	Patched Area	20 FT LONG OF SOUND CONCRETE PATCHING TO CONCRETE RAIL, BEGINNING AT 8 FT FROM END BENT 1.	2	20	Feet

General Comments

Span 1 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 1 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 1 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 1 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 85% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 1 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN	2	1	Each

BOTH MASONRY AND SOLE PLATES.

General Comments

Span 1 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 85% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 1 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 1 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	0	1	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	SECTION LOSS IN THE RIGHT ANCHOR BOLT. UP TO 75% SECTION REMAINING.	3	1	1	Each
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 85% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2			Each

General Comments

Span 2**Deck****Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
12	Reinforced Concrete Deck	1,579	1,198	368	13	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
12	Delamination/Spall	TWO (2) AREAS OF UNSOUND CONCRETE UP TO 2.5 FT LONG X 1 FT HIGH WITH SPALLING UP TO 5 IN DIAMETER X UP TO 1 IN DEEP IN INTERMEDIATE DIAPHRAGM IN BAY 1 AT BENT 1.	3	4	4 Square Feet
12	Delamination/Spall	UP TO 1.5 FT WIDE X 4 IN LONG X UP TO 2 IN DEEP SPALL IN DIAPHRAGM IN BAY 3 AT BENT 1.	3	2	2 Square Feet
12	Exposed Rebar	(3) 6 IN DIAMETER X 1/2 IN DEEP SPALLS WITH EXPOSED REINFORCING, UNDERSIDE OF BAY 1 END DIAPHRAGM, AT BENT 2. 90% SECTION REMAINING IN EXPOSED REINFORCING.	3	3	3 Square Feet
12	Exposed Rebar	5 IN DIAMETER X 1 IN DEEP SPALL WITH EXPOSED REINFORCEMENT IN DIAPHRAGM IN BAY 3 AT BENT 1. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT.	3	1	1 Square Feet
12	Exposed Rebar	THREE (3) 6 IN DIAMETER X 3/4 IN DEEP SPALLS WITH EXPOSED REINFORCING, UNDERSIDE OF BAY 1 END DIAPHRAGM, AT BENT 2. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT.	3	3	3 Square Feet
12	Cracking (RC and Other)	9 FT LONG X 1 FT HIGH CONCRETE PATCH, BAY 2 END DIAPHRAGM, AT BENT 2. PATCH EXHIBITS UP TO 1/8 IN WIDE X 5 FT LONG CRACK IN THE BOTTOM FACE WITH A 5 FT LONG X 5 IN WIDE UNSOUND CONCRETE AND UP TO 0.02 IN WIDE VERTICAL CRACKS IN FRONT FACE, SCATTERED.	2	9	9 Square Feet
12	Cracking (RC and Other)	EIGHT (8) UP TO 0.03 IN WIDE X UP TO 3 FT LONG TRANSVERSE CRACKS IN LEFT OVERHANG. SIX (6) SIMILAR CRACKS IN RIGHT OVERHANG.	2	75	75 Square Feet
12	Cracking (RC and Other)	UP TO 0.02 IN WIDE RANDOM CRACKING IN DECK UNDERSIDE IN ALL BAYS, SCATTERED THROUGHOUT.	2	250	250 Square Feet
12	Delamination/Spall	FIVE (5) UP TO 6 FT IN DIAMETER AREA OF UNSOUND CONCRETE IN UNDERSIDE OF WEST OVERHANG, SCATTERED.	2	5	5 Square Feet
12	Patched Areas	40 IN WIDE X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 1 END DIAPHRAGM, AT BENT 1.	2	4	Square Feet
12	Patched Areas	80 IN LONG X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 3 END DIAPHRAGM, AT BENT 2.	2	7	Square Feet
12	Patched Areas	80 IN WIDE X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 3 END DIAPHRAGM, AT BENT 2.	2	7	Square Feet
12	Patched Areas	82 IN WIDE X 1 FT HIGH SOUND CONCRETE PATCH AREA, BAY 2 END DIAPHRAGM, AT BENT 1.	2	7	Square Feet
12	Patched Areas	NEW REPAIR 3 FT WIDE X 1 FT HIGH SOUND CONCRETE PATCH IN OVERHANG IN EAST FACE AT BENT 2 AND A 1 FT WIDE X 2 FT HIGH SOUND CONCRETE PATCH IN DIAPHRAGM OUTSIDE OF BEAM 4 AT BENT 2.	2	3	Square Feet
12	Patched Areas	NEW REPAIR: 1 FT DIAMETER SOUND CONCRETE PATCH IN DIAPHRAGM OUTSIDE OF BEAM 1 AT BENT 1.	2	1	Square Feet

General Comments**Span 2****Beam 1****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	49	0	1	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	10 IN LONG X 5 IN WIDE AREA OF SECTION LOSS	3	1	1 Feet

BENEATH THE PAINTED SURFACE ABOVE THE BEARING
AT BENT 2. 0.60 IN SECTION REMAINING (PAR).

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 2 **Beam 2**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 2 **Beam 3**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 2 **Beam 4**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

1' OF RUST SCALE ALONG BOTTOM FLANGE, AT BENT 1. - - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

8" X 12" X 6" DELAMINATION, END DIAPHRAGM OUTSIDE BEAM 4, AT BENT 2 - NOT OBSERVED

Span 2 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 2 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each
316	Connection	WELDED BEARING REPAIR WITH ANCHOR ROD.	1			Each

General Comments

Span 2 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 2 Far Bearing**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each
316	Connection	WELDED BEARING REPAIR WITH ANCHOR ROD.	1		Each

General Comments**Span 2 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 2 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each
316	Connection	WELDED BEARING REPAIR WITH ANCHOR ROD.	1		Each

General Comments**Span 2 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each
------------	-----------	---	---	---	------

General Comments

Span 2 Far Bearing

Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each
316	Connection	WELDED BEARING REPAIR WITH ANCHOR ROD.	1		Each

General Comments

Span 3 Deck

Reinforced Concrete Deck

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
12	Reinforced Concrete Deck	1,558	1,182	373	3	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
12	Exposed Rebar	3 FT LONG X 6 IN HIGH UNSOUND CONCRETE PATCH WITH EXPOSED REINFORCEMENT. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT.	3	3	3 Square Feet
12	Cracking (RC and Other)	7 FT LONG DIAGONAL CRACK WITH EFFLORESCENCE, UNDERSIDE OF DECK, BAY 3 AT BENT 2.	2	7	7 Square Feet
12	Cracking (RC and Other)	SEVEN (7) UP TO 0.03 IN WIDE X UP TO 3 FT LONG TRANSVERSE CRACKS IN LEFT OVERHANG. SIX (6) SIMILAR CRACKS IN RIGHT OVERHANG.	2	45	45 Square Feet
12	Cracking (RC and Other)	UP TO 0.03 IN WIDE TRANSVERSE AND RANDOM CRACKING IN DECK UNDERSIDE IN ALL BAYS, SCATTERED	2	300	300 Square Feet
12	Patched Areas	32 IN LONG X 1 FT HIGH SOUND CONCRETE PATCHES IN PATCHED AREA, BAY 1 END DIAPHRAGM, AT BENT 2.	2	3	Square Feet
12	Patched Areas	7 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 2.	2	7	Square Feet
12	Patched Areas	NEW REPAIR: 20 IN HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN EAST OVERHANG AT BENT 2.	2	2	Square Feet
12	Patched Areas	NEW REPAIR: 9 FT LONG X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 3 AT BENT 2.	2	9	Square Feet

General Comments

Span 3 **Beam 1**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	45	0	5	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	2 FT LONG X 5 IN WIDE AREA OF BOTTOM FLANGE HAS SECTION LOSS BENEATH THE PAINTED SURFACE, LOCATED AT 2 FT FROM BEAM END AT BENT 3. 0.74 IN SECTION REMAINING.	3	2	2 Feet
107	Corrosion	3.3 FT LONG X UP TO 5 IN HIGH AREA OF RIGHT FACE OF THE WEB AT 1.25 FT FROM BEAM END AT BENT 3 EXHIBITS SECTION LOSS BENEATH THE PAINTED SURFACE. UP TO 0.575 IN SECTION REMAINING.	3	3	3 Feet

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

30% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

4' OF RUST SCALE ALONG BOTTOM FLANGE, AT BENT 3. - - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 3 **Beam 2**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 3 **Beam 3**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 3 **Beam 4**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

35% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 3 **Left Bridge Rail**
Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	50	48	0	2	0 Feet
515	Steel Protective Coating	50	50	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Delamination/Spall	TWO (2) SPALLS UP TO 8 IN IN DIAMETER X 1 IN DEEP WITH EXPOSED REINFORCEMENT IN BOTTOM OF CURB AT 6 FT AND 10 FT FROM BENT 3 JOINT. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.	3	2	2 Feet

General Comments

Span 3 **Near Bearing**
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 3 **Far Bearing**
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each
------------	-----------	---	---	---	------

General Comments

Span 3 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 3 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 3 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 3 Far Bearing**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each
316	Connection	WELDED REPAIR WITH NEW ANCHOR BOLT.	1			Each

General Comments**Span 3 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments**Span 3 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments**Span 4 Deck****Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	1,579	970	609	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
12	Abrasion/Wear (PSC/RC)	7 FT LONG X 2 FT LONG AREA OF HONEYCOMBING LOCATED AT MID SPAN.	2	14		Square Feet

Structure Number: **500101**

Inspection Date: **06/26/2019**

12	Cracking (RC and Other)	SIX (6) UP TO 0.03 IN WIDE X UP TO 3 FT LONG TRANSVERSE CRACKS IN LEFT OVERHANG.	2	30	30	Square Feet
12	Cracking (RC and Other)	UP TO 0.03 IN WIDE TRANSVERSE AND RANDOM CRACKING IN DECK UNDERSIDE IN ALL BAYS, SCATTERED	2	550	550	Square Feet
12	Exposed Rebar	2 IN WIDE X 7 IN LONG X UP TO 2 IN DEEP SPALLS AND HONEYCOMBING WITH EXPOSED REBAR IN BOTTOM OF DIAPHRAGM IN BAY 1 AT BENT 4. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.	2	3	3	Square Feet
12	Patched Areas	2.5 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH WITH HAIRLINE VERTICAL CRACKS IN BAY 1 ABOVE BENT 3.	2	3		Square Feet
12	Patched Areas	4 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH WITH HAIRLINE VERTICAL CRACKS IN BAY 2 AT BENT 3.	2	4		Square Feet
12	Patched Areas	5 FT LONG X 11 IN HIGH SOUND CONCRETE PATCH IN BAY 1 END DIAPHRAGM, NEXT TO BEAM 1, AT BENT 4.	2	5		Square Feet

General Comments

Span 4 Beam 1

Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 Beam 2

Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 **Beam 3**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 **Beam 4**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 **Right Bridge Rail**
Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	50	48	0	2	0 Feet
515	Steel Protective Coating	50	50	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Delamination/Spall	1.5 FT LONG X 9 IN HIGH X UP TP 1.5 IN DEEP SPALL IN EXTERIOR FACE OF RAIL, LOCATED AT MID SPAN.	3	2	2 Feet

General Comments

Span 4 **Near Bearing**
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE	2	1	Each

PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.

General Comments

Span 4 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 4 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 4 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 4 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 4 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 4 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 4 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN	2	1	Each

BOTH MASONRY AND SOLE PLATES.

General Comments

Span 5 Deck
Reinforced Concrete Deck

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
12	Reinforced Concrete Deck	1,579	1,025	554	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
12	Abrasion/Wear (PSC/RC)	6 FT LONG X 3 FT WIDE X UP TO 3/4 IN DEEP AREA OF HONEYCOMBING IN BAY 3 NEAR BENT 5.	2	18	Square Feet
12	Cracking (RC and Other)	SEVEN (7) UP TO 0.03 IN WIDE X UP TO 3 FT LONG TRANSVERSE CRACKS IN LEFT OVERHANG. TWELVE (12) SIMILAR CRACKS IN RIGHT OVERHANG.	2	75	75 Square Feet
12	Cracking (RC and Other)	UP TO 0.02 IN WIDE RANDOM CRACKING IN DECK UNDERSIDE IN ALL BAYS, SCATTERED THROUGHOUT.	2	450	450 Square Feet
12	Patched Areas	3 FT LONG X 11 IN HIGH SOUND CONCRETE PATCH, BAY 2 END DIAPHRAGM, NEXT TO BEAM 2, AT BENT 4.	2	3	Square Feet
12	Patched Areas	NEW REPAIR: 8 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 5.	2	8	Square Feet

General Comments

Span 5 Beam 2
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

Span 5 Beam 4
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 5 Left Bridge Rail**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	50	49	0	1	0 Feet
515	Steel Protective Coating	50	50	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Delamination/Spall	6 IN DIAMETER X 1 IN DEEP SPALL WITH EXPOSED PAINTED REBAR IN BOTTOM OF CURB AT 10 FT FROM BENT 6 JOINT.	3	1	1 Feet

General Comments**Span 5 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 5 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 5 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 5 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 5 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 5 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 5 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each
------------	-----------	---	---	---	------

General Comments**Span 5 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments**Span 6 Deck****Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	1,579	1,421	158	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
12	Cracking (RC and Other)	EIGHT (8) UP TO 0.03 IN WIDE X UP TO 3 FT LONG TRANSVERSE CRACKS IN LEFT OVERHANG. RIGHT OVERHANG TYPICAL.	2	50	50	Square Feet
12	Delamination/Spall	THREE (3) AREAS OF DELAMINATED CONCRETE UP TO 6 IN DIAMETER IN EAST OVERHANG AT BENT 6.	2	3	3	Square Feet
12	Efflorescence/Rust Staining	SIX (6) 8 FT LONG X HAIRLINE TRANSVERSE CRACKS WITH EFFLORESCENCE, UNDERSIDE OF DECK, AT RANDOM THROUGHOUT BAY 1. SIMILAR IN BAY 3.	2	90		Square Feet
12	Exposed Rebar	12 IN WIDE X 9 IN LONG X 14 IN HIGH IN SOUTH FACE SPALL UP TO 3.5 IN DEEP WITH EXPOSED REINFORCEMENT IN BAY 2 AT BENT 6. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.	2	1	1	Square Feet
12	Exposed Rebar	2.5 FT WIDE X 10 IN LONG X UP TO 6 IN HIGH AREA OF UNSOUND CONCRETE AND SPALL UP TO 2 IN DEEP WITH EXPOSED REINFORCEMENT IN BAY 3 END DIAPHRAGM AT BENT 7. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.	2	3	3	Square Feet
12	Patched Areas	30 IN LONG X 6 IN HIGH SOUND CONCRETE PATCH IN BAY 1 END DIAPHRAGM, AT BENT 6.	2	3		Square Feet
12	Patched Areas	NEW REPAIR: 12 IN DIAMETER SOUND CONCRETE PATCH AT 2ND DRAIN PIPE IN EAST OVERHANG.	2	1		Square Feet
12	Patched Areas	NEW REPAIR: 12 IN DIAMETER SOUND CONCRETE PATCH IN EAST OVERHANG AT DRAIN ONE.	2	1		Square Feet
12	Patched Areas	NEW REPAIR: 18 IN DIAMETER SOUND CONCRETE PATCH IN EAST OVERHANG BETWEEN 5TH AND 6TH DECK DRAINS.	2	1		Square Feet
12	Patched Areas	NEW REPAIR: 2 FT HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN END DIAPHRAGM OUTSIDE BEAM 1 AT BEAM 6.	2	2		Square Feet
12	Patched Areas	NEW REPAIR: 28 IN LONG X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 5. PATCH EXHIBITS HAIRLINE VERTICAL CRACKING, SCATTERED.	2	3		Square Feet

General Comments

Span 6 **Beam 1**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

1' OF RUST SCALE ALONG BOTTOM FLANGE AT BENT 6. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION.

Span 6 **Beam 2**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 6 **Beam 3**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	49	0	1	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
107	Corrosion	UP TO 11 IN HIGH X 10 IN LONG AREA OF SECTION LOSS IN THE WEB BENEATH THE PAINTED SURFACE AT BEAM END AT BENT 6. 0.575 IN SECTION REMAINING.	3	1	1 Feet

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 6 **Beam 4**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 6 **Left Bridge Rail**
Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	50	30	0	20	0 Feet
515	Steel Protective Coating	50	50	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Damage	MODERATE TO HEAVY IMPACT DAMAGE WITH UP TO 5 IN DEFLECTION TOWARDS WEST TO THE SUPPLEMENTAL BRIDGE RAIL FOR 20 FT LONG STARTING AT BENT 6. TWO (2) SPACER BLOCKS CONNECTING THE GUARDRAIL TO POSTS ARE PARTIALLY CRUSHED.	3	20	20 Feet

General Comments

Span 6 **Near Bearing**
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments

Span 6 **Far Bearing**
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS	2	1	Each

INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.

316	Connection	BEARING ASSEMBLY HAS WELDED REPAIR WITH NEW ANCHOR BOLT.	1				Each
-----	------------	--	---	--	--	--	------

General Comments

Span 6 Near Bearing

Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 6 Far Bearing

Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each
316	Connection	BEARING ASSEMBLY HAS WELDED REPAIR WITH NEW ANCHOR BOLT.	1			Each

General Comments

Span 6 Near Bearing

Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 6 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each
316	Connection	BEARING ASSEMBLY HAS WELDED REPAIR WITH NEW ANCHOR BOLT.	1			Each

General Comments

Span 6 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 6 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each
316	Connection	BEARING ASSEMBLY HAS WELDED REPAIR WITH NEW ANCHOR BOLT.	1			Each

General Comments

Span 7 Deck
Reinforced Concrete Deck

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	1,579	1,110	463	6	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

Structure Number: **500101**

Inspection Date: **06/26/2019**

12	Delamination/Spall	3 FT X 2 FT AREA OF DELAMINATION, UNDERSIDE OF WEST OVERHANG, AT MID SPAN.	3	6	6	Square Feet
12	Cracking (RC and Other)	EIGHT (8) UP TO 0.03 IN WIDE X UP TO 3 FT LONG TRANSVERSE CRACKS IN LEFT OVERHANG. RIGHT OVERHANG TYPICAL.	2	55	55	Square Feet
12	Cracking (RC and Other)	UP TO 0.02 IN WIDE RANDOM CRACKING IN DECK UNDERSIDE IN ALL BAYS, SCATTERED THROUGHOUT.	2	300	300	Square Feet
12	Exposed Rebar	24 IN LONG X 2 FT WIDE X 2 IN DEEP DELAMINATION/SPALL WITH EXPOSED REINFORCING, UNDERSIDE OF EAST OVERHANG AT 2/3 POINT. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.	2	4	4	Square Feet
12	Patched Areas	20 IN WIDE X 18 IN HIGH SOUND CONCRETE PATCHED AREA, BAY 1 END DIAPHRAGM, OVER BENT 7, NEXT TO BEAM 2.	2	4		Square Feet
12	Patched Areas	7 FT LONG X 1 FT HIGH SOUND CONCRETE PATCH IN INTERMEDIATE DIAPHRAGM IN BAY 3 AT BENT 7.	2	7		Square Feet
12	Patched Areas	75 SQ FT OF PATCHED AREA, UNDERSIDE OF DECK, AT RANDOM THROUGHOUT ALL BAYS.	2	75		Square Feet
12	Patched Areas	8 FT LONG X 6 IN HIGH SOUND CONCRETE PATCHED AREA IN BAY 2 END DIAPHRAGM, AT BENT 6.	2	8		Square Feet
12	Patched Areas	NEW REPAIR: 18 IN DIAMETER SOUND CONCRETE PATCH IN EAST OVERHANG AT THIRD DRAIN PIPE.	2	2		Square Feet
12	Patched Areas	NEW REPAIR: 2 FT HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN DIAPHRAGM OUTSIDE BEAM 4 AT BENT 7.	2	2		Square Feet
12	Patched Areas	NEW REPAIR: 6 FT LONG X 12 IN HIGH SOUND CONCRETE PATCH BOTTOM OF BAY 3 END DIAPHRAGM, NEXT TO BEAM 3, AT BENT 6. PATCH EXHIBITS UP TO 0.03 IN WIDE VERTICAL CRACKS, SCATTERED.	2	6		Square Feet

General Comments

Span 7

Beam 1

Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 7

Beam 2

Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 7 Beam 3
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

25% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 7 Beam 4
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 7 Right Bridge Rail
Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	50	35	15	0	0 Feet
515	Steel Protective Coating	50	50	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Patched Area	15 FT LONG SECTION OF CONCRETE RAIL HAS BEEN REPLACED, AT MIDSPAN.	2	15	Feet

General Comments

Span 7 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 7 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 7 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 7 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 80% SECTION REMAINING IN	2	1		Each

BOTH MASONRY AND SOLE PLATES.

General Comments**Span 7 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments**Span 7 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments**Span 7 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 7 Far Bearing**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments**Span 8 Deck****Reinforced Concrete Deck**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
12	Reinforced Concrete Deck	1,587	1,584	3	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
12	Patched Areas	3 FT LONG X 10 IN HIGH SOUND CONCRETE PATCHED AREA BOTTOM OF BAY 2 END DIAPHRAGM, AT BENT 7.	2	3		Square Feet

General Comments**Span 8 Beam 1****Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	50	50	0	0	0	Feet
515	Steel Protective Coating	459	459	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 Beam 2**Plate Girder**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
107	Steel Open Girder/Beam	50	50	0	0	0	Feet
515	Steel Protective Coating	459	459	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 **Beam 3**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 **Beam 4**
Plate Girder

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
107	Steel Open Girder/Beam	50	50	0	0	0 Feet
515	Steel Protective Coating	459	459	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 **Left Bridge Rail**
Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	51	50	1	0	0 Feet
515	Steel Protective Coating	51	51	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

333	Delamination/Spall	8 IN WIDE X 8 IN HIGH X UP TO 3 IN DEEP SPALL WITH EXPOSED REINFORCEMENT IN TOP OF RAIL AT FIRST RAIL JOINT FROM END BENT 2. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT.	2	1	1 Feet
-----	--------------------	--	---	---	--------

General Comments

Span 8 Near Bearing**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	0	1	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	3	1	1 Each

General Comments**Span 8 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 8 Near Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1	Each

General Comments**Span 8 Far Bearing****Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
316	Other Bearings	1	0	1	0	0 Each
515	Steel Protective Coating	2	2	0	0	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN	2	1	Each

BOTH MASONRY AND SOLE PLATES.

General Comments

Span 8 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 8 Far Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 8 Near Bearing
Other Bearing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments

Span 8 Far Bearing**Other Bearing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
316	Other Bearings	1	0	1	0	0	Each
515	Steel Protective Coating	2	2	0	0	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
316	Corrosion	BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 90% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.	2	1		Each

General Comments**Bent 1 Pile 7****Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
229	Other Pile	1	0	0	1	0	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
229	Damage	HEAVY VEGETATION GROWTH ON EAST FACE OF PILE.	3	1	1	Each

General Comments**End Bent 1 Abutment****Reinforced Concrete Abutment**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
215	Reinforced Concrete Abutment	33	0	33	0	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
215	Cracking (RC and Other)	UP TO 0.03 IN WIDE RANDOM CRACKING IN BACKWALL FOR FULL LENGTH.	2	33		Feet

General Comments**Bent 2 Pile 7****Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
229	Other Pile	1	0	0	1	0	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
229	Delamination/Spall	18 IN WIDE X 22 IN HIGH AREA OF DELAMINATION, TOP OF NORTH FACE.	3	1	2	Each

General Comments

Bent 3 Pile 1
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 1ft. of scour post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 3 Pile 2
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 1ft. of scour post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 3 Pile 3
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 1ft. of scour post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 3 Pile 4
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 1ft. of scour post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 3 Pile 5
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 1ft. of scour post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 3 Pile 6
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 1ft. of scour post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 3 Pile 7
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Delamination/Spall	4 FT HIGH X 4 IN WIDE SPALL WITH EXPOSED REINFORCEMENT IN EAST FACE. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT (PAR).	3	1	1 Each
229	Cracking	5 FT HIGH X UP TO 6 IN WIDE CONCRETE PATCH WITH HAIRLINE VERTICAL CRACKS IN EAST FACE, LOCATED AT 4 FT BELOW THE CAP.	2		Each
229	Scour	Underwater Inspection 9/13/17: 1ft. of scour post hurricane Matthew.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 4 Cap 1
Reinforced Concrete Pier Cap

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	32	31	0	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Cracking (RC and Other)	30 IN LONG X 1/16 IN WIDE HORIZONTAL CRACK, CENTER OF WEST END.	3	1	1 Feet

General Comments

2' HORIZONTAL CRACK UP TO 1/16" TOP OF NORTH FACE, BELOW BEAM 4. - REPAIRED BY NEW SEALING ON

TOP OF CAP
 2' X 9" DELAMINATION, TOP OF NORTH FACE, BELOW BEAM 3. - NOT OBSERVED

Bent 4 Pile 1
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Cracking	5 FT LONG X 0.02 IN WIDE VERTICAL CRACK, SOUTH FACE BEGINNING AT CAP.	2	1	Each
229	Scour	Underwater Inspection 9/13/17: 2ft. of scour post hurricane Matthew.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 4 Pile 2
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Cracking	1 FT LONG VERTICAL HAIRLINE CRACK, SOUTH FACE, BEGINNING AT CAP.	2	1	Each
229	Scour	Underwater Inspection 9/13/17: 2ft. of scour post hurricane Matthew.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 4 Pile 3
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each
229	Scour	Underwater Inspection 9/13/17: 2ft. of scour with 1ft. of exposed steel pile post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 4 Pile 4
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

229 Scour Underwater Inspection 9/13/17: 2ft. of scour with 1ft. of exposed steel pile post hurricane Matthew. 2 1 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 4 Pile 5**Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour with 1ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 4 Pile 6**Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour with 1ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 4 Pile 7**Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour with 1ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 5 Cap 1**Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	32	32	0	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

24" X 16" DELAMINATION, TOP OF SOUTH FACE, BELOW BEAM 3. - REPAIRED SINCE PREVIOUS INSPECTION BY TOP SEALANT.
7' X 1" X 1" DELAMINATION/SPALL ALONG BOTTOM NORTH CORNER, FROM PILE 3 TO PILE 4. - NOT OBSERVED

Bent 5 Pile 1**Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Deterioration (Other)	ABRASION WITH COARSE AGGREGATE EXPOSED 1/16 IN TO 1/4 IN LOSS OF FACIAL CONCRETE.	3	1	1 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each
229	Scour	Underwater Inspection 9/13/17: 2ft. of scour with 3ft. of exposed steel pile post hurricane Matthew.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 5 Pile 2**Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each
229	Scour	Underwater Inspection 9/13/17: 2ft. of scour with 1ft. of exposed steel pile post hurricane Matthew.	2	1	Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 5 Pile 3**Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 6ft. of scour with 3ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	6 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 5 Pile 4
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 8ft. of scour with 4ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	8 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 5 Pile 5
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 8ft. of scour with 5ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	8 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 5 Pile 6
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 8ft. of scour with 5ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	8 Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 5**Pile 7****Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 8ft. of scour with 3ft. of exposed steel pile post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	Each
229	Corrosion	Underwater Inspection 9/13/17: Random rust blisters on flange edges of exposed steel pile.	2		Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.

Bent 6**Cap 1****Reinforced Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	32	30	2	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
234	Patched Area	2 FT LONG X 17 IN HIGH PATCHED AREA, TOP OF SOUTH FACE, BELOW BEAM 3.	2	2	Feet

General Comments**Bent 6****Pile 1****Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
Steel piles not visible.

Bent 6**Pile 2****Other Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
Steel piles not visible.

Bent 6 Pile 3
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 6 Pile 4
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 6 Pile 5
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 6 Pile 6
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 6 Pile 7
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	0	1 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Scour	Underwater Inspection 9/13/17: 4ft. of scour post hurricane Matthew. (PRIORITY MAINTENANCE ISSUED)	4	1	4 Each

General Comments

H-piles encased in concrete. General condition is water abrasion with coarse aggregate exposed 1/16in. to 1/4in. loss of facial concrete.
 Steel piles not visible.

Bent 7 Cap 1
Reinforced Concrete Pier Cap

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
234	Reinforced Concrete Pier Cap	32	32	0	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

General Comments

3' HORIZONTAL CRACK UP TO 1/16", TOP OF SOUTH FACE, BELOW BEAM 3. - REPAIRED WITH NEW SEALANT
 3' HORIZONTAL CRACK UP TO 1/32", WITH A 48" X 4" DELAMINATION, TOP OF SOUTH FACE, BELOW BEAM 2. - REPAIRED WITH NEW SEALANT
 38" HORIZONTAL CRACK UP TO 1/16" WITH A 40" X 12" X 6" DELAMINATION, TOP OF SOUTH FACE, BELOW BEAM 3. - REPAIRED WITH NEW SEALANT

Bent 7 Pile 1
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Damage	NEW REPAIR 8 FT HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN WEST FACE.	2	1	1 Each

General Comments

1' OF HAIRLINE MAP CRACKING, NORTH FACE. - NOT OBSERVED

Bent 7 Pile 2
Other Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
229	Other Pile	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
229	Delamination/Spall	5 FT HIGH X 2 FT WIDE AREA OF UNSOUND CONCRETE IN NORTH FACE, STARTING AT CAP.	3	1	1 Each
229	Cracking	1 FT WIDE X 1 FT HIGH AREA OF HAIRLINE MAP CRACKING, NORTH AND SOUTH FACE.	2		Each

General Comments

Elements Verified

Location	Name	Component	Element Name	Amount
Span 1	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1587
Span 1	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 1	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 1	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 1	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 1	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	51
Span 1	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	51
Span 1	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	1416
Span 1	Near Bearing	Other Bearing	Other Bearings	1
Span 1	Far Bearing	Other Bearing	Other Bearings	1
Span 1	Near Bearing	Other Bearing	Other Bearings	1
Span 1	Far Bearing	Other Bearing	Other Bearings	1
Span 1	Near Bearing	Other Bearing	Other Bearings	1
Span 1	Far Bearing	Other Bearing	Other Bearings	1
Span 1	Near Bearing	Other Bearing	Other Bearings	1
Span 1	Far Bearing	Other Bearing	Other Bearings	1
Span 2	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1579
Span 2	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 2	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 2	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 2	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 2	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 2	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 2	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 2	Near Bearing	Other Bearing	Other Bearings	1
Span 2	Far Bearing	Other Bearing	Other Bearings	1
Span 2	Near Bearing	Other Bearing	Other Bearings	1
Span 2	Far Bearing	Other Bearing	Other Bearings	1
Span 2	Near Bearing	Other Bearing	Other Bearings	1
Span 2	Far Bearing	Other Bearing	Other Bearings	1
Span 2	Near Bearing	Other Bearing	Other Bearings	1
Span 2	Far Bearing	Other Bearing	Other Bearings	1
Span 3	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1558
Span 3	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 3	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 3	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 3	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 3	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 3	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 3	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 3	Near Bearing	Other Bearing	Other Bearings	1
Span 3	Far Bearing	Other Bearing	Other Bearings	1
Span 3	Near Bearing	Other Bearing	Other Bearings	1
Span 3	Far Bearing	Other Bearing	Other Bearings	1
Span 3	Near Bearing	Other Bearing	Other Bearings	1

Elements Verified

Location	Name	Component	Element Name	Amount
Span 3	Far Bearing	Other Bearing	Other Bearings	1
Span 3	Near Bearing	Other Bearing	Other Bearings	1
Span 3	Far Bearing	Other Bearing	Other Bearings	1
Span 4	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1579
Span 4	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 4	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 4	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 4	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 4	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 4	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 4	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 4	Near Bearing	Other Bearing	Other Bearings	1
Span 4	Far Bearing	Other Bearing	Other Bearings	1
Span 4	Near Bearing	Other Bearing	Other Bearings	1
Span 4	Far Bearing	Other Bearing	Other Bearings	1
Span 4	Near Bearing	Other Bearing	Other Bearings	1
Span 4	Far Bearing	Other Bearing	Other Bearings	1
Span 4	Near Bearing	Other Bearing	Other Bearings	1
Span 4	Far Bearing	Other Bearing	Other Bearings	1
Span 5	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1579
Span 5	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 5	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 5	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 5	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 5	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 5	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 5	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 5	Near Bearing	Other Bearing	Other Bearings	1
Span 5	Far Bearing	Other Bearing	Other Bearings	1
Span 5	Near Bearing	Other Bearing	Other Bearings	1
Span 5	Far Bearing	Other Bearing	Other Bearings	1
Span 5	Near Bearing	Other Bearing	Other Bearings	1
Span 5	Far Bearing	Other Bearing	Other Bearings	1
Span 5	Near Bearing	Other Bearing	Other Bearings	1
Span 5	Far Bearing	Other Bearing	Other Bearings	1
Span 5	Near Bearing	Other Bearing	Other Bearings	1
Span 5	Far Bearing	Other Bearing	Other Bearings	1
Span 6	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1579
Span 6	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 6	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 6	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 6	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 6	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 6	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 6	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 6	Near Bearing	Other Bearing	Other Bearings	1
Span 6	Far Bearing	Other Bearing	Other Bearings	1

Elements Verified

Location	Name	Component	Element Name	Amount
Span 6	Near Bearing	Other Bearing	Other Bearings	1
Span 6	Far Bearing	Other Bearing	Other Bearings	1
Span 6	Near Bearing	Other Bearing	Other Bearings	1
Span 6	Far Bearing	Other Bearing	Other Bearings	1
Span 6	Near Bearing	Other Bearing	Other Bearings	1
Span 6	Far Bearing	Other Bearing	Other Bearings	1
Span 7	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1579
Span 7	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 7	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 7	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 7	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 7	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 7	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	50
Span 7	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 7	Near Bearing	Other Bearing	Other Bearings	1
Span 7	Far Bearing	Other Bearing	Other Bearings	1
Span 7	Near Bearing	Other Bearing	Other Bearings	1
Span 7	Far Bearing	Other Bearing	Other Bearings	1
Span 7	Near Bearing	Other Bearing	Other Bearings	1
Span 7	Far Bearing	Other Bearing	Other Bearings	1
Span 7	Near Bearing	Other Bearing	Other Bearings	1
Span 7	Far Bearing	Other Bearing	Other Bearings	1
Span 8	Deck	Reinforced Concrete Deck	Reinforced Concrete Deck	1587
Span 8	Beam 1	Plate Girder	Steel Open Girder/Beam	50
Span 8	Beam 2	Plate Girder	Steel Open Girder/Beam	50
Span 8	Beam 3	Plate Girder	Steel Open Girder/Beam	50
Span 8	Beam 4	Plate Girder	Steel Open Girder/Beam	50
Span 8	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	51
Span 8	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	51
Span 8	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 8	Expansion Joint	Standard Joint	Pourable Joint Seal	28
Span 8	Near Bearing	Other Bearing	Other Bearings	1
Span 8	Far Bearing	Other Bearing	Other Bearings	1
Span 8	Near Bearing	Other Bearing	Other Bearings	1
Span 8	Far Bearing	Other Bearing	Other Bearings	1
Span 8	Near Bearing	Other Bearing	Other Bearings	1
Span 8	Far Bearing	Other Bearing	Other Bearings	1
Span 8	Near Bearing	Other Bearing	Other Bearings	1
Span 8	Far Bearing	Other Bearing	Other Bearings	1
Bent 1	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	32
Bent 1	Pile 1	Other Pile	Other Pile	1
Bent 1	Pile 2	Other Pile	Other Pile	1
Bent 1	Pile 3	Other Pile	Other Pile	1
Bent 1	Pile 4	Other Pile	Other Pile	1
Bent 1	Pile 5	Other Pile	Other Pile	1

Elements Verified

Location	Name	Component	Element Name	Amount
Bent 1	Pile 6	Other Pile	Other Pile	1
Bent 1	Pile 7	Other Pile	Other Pile	1
End Bent 1	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	33
End Bent 1	Abutment	Reinforced Concrete Abutment	Reinforced Concrete Abutment	33
Bent 2	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	32
Bent 2	Pile 1	Other Pile	Other Pile	1
Bent 2	Pile 2	Other Pile	Other Pile	1
Bent 2	Pile 3	Other Pile	Other Pile	1
Bent 2	Pile 4	Other Pile	Other Pile	1
Bent 2	Pile 5	Other Pile	Other Pile	1
Bent 2	Pile 6	Other Pile	Other Pile	1
Bent 2	Pile 7	Other Pile	Other Pile	1
End Bent 2	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	33
End Bent 2	Abutment	Reinforced Concrete Abutment	Reinforced Concrete Abutment	33
Bent 3	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	32
Bent 3	Pile 1	Other Pile	Other Pile	1
Bent 3	Pile 2	Other Pile	Other Pile	1
Bent 3	Pile 3	Other Pile	Other Pile	1
Bent 3	Pile 4	Other Pile	Other Pile	1
Bent 3	Pile 5	Other Pile	Other Pile	1
Bent 3	Pile 6	Other Pile	Other Pile	1
Bent 3	Pile 7	Other Pile	Other Pile	1
Bent 4	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	32
Bent 4	Pile 1	Other Pile	Other Pile	1
Bent 4	Pile 2	Other Pile	Other Pile	1
Bent 4	Pile 3	Other Pile	Other Pile	1
Bent 4	Pile 4	Other Pile	Other Pile	1
Bent 4	Pile 5	Other Pile	Other Pile	1
Bent 4	Pile 6	Other Pile	Other Pile	1
Bent 4	Pile 7	Other Pile	Other Pile	1
Bent 5	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	32
Bent 5	Pile 1	Other Pile	Other Pile	1
Bent 5	Pile 2	Other Pile	Other Pile	1
Bent 5	Pile 3	Other Pile	Other Pile	1
Bent 5	Pile 4	Other Pile	Other Pile	1
Bent 5	Pile 5	Other Pile	Other Pile	1
Bent 5	Pile 6	Other Pile	Other Pile	1
Bent 5	Pile 7	Other Pile	Other Pile	1
Bent 6	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	32
Bent 6	Pile 1	Other Pile	Other Pile	1
Bent 6	Pile 2	Other Pile	Other Pile	1
Bent 6	Pile 3	Other Pile	Other Pile	1
Bent 6	Pile 4	Other Pile	Other Pile	1
Bent 6	Pile 5	Other Pile	Other Pile	1
Bent 6	Pile 6	Other Pile	Other Pile	1

Elements Verified

Location	Name	Component	Element Name	Amount
Bent 6	Pile 7	Other Pile	Other Pile	1
Bent 7	Cap 1	Reinforced Concrete Pier Cap	Reinforced Concrete Pier Cap	32
Bent 7	Pile 1	Other Pile	Other Pile	1
Bent 7	Pile 2	Other Pile	Other Pile	1
Bent 7	Pile 3	Other Pile	Other Pile	1
Bent 7	Pile 4	Other Pile	Other Pile	1
Bent 7	Pile 5	Other Pile	Other Pile	1
Bent 7	Pile 6	Other Pile	Other Pile	1
Bent 7	Pile 7	Other Pile	Other Pile	1

General Inspection Notes

Bent 5 Cap 1

24" X 16" DELAMINATION, TOP OF SOUTH FACE, BELOW BEAM 3. - REPAIRED SINCE PREVIOUS INSPECTION BY TOP SEALANT.

7' X 1" X 1" DELAMINATION/SPALL ALONG BOTTOM NORTH CORNER, FROM PILE 3 TO PILE 4. - NOT OBSERVED

Bent 7 Cap 1

3' HORIZONTAL CRACK UP TO 1/16", TOP OF SOUTH FACE, BELOW BEAM 3. - REPAIRED WITH NEW SEALANT

3' HORIZONTAL CRACK UP TO 1/32", WITH A 48" X 4" DELAMINATION, TOP OF SOUTH FACE, BELOW BEAM 2. - REPAIRED WITH NEW SEALANT

38" HORIZONTAL CRACK UP TO 1/16" WITH A 40" X 12" X 6" DELAMINATION, TOP OF SOUTH FACE, BELOW BEAM 3. - REPAIRED WITH NEW SEALANT

Span 1 Beam 1

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 1 Beam 2

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 1 Beam 3

2' OF RUST SCALE ALONG BOTTOM FLANGE, AT BENT 1. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 2 Beam 2

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 2 Beam 3

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 2 Beam 4

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

General Inspection Notes

1' OF RUST SCALE ALONG BOTTOM FLANGE, AT BENT 1. - - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

8" X 12" X 6" DELAMINATION, END DIAPHRAGM OUTSIDE BEAM 4, AT BENT 2 - NOT OBSERVED

Span 3 Beam 2

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 3 Beam 3

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 3 Beam 4

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

35% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 Beam 1

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 Beam 2

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 Beam 3

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 4 Beam 4

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW

General Inspection Notes

PAINT SINCE PREVIOUS INSPECTION

Span 5 Beam 2

Span 5 Beam 4

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 6 Beam 1

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

1' OF RUST SCALE ALONG BOTTOM FLANGE AT BENT 6. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION.

Span 6 Beam 2

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 6 Beam 4

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 7 Beam 1

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

5% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 7 Beam 2

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 7 Beam 3

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

25% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW

General Inspection Notes

PAINT SINCE PREVIOUS INSPECTION

Span 7 Beam 4

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 Beam 1

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

10% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 Beam 2

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 Beam 3

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

15% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

Span 8 Beam 4

FRECKLED RUST AT RANDOM ALONG WEB AND FLANGES, IN AREAS OF PAINT PEEL. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

20% OF SURFACE AREA HAS PAINT PEELING THROUGHOUT WEB AND FLANGES. - NOT OBSERVED, NEW PAINT SINCE PREVIOUS INSPECTION

National Bridge and NC Inspection Items

Structure Number: 500101

Inspection Date: 06/26/2019

National Bridge Inventory Items

Item	Grade Scale	Grade
Item 58: Deck	0 - 9 , N	5
Item 59: Superstructure	0 - 9 , N	6
Item 60: Substructure	0 - 9 , N	4
Item 61: Channel and Channel Protection	0 - 9 , N	4
Item 62: Culvert	0 - 9 , N	N
Item 71: Waterway Adequacy	0 - 9 , N	7
Item 72: Approach Roadway Alignment	0 - 9 , N	8

Note: If NBI Inspection Item is not present, code NBI item with "N"

NC SMU Inspection Items

Item	Grade Scale	Grade	Maint. Qty.	Maint. Code
Deck Debris	G, F, P, or C	G	0	3376
Drainage System	G, F, P, or C	F	804	3332
Utilities	G, F, P, or C			
Slope Protection	G, F, P, or C	F	1000	3352
Scour	G, F, P, or C	P		
Wingwall	G, F, P, or C	F	60	3350
Field Scour Evaluation		P		
Drift	G, F, P, or C	G	0	3366
Fender System	G, F, P, or C		0	3364
Movable Span Machinery	G, F, P, or C			
Response to Live Load	G, F, P, or C	G		
Superstructure Paint Code		U		

Note: If NC SMU Inspection Item is not present, leave NC SMU item blank

Inspection Information

Item	Grade Scale	Grade
Sign Noticed Issued	YES/NO	N
Priority Maintenance Request Submitted	YES/NO	Y
Inspection Time	Hours	10
Traffic Control Time	Hours	7
Snooper Time	Hours	4
Ladder Used	YES/NO	N
Bucket Truck Used	YES/NO	N
Boat Used	YES/NO	N
Other Equipment Used	YES/NO	N

National Bridge and NC SMU Inspection Item Details

Structure Number: 500101

Inspection Date: 06/26/2019

Item	Deck - Item 58	Grade 5	Maint Code	Qty. 0
Details	NEW LMC OVERLAY			
Item	Superstructure - Item 59	Grade 6	Maint Code	Qty. 0
Details	NEW PAINT TO THE BEAMS AND BEARINGS SINCE PREVIOUS INSPECTION.			
Item	Substructure - Item 60	Grade 4	Maint Code	Qty. 0
Details	SUBSTRUCTURE IS IN POOR CONDITION DUE TO SCOUR AT BENTS 3, 4, 5, AND 6. POST HURRICANE MATTHEW UNDERWATER INSPECTION REPORT DATED 9/13/2017 INDICATES SCOUR AT BENT 3 PILES AND SCOUR WITH EXPOSED STEEL PILES AT BENTS 4, 5, AND 6.			
	NEW EPOXY SEALING ON TOP OF END BENTS AND BENT CAPS.			
Item	Channel and Channel Protection - Item 61	Grade 4	Maint Code	Qty. 0
Details	POST HURRICANE MATTHEW UNDERWATER INSPECTION REPORT DATED 9/13/2017 RATES 4 DUE TO CHANNEL CONTRACTION SCOUR. SOUNDINGS INDICATE UP TO 5 FT OF AGGRADATION IN THE CHANNEL AT UPSTREAM OF BENT 5.			
Item	Drainage System	Grade F	Maint Code 3332	Qty. 804
Details	ONE BROKEN DRAIN PIPE AND THREE (3) PARTIALLY BROKEN DRAIN PIPES IN SPAN 1 RIGHT OVERHANG.			
	ONE DRAIN BROKEN OFF AND TWO (2) PARTIALLY BROKEN DRAIN PIPES IN SPAN 6, LEFT OVERHANG.			
Item	Slope Protection	Grade F	Maint Code 3352	Qty. 1000
Details	20 FT WIDE X 50 FT LONG X UP TO 5 FT HIGH AREA OF EROSION IN THE SLOPE UNDER SPAN 7.			
	UP TO 2 FT OF EROSION ALONG THE PILES AT BENT 1.			
Item	Scour	Grade P	Maint Code	Qty. 0
Details	POST HURRICANE MATTHEW UNDERWATER INSPECTION REPORT DATED 9/13/2017 INDICATES SCOUR AT BENT 3 PILES AND SCOUR WITH EXPOSED STEEL PILES AT BENTS 4, 5, AND 6.			
Item	Wingwalls	Grade F	Maint Code 3350	Qty. 60
Details	HEAVY VEGETATION ON SOUTHEAST, NORTHEAST, AND NORTHWEST WINGWALL.			
Item	Field Scour Evaluation	Grade P	Maint Code	Qty. 0
Details	POST HURRICANE MATTHEW UNDERWATER INSPECTION REPORT DATED 9/13/2017 RATES FIELD SCOUR EVALUATION AS " P AS PER REFERENCE TO THE PILE TIP ELEVATION DATA SHEET."			
Item	General Comments and Misc Items	Grade	Maint Code	Qty. 0
Details	GUARDRAIL IS CONTINUOUS AT NORTHEAST, NORTHWEST, AND SOUTHEAST CORNERS			
	UP TO 0.03 IN WIDE X 12 FT LONG LONGITUDINAL CRACK IN NORTH APPROACH LOCATED IN RIGHT TRAVEL LANE TO THE RIGHT OF CENTERLINE.			
	DOWNSTREAM READINGS FROM 2018 WERE USED IN INSPECTIONS STREAMBED PROFILE SINCE READINGS COULD NOT BE OBTAINED DUE TO ACCESS.			



Span 1 Deck: UP TO 1 FT WIDE X 9 IN LONG X UP TO 1 IN DEEP SPALL WITH EXPOSED REINFORCEMENT IN RIGHT OVERHANG, LOCATED AT THIRD DRAIN PIPE. 80% SECTION REMAINING IN EXPOSED REINFORCEMENT.



ONE BROKEN DRAIN PIPE AND THREE (3) PARTIALLY BROKEN DRAIN PIPES IN SPAN 1 RIGHT OVERHANG.



Span 1 Deck: 5 FT WIDE X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 3 END DIAPHRAGM, AT BENT 1. PATCH EXHIBITS A HAIRLINE X 1 FT LONG CRACK IN BOTTOM RIGHT CORNER.



Span 1 Beam 4: 5 IN LONG X 5 IN WIDE AREA OF HEAVY SURFACE CORROSION BENEATH THE PAINTED SURFACES IN BOTTOM FLANGE OF LEFT FLANGE ABOVE BEARING AT BENT 1. UP TO 0.8 IN SECTION REMAINING.



Span 1 Beam 4 Far Bearing: SECTION LOSS IN THE RIGHT ANCHOR BOLT. 75% SECTION REMAINING.



NEW EPOXY SEAL ON TOP OF BENT 1 CAP. TYPICAL ON TOP OF ALL BENTS AND BOTH END BENTS.



Span 1 Deck: 4 FT LONG X 8 IN HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 1.



Span 1 Left Bridge Rail: 15 FT LONG AREA OF SOUND CONCRETE PATCHING TO CONCRETE RAIL, BEGINNING AT 15 FT FROM END BENT 1. PREVIOUS REPAIR.



Span 2 Deck: 82 IN WIDE X 1 FT HIGH SOUND CONCRETE PATCH AREA, BAY 2 END DIAPHRAGM, AT BENT 1.



Span 2 Deck: UP TO 1.5 FT WIDE X 4 IN LONG X UP TO 2 IN DEEP SPALL IN DIAPHRAGM IN BAY 3 AT BENT 1.



Span 2 Beam 3 Far Bearing: WELDED BEARING REPAIR WITH ANCHOR ROD. TYPICAL AT BEAMS 1, 2, AND 4.



Span 2 Deck: 9 FT LONG X 1 FT HIGH CONCRETE PATCH, BAY 2 END DIAPHRAGM, AT BENT 2. PATCH EXHIBITS UP TO 1/8 IN WIDE X 5 FT LONG CRACK IN THE BOTTOM FACE WITH A 5 FT LONG X 5 IN WIDE UNSOUND CONCRETE AND UP TO 0.02 IN WIDE VERTICAL CRACKS IN FRONT FACE, SCATTERED.



NEW REPAIR TO SPAN 2 BEAM 1 BEAM END IN BOTH FACES OF THE WEB ABOVE BENT 2.



Span 2 Beam 1: 10 IN LONG X 5 IN WIDE AREA OF SECTION LOSS BENEATH THE PAINTED SURFACE ABOVE THE BEARING AT BENT 2. 0.60 IN SECTION REMAINING (PAR).



Span 3 Deck: 3 FT LONG X 6 IN HIGH UNSOUND CONCRETE PATCH WITH EXPOSED REINFORCEMENT. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT.



Span 3 Deck: 32 IN LONG X 1 FT HIGH SOUND CONCRETE PATCHES IN PATCHED AREA, BAY 1 END DIAPHRAGM, AT BENT 2.



Span 3 Deck: 7 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 2.



Span 2 Deck: 9 FT LONG X 1 FT HIGH SOUND CONCRETE PATCH, BAY 2 END DIAPHRAGM, AT BENT 2. PATCH EXHIBITS UP TO 1/8 IN WIDE X 5 FT LONG CRACK IN THE BOTTOM FACE WITH A 5 FT LONG X 5 IN WIDE UNSOUND CONCRETE AND UP TO 0.02 IN WIDE VERTICAL CRACKS IN FRON FACE, SCATTERED.



Span 3 Deck: NEW REPAIR: 9 FT LONG X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 3 AT BENT 2.



Span 2 Deck: NEW REPAIR: 3 FT WIDE X 1 FT HIGH SOUND CONCRETE PATCH IN OVERHANG IN EAST FACE AT BENT 2 AND A 1 FT WIDE X 2 FT HIGH SOUND CONCRETE PATCH IN DIAPHRAGM OUTSIDE OF BEAM 4 AT BENT 2.



Bent 3 Pile 7: 5 FT HIGH X UP TO 6 IN WIDE CONCRETE PATCH WITH HAIRLINE VERTICAL CRACKS IN EAST FACE, LOCATED AT 4 FT BELOW THE CAP.



Bent 3 Pile 7: 4 FT HIGH X 4 IN WIDE SPALL WITH EXPOSED REINFORCEMENT IN EAST FACE. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT (PAR).



Span 3 Deck: UP TO 0.03 IN WIDE TRANSVERSE AND RANDOM CRACKING IN DECK UNDERSIDE IN ALL BAYS, SCATTERED THROUGHOUT. BAY 3 SHOWN IN PHOTO.



Span 3 Beam 1: 2 FT LONG X 5 IN WIDE AREA OF BOTTOM FLANGE HAS SECTION LOSS BENEATH THE PAINTED SURFACE, LOCATED AT 2 FT FROM BEAM END AT BENT 3. 0.74 IN SECTION REMAINING.



Span 3 Beam 1: 3.3 FT LONG X UP TO 5 IN HIGH AREA OF RIGHT FACE OF THE WEB AT 1.25 FT FROM BEAM END AT BENT 3 EXHIBITS SECTION LOSS BENEATH THE PAINTED SURFACE. UP TO 0.575 IN SECTION REMAINING.



Span 4 Deck: 2.5 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH WITH HAIRLINE VERTICAL CRACKS IN BAY 1 ABOVE BENT 3.



Span 4 Deck: 4 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH WITH HAIRLINE VERTICAL CRACKS IN BAY 2 AT BENT 3.



Bent 4 Pile 1: 5 FT LONG X 0.02 IN WIDE VERTICAL CRACK, SOUTH FACE BEGINNING AT CAP.



Span 4 Right Bridge Rail: 1.5 FT LONG X 9 IN HIGH X UP TP 1.5 IN DEEP SPALL IN EXTERIOR FACE OF RAIL, LOCATED AT MID SPAN.



Span 4 Deck: 7 FT LONG X 2 FT LONG AREA OF HONEYCOMBING LOCATED AT MID SPAN.



Span 4 Deck: 2 IN WIDE X 7 IN LONG X UP TO 2 IN DEEP SPALLS AND HONEYCOMBING WITH EXPOSED REBAR IN BOTTOM OF DIAPHRAGM IN BAY 1 AT BENT 4. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.



Span 5 Deck: 6 FT LONG X 3 FT WIDE X UP TO 3/4 IN DEEP AREA OF HONEYCOMBING IN BAY 3 NEAR BENT 5.



Span 5 Deck: NEW REPAIR: 8 FT LONG X 6 IN HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 5.



Bent 5 Pile 1: ABRASION WITH COARSE AGGREGATE EXPOSED 1/16 IN TO 1/4 IN LOSS OF FACIAL CONCRETE.



Span 6 Deck: NEW REPAIR: 28 IN LONG X 1 FT HIGH SOUND CONCRETE PATCH IN BAY 2 END DIAPHRAGM, AT BENT 5. PATCH EXHIBITS HAIRLINE VERTICAL CRACKING, SCATTERED.



Span 6 Deck: NEW REPAIR: 12 IN DIAMETER SOUND CONCRETE PATCH IN EAST OVERHANG AT DRAIN ONE.



Span 6 Deck: NEW REPAIR: 18 IN DIAMETERE SOUND CONCRETE PATCH IN EAST OVERHANG BETWEEN 5TH AND 6TH DECK DRAINS.



Span 6 Deck: 2.5 FT WIDE X 10 IN LONG X UP TO 6 IN HIGH AREA OF UNSOUND CONCRETE AND SPALL UP TO 2 IN DEEP WITH EXPOSED REINFORCEMENT IN BAY 3 END DIAPHRAGM AT BENT 7. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.



Bent 6 Cap 1: 2 FT LONG X 17 IN HIGH PATCHED AREA, TOP OF SOUTH FACE, BELOW BEAM 3.



Span 6 Deck: 12 IN WIDE X 9 IN LONG X 14 IN HIGH IN SOUTH FACE SPALL UP TO 3.5 IN DEEP WITH EXPOSED REINFORCEMENT IN BAY 2 AT BENT 6. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.



Span 6 Beam 3: UP TO 11 IN HIGH X 10 IN LONG AREA OF SECTION LOSS IN THE WEB BENEATH THE PAINTED SURFACE AT BEAM END AT BENT 6. 0.575 IN SECTION REMAINING.



DECK DRAINS ALONG LEFT BRIDGE RAIL IN SPAN 6. ONE DRAIN BROKEN OFF AND TWO (2) PARTIALLY BROKEN.



Span 6 Deck: NEW REPAIR: 2 FT HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN END DIAPHRAGM OUTSIDE BEAM 1 AT BEAM 6.



Span 7 Deck: 75 SQ FT OF PATCHED AREA, UNDERSIDE OF DECK, AT RANDOM THROUGHOUT ALL BAYS. PHOTO SHOWS BAYS 1 AND 2.



Span 7 Deck: NEW REPAIR: 6 FT LONG X 12 IN HIGH SOUND CONCRETE PATCH BOTTOM OF BAY 3 END DIAPHRAGM, NEXT TO BEAM 3, AT BENT 6. PATCH EXHIBITS UP TO 0.03 IN WIDE VERTICAL CRACKS, SCATTERED.



Span 7 Deck: NEW REPAIR: 18 IN DIAMETER SOUND CONCRETE PATCH IN EAST OVERHANG AT THIRD DRAIN PIPE.



Span 7 Deck: 24 IN LONG X 2 FT WIDE X 2 IN DEEP DELAMINATION/SPALL WITH EXPOSED REINFORCING, UNDERSIDE OF EAST OVERHANG AT 2/3 POINT. NO MEASUREABLE SECTION LOSS IN EXPOSED REINFORCEMENT.



Span 7 Deck: 7 FT LONG X 1 FT HIGH SOUND CONCRETE PATCH IN INTERMEDIATE DIAPHRAGM IN BAY 3 AT BENT 7.



Span 7 Deck: NEW REPAIR: 2 FT HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN DIAPHRAGM OUTSIDE BEAM 4 AT BENT 7.



Span 7 Deck: 7 FT LONG X 1 FT HIGH SOUND CONCRETE PATCH IN INTERMEDIATE DIAPHRAGM IN BAY 3 AT BENT 7.



20 FT WIDE X 50 FT LONG X UP TO 5 FT HIGH AREA OF EROSION IN THE SLOPE UNDER SPAN 7.



Span 7 Deck: NEW REPAIR 2 FT HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN DIAPHRAGM OUTSIDE BEAM 4 AT BENT 7.



Span 7 Beam 2 Far Bearing: BEARINGS HAVE BEEN PAINTED SINCE PREVIOUS INSPECTION. SECTION LOSS REMAINS BENEATH THE PAINTED SURFACES. UP TO 80% SECTION REMAINING IN BOTH MASONRY AND SOLE PLATES.



Bent 7 Pile 1: NEW REPAIR 8 FT HIGH X 1 FT WIDE SOUND CONCRETE PATCH IN WEST FACE.



NEW APPROACH PAVEMENT IN NORTH APPROACH. TYPICAL IN SOUTH APPROACH.



Span 8 Left Bridge Rail: 8 IN WIDE X 8 IN HIGH X UP TO 3 IN DEEP SPALL WITH EXPOSED REINFORCEMENT IN TOP OF RAIL AT FIRST RAIL JOINT FROM END BENT 2. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT.



Span 3 Left Bridge Rail: TWO (2) SPALLS UP TO 8 IN IN DIAMETER X 1 IN DEEP WITH EXPOSED REINFORCEMENT IN BOTTOM OF CURB AT 6 FT AND 10 FT FROM BENT 3 JOINT. NO MEASURABLE SECTION LOSS IN EXPOSED REINFORCEMENT.



2 FT WIDE X 8 IN LONG X UP TO 5 IN DEEP SPALL IN THE TOP OF WINGWALL AT SOUTHWEST CORNER.



Span 6 Left Bridge Rail: MODERATE TO HEAVY IMPACT DAMAGE WITH UP TO 5 IN DEFLECTION TOWARDS WEST TO THE SUPPLEMENTAL BRIDGE RAIL FOR 20 FT LONG STARTING AT BENT 6. TWO (2) SPACER BLOCKS CONNECTING THE GUARDRAIL TO POSTS ARE PARTIALLY CRUSHED.



Span 6 Left Bridge Rail: MODERATE TO HEAVY IMPACT DAMAGE WITH UP TO 5 IN DEFLECTION TOWARDS WEST TO THE SUPPLEMENTAL BRIDGE RAIL FOR 20 FT LONG STARTING AT BENT 6. TWO (2) SPACER BLOCKS CONNECTING THE GUARDRAIL TO POSTS ARE PARTIALLY CRUSHED.



End Bent 1 Abutment/Backwall : UP TO 0.03 IN WIDE RANDOM CRACKING IN BACKWALL FOR FULL LENGTH.



UP TO 2 FT OF EROSION ALONG THE PILES AT BENT 1.

Stream Bed Soundings

(Profile diagram on following sheet)

County **JOHNSTON**

Structure Number: **500101**

Inspection Date **06/26/2019**

Sounding recorded from: **Top of Bridge Rail**

Highwater Mark Distance

Location of Highwater Mark **NONE DETECTED**


Distance (Station) ft.	Downstream Sounding ft.	Upstream Sounding ft.	Description
0.000	2.500	0.000	TOP OF RAIL
1.000	6.000	0.000	TOP OF CAP
5.000	7.500	7.300	END BENT 1
9.000	7.500	0.000	
31.000	19.400	0.000	TOE OF SLOPE
44.000	20.200	0.000	
50.000	23.700	22.700	BENT 1
76.000	21.600	0.000	
100.000	21.500	23.400	BENT 2
129.000	29.300	0.000	
139.000	30.000	0.000	WSWE
150.000	34.900	34.000	BENT 3
176.000	36.900	0.000	
200.000	34.200	36.300	BENT 4
220.000	36.200	0.000	
250.000	36.200	40.900	BENT 5
270.000	36.900	0.000	
300.000	35.300	39.400	BENT 6
323.000	28.400	0.000	
324.000	30.000	30.000	WSWE
340.000	23.900	0.000	
350.000	19.300	16.900	BENT 7
368.000	14.400	0.000	
382.000	12.900	0.000	
389.000	7.000	0.000	
392.000	6.900	6.900	END BENT 2
397.000	6.000	0.000	TOP OF CAP
398.000	2.500	0.000	TOP OF RAIL

Structure Data Worksheet

Span Profile

County: **JOHNSTON**

Structure Number: **500101**



A: SPAN LENGTH
 B: BEARING TO BEARING
 C: DISTANCE FROM NEAR BEARING
 D: DISTANCE TO FAR BEARING

Span Number	Span Length	Bearing to Bearing	Crutch/ Helper Bent	Distance to Near Bearing	Distance to Far Bearing
1	50.250	48.500			
2	50.000	49.000			
3	50.000	49.000			
4	50.000	49.000			
5	50.000	49.000			
6	50.000	49.000			
7	50.000	49.000			
8	50.250	48.500			



SNOOPER USED



TRAFFIC CONTROL USED



SLOPE PROTECTION AT END BENT 1



SOUTHWEST WINGWALL



INTERMEDIATE DIAPHRAGM IN SPAN 1 BAY 2



SOUTHEAST WINGWALL. NOTE HEAVY VEGETATION.



BEARINGS AT BENT 1 BEAM 2



BENT 2 PROFILE. OTHER INTERIOR BENTS SIMILAR.



SUPERSTRUCTURE UNDERSIDE SPAN 2. NOTE NEW PAINT.



BOTTOM FLANGE COVERPLATE CONNECTION AT BEAM 3 SPAN 3. TYPICAL IN BEAMS 2 AND 3 IN ALL SPANS.



NEW REPAIR TO SPAN 3 BEAM 1 BEAM END IN BOTH FACES OF THE WEB ABOVE BENT 3.



UPSTREAM FROM UNDER THE BRIDGE



DOWNSTREAM FROM UNDER THE BRIDGE



NEW REPAIR TO SPAN 5 BEAM 1 BEAM END IN BOTH FACES OF THE WEB ABOVE BENT 4.



BENT 4 PROFILE



WELDED REPAIR TO WEB BELOW END DIAPHRAGM, AT BENT 5.



SLOPE PROTECTION AT END BENT 2



NEW REPAIR TO SPAN 8 BEAM 1 BEAM END IN BOTH FACES OF THE WEB ABOVE BENT 7.



NORTHWEST WINGWALL. NOTE HEAVY VEGETATION GROWTH.



END DIAPHRAGM AT BENT 7 BAY 2



NORTHEAST WINGWALL. NOTE HEAVY VEGETATION.



END BENT 2 PROFILE



BACKWALL AND CAP AT END BENT 2 BAY 1



BEARING AT END BENT 2 BEAM 2. NOTE NEW PAINT.



WEST PROFILE



POST SPACING MID LENGTH NORTHWEST CORNER



POST SPACING MID LENGTH NORTHEAST CORNER



POST SPACING AT BRIDGE NORTHEAST CORNER



POST SPACING AT BRIDGE NORTHWEST CORNER



LOOKING SOUTH



FEATURE INTERSECTED SIGN AT NORTHEAST CORNER



RIGHT BRIDGE RAIL



LEFT BRIDGE RAIL



BRIDGE PLAQUE AT NORTHWEST CORNER. TYPICAL AT SOUTHEAST CORNER.



LEFT BRIDGE RAIL LOOKING SOUTH



DECK JOINT AT END BENT 2. TYPICAL AT END BENT 1.



NORTH APPROACH SLAB



DECK DRAINS ALONG LEFT BRIDGE RAIL IN SPAN 8. TYPICAL ALONG BOTH BRIDGE RAILS AND IN ALL SPANS.



NORTH APPROACH



DECK JOINT AT BENT 7. TYPICAL AT ALL INTERIOR BENTS.



TOP OF DECK. NEW LMC OVERLAY SINCE PREVIOUS INSPECTION.



DOWNSTREAM LOOKING WEST



SOUTH APPROACH



POST SPACING AT BRIDGE SOUTHEAST CORNER



POST SPACING AT BRIDGE SOUTHWEST CORNER



SOUTH APPROACH SLAB. NEW SINCE PREVIOUS INSPECTION. NOTE NEW ASPHALT PAVEMENT IN SOUTH APPROACH.



LOOKING NORTH



GUARDRAIL END TERMINAL AT SOUTHEAST CORNER



END BENT 1 PROFILE



EAST PROFILE



BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 500101

County JOHNSTON

Date:


These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3314	Maintain Steel Superstructure Components	LF	1	Span 2 Beam 1: 10 IN LONG X 5 IN WIDE AREA OF SECTION LOSS BENEATH THE PAINTED SURFACE ABOVE THE BEARING AT BENT 2. 0.60 IN SECTION REMAINING (PAR).	
 3348	Maintain Concrete Substructure Components	LF	1	Bent 3 Pile 7: 4 FT HIGH X 4 IN WIDE SPALL WITH EXPOSED REINFORCEMENT IN EAST FACE. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT (PAR).	

Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 500101


County JOHNSTON

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3314	Maintain Steel Superstructure Components	1 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
06/27/2019	RAGHUVEER SURAPANENI	
Details		
Span 2 Beam 1: 10 IN LONG X 5 IN WIDE AREA OF SECTION LOSS BENEATH THE PAINTED SURFACE ABOVE THE BEARING AT BENT 2. 0.60 IN SECTION REMAINING (PAR).		

MMS Code	MMS Description	Quantity
3348	Maintain Concrete Substructure Components	1 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
06/27/2019	RAGHUVEER SURAPANENI	
Details		
Bent 3 Pile 7: 4 FT HIGH X 4 IN WIDE SPALL WITH EXPOSED REINFORCEMENT IN EAST FACE. 90% SECTION REMAINING IN EXPOSED REINFORCEMENT (PAR).		

Bridge Inspection Field Sketch



Roadway	24ft Wide	2 Paved Lanes	Looking North
Left Shoulder	2.5ft Wide	2.5ft Paved	
Right Shoulder	1.5ft Wide	1.5ft Paved	
Left Guardrail	2.5ft from road		
Right Guardrail	1.5ft from road		


MEASURED AT OUTSIDE APPROACH SLAB AT NORTHWEST CORNER

MODIFIED BY RS ON 6/26/19

Title APPROACH ROADWAY - SBL		Description LOOKING SOUTH	
Bridge No: 500101	Drawn By: A. D. OSBORNE	Date: 06/21/2005	File Name: S0154000026

Bridge Inspection Field Sketch

Deck Width/Out to Out	33.5ft	Between Rails	28.167ft
Clear Roadway	28.167ft	Wearing Surface	0.146ft*
Median Width		Median Height	
Curb Height		Left	0.708ft**
		Right	0.708ft**
Sidewalk Width		Left	
		Right	
Clear Roadway (Rail to Median)		Left	
		Right	
Guardrail Width		Left	2.667ft
		Right	2.667ft
Top of Rail to Deck/Wearing Surface		Left	2.958ft
		Right	2.958ft
Bridge Rail		Left	Type 33
		Right	Type 33



Measurements for Span #	1		
Deck Thickness	0.875'	Left Overhang	4.75'
Top of Rail to Bottom of Beam	6.5'	Right Overhang	4.75'

Beam Number	Beam Type	Spacing	Comments
1	Steel I Beam	8ft	
2	Steel I Beam	8ft	
3	Steel I Beam	8ft	
4	Steel I Beam	ft	


CHANGE IN BEAM SIZES, DECK WIDTH, OVERHANGS, TOP OF RAIL TO DECK, CURB HEIGHT, GUARDRAIL WIDTH, DECK THICKNESS, TOP OF RAIL TO BOTTOM OF BEAM, AND WEARING SURFACE

* MINIMUM


** 0.5FT MINIMUM AT NORTHWEST CORNER

BEAMS 2&3 COVERPLATES = 26'-6" X 9" X 0.623"

BEAMS 2 & 3, ALL SPANS



BEAMS 1 & 4, ALL SPANS



Title MODIFIED BY RS ON 6/26/19
TYPICAL SECTION

Description
4 - LINES STEEL I - BEAMS


Bridge No: 500101

Drawn By: A. D. OSBORNE

Date: 06/21/2005

File Name: S0154000027

Bridge Inspection Field Sketch



Cap Information			Material Cast-in-Place Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
31.167 ft.	2.500 ft.	2.500 ft.	1.583 ft.	1.583 ft.	1.500 ft.	1.500 ft.				
Subcap Information			Material							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
Sill Information			Material							
Length	Width	Height								
Pile #	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar?
1	Steel	4.667 ft.	1.833 ft.	1.833 ft.		Battered	Yes	No	No	No
2	Steel	4.667 ft.	1.833 ft.	1.833 ft.		Vertical	Yes	No	No	No
3	Steel	4.667 ft.	1.833 ft.	1.833 ft.		Vertical	Yes	No	No	No
4	Steel	4.667 ft.	1.833 ft.	1.833 ft.		Vertical	Yes	No	No	No
5	Steel	4.667 ft.	1.833 ft.	1.833 ft.		Vertical	Yes	No	No	No
6	Steel	4.667 ft.	1.833 ft.	1.833 ft.		Vertical	Yes	No	No	No
7	Steel		1.833 ft.	1.833 ft.		Battered	Yes	No	No	No
NOTE: PILES ARE CONCRETE-ENCASED STEEL H-PILES										
VERIFIED BY RS ON 6/25/19										
Bent/Abutment #: 1			Similar Bents: BENT 2-6							

Title SUBSTRUCTURE			Description LOOKING NORTH							
Bridge No: 500101	Drawn By:				Date: 06/22/2005			File Name: S0018000412		

Bridge Inspection Field Sketch

North



ABUT. B

BT. 7

9.4' (2') BT. 6 (3') 5.3'

10.9' (4') BT. 5 (2.5') 6.2'

6.3' (2') BT. 4 (2') 4.2'

4.0' (1') BT. 3 (1') 4.9'

BT. 2

BT. 1

ABUT. A

Current: LIGHT

(2019 WATER DEPTHS)

Streambed Composition: SILT, CLAY AND COARSE RIVER SAND
 Water Surface: 30.0'
 PROBE = 1'

UPDATED BY RS ON 6/26/19

Title

PLAN VIEW

Description

BRIDGE AND WATERWAY

Bridge No: 500101

Drawn By: WTW

Date: 09/19/2005

File Name: S0158000026