

PLOT DRIVER: \$PLTDVYS\$
USER: \$USER\$
FILE: \$PWVARVAULTPATHDESC\$

PENTABLE: \$PENTBLS\$
TIME: 10:25:45 AM

DATE: 6/29/2026

CONTRACT: DA00677

TIP PROJECT: 15BPR.164

STATE OF NORTH CAROLINA
DIVISION OF HIGHWAYS

BEAUFORT COUNTY

LOCATION: FERRY TERMINAL BRIDGE NO. 060321 ON NC306
AT THE PAMLICO SOUND NEAR AURORA

FERRY TERMINAL BRIDGE NO. 060322 ON NC306
AT THE PAMLICO SOUND NEAR BAYVIEW

TYPE OF WORK: STRUCTURAL, MECHANICAL AND ELECTRICAL
REHABILITATION OF EXISTING RAMP STRUCTURES

INDEX OF SHEETS

- G-1

GI-01

SI-01

SI-02

SI-03

SI-04

SI-05

SI-06

SI-07

SI-08

SI-09

SI-10

M1-01

M1-02

E1-01

E1-02

E1-03

E1-04

E1-05
- INDEX OF SHEETS

KEY PLAN AND GENERAL NOTES

PRESTRESSED CORED SLAB REPAIR DETAILS

DOLPHIN FENDER PANEL REPLACEMENT

LIFT BENT REPAIR DETAILS

STEEL BEAM CRACK REPAIR DETAILS

BENT 1 STEEL PILE REPAIR DETAILS

BENT 2 STEEL PILE REPAIR DETAILS

LIFT BENT STEEL PILE REPAIR DETAILS

BENT 2 PILE JACKET REPAIR DETAILS

LIFT BENT PILE JACKET REPAIR DETAILS

FRP PILE JACKET DETAILS

MECHANICAL NOTES

HYDRAULIC AND LUBRICATION REPAIRS

ELECTRICAL GENERAL NOTES

AREA LIGHTING REPAIR DETAILS

CONDUIT REPAIR DETAILS

JUNCTION BOX REPAIR DETAILS

HPU CAPACITOR AND PENDANT REPAIR DETAILS

- G2-01

S2-01

S2-02

S2-03

S2-04

S2-05

S2-06

S2-07

M2-01

M2-02

E2-01

E2-02

E2-03

E2-04

E2-05

SN
- KEY PLAN AND GENERAL NOTES

DOLPHIN FENDER PANEL REPLACEMENT DETAILS

STEEL BEARING REPAIR DETAILS

STEEL BEAM CRACK REPAIR DETAILS

LIFT BENT STEEL PILE REPAIR DETAILS

BENT 2 PILE JACKET REPAIR DETAILS

LIFT BENT PILE JACKET REPAIR DETAILS

FRP PILE JACKET DETAILS

MECHANICAL NOTES

HYDRAULIC AND LUBRICATION REPAIRS

ELECTRICAL GENERAL NOTES

AREA LIGHTING REPAIR DETAILS

CONDUIT REPAIR DETAILS

RACEWAY REPAIR DETAILS

JUNCTION BOX REPAIR DETAILS

STANDARD NOTES

STATE	STATE PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
N.C.	-- -- --	G-1	34
STATE PROJ. NO.	P.A. PROJ. NO.	DESCRIPTION	
15BPR.164.1	-- --	PE	
15BPR.164.3	-- --	CON	

