

Structure: 750009

Priority Action Repair Report

PM 24 Month

Status: Created

Priority Action Request

Request Date: 04/10/2026

Requested By: L. Stevens

Request Description:

Span 2 Beam 8: (2) AREAS OF IMPACT DAMAGE UP TO 4 FOOT LONG WITH UP TO 1 INCH DEFLECTION IN LEFT EDGE OF BOTTOM FLANGE AND COVER PLATE, AT 17 FOOT AND 18 1/2 FOOT FROM BENT 1.

Reviewed Date: 04/14/2026

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 750009



Span 2 Beam 8: (2) AREAS OF IMPACT DAMAGE UP TO 4 FOOT LONG WITH UP TO 1 INCH DEFLECTION IN LEFT EDGE OF BOTTOM FLANGE AND COVER PLATE, AT 17 FOOT AND 18 1/2 FOOT FROM BENT 1

Structure: 750009

Priority Action Repair Report

PM 24 Month

Status: Created

Priority Action Request

Request Date: 04/10/2026

Requested By: L. Stevens

Request Description:

Span 2 Beam 9: (2) AREAS OF IMPACT DAMAGE UP TO 30 INCH LONG WITH UP TO 1 INCH DEFLECTION IN LEFT EDGE OF BOTTOM FLANGE AND COVER PLATE, AT 22 FOOT 11 INCH AND 17 FOOT 4 INCH FROM BENT 1.

Reviewed Date: 04/14/2026

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 750009



Span 2 Beam 9: (2) AREAS OF IMPACT DAMAGE UP TO 30 INCH LONG WITH UP TO 1 INCH DEFLECTION IN LEFT EDGE OF BOTTOM FLANGE AND COVER PLATE, AT 22 FOOT 11 INCH AND 17 FOOT 4 INCH FROM BENT

Structure: 750009

Priority Action Repair Report

PM 24 Month

Status: Created

Priority Action Request

Request Date: 04/10/2026

Requested By: L. Stevens

Request Description:

Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DELECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE.

Reviewed Date: 04/14/2026

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: **750009**



Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DEFECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE

Structure: 750009

Priority Action Repair Report

PM 12 Month

Status: Created

Priority Action Request

Request Date: 11/19/2025

Requested By: W.A. VAUGHAN

Request Description:

Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DELECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE. -PAR

Reviewed Date: 11/20/2025

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 750009



Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DELECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE.



Priority Action Request Photos

Structure: 750009

Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DELECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE.



Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DELECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE.



Priority Action Request Photos

Structure: 750009



Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DEFECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE.



Span 2 Beam 10: IMPACT-11/19/2025- PRIOR DAMAGE; LOCATED 21.2 FEET FROM INTERIOR BENT 1 - AREA 8 FEET LONG DEFLECTED TOWARDS SOUTH 1.25 INCHES WITH SEGMENT OF BOTTOM FLANGE DEFLECTED UPWARDS 1.5 INCHES - ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [8 FOOT LONG] WITH AREA OF DEFECTION [1/4 INCH X 3 FOOT LONG] ON SOUTH FACE AND DEFLECTED UP [1.25 INCH X 4 FOOT LONG] ON NORTH FACE.

Structure: 750009

Priority Action Repair Report

PM 12 Month

Status: Created

Priority Action Request

Request Date: 11/19/2025

Requested By: W.A. VAUGHAN

Request Description:

Span 2 Beam 9: ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [6 FOOT LONG] WITH DEFLECTION [UP TO 1/2 INCH].

Reviewed Date: 11/20/2025

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:


Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 750009



Span 2 Beam 9: ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [6 FOOT LONG] WITH DEFLECTION [UP TO 1/2 INCH].



Span 2 Beam 9: ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [6 FOOT LONG] WITH DEFLECTION [UP TO 1/2 INCH].

Priority Action Request Photos

Structure: 750009



Span 2 Beam 9: ALONG BOTTOM FLANGE AT MID SPAN, AREA OF IMPACT DAMAGE [6 FOOT LONG] WITH DEFLECTION [UP TO 1/2 INCH].

Structure: 750009

Priority Action Repair Report

PM 12 Month

Status: Created

Priority Action Request

Request Date: 11/19/2025

Requested By: W.A. VAUGHAN

Request Description:

Span 2 Beam 8: LOCATED 18.5 FEET FROM INTERIOR BENT 1 - ALONG MIDSPAN OF BOTTOM FLANGE AND COVER PLATE, AREAS OF IMPACT DAMAGE [4 FOOT X UP TO 1 INCH DEFLECTION] -PAR

Reviewed Date: 11/20/2025

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 750009



Span 2 Beam 8: LOCATED 18.5 FEET FROM INTERIOR BENT 1 - ALONG MIDSPAN OF BOTTOM FLANGE AND COVER PLATE, AREAS OF IMPACT DAMAGE [4 FOOT X UP TO 1 INCH DEFLECTION]



Span 2 Beam 8: LOCATED 18.5 FEET FROM INTERIOR BENT 1 - ALONG MIDSPAN OF BOTTOM FLANGE AND COVER PLATE, AREAS OF IMPACT DAMAGE [4 FOOT X UP TO 1 INCH DEFLECTION]