

Structure: 760011

Priority Action Repair Report

PM 12 Month

Status: Created

Priority Action Request

Request Date: 09/25/2025

Requested By: JONATHAN M. SIMPSON

Request Description:

SPAN 2 Beam 5: (PAR) DAMAGE TO BOTTOM FLANGE APPROXIMATELY 25 FEET FROM BENT 2, UP TO 2 INCH DIAMETER GOUGE ON SOUTH EDGE AND UP TO 1/2 INCH DISTORTION TO BOTTOM WEB

Reviewed Date: 09/29/2025

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 760011



SPAN 2 Beam 5: (PAR) DAMAGE TO BOTTOM FLANGE APPROXIMATELY 25 FEET FROM BENT 2, UP TO 2 INCH DIAMETER GOUGE ON SOUTH EDGE AND UP TO 1/2 INCH DISTORTION TO BOTTOM WEB



SPAN 2 Beam 5: (PAR) DAMAGE TO BOTTOM FLANGE APPROXIMATELY 25 FEET FROM BENT 2, UP TO 2 INCH DIAMETER GOUGE ON SOUTH EDGE AND UP TO 1/2 INCH DISTORTION TO BOTTOM WEB

Structure: 760011

Priority Action Repair Report

PM 12 Month

Status: Created

Priority Action Request

Request Date: 09/25/2025

Requested By: JONATHAN M. SIMPSON

Request Description:

SPAN 2 Beam 5: 12 FEET X 1/2 INCH DISTORTION FROM IMPACT DAMAGE ON BOTTOM FLANGE AND WEB STARTING 25 FEET FROM BENT 2 (PAR)

Reviewed Date: 09/29/2025

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 760011



SPAN 2 Beam 5: 12 FEET X 1/2 INCH DISTORTION FROM IMPACT DAMAGE ON BOTTOM FLANGE AND WEB
STARTING 25 FEET FROM BENT 2 (PAR)

Structure: 760011

Priority Action Repair Report

PM 12 Month

Status: Created

Priority Action Request

Request Date: 09/25/2025

Requested By: JONATHAN M. SIMPSON

Request Description:

SPAN 2 Beam 5: (2025 NO HANDS-ON ACCESS) 5-1/4 INCHES LONG HORIZONTAL CRACK IN WEB ABOVE BOTTOM FLANGE AT 37 FEET FROM BENT 2 BEARING (PAINT APPLIED) (PAR)

Reviewed Date: 09/29/2025

Reviewed By: Amph Sorsenginh

Review Comments

Repair Details

Repair Date:

Repaired Quantity:

Repair Description:

Reviewed Date:

Reviewed By:

Reviewer Comments

Priority Action Request Photos

Structure: 760011



SPAN 2 Beam 5: (2025 NO HANDS-ON ACCESS) 5-1/4 INCHES LONG HORIZONTAL CRACK IN WEB ABOVE BOTTOM FLANGE AT 37 FEET FROM BENT 2 BEARING (PAINT APPLIED) (PAR)