

# UNDERWATER BRIDGE INSPECTION REPORT

	INSPEC	TION TYPE: 4Y	ear Underwater I	nspection		to to
COUNTY ONS	SLOW	BR	IDGE NUMBER	660028 INSPECTI	ON CYCLE 4 YRS	Office
ROUTE NO	210	AC	ROSS INTRAC	DASTAL WATE	OFFICE	
Inspection Date	05/26/2	2011	Ins	spected By WI	LLIAM MUELLER	
Type Work Peri	formed		710	DASTAL WATE  Spected By  WI  WI  WI  WI  WI  WI  WI  WI  WI  W	Series Justice Justice Series Justice	
Man Hours	(Spec	c. Work Only)		- RONG JAG		
			**************************************		ter updo	
EQUIPMENT	USED	COMPRESSOR	EXE /	WET SUIT X	COMMUNICATION -	
		SCUBA	X	DRY SUIT	COMMUNICATI	ONOTS X
		CURRENT	X CON	ROPE UI	NDERWATER PHOTOS	STAKEN
DATE	DIVER	CURRENT	VISIBILITY	METEOROLOGY	DEPTH	DIVE TIME
5/25/2011	LEJH V	TIDAL	1.5'	90 DEG/CLEAR	6.0'	120 MIN.
5/26/2011	WRM	TIDAL	1.5'	86 DEG/CLEAR	14.2'	120 MIN.
					1101	

JRO COO JROKE O

### NATIONAL BRIDGE INVENTORY------- STRUCTURE INVENTORY AND APPRAISAL Run Date: 07/19/2011

(1) STATE NAME -NORTH CAROLINA	BRIDGE 660028	SUFFICIENCY RATING =	23			
	000000001330028		23			
(8) STRUCTURE NUMBER(FEDERAL)		STATUS = Structurally Deficient				
INVENTORY ROUTE (ON/UNDER) - ON	131002100	CLASSIFICATION	CODE			
(2) STATE HIGHWAY DEPARTMENT DISTRICT	3		CODE			
(3) COUNTY CODE 133 (4) PLACE CO		(112)NBIS BRIDGE SYSTEM -	YES			
(6) FEATURE INTERSECTED - INTRACOASTAL WAT	E	(104)HIGHWAY SYSTEM NON NHS Route	(			
(7) FACILITY CARRIED NC210		(26) FUNCTIONAL CLASS - Major Collector	07			
(9) LOCATION .3 MI. N JCT SR1568		(100)STRAHNET HIGHWAY - Not a STRAHNET Route	(			
(11)MILEPOINT	0	(101)PARALLEL STRUCTURE - No Parallel Structure	N			
(16)LAT 34° 29' 58.1" (17)LONG	77° 25' 44.9"	(102)DIRECTION OF TRAFFIC - 2-way Traffic	2			
(98)BORDER BRIDGE STATE CODE	PCT SHARE	(103)TEMPORARY STRUCTURE - Not Temporary				
(99)BORDER BRIDGE STRUCTURE NO		(110)DESIGNATED NATIONAL NETWORK - Not Part of	0			
		(20) TOLL On Free Road	3			
STRUCTURE TYPE AND MA	TERIAL ———	(31) MAINTAIN - State Highway Agency	01			
(43) STRUCTURE TYPE MAIN: Prestressed Concrete		(22) OWNER - State Highway Agency	01			
TYPE - Stringer Mutlibeam or Girder	CODE 502	(37) HISTORICAL SIGNIFICANCE - Not Eligible	5			
(44) STRUCTURE TYPE APPR:						
TYPE -	CODE	CONDITION	CODE			
(45) NUMBER OF SPANS IN MAIN UNIT	27	(58) DECK				
(46) NUMBER OF APPROACH SPANS		(59) SUPERSTRUCTURE				
(107)DECK STRUCTURE TYPE - Concrete cast-in-pla	ce CODE 1	(60) SUBSTRUCTURE	3			
(108)WEARING SURFACE / PROTECTIVE SYSTEM:		(61) CHANNEL & CHANNEL PROTECTION	6			
(A) TYPE OF WEARING SURFACE - Concrete	CODE 1	(62) CULVERTS	N			
(B) TYPE OF MEMBRANE - None	CODE 0					
(C) TYPE OF DECK PROTECTION - None	CODE 0	LOAD RATING AND POSTING	CODE			
(0)		(31) DESIGN LOAD HS 15	3			
AGE AND SERVICE		(64) OPERATING RATING - HS-53	195			
(27) YEAR BUILT	1968	(66) INVENTORY RATING - HS-20	136			
	1900		5			
(106)YEAR RECONSTRUCTED		(70) BRIDGE POSTING - No Posting Required				
(42) TYPE OF SERVICE : ON - Highway	0005 45	(41) STRUCTURE OPEN, POSTED ,OR CLOSED	A			
UNDER - Waterway	CODE 15	DESCRIPTION - Open, No Restriction				
	STRUCTURE					
(29) AVERAGE DAILY TRAFFIC	3900		CODE			
(30) YEAR OF ADT 2009 (109) TRUCK AD		(67) STRUCTURAL EVALUATION	3			
(19) BYPASS OR DETOUR LENGTH	99 MI	(68) DECK GEOMETRY	4			
GEOMETRIC DATA		(69) UNDERCLEARANCES, VERTI & HORIZ	N			
(48) LENGTH OF MAXIMUM SPAN	132 FT	(71) WATERWAY ADEQUACY	7			
(49) STRUCTURE LENGTH	2532 FT	(72) APPROACH ROADWAY ALIGNMENT	8			
(50)CURB OR SIDEWALK: LEFT 1.7 F	T RIGHT 1.7 FT	(36) TRAFFIC SAFETY FEATURES	0011			
(51) BRIDGE ROADWAY WIDTH CURB TO CURB	28.0 FT	(113)SCOUR CRITICAL BRIDGES	- 5			
(52) DECK WIDTH OUT TO OUT	33.7 FT	SCOUR PLAN OF ACTION				
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)	27.0 FT					
(33) BRIDGE MEDIAN - No Median	CODE 0	PROPOSED IMPROVEMENTS				
(34) SKEW 0° (35) STRUCTURE FLARED	) NO	(75) TYPE OF WORK - CODE				
(10) INVENTORY ROUTE MIN VERT CLEAR	99 FT 99 IN	(76) LENGTH OF STRUCTURE IMPROVEMENT	0 FT			
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR	28.0 FT	(94) BRIDGE IMPROVEMENT COST				
(53) MIN VERT CLEAR OVER BRIDGE RDWY	99 FT 99 IN	(95) ROADWAY IMPROVEMENT COST				
(54) MIN VERT UNDERCLEAR REF Not a Highway or	Railroad	(96) TOTAL PROJECT COST				
(55) MIN LAT UNDERCLEAR RT REF Not a Highway or	Railroad 99.9 FT	(97) YEAR OF IMPROVEMENT COST ESTIMATE	20			
(56) MIN LAT UNDERCLEAR LT REF -	0.0 FT	(114)FUTURE ADT 7800 (115) YEAR FUTURE ADT	2025			
NAVIGATION DATA —			/10/2010			
(38) NAVIGATION CONTROL - Navigational Control	CODE 1		TOTEUT			
(111)PIER PROTECTION - In Place Functioning	CODE 2	(92) CRITICAL FEATURE INSPECTION : (93) CFI DATE				
(39) NAVIGATION VERTICAL CLEARANCE	65	A) FRACTURE CRIT DETAIL - NO A)  B) LINDERWATER INCO P. VES 48MO B) 05/	01/2014			
(116)VERT - LIFT BRIDGE NAV MIN VERT CLEAR		B) UNDERWATER INSP - YES 48Mo B) 05/0 C) OTHER SPECIAL INSP NO C)	01/2011			
	90	,				

BRIDGE I & A FORM1 (90)A

## BRIDGE INSPECTION RECORD AND SUMMARY

INSPECTION TYPE 4 Year Underwater Inspection BRIDGE NO. 660028 COUNTY ONSLOW

ROUTE NC210

OVER INTRACOASTAL WATE

	EVALUATION CODES: CRITICAL	(C, 0 - 3):	POOR (P. 4): FA	AIR (F, 5, 6): GOOD (G.	7 - 9)		
	INSPECTION ITEM	. (0, 0 0),	1 0011(1,1),11	ITEM 6			
		RADES	45. CHANNEL a. WATERWAY			G	
1. WEARING S			& CHANNEL	b. ALIGNMENT		G	
DECK NO.	a. CONCRETE		PROT.	c. SCOUR		F	
OF EA TYPE	b. TIMBER		d. SLOPE PROT., RIP-RAP, DIKES, ETC.				
SPN GRADE	c. STEEL PLANK		50. APPROACH ROADWAY CONDITION				
TEM 58	d. OPEN GRID		51. APPROACH SLABS				
3. RAILING	a. CONCRETE		52. PAINT SYSTEM CODE				
	b. TIMBER		53. UTILITIES				
	c. ALUMINUM		54. RESPONSE TO LIVE LOAD				
	d. STEEL		55. ESTIMATE	D REMAINING LIFE			
4. CURBS, WI	HEELGUARDS, PARAPETS, MEDIANS	WATER OF					
5. WALKWAY	S (ON OR ATTACHED TO STRUCTURE)		60. REGULATO	ORY SIGN NOTICE ISS	SUED	NO	
	a. STEEL PL OR FINGER		61. PROMPT-ACTION NOTICE ISSUED				
JTS. OR	TS. OR b. MISC PREFAB		62. PRESENT	LY POSTED		NO	
DEVICES.	c. COMPRESSION SEAL		63. TOT. FIELD	D INSP TIME (INCLUDE	WRITE UP)(MAN HR)	56	
to. or Eriori	d. STANDARD JOINTS		64. TOTAL SNOOPER INSP. TIME (HRS)				
	e. OPEN JOINTS		65. TOTAL TR	AFFIC CONTROL TIME	(MAN HRS)		
7. DECK DEB	RIS (INCLUDES EXCESS SAND/GRAVEL)						
			7	0. SI&A GENERAL CO	NDITION RATINGS		
S	UPER STR. (FM. 1 (90)B TRUSS) ITEM 59		a. DECK		ITEM 58		
10. LONGITUDINAL BEAMS OR GIRDERS			b. SUPERSTE	RUCTURE	ITEM 59		
11. LONGITUDINAL JOIST OR STRINGERS			c. SUBSTRUC	CTURE	ITEM 60	5	
12. INT. DIAP'S, X-FRAMES, BRACING & CONN'S			d. CHANNEL	& CHANNEL PROT.	ITEM 61	5	
13. END DIAP	'S, CURTAIN WALLS, & CONN'S			0			
14. FLOOR BI	EAMS AND CONNECTIONS			71. SI&A FIELD APPE	RAISAL RATINGS		
15. BEARING	ASSEMBLIES (INCLUDING MISALIGN)		a. WATERWAY ADAQUACY				
16. DRAINAG	E SYSTEM (ON STRUCTURE)		b. APPR. RDWY. ALIGNMENT				
17. MOVABLE	SPAN MACHINERY						
			72. FIELD SC	OUR EVALUATION		Е	
SU	B STR. ITEMS. ITEM 60 (INCLUDE SCOUR)						
35. TIM SUB	a. ABUT. & INT. BENT CAPS & RISERS		U	SE OF INSP. ACCESS	BILITY EQUIPMENT		
STR.	b. PILES, POST, SILLS, & BRACING		SNOOPER (C	CODE S, 4, OR N)	HRS	NO	
	c. BULKHEADS, WING'S, & TIE BACKS		LADDER			NO	
36. CONC	a. ABUT. & INT. BENT CAPS		BUCKETTRUCK			NO	
SUB STR.	b. ABUT, & BENT COL'S BREASTWALLS	F	BOAT			YES	
	c. ABUT. & INT. BENT PILES		OTHER			NO	
	d. BACKWALLS, WING'S, RETAIN. WALLS						
	e. ABUT. & BENT FOOTINGS & SILLS	F					
37. STEEL	a. ABUT. & INT. BENT CAPS & RISERS		SPECIAL INS	PECTION REQUESTE	D FOR		
SUB STR.	b. PILES, BRACING, AND BULKHEADS						
38. FOUNDAT	TION PILES TYPE MATERIAL	F	NOTE				
39. SLOPE PI	ROT., RIP-RAP (INCLUDE DRAINAGE)						
40. FENDER	SYSTEMS		80. INSPECTE	ED BY:	our ne		
41. DRIFT		G	81. REVIEWE	D BY:			

#### BRIDGE INSPECTION RECORD AND SUMMARY

REV. 5-30-97

NSPECTION T	***************************************	ROUTINE		(U/W)	(FOR	ENDER O		INSPECTION		6/21/11
BRIDGE NO.	660028	COUNTY	ONSLOW			ROUTE	E NC 210	OVER	INTRACOASTAL	WATERWA
TRUCTURE T	YPE		ES AND WAL	***************************************			/	YEAR BUILT		110
ENGTH		ROUTE O	RIENTATION	WTOE	FOR S	PANS	13 AND 14	OF	SPA	NS
		EVALUATIO	N CODE: 0 -	CRITICAL	3 & 4 PO	OR 586	FAIR, 7 - 9 GO	OD		
	IN	SPECTION I	TEM						ITEM 61	GRADE
		DECK ITEM	S	GRAD	E	45 CHANNEL a. WATERWAY				8
1 WEARING S	SURFACE					&		b. ALIGNME	NT	8
2 DECK	a. CONCRE	TE				CHANN	NEL	c. SCOUR		8
NO. OF EA.	b. TIMBER			PROT.		d. SLOPE F	PROT., DIKES			
TYPE SPN.	c. STEEL P	LANK						RIP-RAP ET	C.	
GRADE	d. OPEN G	RID				50 APPR	OACH ROADV	VAY CONDITIO	N	
RATES						51 APPR	OACH SLABS			
SI & A ITEM							SYSTEMS		CODE	
58						53 UTILITIES 54 RESPONSE TO LIVE LOAD				
3 RAILING	a. CONCRE	TE	***************************************							
	b. TIMBER	Since contract management of the contract of t				55 ESTIN	MATED REMA	INING LIFE		
	c. ALUMINU	<u>IM</u>							was well as the second	
	d. STEEL							N NOTICE ISS		N
4 CURBS - WH	EELGUARDS	- PARAPET	S - MEDIANS			61 PROM	MPT - ACTION	NOTICE ISSU	ED	Y
5 WALKWAYS	7						ENTLY POST			N/A
6 DECK EXP.									E WRITE UP )(M	I/HI 20 MHI
JTS. OR						ISP. TIME (HRS				
DEVICES				65 TOTAL	L TRAFFIC CO	NTROL TIME (	<i>N/</i> H)			
NO. OF	d. STANDA		***************************************							
EACH	e. OPEN JO							GENERAL C	ONDITION RATIN	GS
7 DECK DEB		-	The second secon	Marchael California (1990)		a. DEC	MATTER STATE OF THE PARTY OF TH		ITEM 58	
4010H0ITH		<del></del>	0) B TRUSS )	ITEM 59			PERSTRUCTU		ITEM 59	
10 LONGITUE					-		BSTRUCTURE		ITEM 60	*3
11 LONGITUE					_	a. CHI	ANNEL & CH	ANNEL PROT.	ITEM 61	8
12 INT. DIAP	Marie	<del>and the same of t</del>	The second second							
13 END DIAP					_	71 SI& A FIELD APPRAISAL RATINGS a. WATERWAY ADEQUACY				
	EAMS AND				_	b. APPR. RDWY. ALIGNMENT				
			E MISALIGN	)	_	D. API	PR. RUVYT. A	LIGNMENT	***************************************	
	SYSTEMS		TUKES)		-	72 FIELD SCOUR EVALUATION				
17 MOVABLE	SPAN MACI		60 ( INCLUDE	ecoup \	-	12 FIEL	D SCOOK EV	ALUATION		N/A
35 TIM.			CAPS & RIS	***************************************			IISE	OF INSP ACC	ESSIBILITY EQU	ROMENT
SUB			& BRACING			SNOOPE	R (CODE P.		ZOOIDIEITT EGG	N
STR.			S, & TIE BAC	-		LADDER		-, -, -, -,	Y/N	
36 CONC.		INT. BENT					DE LADDER		Y/N	
SUB			'S & BREAS'	TWALLS		1			Y/N	
STR	c. ABUT. &	INT. BENT	PILES	****		BUCKET TRUCK Y/N BOAT Y/N				
			S - RETAIN. V	VALLS		OTHER		***************************************	Y/N	
	e. ABUT. A	ND BENT F	OOTINGS &	SILLS				eterrorreesi austriaes carroren en e		
37 STEEL			CAPS & RIS	***************************************		NOTE:	* ITEM 700	FOR FENDER	ONLY	
SUB. STR.	b. PILES A	ND BRACIN	G AND BULK	HEADS					***************************************	
38 FOUNDATI	ON PILES T	YPE MATER	IAL							***************************************
39 SLOPE PR	OT., RIP - R	AP (INCLUD	E DRAINAGE	)			***************************************			
40 FENDER S	YSTEMS				3					
41 DRIFT						80 INSPE	CTED BY :	W.R. MUEL	LER WINY	well
					1	81 DEVIE	EWED BY:	012		

Bridge I&A Form 1(82)H

State of North Carolina Dept. of Transportation Division of Highways

### FIELD INSPECTION REPORT

**Bridge Inspecion & Analysis** 

Team Leader WILLIAM MUELLER

Itaan Na	0 1	
Item No.	Grade	
36b	F	CONCRETE COLUMNS BENTS 13 AND 14 ARE FOOTED BENTS ON SILLS WITH COLUMNS HAVING RANDOM HAIRLINE CRACKS AND SMALL SHALLOW SPALLS THROUGHOUT.
36e	F	FOOTINGS AND SILLS RANDOM CRACKS TO 1/16" EXTEND OUT AND UP THE SIDES. THE FOOTINGS HAVE HONEYCOMB AREAS ON CORNERS AND ON THE UNDERSIDE. AREAS OF COARSE AGGREGATE EXPOSED WITH HAIRLINE TO 1/16" CRACKS.
		BENT 13
		WEST FACE CRACKS TO 1/16" X FULL HEIGHT. LOCATED 12.8' AND 4.3' FROM THE EAST END. EAST FACE
		CRACKS TO 1/16" X FULL HEIGHT. LOCATED 12.5' AND 20.3' FROM THE EAST END.
		BENT 14 WEST FACE
		SPALL 16" X 2" X 1.5" PENETRATION. LOCATED 7.3' FROM THE SOUTH END. SPALL 4 X 3" X 1.5" PENETRATION. LOCATED 12' FROM THE SOUTH END. SPALL 14" X 16" X 1 PENETRATION. LOCATED 13.5' FROM THE NORTH END. EAST FACE
		AREA OF CONCRETE LAITANCE 18" X 1" PENETRATION AT THE TOP OF THE FOOTING NORTHWEST CORNER.
		NORTH FACE 2 SPALLS 3" X 1.5" X 1" PENETRATION AT THE NORTHWEST CORNER.
		BOTH FOOTINGS HAVE RANDOM VOIDS AT JUNCTION OF FOOTING AND SILLS DUE TO CONCRETE CRUMBLING AWAY. 8" HIGH MAX. X 2' PROBE MAX.  BENTS 13 AND 14 SILLS HAVE NUMEROUS CRACKS RANGING FROM 1" TO 7" WIDE WITH PROBES FROM 1" TO 8". SILLS ALSO HAVE AREAS OF CONCRETE LAITANCE AND SPALLS.  FOOTINGS AT BENT 13 AND 14 HAVE SEVERAL CRACKS AND SPALLS.
38	F	CONCRETE FOUNDATION PILES  NUMEROUS PILES HAVE HAIRLINE TO 1/32" CRACKS WITH EFFLO.  IN THE TIDAL ZONE. RANDOM PILES CRACKED TO 1/8".  REFER TO CRACK SHEETS.
41	G	DRIFT NO PROBLEMS NOTED
45a	G	WATERWAY NO PROBLEMS NOTED.
45b	G	CHANNEL ALIGNMENT NO PROBLEMS NOTED.

BI	COUR SENT 13										
rade Si Bi											
F SO BI											
BI											
BI N 3	NW- 0.0' SW- 1.5' NE- 2.2' SE- 3.8' SENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' IORTHWES	E PILES	EXPOSI	ED FOR						ONG ACRO	oss
	N 3 N E	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWES 3 CONCRET NORTH SIDE	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORN 3 CONCRETE PILES NORTH SIDE X 9' LO	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BEN 3 CONCRETE PILES EXPOS NORTH SIDE X 9' LONG ACF	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BENT 14 3 CONCRETE PILES EXPOSED FOR NORTH SIDE X 9' LONG ACROSS WI	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BENT 14 3 CONCRETE PILES EXPOSED FOR 2.5'. SCO NORTH SIDE X 9' LONG ACROSS WEST SIDE.	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BENT 14 3 CONCRETE PILES EXPOSED FOR 2.5'. SCOUR 5.4' NORTH SIDE X 9' LONG ACROSS WEST SIDE. (SEE SEED)	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BENT 14 3 CONCRETE PILES EXPOSED FOR 2.5'. SCOUR 5.4' VER' NORTH SIDE X 9' LONG ACROSS WEST SIDE.(SEE SCOUR	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BENT 14 3 CONCRETE PILES EXPOSED FOR 2.5'. SCOUR 5.4' VERTICAL NORTH SIDE X 9' LONG ACROSS WEST SIDE.(SEE SCOUR PRO FIELD SCOUR EVALUATION	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BENT 14 3 CONCRETE PILES EXPOSED FOR 2.5'. SCOUR 5.4' VERTICAL X 9' LO NORTH SIDE X 9' LONG ACROSS WEST SIDE.(SEE SCOUR PROFILE) FIELD SCOUR EVALUATION	BENT 14 NW- 5.4' SW- 1.2' NE- 5.0' SE- 0.0' NORTHWEST CORNER BENT 14 3 CONCRETE PILES EXPOSED FOR 2.5'. SCOUR 5.4' VERTICAL X 9' LONG ACRO NORTH SIDE X 9' LONG ACROSS WEST SIDE.(SEE SCOUR PROFILE)

#### BRIDGE INSPECTOR'S RECOMMENDATIONS FOR MAINTENANCE REPAIRS

Bridge: 660028

County: ONSLOW Division:

3

Insp. By William R. Mueller

Date

6/21/11 Check By:

Date

These Repairs Should Be Made Within Twelve Months From The Date Of This Inspection.

Function Code	Description of Function	Unit	Quantity	Remarks	Est.
	MAINT. OF TIMBER FENDER	M/HRS	1000	REPLACE/ REPAIR DETERIORATED FENDER SYSTEM COMPONENTS AS NEEDED.	
•					

### BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 660028

County ONSLOW

Date:

05/26/2011

#### These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
3348	Maintain Concrete Substructure Components	LF	1000	SPALLED FOOTINGS AND VERTICAL CRACKS AS NOTED IN CRACK SHEETS	



BENT 4 NORTHWEST CORNER SPALL ON FOOTING



BENT 5 NORTHWEST CORNER SPALL ON FOOTING



BENT 6 P-2 F-3 H/L - 1/16" CRACK




BENT 12 SPAN 13 SIDE



MARINE GROWTH BENT 13




MARINE GROWTH ON PILES



Title		Descri	Description			
APPROACH ROADWAY			WEST	APPROACH, LOOKING	EAST	
Bridge No: 660028	Drawn By:	FER		Date: 08/20/2010	File Name: S0318000045	







Measurements for Span #

Top of Rail to Bottom of Beam

**Deck Thickness** 

eft Overhang	4.2083
ight Overhang	4.2083

**ELECTRICAL** 

CABLE


13" DIAM. UTILITY PIPE

Beam Number	Beam Type	Spacing	Comments
1	PPC Girder	8.42ft	
2	PPC Girder	8.42ft	
3	PPC Girder	8.42ft	
4	PPC Girder	ft	

Right Overhang


0.833

8.25




#### TYPICAL GIRDER SECTION

Title TYPICAL SECTION		Descrip LOOKIN	otion NG EAST	
Bridge No: 660028	Drawn By: FER		Date: 08/23/2010	File Name: S0318000046








Cap Inf	formation		Material	Cast-in-l	Place Concre	ete				
Lengt	h Width	Height	Left Over	hang	Right Overh	ang Left B	eam to En	d of Cap. Rig	ht Beam to En	d of Cap
31.250	ft. 3.667 ft.	4.000 ft.	6.330	ft.	6.330 ft	. 3.0	000 ft.		3.000 ft.	
Subcap	Information		Material							
Lengt	h Width	Height	Left Over	hang	Right Overh	nang Left P	ile to Splic	e.		
Sill Info	ormation		Material							
Lengt	h Width	Height								
10.0 ft.	10.0 ft.	5.0 ft.	x2 PII	LE CAPS						
Pile#	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar
	Concrete	18.58 ft.	3.5 ft.			Battered	No	No	No	No
1	Concrete						No	No	No	No

Title		Description			
SUBSTRUCTURE ELEV	/ATION	BENT 1, LOOKING EAST			
Bridge No: 660028	Drawn By: FER	Date: 08/23/2010	File Name: S0318000053		



#### IN COASTAL WATERS HTM IS TAKEN AS W/S

HTM=HIGH TIDE MARK LTM=LOW TIDE MARK M/L=MUD LINE W/S=WATER SURFACE BOF=BOTT. OF FOOTING

110011		- 1 141 -	OTT TIBE INDUCTOR	TE THOSE ENTE THOSE TO THE TENTON TO THE
BT.#	PILE#	FACE	LOCATION	REMARKS
1RF	4	2	FOOTING	HONEYCOMB 9" X 15" X 1/4" PENETRATION
1LF	4	2	FOOTING	HONEYCOMB 12" X 6" X 1/2" PENETRATION'
1 LF	2	3	FOOTING TO M/L	2 CRACKS H/L TO 1/16*
1 LF	1	2	FOOTING DOWN 2'	SPALL 5" DIA. X 1/2" DEEP.
2 RF	1	5	FOOTING TO M/L	H/L TO 1/32*
2 LF	1	2	FOOTING TO M/L	1/64" CRACK WITH EFFLO.
2 LF	6	2	FOOTING TO M/L	H/L TO 1/64" WITH EFFLO.
2 LF	6	5	FOOTING TO M/L	H/L TO 1/64"
2 LF	6	8	FOOTING TO M/L	H/L TO 1/64" WITH EFFLO.
2 LF	4	2	FOOTING	HONEYCOMB 9" X 2" X 1/2" PENETRATION
2 LF	5	2	FOOTING	HONEYCOMB 12" X 12" X 1/2" PENETRATION
2 RF	1	2	FOOTING TO M/L	2 CRACKS H/L TO 1/16*
2 LF	1	1&2	FOOTING TO M/L	H/L-1/16"
3 RF	7	6	FOOTING TO M/L	1/32" CRACK
3 RF	7	8	FOOTING TO M/L	1/32" CRACK
3 LF	5	5	FOOTING DOWN 2'	H/L TO 1/16" WITH EFFLO.
3 RF	3	1	FOOTING TO M/L	H/L TO 1/16"
3 RF	3	6	FOOTING TO M/L	1/32" CRACK WITH EFFLO.
3 LF	1	2&4	FOOTING TO M/L	H/L TO 1/16"
4 LF	7	7	FOOTING TO M/L	H/L TO 1/64"WITH EFFLO.
4 LF	1	2	HTM DOWN 8"	SPALL 2.5"X 1.5"X 1/4"PENETRATION
4 LF	7	1	FOOTING TO M/L	H/L TO 1/16"
4 LF	7	6	FOOTING TO M/L	H/L TO 1/16"
4 RF	1	2	2" ABOFE W/L	SPALL 4" X 3.5" X 1/4" PENETRATION
4 RF	2	6	FOOTING TO M/L	H/L TO 1/32*
5 LF	7	7	FOOTING TO M/L	H/L-1/16"
5 RF	7	4	FOOTING TO M/L	H/L-1/16"
5 RF	7	6	FOOTING TO M/L	1/16" SPALLED TO 1/8"
5 LF	4	6	FOOTING TO M/L	H/L TO 1/16"
5 LF	5	5	FOOTING TO M/L	H/L TO 1/16" WITH EFFLO. SPALLED TO 1/4"
6 RF	7	2	FOOTING	HONEYCOMB 10" X 6" X 1/2" PENETRATION
6 LF	2	3	FOOTING DOWN 2'	2 CRACKS H/L TO 1/8, H/L TO 1/6*
6 LF	4	6	FOOTING	HONEYCOMB 18" X 12" X 3/4" PENETRATION
6LF	4	4	FOOTING TO M/L	H/L TO 1/16"
7 RF	6	7	FOOTING	HONEYCOMB 38" X 12" X 1/2" PENETRATION
7 LF	2	3	FOOTING TO M/L	H/L TO 1/16"
10 RF	8	4	FOOTING	SPALL 12" X 14"X 3/4" PENETRATION
10 RF	1	3	FOOTING TO M/L	H/L TO 1/32"
10 LF	6	1	FOOTING TO M/L	H/L TO 1/64"

 Title
 Description

 CRACK SHEET 1
 CRACK SHEET 1

 Bridge No: 660028
 Drawn By: 0
 Date: 0
 File Name: S0178000441

IN COASTAL WATERS HTM IS TAKEN AS W/S

HTM=HIGH TIDE MARK LTM=LOW TIDE MARK M/L=MUD LINE W/S=WATER SURFACE BOF=BOTT. OF FOOTING

"				PEMARKO		
BT.#	PILE#			REMARKS		
11 LF	6	8	НТМ	SPALL 6" DIA. X 1/2" DEEP		
11 RF	1		CORNER OF FOOTING	SHEARED EXPOSING STEEL		
11 RF	4	6	FOOTING	SPALL 18" X 6" X 1/2" PENETRATION		
11 RF	4	5	FOOTING	SPALL 18" X 6" X 1/2" PENETRATION		
11 RF	1	2	FOOTING DOWN 2'	H/L TO 1/16"		
11 LF	8	6	FOOTING DOWN 10"	SPALL 3"X 4" X 1/2" PENETRATION		
11 LF	3	1 .	FOOTING	H/L TO 1/16"		
12 RF	1	6	НТМ	SPALL 3" DIA. X 1/2" PENETRATION		
12 LF	3	4	M/L UP 3'	H/L - 1/16*		
12 RF	1	2	FOOTING DOWN 3'	SPALL 12" X 12"X 1/4"PENETRATION		
12 LF	1		FOOTING	SPALL 18" X 6" X 1"PENETRATION		
12 LF	4	1	FOOTING DOWN 3'	H/L TO 1/16" W/ RUST STAINS		
12 LF	2	8	FOOTING TO M/L	H/L TO 1/32"		
12 LF	5	2	FOOTING TO M/L	H/L TO 1/32"		
12 LF	7	2	FOOTING TO M/L	H/L TO 1/32"		
15 LF	1	2	2' ABOVE M/L	H/L TO 1/16"		
15 LF	4	1	M/L UP 4.5'	H/L TO 1/8"SPALLED TO 1/2" W/RUST STAIN		
15 RF	2		FOOTING	SPALL 1' X 2' X 3/4" PENETRATION		
15 LF	6	3 & 4	FOOTING TO M/L	H/L TO 1/32" EFFLO.		
15 LF	6	6	FOOTING TO M/L	H/L TO 1/16"		
16 RF	3	8	FOOTING DOWN 2'	H/L TO 1/16"		
16 RF	3	4	FOOTING DOWN 2'	H/L TO 1/16"		
16 RF	2	2	FOOTING DOWN 2'	H/L TO 1/16"		
16 LF	8	3	FOOTING TO M/L	H/L TO 1/16"		
17 RF	2	3	FOOTING TO M/L	H/L TO 1/16"		
17 RF	3	2	FOOTING TO M/L	H/L TO 1/16"		
17 RF	2	2	FOOTING TO M/L	H/L TO 1/16"		
17 LF	8	1	FOOTING TO M/L	H/L TO 1/16"		
17 LF	1	3	FOOTING TO M/L	H/L TO 1/16"		
17 LF	1	8	FOOTING TO M/L	H/L TO 1/16"		
17 LF	1	7	FOOTING TO M/L	H/L TO 1/16"		
17 LF	3	3&4	FOOTING TO M/L	H/L TO 1/16"		
17 LF	3	2	FOOTING TO M/L	H/L TO 1/16"		
18 RF			FOOTING	RANDOM RUST STAINS		
18 RF	3	3	FOOTING TO M/L	H/L TO 1/16"		
18 RF	7		FOOTING	HONEYCOMB 3' X 3'		
	-	-		Description		

Title

Description

**CRACK SHEET 2** 

**CRACK SHEET 2** 

Bridge No: 660028

Drawn By: 0

Date: 0


File Name: S0178000442

IN COASTAL WATERS HTM IS TAKEN AS W/S

HTM=HIGH TIDE MARK LTM=LOW TIDE MARK M/L=MUDLINE W/S=WATER SURFACE BOF=BOTT. OF FOOTING


. 1415 (1 2)	· - 11111		TIDE WAY THE THE	
BT.#	PILE#	FACE	LOCATION	REMARKS
18 LF	4	1	FOOTING TO M/L	H/L TO 1/6" SPALLED TO 1/8"
18 LF	2&7		FOOTING	HONEYCOMB 2' WIDE
18 LF	1	3	FOOTING TO M/L	H/L TO 1/32"
18 LF	7	1	FOOTING TO M/L	H/L TO 1/16"
19 RF	5		FOOTING	HONEYCOMB 8"WIDE
19 RF	2	1	FOOTING TO M/L	SPALLED 1.5" PENETRATION
19 RF	2	2	FOOTING TO M/L	H/L TO 1/8"
19 RF	1	1	FOOTING TO M/L	H/L TO 1/8"
19 RF	1	2	FOOTING TO M/L	H/L TO 1/16"
19 RF	1	8	FOOTING TO M/L	H/L TO 1/16"
19 LF	2	2	FOOTING	HONEYCOMB 3' X 2'
19 LF	6	3&8	FOOTING TO M/L	H/L TO 1/64"
19 LF	8	4&5	1' BELOW FOOTING	VOID 3"X 3/8"PENETRATION
20 LF	1	3&4	1' BELOW FOOTING	PATCHED AREA 3"V X 4"WIDE EACH FACE
20 RF	8	3	HTM TO M/L	SURFACE LOSS 1/16"TO 1/8"
20 RF	8	4	HTM TO M/L	SURFACE LOSS 1/16" TO 1/8"
20 RF	8	5	HTM TO M/L	SURFACE LOSS 1/16" TO 1/8"
20 LF	7	3	FOOTING TO M/L	H/L TO 3/16"
20 LF	8	1	FOOTING	SPALL 4" X 4"
21 RF	1	4&5	FOOTING DOWN 2'	FACE SHEARED OFF UP TO 2"LOSS
21 LF	4	3&4	8" BELOW FOOTING	SPALL 3"X 4" X 1.25" PENETRATION
22 LF	2	2	FOOTING TO M/L	1/64" CRACK WITH EFFLO.
23 RF	6	4	1' BELOW FOOTING	3/4" SURFACE LOSS
24 RF	4		FOOTING	SURFACE LOSS 1/2"
24 LF	4		FOOTING	SURFACE LOSS 1/2"
25 LF	3	4	FOOTING TO M/L	1/8"CRACK
	W. Par			

Title		Description		
CRACK SHEET 3		CRACK SHEET 3		
Bridge No: 660028	Drawn By: 0	Date: 0	File Name: S0178000443	






LOOKING WEST ALONG SOUTH SIDE FROM FENDER




LOOKING NORTH




BENT 14 SPAN 15 SIDE




LOOKING EAST ALONG SOUTH SIDE



LOOKING EAST ALONG NORTH SIDE



LOOKING SOUTH



LOOKING WEST ALONG NORTH SIDE