



NCDOT Risk Management Flowchart

Project Initiation (Stage 1)




PDN Stages 2, 3 & 4

Developing RAW



Continuous Monitoring & Managing



Responsible Leads

Division of Planning and Programming

Project Manager

Project Team Members

Risk Owner