



Guardrail proposed to be upgraded to current standard. Note terminal ends, and lack of blocks, and substandard height.