

MATTHEW

SITE CODE	ROUTE	M.P.	LOCATION	WBS	STRUCTURE NUMBER	COMMENT	CHARGES
780167	I-95	25.60	0.55 miles N of US 301	15006.1078167		017-23-078 Culvert(NI)-Wing SW Corner Broken Off. Undermined Under Culvert	\$987,313.41
780172	I-95	17.80	0.77 miles N of NC 711	15006.1078172	B-144 & B-146	001-19-078 Substructure flooded, end bent, bent 1 and bent 2 fill washed partly away	\$892,629.09
780218	I-95	38.50	0.1miles N of SR 1718	15006.1078218		300' of Shoulder Washing, 75' Weekend Guardrail, Tree Debris	\$30,137.77
780253	I-95	34.90	0.8 miles north of SR 1726	15006.1078253		Shoulder washed out & 2' +/- of asphalt emergency lane for 20'+/-	\$1,190,489.92
780254	I-95	17.10	Exit 17	15006.1078254		Shoulder wash outs	\$62,276.96
780268	I-95	18.50	0.3 miles south from SR 1536	15006.1078268	Bridge #147	Bent 6 Pile 2 has a scour hole around pile 30'x40'x60'	\$272,518.81

SUBTOTAL \$3,435,365.96

FLORENCE

SITE CODE	ROUTE	M.P.	LOCATION	WBS	STRUCTURE NUMBER	COMMENT	CHARGES
780175	I-95	18.40	.35 mile from Exit 19 MP 18.4	15406.1078175	B-147	Voids found under approach slab of south side of SBL. Applied on site during repair.	\$2,995.80
780221	I-95	30.75	MP 30.75	15406.1078221		Approaches have settled on approach and departure sides of bridges 156 & 158.	\$8,524.67

SUBTOTAL \$11,520.47

GRAND TOTAL \$3,446,886.43