COLINGTON CREEK AND CUT INSPECTION REPORT

MITIGATION SITE NAME Colington Creek and Cut		TIP# B-2024		WBS # N/A		INSPECTION DATE 9/16/2015	
COUNTY # Dare		# ACRE 0.08	# ACRES 0.08		ONEID 028-015		
MONITORING ORGANIZATION INSPEC Kimley-Horn JRH/I							
INSPECTION ACTIVITIES: Complete all that apply.							
Walked boundaries YES NO N/A			Walked trails / roads				
Walked road frontage			Walked interior				
Monitored from air YES NO N/A							
Condition of boundaries Sood Fair Poor Condition Condition							
COMMENTS: Site boundary remains in good condition. No trespass or disturbance was observed at the time of inspection. Phragmites is dominating the site. The "Control Plot" sign observed during the 2014 site visit was not observed due to dense vegetation. Some trash was observed in the site.							
WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION? Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.							
□FLOODING	FIRE		□STO	RM	□E	EARTH MOVEMENT	
NVASIVE EXOTIC ☐INSECT VEGETATION INFESTATION				IMAL TIVITY	_	OTHER ACTIVITIES/ CHANGES? (Please Explain) NO CHANGE	
EXPLAIN: Phragmites continues	to dominate the site to		the exclusion of other				
		2 2200 00		2- 3 4131	-6		

COLINGTON CREEK AND CUT INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

NEW STRUCTURE / DUMPING OR STORING NEW TRAILS OR ROADS CONSTRUCTION EXCAVATION TIMBER HARVEST/ ALTERATION TO DRAINAGE (DREDGING, FILLING, GRADING, VEGETATIVE CUTTING PATTERNS/WATER QUALITY MINING) INDUSTRIAL, RESIDENTIAL, OR SUBDIVISION LAND CLEARING COMMERCIAL USE MOTORIZED VEHICLE TRESPASS/VANDALISM AGRICULTURAL USE DAMAGE OTHER ACTIVITIES / CHANGES? ENCROACHMENT FROM ACTIVITY ON (Please Explain) ADJACENT PROPERTY ABUTTING LAND No Change **EXPLAIN:** Site continues to look good, no manmade impacts or activities were observed within the site. The site is bordered by a walking path leading to a small fishing area adjacent to the bridge. It is likely due to the ample access around (and bypassing) the site that there is no need or advantage for unauthorized persons to enter the site. REQUEST FOLLOW-UP BY PROGRAM MANAGER YES \boxtimes No FOR POSSIBLE VIOLATIONS. No Were corrective actions **EXPLAIN:** YES completed for previous inspection(s)? N/A Are you aware of any plans **EXPLAIN:** \boxtimes No □YES that may affect property? Are there concerns about **EXPLAIN:** □YES \boxtimes No boundaries by adjacent property owners? Are there changes in land use **EXPLAIN:** on adjacent property? YES \boxtimes No Are deed restrictions being No **EXPLAIN: YES** adhered to? If new property owner, do No they have a written copy of YES the restrictions? N/A**ATTACHMENTS:** 1) SITE PHOTOGRAPHS WITH CAPTIONS 2) SITE MAP

COLINGTON CREEK AND CUT INSPECTION REPORT




Photo 1 – View of site as seen from between the two mitigation areas facing west.



Photo 2 – View of site looking east from the adjacent footpath.



Aerial Imagery
TIP B-2024 Colington Cut (028-015)
Division 1, NCDOT October 2015