MITIGATION SITE NAME Tulula		TIP # A-0009WM			ID # -001	INSPECTION DATE AUGUST 19, 2020	
COUNTY Graham		# ACRES 242.30					
MONITORING ORGANIZATION KCI for NCDOT TS/KOB		-	PHONE (919) 783-9214		EMAIL ADDRESS tommy.seelinger@kci.com		
INSPECTION ACTIVITIES: Complete all that apply. Describe location of visited areas if <100%.							
Walked boundaries	Yes 🗌 No 🗌]N/A	Walked tr	ails / roads	YES YES	NO N/A	
Walked road frontage	Kes 🗌 No 🗌] N/A	Walked in	terior	YES YES	NO N/A	
Monitored from air	Kes 🗌 No 🗵	N/A					
Condition of boundaries			Good	FAIR P	OOR		
COMMENTS: Lock on gate leading into site from northeast corner has been broken. Spoke to WRC Ranger							

who said that haven't noticed any other signs of trespass. Main road through site shows signs of WRC access, but most roads through site are overgrown. There are also several large beaver dams backing up the stream on site. Land clearing/storage mentioned in last year's report is an allowed use.

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION? Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

FLOODING	FIRE	STORM	EARTH MOVEMENT					
∑Invasive Exotic Vegetation	INSECT INFESTATION	Animal Activity	OTHER ACTIVITIES/ CHANGES? (Please Explain)					
COMMENTS: Lots of Kudzu was observed along site perimeter. Several large beaver dams are blocking up the stream on site.								

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note	e location and	extent. D	ocument with	photos.		
NEW STRUCTURE / CONSTRUCTION	DUMPING OR STORING			NEW TRAILS OR ROADS		
TIMBER HARVEST/ VEGETATIVE CUTTING	EXCAVATION (DREDGING, FILLING, GRADING, MINING)			ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY		
SUBDIVISION	INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE			☐ LAND CLEARING		
DAMAGE	TRESPASS/VANDALISM			AGRICULTURAL USE		
ENCROACHMENT FROM ADJACENT PROPERTY	ACTIVITY ON ABUTTING LAND			OTHER ACTIVITIES / CHANGES? (Please Explain)		
EXPLAIN: Lock on gate to northeastern portion of site has been cut, but WRC ranger reports no other signs of trespass.						
R EQUEST FOLLOW-UP BY P ROGRAM M ANAGER FOR POSSIBLE VIOLATIONS.				YES	No	
XX7			Trans			
Were corrective actions completed for previous inspection(s)?	YES	NO N/A	EXPLAIN:			
Are you aware of any plans that may affect property?	YES	No	EXPLAIN:			
Are there concerns about boundaries by adjacent property owners?	YES	No	EXPLAIN:			
Are there changes in land us on adjacent property?	e YES	No	EXPLAIN:			
Are deed restrictions being adhered to?	YES	No	EXPLAIN:			
If new property owner, do they have a written copy of the restrictions?	YES	No				
		N/A				
ATTACHMENTS:						
1) PHOTOGRAPHS WITH CAPTIONS 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES						



Photo 1 - Interior of site. Road shows access by WRC.



Photo 2 – View of site interior.



Photo 3 – Site boundary with signage visible and present.



Photo 4 – One of the large beaver dams on site.



Photo 5 – Aerial view of the site looking east

