

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Spring Branch Bridge	TIP # B-2059	ONEID 065-008	INSPECTION DATE September 16, 2021
--	-----------------	------------------	--

COUNTY New Hanover	# ACRES 0.12
-----------------------	-----------------

MONITORING ORGANIZATION NCDOT	INSPECTOR David Johnson	PHONE (919)-707-6130	EMAIL ADDRESS ddjohnson@ncdot.gov
----------------------------------	----------------------------	-------------------------	--------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply.</i>			
Walked boundaries	Yes	Walked trails / roads	No
Walked road frontage	Yes	Walked interior	No
Monitored from air	No		
Condition of boundaries	Good		
COMMENTS: Site in good condition at time of inspection.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> Flooding <input type="checkbox"/> Invasive or Exotic Vegetation	<input type="checkbox"/> Fire <input type="checkbox"/> Insect Infestation	<input type="checkbox"/> Storm <input type="checkbox"/> Animal Activity	<input type="checkbox"/> Earth Movement <input type="checkbox"/> Other Activity or Changes (Add Comments) <input checked="" type="checkbox"/> No Change
EXPLAIN:			

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> New Structure Construction	<input type="checkbox"/> Dumping or Storage	<input type="checkbox"/> New Trails or Roads
<input type="checkbox"/> Timber Harvest or Vegetative Cutting	<input type="checkbox"/> Excavation (Dredging, Filling, Grading, Mining)	<input type="checkbox"/> Alteration To Drainage Patterns or Water Quality
<input type="checkbox"/> Utility Activity	<input type="checkbox"/> Industrial Residential or Commercial Use	<input type="checkbox"/> Land Clearing
<input type="checkbox"/> Motorized Vehicle Damage	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/CHANGES <input checked="" type="checkbox"/> NO CHANGE
EXPLAIN:		
REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. <div style="float: right; text-align: right;"> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No </div>		

Were corrective actions completed for previous inspection(s)? <div style="text-align: right;"> <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A </div>	EXPLAIN:
Are you aware of any plans that may affect property? <div style="text-align: right;"> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No </div>	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <div style="text-align: right;"> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No </div>	EXPLAIN:
Are there changes in land use on adjacent property? <div style="text-align: right;"> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No </div>	EXPLAIN:
Are deed restrictions being adhered to? <div style="text-align: right;"> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No </div>	EXPLAIN:
If new property owner, do they have a written copy of the restrictions? <div style="text-align: right;"> <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A </div>	EXPLAIN:
ATTACHMENTS:	
1) PHOTOGRAPHS WITH CAPTIONS 2) MAP OF PHOTO LOCATIONS AND INSPECTION ROUTE	

DOT SITE INSPECTION REPORT

Image #1: View looking South from Kerr Avenue



Date: 2021/09/16
Time: 12:39:34
Longitude: -77.8878885
Latitude: 34.26023969444444

2021 Stewardship Inspection Map

Spring Branch Bridge

ONEID: 065-008
TIP: B-2059

Division: 3
County: New Hanover



Map Center: 77.888°W 34.2601°N

1 inch equals 19'

0.121846 AC.

● Ground Photo Points 🚁 UAS Photo Points ➡ Inspection Route □ Mitigation Site Boundary