Highway Geophysical Applications From the Rocky Mountains to the Volcano National Park Jacob Sheehan

Collier Geophysics

Jacob@collierconsulting.com



The Problem

We were asked by Colorado DOT to perform a geophysical survey located along I70 west of Eagle and east of Gypsum to investigate the cause of a subsidence or erosional feature

Site Conditions



Site Overview



Results



- The resistivity results show a conductive zone that is centered to the east of the sinkhole feature that is 20 to 30 feet deep at the center
- The shear-wave velocity shows a low velocity zone in the same area as the conductive zone noted in the resistivity
- Combined, this suggests that there is a soft and possibly moist zone that is settling, causing the erosional/collapse feature observed.
 - We concluded that the hillside was slumping in the area of this soft moist zone, creating fissures at the edges of the slump.



NPS Emergency Response Problem Statement: pavement distress and holes/voids along Chain of Craters Road





Home > Geology > Earthquake, Tremor > Rare M5.3 earthquake hits Big Island in Hawaii

Geology Earthquake, Tremor

Rare M5.3 earthquake hits Big Island in Hawaii

June 8, 2017

Introduction

July 27th CFL performed site assessment and based on field observations identified 5 areas displaying pavement distress each needed to be studied by **non-destructive methods** (with minimal impact to traffic!).

- Geophysical methods selected were: 3D Ground Penetrating Radar (GPR) and 3D Seismic Refraction Tomography (SRT).
- Geophysical investigation performed August 28th and 29th, 2017.

Five Study Areas



Site "Issues" - small to very

Google Earth Views -

Hilling Palling

© 2017 Google

Devils Throat!!

Chain of Craters ad

Most Appropriate Approaches:





3D GPR: The 3D RADAR DXG 0908 multichannel, step frequency array was used, with 8 antenna at ~1.5-inch spacing, and a 18-inch 'swath width'; reflector tape and GPS used for positioning. ~20-foot roadway, thus 18 line-passes to get overlap and full coverage (at 1.5"). The GeoScope MkIV was mounted on the cart with 2 12volt batteries.

The 3D RADAR instrument covers radar frequencies between 200 and 3000MHz (3.0GHz); with 4MHz steps. This is the



Most Appropriate Approaches:



3D SRT: 1-meter spaced gimbaled 14Hz geophones, on three 24-ch landstreamer arrays for a 72-receiver 3D array (every SP and receiver position GPS'd)..



Anomalies

- *Anomaly*: Something that deviates from what is standard, normal, or expected.
- Several anomalies were detected different number, size and character at each site.
- CFL categorized the anomalies into three severity classes based on the quality and reliability of the geophysical data, the risk of near-future distress, and public safety.
 - <u>Class 1 (High Severity)</u>: Immediate remediation is a high priority.
 - <u>Class 2 (Medium Severity)</u>: Immediate remediation is beneficial. Site should be visually monitored regularly.
 - Class 3 (Low Severity): Immediate remediation unnecessary. Occasional visual monitoring should be performed.

3D GPR - Video Result (Study Area 2) This .wmv file is a final



3D SRT - Video Result (Study Area 2)



Study Area No. 1



3D GPR RESULTS

3D SRT RESULTS

Study Area No. 2



Conclusions

- Both methods were successful for the ER and detected anomalies.
- GPR identified narrow cracks and voids very shallow beneath the roadway and to **a minimum of 7-8' bgs**.
- SRT identified anomalies interpreted to be voids and/or soft (rock) zones, to depths of ~50 feet. (SRT could <u>not</u> resolve features <5 feet bgs).
- Each method showed promise for fast (ER) data acquisition, fast data processing, and delivery of *useful results within days* of data acquisition.
- CFLHD made mitigation recommendations without additional geotechnical investigation (NO DRILLING!).

Questions?