

Figure 1: Deck panels being prepared for casting. <u>DURING THE POUR</u>, USE "SPOT CHECK" tabs on the truck chute. <u>AFTER THE POUR</u>, USE "SPOT CHECK" tabs to check the integrity of the components cast. <u>Tabs need to turn BRIGHT PURPLE</u>. For a long square pile, every 15 feet or so.



Figure 2: Extracting nitrite-laden bleedwater from the Dead end cylinder in its plastic state.



Figure 3: The cups have 20 mL of water in each one. (*TAP water is no longer used. Distilled water ONLY!) The "dot sandwich" is carefully opened and a dot is picked up with a sharp toothpick. TWO per cup.



Figure 4: Dots being placed into the second cup. (*TAP water is no longer used. Distilled water ONLY!)



Figure 5: Stirring the first cup for 15 seconds.



Figure 6: Inserting the nitrite tab into the stirred solution.



Version: Rev 1, 20070328

NEXT SHEET PLEASE

