14 BEFORE & AFTER COLLISION DIAGRAMS AT ROUNDABOUTS IN NORTH CAROLINA

LOCATION MAP: Roundabout Locations for Preliminary Evaluation

- Oroup 1. Seven Locations with Mainline Speed Limit At or Below 35 mph (Prior Control Stop Sign)
- Group 2. Six Locations with Mainline Speed Limit Above 35 mph (Prior Control Stop Sign)
- Group 3. One Location with Mainline Speed Limit At or Below 35 mph (Prior Control Signal)





GROUP 1

Pullen at Stinson











Park at Tremont











Washington at Glendale











Westview at Buckingham











WT Weaver at University Heights











NC 801 at I-40 EB Ramp











Lake at Mountain











GROUP 2

Styers Ferry at Utility












Williams Road at US 421 SB Ramps











Williams at US 421 NB Ramps











NC 751 at Old Erwin











Fraternity Church at Hope Church









INTERSECTION OF FRATERNITY CH ROAD

AT HOPE CH ROAD

DIAGRAM REVIEWED BY: CLS

SCALE: DATE:

N.C. DEPARTMENT of TRANSPORTATION
DIVISION of HIGHWAYS
TRAFFIC ENGINEERING AND SAFETY
SYSTEMS BRANCH


LOG NUMBER:

NOT TO SCALE


08/29/2007


200706083

LEGEND



Yellowbanks at Haymeadow – No Photos Available





GROUP 3

Ninth at Davidson

