TOTAL BILL OF MATERIAL

BRIDGE	MOBILIZATION	INCIDENTAL MILLING	ASPHALT CONCRETE SURFACE COURSE, TYPE S9.5B	ASPHALT BINDER FOR PLANT MIX	GROOVING BRIDGE FLOORS	CLASS II SURFACE PREPARATION	CLASS III SURFACE PREPARATION	FOAM JOINT SEALS	CLEANING & REPAINTING OF BRIDGE #__	PAINTING CONTAINMENT FOR BRIDGE #__	POLLUTION CONTROL	VOLUMETRIC MIXER	LATEX MODIFIED CONCRETE OVERLAY-VES	CONCRETE DECK REPAIR	BEAM REPAIR	BRIDGE JOINT DEMOLITION	CONCRETE DECK REPAIR FOR EPOXY OVERLAY	EPOXY OVERLAY SYSTEM	HYDRO-DEMOLITION OF BRIDGE DECK	PLACING & FINISHING LATEX MODIFIED CONCRETE-VES	SCARIFYING BRIDGE DECK	BEARING REPLACEMENT	PACOMETER TESTING
	LUMP SUM	SQ. YDS.	TONS	TONS	SQ. FT.	SQ. YDS.	SQ. YDS.	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	C.Y.	CU. FT.	LBS.	SQ. FT.	SQ. FT.	SQ. FT.	SQ.YDS.	SQ.YDS.	SQ. YDS.	EACH	EACH
DUPLIN #30	LUMP SUM	295	25	2	—	—	—	LUMP SUM	—	—	—	—	—	—	—	85	5 *	5,900	—	—	—	—	—
SAMPSON #6	LUMP SUM	535	45	3	2,650	20	2 *	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM *	22	1 *	775	77	—		398	398	398	24	1
TOTAL	LUMP SUM	830	70	5	2,650	20	2 *	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM	LUMP SUM *	22	1 *	775	162	5 *	5,900	398	398	398	24	1

* CLASS III SURFACE PREPARATION, VOLUMETRIC MIXER, CONCRETE DECK REPAIR FOR EPOXY OVELAY, AND CONCRETE FOR DECK REPAIR ARE NOT ANTICIPATED. TOKEN PAY ITEMS ARE INDICATED FOR PRICING PURPOSES, IN CASE UNANTICIPATED REPAIR AREAS ARE ENCOUNTERED.

PROJECT NO. BP-5500G
DUPLIN & SAMPSON COUNTY
BRIDGE NO. 30 & 6

DocuSigned by:
William M. Clarke
1EB20097EAAF437...

5/13/2015

NORTH CAROLINA PROFESSIONAL SEAL 40257 ENGINEER W. MATTHEW CLARKE

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

TOTAL BILL OF MATERIAL

REVISIONS						SHEET NO.
NO.	BY:	DATE:	NO.	BY:	DATE:	S-1
1			3			TOTAL SHEETS
2			4			20

DRAWN BY : S. T. SANDOR DATE : 11/2014
CHECKED BY : W. M. CLARKE DATE : 12/2014

13-MAY-2015 13:21
R:\Structures\FinalDrawings\BP-5500G_SD_BM.dgn
ssandor