UT to West Fork French Broad Inspection Report

Mitigation Site Name	TIP #	WBS #	Inspection Date
UT to West Fork French Broad Site #8	R-0619EI	34634.2.14	10/15/13

County	# Acres
Transylvania	0.70

Monitoring Organization	Inspector	Phone	Email Address
HDR for NCDOT	JT/SE	(919) 785-1118	jessica.tisdale@hdrinc.com

Inspection Activities: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	☐ Yes	☒ No	☐ N/A	Walked trails / roads	☐ Yes	☒ No	☐ N/A
Walked road frontage	☒ Yes	☐ No	☐ N/A	Walked interior	☐ Yes	☒ No	☐ N/A
Monitored from air	☐ Yes	☐ No	☒ N/A				

Condition of boundaries: ☒ Good ☐ Fair ☐ Poor

Comments: The site has a roadside channel adjacent to a very steep slope. The site is currently being mowed along the roadside channel that is within the road shoulder.

Which natural activities / changes have taken place since last monitoring inspection?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ Flooding	☐ Fire	☐ Storm	☐ Earth Movement
☒ Invasive Exotic Vegetation	☐ Insect Infestation	☐ Animal Activity	☐ Other activities/ changes? *(Please Explain)*
			☒ No Change

Explain: Lespedeza noted on site.

UT to West Fork French Broad Inspection Report

Which manmade activities / changes have taken place since last monitoring?
Check all that apply. Note location and extent. Document with photos.

☐ New structure / construction	☐ Dumping or storing	☐ New trails or roads
☒ Timber harvest/ Vegetative cutting	☐ Excavation (dredging, filling, grading, mining)	☐ Alteration to drainage patterns/water quality
☐ Subdivision	☐ Industrial, residential, or commercial use	☐ Land clearing
☐ Motorized vehicle damage	☐ Trespass/vandalism	☐ Agricultural use
☐ Encroachment from adjacent property	☐ Activity on abutting land	☐ Other activities / changes? *(Please Explain)*
		☒ No change

Explain: Mowing is occurring over the channel portion (~550' in length) located within the road shoulder. A solution for this issue may not be available since it is abutting the roadside and must be maintained.

Request follow-up by Program Manager for possible violations. ☐ Yes ☒ No

Were corrective actions completed for previous inspection(s)?	☐ Yes	☐ No ☒ N/A	**Explain:**
Are you aware of any plans that may affect property?	☐ Yes	☒ No	**Explain:**
Are there concerns about boundaries by adjacent property owners?	☐ Yes	☒ No	**Explain:**
Are there changes in land use on adjacent property?	☐ Yes	☒ No	**Explain:**
Are deed restrictions being adhered to?	☒ Yes	☐ No	**Explain:**
If new property owner, do they have a written copy of the restrictions?	☐ Yes	☐ No ☒ N/A	

Attachments:

1) Map of permanent photo plots
2) Photographs with captions
3) map and photographs with captions of relevant natural and Manmade activities
4) Other (specify)

Facing southwest and upstream of channel from southeast boundary

Facing southeast and downstream from western roadside boundary

Facing southwest and upstream, the stream vegetation is not maintained and is further from road edge

UT to West Fork French Broad Site #8

\\cltsmain\gis_data\GIS\Projects\00166_NorthCarolinaDeptofTransportation\021759 7_NCDOTStewardshipMonitoring\#8\map_docs\mxd\working\16_UtToWestForkFrenchBroadSite8.mxd | Last Updated: 10 23 2013