
Build
2040
Dunn
Four Oaks
Smithfield
Selma
Kenly
HARNETT COUNTY
JOHNSTON COUNTY
WILSON COUNTY
Exit 72
Exit 73
Exit 75
Exit 77
Exit 79
Exit 81
Exit 87
Exit 90
Exit 93
Exit 95
Exit 97
Exit 98
Exit 101
Exit 102
Exit 105
Exit 106
Exit 107
Exit 116
Rest Area
Weigh Station
Rest Area
Weigh Station
Rest Area
Weigh Station