## 2_55 Locating Existing EOP

**Question:**

When I entered my pavement information for this area I entered an IEOP and an OOEP.  This seems to be confusing the template in some areas, as it is widening pavement beyond the paved shoulder.

**Answer:**

The reason why the inside pavement is extending past the outside paved shoulders is because you are showing the template the existing edge of pavement where pavement wedging does not occur.



Delete the existing edge of pavement lines when you cannot wedge so the template will display a new pavement section.