UT to Mud Creek Inspection Report

Mitigation Site Name	TIP #	WBS #	Inspection Date
UT to Mud Creek (Bridge No. 335)	B-3856	34634.2.14	8/22/14

County	# Acres
Henderson	0.45

Monitoring Organization	Inspector	Phone	Email Address
HDR for NCDOT	SE / VM	(919) 785-1118	sara.easterly@hdrinc.com

Inspection Activities: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	☒ Yes	☐ No	☐ N/A	Walked trails / roads	☒ Yes ☐ No ☐ N/A
Walked road frontage	☒ Yes	☐ No	☐ N/A	Walked interior	☒ Yes ☐ No ☐ N/A
Monitored from air	☐ Yes	☒ No	☐ N/A		
Condition of boundaries	☒ Good	☐ Fair	☐ Poor		

Comments: There were no trespassing issues observed during the site inspection. The site was very heavily vegetated.

Which natural activities / changes have taken place since last monitoring inspection?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ Flooding	☐ Fire	☐ Storm	☐ Earth Movement
☐ Invasive Exotic Vegetation	☐ Insect Infestation	☐ Animal Activity	☐ Other activities/ changes? *(Please Explain)*
			☒ No Change

Explain:

UT TO MUD CREEK INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?
Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☐ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☐ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? *(Please Explain)*
		☒ NO CHANGE

EXPLAIN:

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES	☒ NO	**EXPLAIN:**
Are there concerns about boundaries by adjacent property owners?	☐ YES	☒ NO	**EXPLAIN:**
Are there changes in land use on adjacent property?	☐ YES	☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES	☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO ☒ N/A	

ATTACHMENTS:

1) MAP
2) PHOTOGRAPHS WITH CAPTIONS

View looking east from the bridge

View looking east

View looking south

View looking west

View looking west

Crab Creek Road

Pearl Lane

UT's to Mud Creek Site #'s 1 and 3
AKA Bridge #335 over Mud Creek on SR 1238

N

0 100 200 400
Feet

D:\GIS\Projects\000166 NorthCarolinaDeptofTransportation\0238152 NCDOTStewardshipMonitor(s)\map docs\mxd\working\UTrib Mud Creek Site.mxd | Last Updated: 09.29.2014

UT's to Mud Creek Sites 1 and 3