

This electronic collection of documents is provided for the convenience of the user and is Not a Certified Document –

The documents contained herein were originally issued and sealed by the individuals whose names and license numbers appear on each page, on the dates appearing with their signature on that page.

This file or an individual page shall not be considered a certified document.





Asphalt Pavement Repair Typical Section

٧

MIII approximately 3" in depth and replace with asphalt surface course, type S 9.5D

Asphalt Repair Detail I-77 Iredell County