SCO ID.# 20-21659-01A

2 T [] MBE

4


2008 ARCHITECT: FACILITIES DESIGN UNIT NCDOT FACILITIES MANAGEMENT 1 SOUTH WILMINGTON STREET COUNTY DEP' WILSON STREET, MA O H INTENANCE TRANSPORT DIVISION TION, ARD, ARBORO, **709 W. JONES** STRUCTURAL ENGINEER: EDGEC HIGHW N AY DIVISION STREET MBE COUNTY, NC 27886

RALEIGH,


NO

27601

RALEIGH, NC ROSS LINDEN ENGINEERS PC 27603



CODE DATA EQUIPMENT SHOP: NOT APPLICABLE SUMMARY



STRUCTURAL DESIGN (PROVIDE ON THE STRUCTURAL SHEETS IF APPLICABLE)	
,	(PROVIDE ON THE ELECT
Factors: Snow (I _S) $\frac{1.0}{1.0}$ Seismic (I _E) $\frac{1.0}{1.0}$	ELECTR
	ELECTRICAL SYSTEM AND EQUIPMENT
Mezzanine 40 psf Floor 100 psf	Method of Compliance: Energy Code
ww Load:15psf	TING TONITION
	Lighting schedule (each fixture type)
Ultimate Wind Speed 116 mph (ASCE-7) Exposure Category C	lamp type required in fixture number of lamps in fixture
] 	number of ballasts in fixture
CATEGORY: A B C D	total wattage per fixture
Seismo Design Farameters: Seismo Design Farameters: I I I II I IV	total exterior wattage specified vs. a
Ss 12.2 %g	
□A □B □C ■D □E □F	Additional Efficiency Package Options (When using the 2018 NCECC; not requir
ural system Bearing Wall Dual w/Special Moment Frame	C406.2 More Efficient HVAC B
☐ Building Frame ☐ Dual w/Intermediate R/C or Special Steel ☐ Moment Frame ☐ Inverted Pendulum	C406.4 Enhanced Digital Lighti
Equiv	C406.6 Dedicated Outdoor Air S
CONTROL: Earthquake Wind	
PACTITIES.	

- DRAWING INDEX


 G1 EQUIPMENT SHOP CODE DATA S
 LOCATION MAPS
- EQUIPMENT SHOP CODE DATA SUMMARY LOCATION MAPS

 LUBE SHOP CODE DATA SUMMARY

EXISTING - NO CHANGE

- G2 S1 S2 A1 A2 LUBE SHOP — CODE DATA SUMMARY
 EQUIPMENT SHOP RENOVATION PLAN
 LUBE SHOP RENOVATION PLAN & DETAILS
 EQUIPMENT SHOP & LUBE SHOP — FOUNDAT
 EQUIPMENT SHOP & LUBE SHOP —
 ROOFING REPLACEMENT PLANS & DETAILS

|--|



	STATE CONSTRU ID.# 20-2165	Repairs to NCDOT Edgecombe County Equipment and Lube Shops NCDOT HIGHWAY DIVISION 4 2008 W. WILSON STREET, TARBORO, NC 27886
9-01A	01A	NCDOT HIGHWAY DIVISION 4 2008 W. WILSON STREET, TARBORO, NC 27886

CODE DATA SUMMARY & LOCATION MAPS

Raleigh Tarboro Raleigh Wilmington of Tarboro	
DATE IS DRAWN CHECKE	Repairs to


SSET NUMBER:
SITE.# BLDG.#


DATE


EQUIPMENT SHOP -




	### BUILDING CODE SUMMARY FOR ALL COMMERCIAL PROJECTS EXCEPT AND 2-FAMILY DWELLINGS AND TOWNHOUSES (Reproduce the following data on the building plans sheet 1 or 2)	
REMONITATION STATE PROFESSION REQUIREMENTS	EXISTING - NO CHANGE	LUBE SHOI
EXTERCY REQUIREMENTS The following data shall be considered minimum and any special arthrite required to recent the energy code shall fan be provided factor being seed factor being seed for the control of the proposed design.	ACCESSIBLE DWELLING UNITS EXISTING - NO CHANGE PROVIDED FROUDED FRO	P: CODE DATA SUMMAR
MECHANICAL SISTEMS EXPLICABLE) MECHANICAL SISTEMS SERVICE SYSTEMS AND EQUIPMENT Thermal Zone Mechanical Systems, Service Systems and Equipment Interder deep conditions winter day bulb. manner of yolb. manner of yolb. Balding soling lead: Balding soling lead: Mechanical Spating Conditioning System Liderspring of white monitor mealways of white Size deepoy. If overland, state reason: Callier Size deepoy. If overland, state reason: List equipment efficiencies: List equipment efficiencies: List equipment efficiencies: Mechanical Spating Conditioning System Mechanical Spating Conditioning System Mechanical Spating Conditioning System List equipment efficiency: Both of the conditioning System List equipment efficiencies: List equipment efficiencies: Mechanical Spating Conditioning System List equipment efficiencies: Mechanical Spating Conditioning System Mechanical Spating Conditioning Syst	DESIGN LOADS: Importance Factors:	
	ELECTRICAL SHEETS IF APPLICABLE) ELECTRICAL SHEETS IF APPLICABLE) ELECTRICAL SHEETS IF APPLICABLE) ELECTRICAL SHEETS IF APPLICABLE) EXISTING - NO CHANGE Method of Compliance: Energy Code Performance Prescriptive ASHRAE 90.1 Performance Prescriptive Lighting schedule (each fixture type) lamp type required in fixture number of lamps in fixture number of ballasts in fixture total interior wattage specified vs. allowed (whole building or space by space) total interior wattage specified vs. allowed (whole building or space by space) Additional Efficiency Package Options (When using the 2018 NCECC, not required for ASHRAE 90.1) C406.2 More Efficient HVAC Equipment Performance C406.3 Reduced Lighting Power Density C406.4 Chilanced Digital Lighting Controls C406.5 Optionat Ondior Air System C406.7 Reduced Energy Use in Service Water Heating	











EQUIPMENT SHOP RENOVATION PLAN


DRAWING TITLE / DISCRIPTION:



CONSULTANT:









2008 W. WILSON STREET, TARBORO, NC 27886

I GENERAL 5. ENGINEER'S SEAL APPLIES TO STRUCTURAL COMPONENTS ONLY AND DOES NOT CERTIFY ARCHITECTURAL LAYOUT OR DIMENSIONAL ACCURACY. 1. DESIGN CODES 8. THE GENERAL CONTRACTOR AND FOUNDATION REPAIR SPECIALIST SHALL VERIFY ALL FIELD CONDITIONS, ELEVATIONS, AND DIMENSIONS PRIOR TO CONSTRUCTION. DO NOT SCALE FROM PLANS. 4. DETAILED SHOP DRAWINGS SHALL BE PROVIDED FOR REVIEW AND APPROVAL PRIOR TO CONSTRUCTION. SHOP DRAWINGS FOR HELICAL ANCHORS SHALL BE SIGNED AND SEALED BY A LICENSED NORTH CAROLINA PROFESSIONAL ENGINEER 6. ROSS LINDEN ENGINEERS PC ASSUMES NO LIABILITY FOR CHANGES OR MODIFICATIONS MADE TO THESE DRAWINGS BY OTHERS, OR FOR CONSTRUCTION METHODS, OR FOR ANY DEVIATION FROM THESE DRAWINGS. . THE GENERAL CONTRACTOR IS RESPONSIBLE FOR COORDINATION AND ISTRIBUTION OF ALL CHANGES IN CONTRACT DOCUMENTS TO ALL UBCONTRACTORS. DESIGN LOADS BUILDING RISK CATEGORY II IMPORTANCE FACTOR 1.0 Ss = 0.122 S1 = 0.062 SITE CLASS D ASCE 7-10 MIN STRUCTURES GROUND SNOW LOAD 15 PSF LIVE LOADS: AISC MANUAL OF STEEL CONSTRUCTION - ALLOWABLE STRESS DESIGN NINTH EDITION ACI BUILDING CODE REQUIREMENTS FOR STRUCTURAL CONCRETE (ACI 318-14) ALTERNATE NO. 4 (SEE ARCH. DWGS.):

IF VOIDS UNDER THE CONCRETE FLOOR SLAB ARE DETECTED,
FOUNDATION REPAIR CONTRACTOR SHALL PROVIDE AN
INJECTION OF FLOWABLE MATERIAL TO FILL THE VOIDS WITH
THE INTENT TO LIMIT THE LIKELIHOOD OF FUTURE
SETTLEMENT AND CRACKING. INJECTION MATERIAL AND
METHOD SHALL BE SUBMITTED FOR REVIEW AND APPROVAL
PRIOR TO CONSTRUCTION. THE COMPRESSIVE STRENGTH OF
THE FLOWABLE MATERIAL SHALL NOT BE LESS THAN 2000 PSI.
ESTIMATED VOLUME OF MATERIAL 52 CUBIC FEET,
CORRESPONDING TO A 1" VOID OVER THE LENGTH OF
THE BUILDING, EXTENDING APPROXIMATELY 10 FT INTO
THE BUILDING. BASE BID:
FOUNDATION REPAIR CONTRACTOR SHALL DRILL EXPLORATORY
HOLES ALONG THE FRONT WALL OR AS HE RECOMMENDS TO
DETERMINE IF VOIDS EXIST BENEATH THE CONCRETE FLOOR SLAB.
THE FOUNDATION REPAIR CONTRACTOR SHALL PREPARE A REPORT
OF THE FINDINGS OF THE EXPLORATION AND PROVIDE
RECOMMENDATIONS. PATCH THE EXPLORATORY HOLES TO MATCH
THE ADJACENT CONCRETE. THE GENERAL CONTRACTOR (GC) SHALL PROVIDE SPECIALIZED SERVICES FOR FOUNDATION REPAIR AS INDICATED ON THE DRAWINGS. THE SPECIALIZED FOUNDATION REPAIR SHALL BE PERFORMED BY A FOUNDATION REPAIR SPECIALIST WITH EXPERIENCE IN THE REPAIR OF DAMAGED BUILDING FOUNDATIONS. 2. MAXIMUM SPACING OF HELICAL ANCHORS SHALL BE APPROXIMATELY 4'-0" BASED ON THE ASSUMED FOOTING DIMENSIONS. 1. PROVIDE FOOTING REINFORCEMENT AT SHADED AREAS.
REINFORCEMENT SHALL CONSIST OF HELICAL ANCHORS
PROVIDED BY FOUNDATION REPAIR SPECIALIST WITH BRACKET
ATTACHMENT TO THE EXISTING CONCRETE WALL FOOTING.
NOTE THAT APRON SLAB IS TO BE REPLACED. SEE DETAILS ON
SHEET S2. THE GC SHALL ALSO BE RESPONSIBLE FOR THE REPAIR OF EXISTING CMU WALLS AS INDICATED ON THE DRAWINGS, AND PAINTING THE REPAIRED AREAS TO MATCH ADJACENT SURFACES. THE GC SHALL BE RESPONSIBLE FOR THE REPAIR OF THE EXISTING PAVEMENT AS INDICATED ON DETAIL 2/S2. 4. DUE TO SETTLEMENT OF WALLS, IT IS POSSIBLE THAT VOIDS EXIST BENEATH THE EXISTING CONCRETE FLOOR SLAB. THE PRESENCE OF VOIDS COULD LEAD TO FURTHER CRACKING OF THE BUILDING STRUCTURE OVER TIME. 3. AFTER INSTALLATION OF ANCHORS, REPAIR EXISTING CRACKS IN CMU WALLS. REPOINT MORTAR JOINTS AND FILL JOINTS SOLID. SEAL ANY CRACKS EXTENDING THROUGH CMU BLOCKS (SEAL ON EACH SIDE OF WALL, WHEREVER CRACKS ARE VISIBLE). PROVIDE A FLEXIBLE SEALANT OR POLYURETHANE FOAM INJECTION. PROVIDE SAMPLE FOR OWNER REVIEW AND APPROVAL PRIOR TO REPAIR. REPAIR NOTES 3. UNLESS OTHERWISE NOTED, ALL REINFORCING STEEL SHALL BE NEW BILLET STEEL, CONFORMING TO ASTM A-615, GRADE 60, DEFORMED. 2. ALL CONCRETE SHALL BE MOIST CURED PER ACI 301 OR CURED WITH AN APPROVED CURING COMPOUND. CONTRACTOR SHALL VERIFY THAT THE CURING COMPOUND IS COMPATIBLE WITH FLOOR COVERING ADHESIVES, COATINGS, OR TOPPINGS TO BE USED. CONCRETE SHALL BE CURED FOR A MINIMUM OF 7 DAYS. 5. ALL BAR SPLICES SHALL BE CLASS "B" TENSION SPLICES PER ACI 318-14, UNLESS OTHERWISE SHOWN. 1. UNLESS OTHERWISE NOTED, ALL CONCRETE SHALL HAVE THE FOLLOWING STRENGTH REQUIREMENTS:
SLAB ON GRADE: 4,000 PSI 28-DAY COMPRESSIVE STRENGTH
ALL OTHER CONCRETE: 3,000 PSI 28-DAY COMPRESSIVE STRENGTH UNLESS OTHERWISE NOTED, ALL DETAILING, FABRICATION, AND PLACING OF EINFORCING STEEL SHALL CONFORM TO THE MANUAL OF STANDARD PRACTICE OR DETAILING REINFORCED CONCRETE STRUCTURES. (ACI 315) — BASED ON THE OBSERVED CRACKING PATTERN IN THE SIDE WALLS, SETTLEMENT APPEARS TO HAVE OCCURRED ALONG FRONT WALL OF BUILDING. THE LOCATION OF GREATEST SETTLEMENT APPEARS TO BE FRONT LEFT CORNER. BRACKET ATTACHMENT AND ANCHOR DEPTH BY FOUNDATION REPAIR SPECIALIST—— TYPICAL WALL +++ - SETTLEMENT OF EXISTING LINTEL ABOVE WALL OPENING OBSERVED AT INTERSECTION WITH EXTERIOR WALL. UBE \triangle REINFORCEMENT S HQP – NOTE: EVIDENCE OF SETTLEMENT NOT OBSERVED AT REAR WALL OF BUILDING **EXISTING GABLE ROOF FRAMING** 8 W 2" CLR. TYP. **APRON SLAB** DETAIL 32'-0" 12'-0" 44'-0" - EXISTING 12" CMU EXTERIOR SIDE WALLS (TYPICAL) 2 4 DETAIL SAW JOINTS AS SOON AS CONCRETE WILL NOT RAVEL UNDER SAW BLADE.
JOINT SPACING ± 15'-0" TP. SLAB CONTROL JOINT 20" LONG SMOOTH DOWELS AT 12" o.c

DRAWING TITLE / DISCRIPTION:





REPAIR NOTES:

1. AFTER FOUNDATION REPAIR WORK HAS BEEN COMPLETED, DEMOLISH EXISTING CONCRETE APRON IN ITS ENTIRETY. CAST NEW CONCRETE APRON TO MATCH THE DIMENSIONS OF THE EXISTING. NEW CONCRETE APRON SHALL BE 6" THICK 4000 PSI REINF W/ #4 @ 16" EW ON VAPOR RETARDER ON 4" COMPACTED GRANULAR BASE. PROVIDE CONTROL JOINTS AND EXPANSION JOINTS AS INDICATED.

2. AFTER FOUNDATION REPAIR WORK HAS BEEN COMPLETED, FILL REMAINING PIER EXCAVATIONS WITH NO. 411 CRUSHED STONE TO WITHIN 4" OF GRADE. FINISH THE FILL WITH MATERIALS TO MATCH ADJACENT.

SEE SPECIFICATION SECTION 01 2300 "ALTERNATES" FOR CONCRETE FLOOR SLAB UNDERPINNING. SEE NOTE #4 ON DRAWINGS S1 AND S2.

4. AFTER FOUNDATION REPAIR WORK HAS BEEN COMPLETED, REPLACE SPALLED OR BROKEN CMU MASONRY TO MATCH ADJACENT MASONRY WHERE INDICATED OR DIRECTED BY ARCHITECT. SEE SPECIFICATIONS FOR ALLOWANCES AND UNIT PRICES RELATED TO MASONRY REPLACEMENT. 3. AFTER FOUNDATION REPAIR WORK HAS BEEN COMPLETED, REPOINT MORTAR JOINTS IN CMU AS INDICATED IN STRUCTURAL AND ARCHITECTURAL DRAWINGS OR AS DIRECTED BY ARCHITECT. SEE SPECIFICATIONS FOR ALLOWANCES AND UNIT PRICES RELATED TO REPOINTING.

Sheel No.	DATE ISSUED: 9/3/2021 DRAWN BY: MDG CHECKED BY: MDG	REVISIONS NO. DATE	ASSET NUMBER: _CO.# SITE.# BLDG.# 88 = 02 = 00	STATE CONSTRUCTION ID.# 20-21659-01A	Repairs to NCDOT Edgecombe County Equipment and Lube Shops NCDOT HIGHWAY DIVISION 4 2008 W. WILSON STREET, TARBORO, NC 27886



