June 14, 2023

STRUCTURE BULLETIN

NCDOT Construction Unit

Website email

Current Issues: Wide Flange Girder Diaphragms



Diaphragms stiffen the end of the deck slab between the girders. As shown above, the diaphragm typically extends from the girder web to the adjacent girder web. This poses several potential problems during construction.

First, it is difficult to get the space directly under the flange and over the deep part of the diaphragm completely filled with concrete (pictures at right). You should always make sure the contractor thoroughly vibrates this area to reduce the chance of voids.

Second, it is almost impossible to get concrete between the top flange and the form in the shallow part of the diaphragm as you can see below. Even if you could, it is unreinforced and would likely spall out over time.





- 1. Current Issues: Wide Flange Girder Diaphragms
- 2. Spec Question Can fiber be used in concrete slope protection?

Diaphragm Details:

Void between the diaphragm and top flange



Page 1 of 2

As a result, the best practice is to block out the area between the top flange and the shallow part of the diaphragm pour. There are several possible ways to accomplish this, but if urethane foam is used make sure to trim it neatly and clean it up thoroughly when the forms are removed.



Spec Question: Can a contractor use fibers in the concrete instead of wire mesh for slope protection?

Answer: No. This has been tried before and resulted in an unacceptable amount of cracking in the slope protection. Section 462 of the Standard Specifications states that wire reinforcement is required. As a side note, the wire is supposed to be in the middle of the slope protection thickness. Did you ever wonder what that hook on the back of a concrete rake was for? That's to pull the wire up to the proper height if the concrete pushes it down. Check out the video.



Area Construction Engineers:

| Div | Contact | Phone |
|-------|--------------------|--------------|
| 1&2 | Randy Hall | 252-402-9957 |
| 3&4 | David Candela | 910-524-4931 |
| 5 | Troy Brooks | 336-972-4627 |
| 6&8 | <u>John Partin</u> | 336-847-1226 |
| 7 | Marcus Kiser | 336-972-3412 |
| 9 | Vickie Davis | 704-202-0945 |
| 10 | Christopher Fine | 336-225-4266 |
| 11&12 | Mark Biggerstaff | 828-803-9954 |
| 13&14 | Aaron Powell | 828-417-2629 |
| | | |

Videos:

Inspection training videos can be found on the <u>Construction</u> <u>Unit YouTube playlist</u>.

Training:

The 2023 Construction Inspector Training classes are in the bag. Thank you all for your participation. Videos of the classes are currently being edited and will be available on YouTube soon. This <u>Link</u> will take you to the location of the PDF versions of the presentations.

Structure Bulletins

are archived on the <u>Construction Unit</u> website under <u>Construction Resources.</u>

Structure Bulletin Signup:

Please scan the QR code below to sign up for the distribution lists to avoid missing any valuable information.



If you have a topic you would like to see in a future edition of the Structure Bulletin, please email us at <u>aearwood@ncdot.gov or</u> <u>aegriffith@ncdot.gov</u>

Page 2 of 2