

NORTH CAROLINA

Department of Transportation



















2022 AGC/NCDOT Workshop Don Parker, PE, Kenneth Thornewell, PE, PTOE Work Zone Traffic Control


Today's Topics

- Work Zone Crash Data
- National WZ Safety Awareness Week
- WZ Installer Certification
- Pattern Masking Update
- WZ Safety Reviews
- Material and Equipment Storage
- Law Enforcement


Work Zone Crash Data

- 2020 5,942 work zone crashes resulting in 43 fatalities
 - 40% higher than 2019 and 45% above than the 5-year average
- 2021 6,217 work zone crashes resulting in 28 fatalities
 - 32% lower than 2020 and 10% below the 5-year average
 - Data through 12/31/2021, however number aren't considered final until late spring to account for delayed fatalities and updated investigations

5 Year Trend of Work Zone Crashes



5 Year Trend for WZ Fatalities



UPDATE: Three construction workers on crew truction worker dead, three others injured after repairing guard rail on I-40 killed Thursday g hit by drunk driver near Concord Mills Mall

morning

DONNA SWICEGOOD Feb 27, 2020 Updated Feb 29, 2020 50







DONNA SWICEGOOD

The investigation into a crash that killed three construction workers o Interstate 40 early today is still ongoing.

Master Trooper Jeffrey Swagger of the North Carolina Highway Patrol said names of the three will be released once next-of-kin notifications have been completed.

He said the three workers were part of a crew that was repairing a guard ra I-40 west near the 157-mile maker.

Swagger said there was a truck in the right lane, which was closed, and the workers were in the road ahead of that truck. A second truck was in front o three workers, he said.





earch

Jear

ENTERTAINMENT SPORTS WEATHER STATION CHIM

Candler man killed in late night crash while working along I-26 in Buncombe County

BY KRISTY KEPLEY-STEWARD, LAUREN BRIGMAN | MONDAY, DECEMBER 6TH 2021



Dec. 6, 2021 - Police say on Sunday, Dec. 5, 2021, at approximately 11:46 p.m. a vehicle driven by Caleb Luke Grindstaff, 30, of Bakersville, crashed on Future I-26 West between the exits for UNC Asheville (25) and Elk Mountain Road (24). Road construction worker Dario Caravajal Dominguez, 50, of Candler, died at the scene. (Photo credit: WLOS Staff)

TRENDING



Former Asheville police officer sues police chief, bdistrict attorney, City of Asheville



Another Rutherford County detainee hospitalized after apparent overdose



Friday Weather Update:
Major snowstorm makes
its way toward Western



Union members at Evergreen Packaging undergo safety training



National Work Zone Safety Awareness Week April 11-15, 2022





























Wear Orange Day April 13th


Show support for those killed in work zones as well as their families.

Post images to social media #Orange4Safety #GoOrangeDay



Welcome Center I-95 SB in Northampton County just south of the Virgina Line

April 5-7, 2022 Press Conference TBA



Work Zone Installer Certification


- Effective July 1, 2021
- At least one member of every crew responsible for setup, installation, and removal of traffic control devices within any highway right of way shall be trained and certified as a Work Zone Installer.
- The certified Work Zone Installer should serve as crew leader and shall be on site and directing the installation and removal of temporary traffic control.

Work Zone Installer Certification

- The Work Zone Installer does not replace or change the requirements of a Work Zone Supervisor as described in article 1101-13 of the Standard Specifications.
- A supervisor can replace an installer during a TTC installation, but an Installer cannot be a replacement for the Supervisor


Updated Work Zone Safety Website

- Latest Memo is at the top of the page.
- Historical memos are to the right
- Added Installer course guidelines
- NEW in 2021: Work
 Zone Education
 Verification App
 (WZ-EVA)



Work Zone Education Verification App (WZ-EVA)

- Online database for Residents and Inspectors to verify WZ training credentials
- Records are uploaded by training firms



Work Zone Education Verification App (WZ-EVA)

- July 1, 2022 Deadline to have all training records uploaded to WZ-EVA
- Public-facing site does not allow for printing wallet cards
 - Only individuals approved to upload records can print wallet cards.
 - Trainers need to provide wallet cards to students.
- NCDOT does not provide hard-copy wallet cards. We will issue digital wallet cards only to individuals seeking 1-year SC/VA reciprocity.

Work Zone Education Verification App (WZ-EVA)

- Each certification has a unique identifying number.
- Re-certifications will get a unique number
- System will generate flagger/installer/supervisor wallet cards



Name Trainee Name

NCDOT Certification Type: Flagger

Training: 5/30/2017-Expires: 7/1/2021

🏴 Unique ID Number

Card holder completed approved training program developed by ITRE, training conducted by Tim Baughman of ITRE.

Pattern Masking Update





Pattern Masking Update

- Conceals existing pavement markings eliminating grind marks and ghost lines
- Failures/Success
- Poor Dry Time
 - Durability
 - Increases Risk to Contractor
- Put a pause on including in new contracts
- Opportunities in lower profile, bid build projects

Pattern Masking Update

- Current Efforts
 - Realistic Dry Time Requirements
 - Timing of the Application
- A lot must go right for a successful application, little or no room for error
- What if we installed the pattern masking after the traffic shift?
 - Line removal to paint to complete the initial traffic shift
 - Mask in successive work periods
- New Manufacturer

	CORRECT IMMEDIATELY DOES NOT MEET STANDARDS			MEETS STANDARDS EXCEEDS STANDARDS		EXCEEDS STANDARDS	
	1 2					3	4
CATEGORIES				SCORE		NOTES	
	TEMPORARY SIGNING- Portable/Stationary/Barricade Mount (Signs, Sign Supports)		Α	CONDITION	3		
1			В	PLACEMENT	3		
			С	SPACING	3		
2	TEMPORARY SIGNING- Digital Speed Limit (Speed/Flashing Beacons/Brightness)		Α	CONDITION			
			В	PLACEMENT			
			С	SPACING			
3	CHANNELIZATION DEVICES (Cones, Drums, Skinny Drums, Barricades)		Α	CONES	3	Drums throughout project have past useful life & need replacing. Type III barricades need to be installed across roadway to indicate roadway/exit is closed, SB 52 exit 117.	
			В	DRUMS	2		
			С	SKINNY DRUM	3		
			D	BARRICADES	2		
4	TEMPORARY PAVEMENT MARKINGS (Paint, Tape, Raised Markers)		Α	CONDITION	2	Markings throughout project are missing and/or need refreshing.	
			В	PLACEMENT	3		
			С	REMOVAL or MASKING	3		
_	BARRIER- Concrete, Water-filled, Other		Α	CONDITION	2	See Comments. Many runs of PCB not shown on TMP or installed	
3	(Delineators?) (Anchored?)			PLACEMENT	2	in violation of TMP and RFP.	
6	CRASH CUSHIONS		Α	CONDITION	1	CC on NB 52 @ exit 118 struck and needs to be repaired	
			В	PLACEMENT	2	immediately. CC at same location not on approved TMP.	
7	IMPACT ATTENUATORS (Truck /Trailer Mtd)		Α	CONDITION			
			В	PLACEMENT			
8	PORTABLE CHANGEABLE MESSAGE SIGNS (PCMS)		Α	CONDITION	3		
			В	PLACEMENT	2	See Comments.	
			С	MESSAGE	3		
	I		Α	CONDITION			

Common Items

Damaged Crash Cushions - URGENT





Common Items

Damaged/Incorrect Guardrail - URGENT



Common Items

 Barrier Reflectors – Should be <u>TOP</u> mounted per <u>RSD 1261.02</u>



Common Items

 Conflicting Marker Castings – Per 1250-3(c): "Lens removal in lieu of total casting removal is not an acceptable practice for snowplowable

markers"





Common Items

Non-Compliant Sidewalk Closures



Common Items

Material and Equipment Inside the Clear Zone



Common Items

Equipment Inside the Clear Zone



Changes to Material and Equipment Storage Specification

Current Specification:

1101-8 MATERIAL AND EQUIPMENT STORAGE

When work is not in progress, keep all personnel, equipment, machinery, tools, construction debris, materials and supplies at least 40 feet away from active travel lanes. When vehicles, equipment and materials are protected by concrete barrier or guardrail, they shall be offset at least 5 feet from the barrier or guardrail.

Changes to Material and Equipment Storage Specification

Revised Specification (Effective July 2021):

When work is not in progress, keep all personnel, equipment, machinery, tools, construction debris, materials and supplies away from active travel lanes that meets Table 1101-1.

TABLE 1101-1								
MATERIAL AND EQUIPMENT STORAGE FROM ACTIVE TRAVEL LANES								
Posted Speed Limit (mph)	Distance (ft)							
40 or less	≥ 18							
45-50	≥ 28							
55	≥ 32							
60 or higher	≥ 40							

When vehicles, equipment and materials are protected by concrete barrier or guardrail, they shall be offset at least 5 feet from the barrier or guardrail.

Changes to Law Enforcement Provision





- Currently require Marked LE Vehicles
- Not Always Available
- Specification will be revised to allow unmarked vehicles
 - Must have Blue Light
 - Officer in Uniform
- Marked is better than Unmarked

Questions? / Comments

- Don Parker, PE, State Work Zone Engineer
- Phone: (919) 814 4935, <u>Email</u>: daparker@ncdot.gov

