| MITIGATION SITE NAME Brock's Mill Pond | | TIP # R-2301WM | | WBS # N/A | | INSPECTION DATE 8/10/2015 |
|--|----------------------|-------------------|----------------------------------|----------------|--|---|
| COUNTY Jones | # ACRE 110.5 | | | | ONEID 052-004 | |
| MONITORING ORGANIZATION Kimley-Horn | INSPECTOR JRH/BAR | | PHONE (919)678-4155 | | EMAIL ADDRESS Jason.Hartshorn@Kimley- Horn.com | |
| Inspection Activities: Complete all that apply. Describe location of visited areas if <100%. | | | | | | |
| Walked boundaries ☐ YES ☐ NO ☐ N/A | | | Walked trails / roads YES NO N/A | | | |
| Walked road frontage \(\sum Y | ES NO | N/A | Walked interior YES NO NO N/A | | | |
| Monitored from air ☐ YES ☐ NO ☐ N/A | | | | | | |
| Condition of boundaries Condition of boundaries | | | | | | |
| COMMENTS: No trespass issues were observed. The majority of the site is not easily accessible due to thick, forested wetland areas, but the upper mill pond portion of the site is readily accessible but appears to be in great condition. Site looks to be in great condition, however no NCDOT signage was visible along the boundary. | | | | | | |
| WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION? Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos. | | | | | | |
| FLOODING | | | STO | RM | □E | ARTH MOVEMENT |
| ☐INVASIVE EXOTIC ☐INSECT VEGETATION INFESTATIO | | | | IMAL TIVITY | | OTHER ACTIVITIES/ CHANGES? (Please Explain) |
| EXPLAIN: No changes were ob | served | | | | | NO CHANGE |
| EM LAIN. NO changes were of | osei veu. | | | | | |

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos. NEW STRUCTURE / DUMPING OR STORING NEW TRAILS OR ROADS CONSTRUCTION **EXCAVATION** TIMBER HARVEST/ ALTERATION TO DRAINAGE (DREDGING, FILLING, GRADING, VEGETATIVE CUTTING PATTERNS/WATER QUALITY MINING) INDUSTRIAL, RESIDENTIAL, OR SUBDIVISION LAND CLEARING COMMERCIAL USE MOTORIZED VEHICLE AGRICULTURAL USE TRESPASS/VANDALISM DAMAGE OTHER ACTIVITIES / CHANGES? ENCROACHMENT FROM ACTIVITY ON (Please Explain) ADJACENT PROPERTY ABUTTING LAND No Change **EXPLAIN:** A property owner along the southeast bank of the mill pond has installed a satellite dish on the waterward side of a bald cypress tree. The satellite dish appears to be within NCDOT property, and is clearly visible from public access points and within the pond. REQUEST FOLLOW-UP BY PROGRAM MANAGER □YES \boxtimes No FOR POSSIBLE VIOLATIONS. Were corrective actions No **EXPLAIN:** completed for previous YES N/A inspection(s)? Are you aware of any plans **EXPLAIN:** \boxtimes No YES that may affect property? Are there concerns about **EXPLAIN:** boundaries by adjacent YES \boxtimes No property owners? Are there changes in land use **EXPLAIN:** \boxtimes No on adjacent property? YES Are deed restrictions being No **EXPLAIN: ⊠**YES adhered to? If new property owner, do \square No they have a written copy of YES the restrictions? N/A **ATTACHMENTS:** 1) SITE PHOTOGRAPHS WITH CAPTIONS 2) SITE MAP



Photo 1 – View of Brock's Mill Pond.



Photo 2 – View of the old mill.




Photo 3 – Looking south at the dam from Brock's Mill.



Photo 4 – Looking west at the dam and Brock's Mill.



Photo 5 – The eastern limits of the site where Crooked Run crosses under NC 58.



Division 2, NCDOT October 2015