MITIGATION SITE NAME Thoroughfare Bay Bridge		TIP # B-1098		ONEID 016-005		INSPECTION DATE August 31, 2021	
COUNTY Carteret	# ACRES 3.35						
MONITORING ORGANIZATION NCDOT	INSPECTOR Randy Griffin		(919)-	PHONE (919)-707- 6121		EMAIL ADDRESS rgriffin@ncdot.gov	
INSPECTION ACTIVITIES: Complete all that apply.							
Walked boundaries No			Walked trails / roads No				
Walked road frontage Yes			Walked interior No				
Monitored from air	No						
Condition of boundaries			Good				
COMMENTS: Site looks good.	Signs are vi	isible ard	ound perime	eter.			
Which natural activities / changes have taken place since last monitoring inspection? Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.							
☐ Flooding	□ Fire			Storm		Earth Movement	
☐ Invasive or Exotic ☐ Insect Infestatio		ation	☐ Animal Activity		Chan Comr	Other Activity or ges (Add ments) No Change	
EXPLAIN: N/A							
LAPLAIN. IV/A							

#### WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos. □ New Structure ☐ Dumping or Storage □ New Trails or Roads Construction ☐ Timber Harvest or ☐ Excavation (Dredging, Filling, ☐ Alteration To Drainage Patterns or VegetativeCutting Grading, Mining) Water Quality ☐ Industrial Residential or ☐ Utility Activity □ Land Clearing Commercial Use □ Motorized Vehicle ☐ TRESSPASS/VANDALISM ☐ AGRICULTURAL USE Damage ☐ OTHER ACTIVITIES/CHANGES ☐ ENCROACHMENT FROM ☐ ACTIVITY ON ABUTTING LAND ✓ No Change **ADJACENT PROPERTY EXPLAIN:** N/A REQUEST FOLLOW-UP BY PROGRAM MANAGER ☐ Yes ✓ No FOR POSSIBLE VIOLATIONS. Were corrective actions □ No **EXPLAIN:** completed for previous □ Yes inspection(s)? ☑ N/A Are you aware of any **EXPLAIN:** plans that may affect ☐ Yes ✓ No property? Are there concerns **EXPLAIN:** about boundaries by ☐ Yes ✓ No adjacent property owners? Are there changes in **EXPLAIN:** land use on adjacent □ Yes √ No. property? Are deed restrictions **EXPLAIN:**  ✓ Yes being adhered to? □ No If new property owner, □ No do they have a written □ Yes ☑ N/A copy of the restrictions? **ATTACHMENTS:** 1) PHOTOGRAPHS WITH CAPTIONS 2) MAP OF PHOTO LOCATIONS AND INSPECTION ROUTE



Time: 10:16:25 Longitude: -76.36707 Latitude: 34.92172

**DOT Site Inspection Program**Page 3 of 7

Image #2: Southside boundary of site



Date: 2021/08/31 Time: 10:16:45 Longitude: -76.3671 Latitude: 34.9224

Image #3: Site boundary and sign



Date: 2021/08/31 Time: 10:17:02 Longitude: -76.36626 Latitude: 34.92339

**DOT Site Inspection Program**Page 5 of 7

Image #4: Northside of site



Date: 2021/08/31 Time: 10:20:41 Longitude: -76.36106 Latitude: 34.93005

Image #5: Northside of site



Date: 2021/08/31 Time: 10:21:17 Longitude: -76.36114 Latitude: 34.93009

**DOT Site Inspection Program**Page 7 of 7

# 2021 Stewardship Inspection Map

# Thorofare Bay Bridge

ONEID: 016-005 Division: 2

County: Carteret TIP: B-1098



Map Center: 76.3643°W 34.9258°N

1 inch equals 404'

3.352148 AC.