

MEMORANDUM TO: Project Engineers Project Design Engineers FROM: W. J. Rogers, P. E. State Bridge Design Engineer DATE: May 27, 1997 SUBJECT: DESIGN MANUAL ERRATA

Following is a list of errata contained in the Design Manual revision dated 2/6/97. Please make the appropriate corrections in your copy of the manual.

## English Manual Errata

pg. 14 - 3-1-1 future bituminous wearing surface should be 20 # / sf not 1 # / sf

pg. 32 - Keep Fig. 5-2, Const. Limits for Culvert

pg. 51 - 7-2-1 (a), 2, (e) Use # 4 dowels @ 1' -1" centers not 1' -3" centers. Fig. 7-3 is correct.

pg. 89 - Keep Fig. 7-1 sheet 1 of 10

- pg. 158 45" girder w = 583 # / ft
- pg. 253 Delete 1st 6 lines of text on page

## Metric Manual Errata

- pg. 16 3-1-12 Tension for cored slabs should be 0.25 (f' ci
- pg. 32 Keep Fig. 5-2, Const. Limits for Culvert
- pg. 46A Delete note regarding sheet piling from (mm), (2)
- pg. 51 (2), (e) 380 mm centers should be 340 mm centers
- pg. 197 8-3-1, (a) Single row cap width should be 1.120 m for 508 mm piles
- pg. 252 Delete last 3 lines on page


## WJR/RGW/ap

cc: T. V. Rountree, P. E.

N. M. Salmon, P. E.





Back to Structures Main Page Last Updated: 8/11/98 by:Steven Rackley E-mail Structure Design



DATE: REVISED 3-10-89

89





DATE: 3-1-84

32