

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
3/1/2023	ADD	Econolite Control Products	ECOVILEDSCIP	AENCORE	Discontinued by Econolite
1/13/2023	CHG	Intelight	INTCONT2070LX2009TEES	2070LC	Not available
4/29/2022	CHG	Murray/Siemens	SLGESMMBDC200ARLO	LG0606L1200R	Not NEC 2020 Compliant
4/29/2022	CHG	Murray/Siemens	SMRESMMBDC100AROSO	JC002CS	Not NEC 2020 Compliant
4/29/2022	CHG	Milbank Mfg.Co.	MILESMMBDC200APTDBR	U5136-O w/ K5745-DB cover	Not NEC 2020 Compliant
4/29/2022	CHG	Midwest Elec. Products Inc.	MIDESMMBDC100AROSOMEGA	R102EN	Not NEC 2020 Compliant
2/28/2022	ATD	ENCOM Wireless Data Solutions	ENCWC900MhzBERSM	CommPak BB900S	Discontinued by MFG.
5/24/2019	ATD	Intuicom, Inc.	INTWC5.8GHzBEDRI23GA	BBSA5858-NC	Remove because of poor performance
5/24/2019	ATD	Intuicom, Inc.	INTWC2.4GHzBEDRI20GA	BBSA2424-NC	Remove because of poor performance
5/24/2019	ATD	Intuicom, Inc.	INTWCSSR900MhzSE	EB-6 Plus	This product is no longer made.
5/24/2019	ATD	Intuicom, Inc.	INTWCBBR4.9GHzSM	BroadBand Solutions 4.9GHz	Remove because of poor performance
5/24/2019	ATD	Intuicom, Inc.	INTWCSSR900MhzSE	EB-6 Plus	This product is no longer made.
5/22/2019	ATD	Intuicom, Inc.	INTWC5.8GHzBEDRI23GA	BBSA5858-NC	Remove because of poor performance
5/22/2019	ATD	Intuicom, Inc.	INTWC2.4GHzBEDRI20GA	BBSA2424-NC	Remove because of poor performance
5/22/2019	ATD	Intuicom, Inc.	INTWCBBR4.9GHzSM	BroadBand Solutions 4.9GHz	Remove because of poor performance
3/22/2019	ADD	GridSmart/Aldis	GRVILEDSCF	GS-3-CAM	Part number changed
3/22/2019	ADD	GridSmart/Aldis	GRVILEDSC	GS-3-TRC	Part number changed
3/11/2019	CHG	Safetran Brand by Econolite	SAFCONT2070LX2009TEES	2070C1H5500	Part number changed
3/11/2019	CHG	Safetran Brand by Econolite	SAFCONT2070E2009TEES	2070E6E5550	Part number changed
2/21/2019	CHG	EDI	EDICMM2018	2018ECL-NC v0155	This product design was updated
2/21/2019	CHG	EDI	EDICMM2018WEP	2018ECLip-NC v0155	This product design was updated
2/8/2019	DMS	Daktronics, Inc.	DAKDMSFMFALED27X6030VA	VF-2420-27X60-66-A	This product design was updated
2/8/2019	DMS	Daktronics, Inc.	DAKDMSG3FMWILED27X9030VA	VF-2020-27X90-66-A GIII	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S35L3Z1	50054-B908-Y3	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S35L2Z2Z3Z5	50054-B907-Y3	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S35L1Z4	50054-B897-Y3	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S35H3Z1	50054-B908-Y5	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S35H2Z2Z3Z5	50054-B907-Y5	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S35H1Z4	50054-B897-Y5	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S30L3Z1	50054-B908-Y2	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S30L2Z2Z3Z5	50054-B907-Y2	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S30L1Z4	50054-B897-Y2	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S30H3Z1	50054-B908-Y4	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S30H2Z2Z3Z5	50054-B907-Y4	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S30H1Z4	50054-B897-Y4	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S26L3Z1	50054-B908-Y1	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S26L2Z2Z3Z5	50054-B907-Y1	This product design was updated
11/27/2018	MPG	Union Metal Industries Corp	UMCMSPC#S26L1Z4	50054-B897-Y1	This product design was updated
9/11/2018	ADD	Econolite Control Products	ECOVILEDSC-2	AISVCRZOOMU0S	This product is no longer made.
9/11/2018	ADD	Econolite Control Products	ECOVILEDSC-2	AISVCRZOOMU0S	This product is no longer made.
9/10/2018	ATD	ENCOM Wireless Data Solutions	ENCWCSSR900MhzSM-2	Model# 5200S Spread Spectrum Radio	This product is no longer made.
9/10/2018	ATD	ENCOM Wireless Data Solutions	ENCWCSSR900MhzSM	Model# 5100S Spread Spectrum Radio	This product is no longer made.
9/10/2018	ATD	ENCOM Wireless Data Solutions	ENCWCSSR900MhzSE	Commpak - IP	This product is no longer made.
9/10/2018	ATD	ENCOM Wireless Data Solutions	ENCWCSSR900MhzSM-2	Model# 5200S Spread Spectrum Radio	This product is no longer made.
9/10/2018	ATD	ENCOM Wireless Data Solutions	ENCWCSSR900MhzSM	Model# 5100S Spread Spectrum Radio	This product is no longer made.
9/10/2018	ATD	ENCOM Wireless Data Solutions	ENCWCSSR900MhzSE	Commpak - IP	This product is no longer made.
2/22/2018	SHG	ELTEC Electrotechnics Corporation	ELTRRFB	ELTEC RRFB--DC	FHWA ruling
2/22/2018	SHG	JSF Technologies	JSFRRFB-2	AB-9407	FHWA ruling
2/22/2018	SHG	JSF Technologies	JSFRRFB-1	AB-9207	FHWA ruling
2/22/2018	SHG	Carmanah Technologies, Inc.	CARRRFB	R920-69020	FHWA ruling
2/22/2018	SHG	TAPCO	TAPRRFB	2180-RRFBXLS-Y	FHWA ruling
2/22/2018	SHG	ELTEC Electrotechnics Corporation	ELTRRFB	ELTEC RRFB--DC	FHWA ruling
2/22/2018	SHG	JSF Technologies	JSFRRFB-2	AB-9407	FHWA ruling
2/22/2018	SHG	JSF Technologies	JSFRRFB-1	AB-9207	FHWA ruling
2/22/2018	SHG	Carmanah Technologies, Inc.	CARRRFB	R920-69020	FHWA ruling
2/22/2018	SHG	TAPCO	TAPRRFB	2180-RRFBXLS-Y	FHWA ruling
10/4/2017	SHG	Polara	POLPPBADAYMPO	BDLM/BDPM-Y	Can not be used without panel to latch LED
10/4/2017	SHG	Polara	POLPPBADAY	BDL3-Y w/ APBC-Y	Can not be used without panel to latch LED

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
10/4/2017	SHG	Polara	POLPPBADAYMPO-2	BDL3-Y w/ BDPM3-Y	Can not be used without panel to latch LED
10/4/2017	SHG	Pelco Products, Inc.	PELPPBADAY-2	SE-2120-P29	Can not be used without panel to latch LED
10/4/2017	SHG	Campbell Company	CAMPPBADAYMPO-3	4 EVR 10 w/ 3" SR	Can not be used without panel to latch LED
8/17/2017	CHG	Trimble Navigation Limited	TRIGPSA	Acutime GG	This product is no longer made.
1/12/2017	ADD	Iteris, Inc.	ITEVILEDS	VAN-CAM-R23	This product is no longer made.
12/6/2016	ADD	Traficon	TRAVILEDSRVMU	View Comm - 10-4500	Name change to FLIR
12/6/2016	ADD	Traficon	TRAVILEDSPU2CICRT	VIP 3.2 - 10-4300	Name change to FLIR
12/6/2016	ADD	Traficon	TRAVILEDSPU1CICRT	VIP 3.1 - 10-4350	Name change to FLIR
12/6/2016	ADD	Traficon	TRAVILEDS4CEMCRT	VIP 4 I/O Expansion Card - 10-4400	Name change to FLIR
12/6/2016	ADD	Traficon	TRAVILEDS2CEMCRT	VIP 2 I/O Expansion Card - 10-4450	Name change to FLIR
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSOPSMPPMPA	M25214	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSOPSMPPCEWPA	M25212	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSOPSMESA	B2111B-12	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSMHULATSASSHY2W	B2501-12	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSMHWSBAMISSHY1W	B2408NC1-12	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSMHPTSAY	B2201NC-12	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSMHPTS2WAY	B2202NC-12	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHVL0D8	A 852233-14	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHVL0D12	A 701861-14	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV5S12CPYERYGS	SG1T5H1C11YYY50	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV5S12CAERYGS	SG1T5H2C11YYY50-26	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV4S12VPYERYGS	SS104A1C11YYY40	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV4S12VAYERYGS	SG104A2C11YYY40-18	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV3S8VPYERYGS	SG130A1C11YYY30-00	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGBSH5S12	BPA505HNF01 BPA505HNF01	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGBSH4S12	BPA504ANF BPA504ANL	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGBSH3S8	BPA530ANF BPA530ANL	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGBSH3S12	BPA503ANF BPA503ANL	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV3S12VPYERYGS	SG103A1C11YYY30-00	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV3S12VAYERYGS	SG103A2C11YYY30-00	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV1S12PYE	SG101A1C11YYY10	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHV1S12AYE	SG101A2C11YYY10	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHP1S16AYETV	SG7S220C3YBY w/ M20466(serrated ring)	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHP1S16AYECMRTV	SG7RZ20C3YBY w/ BK15608P001(clam shell)	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHP1S16AYECMLTV	SG7LZ20C3YBY w/ BK15608P001(clam shell)	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSHP1S12AYE	SG301B2C31YYY10	Name change to MoboTrex
2/3/2016	CHG	Eagle Traffic/ Brown Traffic	BROCCT170332AWORMB	CAB541-4001-529 (JBS2332TNC05 Rev. 1)	Name change to MoboTrex
2/3/2016	CHG	Eagle Traffic/ Brown Traffic	BROCCT170336SWORMB	JBS2336TNC03 (Rev. 8)	Name change to MoboTrex
2/3/2016	CHG	Eagle Traffic/ Brown Traffic	BROCCT170332AAUXFWORMB	JBS2332TNC04 (Rev. 6)	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGBSHPVFABSP5S12	BPB505HNF01	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGBSHPVFABSP4S12	BPB504ANF	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGBSHPVFABSP3S12	BPB503ANF	Name change to MoboTrex
2/3/2016	SHG	Eagle Traffic/ Brown Traffic	EAGSMHPBAB3/4HDG18PPBT1	UA-246	Name change to MoboTrex
1/26/2016	PLH	United Wood Treating Company Inc.	UNIPW40FTCL3	Class 3 - 40'	Name change to McFarland Cascade.
8/5/2015	ADD	Sensys Networks, Inc.	SENWVMVDTFSM	VSN240-T	This product is no longer made.
8/5/2015	ADD	Sensys Networks, Inc.	SENWVMVDR	RP240-B	This product is no longer made.
5/5/2015	CHG	Safetran Brand by Econolite	SAFCCT170336SPMRAI	STCABS#1943-PM (S70233 Rev. A)	No longer needed
5/5/2015	CHG	Safetran Brand by Econolite	SAFCCT170336BMRAI	STCABS#1943-BM (S70233 Rev. A)	No longer needed
5/5/2015	CHG	Safetran Brand by Econolite	SAFCCT170332ARAI	STCABS#1941 (S70232 Rev. A)	No longer needed
5/5/2015	CHG	Safetran Brand by Econolite	SAFCCT170332AAUXFRAI	STCABS#1942 (S70232 Rev. A)	No longer needed
5/5/2015	LED	Leotek	LEOSHVYLED8BETLC	TSL-08Y-LX-IL3-A1	No longer listed on ETL
5/5/2015	LED	Leotek	LEOSHVYLED12ETLC	TSL-12Y-LX-IL3-A1-C	No longer listed on ETL
5/5/2015	LED	Leotek	LEOSHVYLED8BETLC	TSL-08R-LX-IL3-A1	No longer listed on ETL
5/5/2015	LED	Leotek	LEOSHVYLED8BETLC	TSL-08G-LX-IL3-A1	No longer listed on ETL
5/5/2015	LED	Leotek	LEOSHVYLED12ETLC	TSL-12R-LX-IL3-A1	No longer listed on ETL
5/5/2015	LED	Leotek	LEOSHVYLED12ETLC	TSL-12G-LX-IL3-A1	No longer listed on ETL
5/5/2015	LED	GE Lighting Solutions	GELSHVYLED8BETLC	DR4-YTFB-17A-YX-21	No longer listed on ETL
5/5/2015	LED	GE Lighting Solutions	GELSHVYLED12ETLC	DR6-YTFB-17A-YX1-21	No longer listed on ETL
5/5/2015	LED	GE Lighting Solutions	GELSHVYLED8BETLC	DR4-RTFB-17A-21	No longer listed on ETL
5/5/2015	LED	GE Lighting Solutions	GELSHVYLED12ETLC	DR6-RTFB-17A-21	No longer listed on ETL
5/5/2015	LED	GE Lighting Solutions	GELSHVYLED8BETLC	DR4-GTFB-17A-21	No longer listed on ETL
5/5/2015	LED	GE Lighting Solutions	GELSHVYLED12ETLC	DR6-GTFB-17A-21	No longer listed on ETL

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
5/5/2015	LED	Dialight Corporation	DIASHVYLEDA12IL0ETLC-2	431-3335-901XODNC	No longer listed on ETL
5/5/2015	LED	Dialight Corporation	DIASHVYLEDA12IL0ETLC-1	431-3335-901XOD	No longer listed on ETL
3/19/2015	LED	Leotek	LEOSHVGLDEDB12ETLC-2	TSL-12G-LX-IL6-A1-P2	Due to the loss of indication and defective failed state impedance function
3/19/2015	LED	Leotek	LEOSHVLEDB12ETLC-2	TSL-12Y-LX-IL6-A1-P2	Due to the loss of indication and defective failed state impedance function
3/19/2015	LED	Leotek	LEOSHVRLDEDB12ETLC-2	TSL-12R-LX-IL6-A1-P2	Due to the loss of indication and defective failed state impedance function
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD96F	ETH1JKT-12-ES-096-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD72F	ETH1JKT-12-ES-072-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD60F	ETH1JKT-12-ES-060-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD48F	ETH1JKT-12-ES-048-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD36F	ETH1JKT-12-ES-036-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD30F	ETH1JKT-12-ES-030-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD24F	ETH1JKT-12-ES-024-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD18F	ETH1JKT-12-ES-018-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD144F	ETH1JKT-12-ES-144-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD12F	ETH1JKT-12-ES-012-ES	remove "ES" from part and replaced with "E3"
2/12/2015	FOP	Draka Communication	DRAFOCABSMLTAD06F	ETH1JKT-12-ES-006-ES	remove "ES" from part and replaced with "E3"
12/17/2014	CHG	EDI	EDICMM2018	2018ECL-NC Rev. 153	Firmware update
10/13/2014	FOP	Corning Cable Systems	CORFOIC24FCM	C-MIC-024	This product is no longer made.
3/13/2014	ADD	Iteris, Inc.	ITEVILEDSRVMU	VAN-VIEWER	This product is no longer made or supported.
3/13/2014	ADD	Iteris, Inc.	ITEVILEDSPU6CI	VAN-AR61	This product is no longer made or supported.
3/13/2014	ADD	Iteris, Inc.	ITEVILEDSPU5CI	VAN-AR51	This product is no longer made or supported.
3/13/2014	ADD	Iteris, Inc.	ITEVILEDSPU4CI	VAN-AR41	This product is no longer made or supported.
2/21/2014	CHG	Safetran Brand by Econolite	SAFCCT170332A	STCABS#1841 (S70232 Rev. A)	Requested to be removed by John Madden. Only sells the w/o red monitor board type.
2/21/2014	CHG	Safetran Brand by Econolite	SAFCCT170336S	STCABS#1631 (S70233 Rev. A)	Requested to be removed by John Madden. Only sells the w/o red monitor board type.
2/21/2014	CHG	Safetran Brand by Econolite	SAFCCT170332AAUXF	STCABS#1630 (S70232 Rev. A)	Requested to be removed by John Madden. Only sells the w/o red monitor board type.
12/12/2013	ADD	Naztec, Inc.	NAZOSDMSFPD	Accuwave 150 LX	This product is no longer made.
12/12/2013	ADD	Electronic Integrated Systems Inc.	EISOSDWMFSFAD	RTMS X3	This product is no longer made.
11/7/2013	ATD	Polyphaser Corp.	POLWCLA	DSXL-BFN	Obsoleted
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSOPSMPPMPA	M25214	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSOPSMPPCEWPA	M25212	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSOPSMESA	B2111B-12	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSMHULATSASSHY2W	B2501-12	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSMHWSBAMISSHY1W	B2408NC1-12	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSMHPTSAY	B2201NC-12	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSMHPTS2WAY	B2202NC-12	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHVL0D8	A 852233-14	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHVL0D12	A 701861-14	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV5S12CPYERYGS	SG1T5H1C11YYY50	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV5S12CAYERYGS	SG1T5H2C11YYY50-26	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV4S12VPYERYGS	SS104A1C11YYY40	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV4S12VAYERYGS	SG104A2C11YYY40-18	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV3S8VPYERYGS	SG130A1C11YYY30-00	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGBSH5S12	BPA505HNF01 BPA505HNF01	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGBSH4S12	BPA504ANF BPA504ANL	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGBSH3S8	BPA530ANF BPA530ANL	Name change to Brown Traffic

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGBSH3S12	BPA503ANF BPA503ANL	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV3S12VPYERYGS	SG103A1C11YYY30-00	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV3S12VAYERYGS	SG103A2C11YYY30-00	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV1S12PYE	SG101A1C11YYY10	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHV1S12AYE	SG101A2C11YYY10	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHP1S16AYETV	SG7S220C3YBY w/ M20466(serrated ring)	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHP1S16AYECMRTV	SG7R220C3YBY w/ BK15608P001(clam shell)	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHP1S16AYECLTV	SG7L220C3YBY w/ BK15608P001(clam shell)	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSHP1S12AYE	SG301B2C31YYY10	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGBSPVVFABSP5S12	BPB505HNF01	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGBSPVVFABSP4S12	BPB504ANF	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGBSPVVFABSP3S12	BPB503ANF	Name change to Brown Traffic
10/30/2013	SHG	Eagle Traffic/Siemens ITS	EAGSMHPBAB3/4HDG18PPBT1	UA-246	Name change to Brown Traffic
7/15/2013	PLH	Allied Bolt Inc.	ALLCG3BH DG5/8	5056	Remove span size restriction
4/11/2013	LED	GE Lumination	GELSHVLEDA12I0ETLC	DR6-GTAAN-17A-21	Changed Part #
4/11/2013	LED	GE Lumination	GELSHVRELEDA12I0ETLC	DR6-RTAAN-17A-21	Changed Part #
4/11/2013	LED	GE Lumination	GELSHVLEDA12I0ETLC	DR6-YTAAN-17A-YX-21	Changed Part #
4/11/2013	ADD	Econolite Control Products	ECOVILEDSPU8CICRTTS2	AMINIHUBTS2	This product is no longer made.
4/11/2013	ADD	Econolite Control Products	ECOVILEDSPU8CICRT170	AMINIHUB2	This product is no longer made.
4/11/2013	ADD	Econolite Control Products	ECOVILEDSC	ASOLOPROUS	This product is no longer made.
10/4/2012	SHG	Pelco Products, Inc.	PELSMHPBSA	PB-5335	Changed Part # to reference alum door
10/4/2012	SHG	Pelco Products, Inc.	PELSMHPBSA	PB-5335	Changed Part # to reference alum door
10/3/2012	SHG	Pelco Products, Inc.	PELSMHSWSBAMISSSHY1W	SP-1006-NC	Changed Part # to reference yellow paint
10/3/2012	SHG	Pelco Products, Inc.	PELSMH5SSHSWMAY	SP-1007-NC	Changed Part # to reference yellow paint
10/3/2012	SHG	Pelco Products, Inc.	PELSMHSWSBAMISSSHY1W	SP-1006-NC	Changed Part # to reference yellow paint
10/3/2012	SHG	Pelco Products, Inc.	PELSMH8ASSSHY	SP-1008-NC	Changed Part # to reference yellow paint
10/3/2012	SHG	Pelco Products, Inc.	PELSMH5SSHSWMAY	SP-1007-NC	Changed Part # to reference yellow paint
3/26/2012	SHG	Guardway	GUASPPBR103ERA	R10-3ER	Removed at request of Milton Dean
3/26/2012	SHG	Guardway	GUASPPBR103ELA	R10-3EL	Removed at request of Milton Dean
3/26/2012	SHG	Guardway	GUASPPBR103ERA	R10-3ER	Removed at request of Milton Dean
3/26/2012	SHG	Guardway	GUASPPBR103ELA	R10-3EL	Removed at request of Milton Dean
3/26/2012	SHG	Guardway	GUASPPBR103BRA	R10-3BR	Removed at request of Milton Dean
3/26/2012	SHG	Guardway	GUASPPBR103BLA	R10-3BL	Removed at request of Milton Dean
3/26/2012	SHG	Korman Signs, Inc.	KORSPPBR103ERA	R10-3ER	Removed at request of Milton Dean
3/26/2012	SHG	Korman Signs, Inc.	KORSPPBR103ELA	R10-3EL	Removed at request of Milton Dean
3/26/2012	SHG	Korman Signs, Inc.	KORSPPBR103ERA	R10-3ER	Removed at request of Milton Dean
3/26/2012	SHG	Korman Signs, Inc.	KORSPPBR103ELA	R10-3EL	Removed at request of Milton Dean
3/26/2012	SHG	Korman Signs, Inc.	KORSPPBR103BRA	R10-3BR	Removed at request of Milton Dean
3/26/2012	SHG	Korman Signs, Inc.	KORSPPBR103BLA	R10-3BL	Removed at request of Milton Dean
3/20/2012	DMS	Daktronics, Inc.	DAKDMFMWILED27X9030VA	VF-2020-27X90-66-X	Removed at request of the manufacturer
3/20/2012	DMS	Daktronics, Inc.	DAKDMFMWILED27X9015VA	VF-2000-27X90-66-X	Removed at request of the manufacturer
3/20/2012	DMS	Daktronics, Inc.	DAKDMSC	VCF-3000	Removed at request of the manufacturer
3/20/2012	DMS	Daktronics, Inc.	DAKDMFMWILED27X9030VA	VF-2020-27X90-66-X	Removed at request of the manufacturer
3/20/2012	DMS	Daktronics, Inc.	DAKDMFMWILED27X9015VA	VF-2000-27X90-66-X	Removed at request of the manufacturer

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
3/20/2012	DMS	Daktronics, Inc.	DAKDMSC	VCF-3000	Removed at request of the manufacturer
6/14/2011	ADD	Sensys Networks, Inc.	SENWMVDEC2C170	EX-170	Changed Part #
6/14/2011	ADD	Sensys Networks, Inc.	SENWMVDCCC2C170	CC-170	Changed Part #
3/17/2011	ATD	Pelco Products, Inc.	PELWCAMHK	AB-0604-84	Not longer used
3/4/2011	CHG	Carolina Precast Concrete, Inc.	CPCPPC170C78X30X8	78" x 30" x 8"	Acquired by Hanson Pipe and Precast
2/1/2011	ADD	Wavetronix	WAVOSDWRFFAD	SS200	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHV5S12CAYERYGS	MTSTA-5X-2-GA with MMP1213Y visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHV4S12VAYERYGS	MTSTA-4X-2-GA with MMP1213Y visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHV3S8VAYERYGS	MTSEA-3X-XX with MMP813 visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHV3S12VAYERYGS	MTSTA-3X-2-GA with MMP1213Y visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHV2S12AYE	MTSTA-2X-2-GA with MMP1213Y visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHV1S8AYE	MTSEA-1X-XX with MMP813 visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHV1S12AYE	MTSTA-1X-2-XX with MMP1213Y visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHP1S16AYETV	PSXX6S-A with M28026 visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHP1S16AYECMTV	PSXX6S-A with P9050-C-Y with M28026 visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHOP3S12VYRYG	MTS HP-3022 with MMP1213 visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHOP3S12CY	MTS HP-5622 with MMP1213 visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHOP1S12VYGA	MTS HP-1522 with MMP1213 visor	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCSHOP1S12VYG	MTS HP-1222 with MMP1213 visor	Changed Part #
11/17/2010	CHG	McCain Traffic Supply	MCCCT170332AAUXF	9500-332-NCDOT w/ AUXFILE	Changed Part #
11/17/2010	CHG	McCain Traffic Supply	MCCCT170332A	9500-332-NCDOT	Changed Part #
11/17/2010	CHG	McCain Traffic Supply	MCCCONT2070L1BCPU2002TEES	M33160	Changed Part #
11/17/2010	CHG	McCain Traffic Supply	MCCCT170336S	9500-336NCDOT	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCBSH5S12	TA565BSN3 TA565BSL3	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCBSH4S12	TA405BSN1 TA405BSL1	Changed Part #
11/17/2010	SHG	McCain Traffic Supply	MCCBSH3S12-2	TA305BSN1 TA305BSL1 TA305BSN4 TA305BSL4	Changed Part #
11/17/2010	CHG	Safetran Traffic Systems Inc.	SAFCONT170	Type 170E	
11/17/2010	CHG	Safetran Traffic Systems Inc.	SAFCT170336SWOB	STCABS#1128 (288974D336-00 Rev. D)	Changed Part #
11/17/2010	CHG	Safetran Traffic Systems Inc.	SAFCT170336SWB	STCABS#1088 (288974D336-00 Rev. D)	Changed Part #
11/17/2010	CHG	Safetran Traffic Systems Inc.	SAFCT170332AAUXF	STCABS#1082 (288973D332-00 Rev. E)	Changed Part #
11/17/2010	CHG	Safetran Traffic Systems Inc.	SAFCT170332A	STCABS#1061 (288973D332-00 Rev. E)	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSOPMESA	B2111B	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSMHULATSASSHY2W	B2501	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSMHWSBAMISSHY1W	B2408NC1	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSMHSHWOBMIY	A32132	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSMHWCMIY	A31926	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSMHPTSAY	B2201NC	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSMHPTS2WAY	B2202NC	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSMHBAMISSHY	A32000	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSHV5S12CAYERYGS	SS1T5H2C31YYY50	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSHV4S12VAYERYGS	SS104A2C31YYY40	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSHV3S8VPYERYGS	SG130A1C11YYY30	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSHV3S12VPYERYGS	SG103A1C11YYY30	Changed Part #
11/17/2010	SHG	Eagle Traffic/Siemens ITS	EAGSHV3S12VAYERYGS	SG103A2C31YYY30	Changed Part #
10/11/2010	CHG	Cutler-Hammer	CUTESMMBDC125ARLO	CHRS	Product not marked "Suitable for Use as Service Equipment".
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDSPCU4CH	2140-M4SPM	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDSPCU3CH	2140-M3SPM	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDSPCU2CH	2140-M2SPM	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDSPCU1CH	2140-M1SPM	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDS	OSPsoft 2.1	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDOE-2	3060, 2060 Cable	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDOE-1	2060, 2060-CODE, 2060 Cable	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDODSWM	2091-S	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDOD1D1CH	2090-SD	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDEPS	ECMPS 2.0	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDDC-2	M914(4 Cond)	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDDC-1	M913(3 Cond)	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	ATD	Tomar Electronics, Inc.	TOMEVIPDCR	1881	Removed due to the injunction against Tomar preventing them from manufacturing a device that includes vehicle identification detection.
8/6/2010	SHG	Eagle Traffic/Siemens ITS	EAGSHV5S8CAYGRYGYAGA	SPS150H2131YYY (Left arrow) SPS150K2131YYY (Right arrow)	This product is no longer made.
8/6/2010	SHG	Eagle Traffic/Siemens ITS	EAGSHV3S8VAYERYGS	SG130A2C31YYY30	This product is no longer made.
8/6/2010	SHG	Eagle Traffic/Siemens ITS	EAGB5H5S8	BPA550HNF01 BPA550HNL01	Product no longer needed.
8/6/2010	SHG	Eagle Traffic/Siemens ITS	EAGB5H4S8	BPA540ANF BPA540ANL	Product no longer needed.
11/3/2009	ADD	Sensys Networks, Inc.	SENWMMVDAPSI	900-240-015-6-000	Changed Part #
11/3/2009	ADD	Sensys Networks, Inc.	SENWMMVDEC2C170	900-240-025-0-000	Changed Part #
11/3/2009	ADD	Sensys Networks, Inc.	SENWMMVDCCC2C170	900-240-015-6-000	Changed Part #
11/3/2009	ADD	Sensys Networks, Inc.	SENWMMVDT5FM	900-240-101-0-000	Changed Part #
11/3/2009	ADD	Sensys Networks, Inc.	SENWMMVDR	900-240-020-0-000	Changed Part #
8/6/2009	LED	GE Lumination	GELSHVYLEDB12	DR6-YTFB-17A-YX1-21	This product is no longer made.
8/6/2009	LED	GE Lumination	GELSHVYLEDB12	DR6-YTFB-17A-YX-21	This product is no longer made.
1/7/2009	LED	U.S. Traffic Corp.	USTSHVLEDA12	LEDT-12YA-001	This product is no longer made.
1/7/2009	LED	U.S. Traffic Corp.	USTSHVRLEDA12	LEDT-12RA-001	This product is no longer made.
1/7/2009	LED	U.S. Traffic Corp.	USTSHVGLLEDA12	LEDT-12GA-001	This product is no longer made.
1/7/2009	LED	Precision Solar Controls Inc.	PRESHVLEDA12	2405	This product is no longer made.
1/7/2009	LED	Precision Solar Controls Inc.	PRESHVRLEDA12	2404	This product is no longer made.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
1/7/2009	LED	Precision Solar Controls Inc.	PRESHVGLEDA12	2406	This product is no longer made.
1/7/2009	CHG	Midwest Electric Products, Inc.	MIDESMMBDC100APTDBR	R101CP6	Changed to new part #. R101CP6HP
10/13/2008	CHG	Safetran Traffic Systems Inc.	SAFCCT170336S	288544D336-00 Rev.D	Changed to new part #.
10/13/2008	CHG	Safetran Traffic Systems Inc.	SAFCCT170332A	288543D332-00 Rev.D	Changed to new part #.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD96F	A-LT-96-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD72F	A-LT-72-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD60F	A-LT-60-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD48F	A-LT-48-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD36F	A-LT-36-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD30F	A-LT-30-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD24F	A-LT-24-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD18F	A-LT-18-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD144F	A-LT-144-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD12F	A-LT-12-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
8/4/2008	FOP	Alcatel Wire & Cable	ALCFOCABSMLTAD06F	A-LT-06-NA-S1	Alcatel Wire & Cable was brought out by Draka Communication and the Part #'s changed.
7/7/2008	SHG	Pelco Products, Inc.	PELSMHPBAB3/4HDG18	PB-5306	Standard Drawings require a different bolt for pedestals.
7/7/2008	SHG	Component Product Inc.	COMSMHPBAB3/4HDG18	CPI-AB-18	Standard Drawings require a different bolt for pedestals.
7/3/2008	SHG	Pelco Products, Inc.	PELSMHBAMISSHY	SP-1005-NC	This product was replaced by a newer product.
7/3/2008	SHG	Pelco Products, Inc.	PELSMH5SSHSWMAY	SP-1004-NC	This product was replaced by a newer product.
7/3/2008	SHG	Pelco Products, Inc.	PELSMHSWSBAMISSHY1W	SP-1003-NC	This product was replaced by a newer product.
4/16/2008	CHG	Eagle Traffic/Siemens ITS	EAGCONT2070L1BCPU	AAZ14068P019 w/ AAD13982P001 com module w/o software	This product was removed due to communication problems within Closed Loop Systems.
4/16/2008	CHG	Eagle Traffic/Siemens ITS	EAGCONT2070L1BCPU2002TEES	AAZ14068P026 w/ AAD13982P001 com module w/o software	This product was removed due to communication problems within Closed Loop Systems.
10/17/2007	SHG	Pelco Products, Inc.	PELSMH5SSHSWMAY	SP-5512-P29 painted yellow	Balance Adjuster fails to maintain Signal Head angle and did not have stainless steel hardware.
10/17/2007	SHG	Pelco Products, Inc.	PELSMH5SSHSWMAY	SP-5512-P29 painted yellow	Balance Adjuster fails to maintain Signal Head angle and did not have stainless steel hardware.
10/15/2007	GHG	Joslyn Manufacturing Co.	JOSGRCB10F5/8	J8340	This product is no longer made.
10/15/2007	GHG	Blackburn/Thomas & Betts	BLAGRCB10F5/8	6260	This product is no longer made.
10/15/2007	GHG	Joslyn Manufacturing Co.	JOSGRCB10F5/8	J8340	This product is no longer made.
10/15/2007	GHG	Blackburn/Thomas & Betts	BLAGRCB10F5/8	6260	This product is no longer made.
9/10/2007	LED	Dialight Corporation	DIASHVLEDB12	433-3230-001X	This product is no longer being sold by RAI.
9/10/2007	LED	Dialight Corporation	DIASHVRLEDB12	433-1210-003X	This product is no longer being sold by RAI.
9/10/2007	LED	Dialight Corporation	DIASHVLEDB12	433-2220-001X	This product is no longer being sold by RAI.
9/5/2007	LED	Cooper Lighting	COOSHVLEDA12	CLA12YAS	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVLEDA12	CLA12RAS	This product is no longer made.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
9/5/2007	LED	Cooper Lighting	COOSHVGLEDA12	CLA12GAS	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVYLEDB8	CLB8YAS (EV)	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVYLEDB12	CLB12YAS (EV)	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVYLEDA12	CLA12YAS	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVRLLEDB8	CLB8RAS (EV)	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVRLLEDB12	CLB12RAS (EV)	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVRLLEDA12	CLA12RAS	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVGLEDB8	CLB8GAS (EV)	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVGLEDB12	CLB12GAS (EV)	This product is no longer made.
9/5/2007	LED	Cooper Lighting	COOSHVGLEDA12	CLA12GAS	This product is no longer made.
9/5/2007	LED	Dialight Corporation	DIASHVYLEDB8	433-3130-001X	Product number changed
9/5/2007	LED	Dialight Corporation	DIASHVRLLEDB8	433-1110-003X	Product number changed
9/5/2007	LED	Dialight Corporation	DIASHVGLEDB8	433-2120-001X	Product number changed
9/5/2007	LED	Dialight Corporation	DIASHVGLEDB12-1	433-2220-001XL	Product number changed
9/5/2007	LED	Dialight Corporation	DIASHVRLLEDB12-1	433-1210-003XL	Product number changed
9/5/2007	LED	Dialight Corporation	DIASHVYLEDB12-1	433-3230-001XL	Product number changed
7/26/2007	CHG	Safetran Traffic Systems Inc.	SAFCONT2070L1BCPU	2070L	This company was brought out by Econolite and this product was discontinued.
7/26/2007	CHG	Safetran Traffic Systems Inc.	SAFCONT2070L1BCPU	2070L	This company was brought out by Econolite and this product was discontinued.
7/18/2007	LSG	Chemrex Inc.	CHELS2PPES	Gold Label Flex	
7/18/2007	LSG	Chemrex Inc.	CHELS2PPES	Gold Label Flex	
7/3/2007	SHG	Pelco Products, Inc.	PELSMHSWSBAMISSHY1W	SP-1001-NC painted yellow	Balance Adjuster fails to maintain Signal Head angle and did not have stainless steel hardware.
7/3/2007	SHG	Pelco Products, Inc.	PELSMHSWCMIY	SE-0338-P29 painted yellow	Did not have stainless steel hardware.
7/3/2007	SHG	Pelco Products, Inc.	PELSMHBAMISSHY	SE-3219-P29 painted yellow	Balance Adjuster fails to maintain Signal Head angle.
7/3/2007	LED	TraStar Inc.	TRASHVRLLEDB12	JXC-300CAR	Did not submit test from a qualified test lab.
7/3/2007	SHG	Pelco Products, Inc.	PELSMHSWSBAMISSHY1W	SP-1001-NC painted yellow	Balance Adjuster fails to maintain Signal Head angle and did not have stainless steel hardware.
7/3/2007	SHG	Pelco Products, Inc.	PELSMHSWCMIY	SE-0338-P29 painted yellow	Did not have stainless steel hardware.
7/3/2007	SHG	Pelco Products, Inc.	PELSMHBAMISSHY	SE-3219-P29 painted yellow	Balance Adjuster fails to maintain Signal Head angle.
7/3/2007	CHG	Naztec, Inc.	NAZCONT2070L1BCPU	2070L1B2A3B4A7A	Upgraded to 2002 TEES Controller.
7/3/2007	CHG	Econolite Control Products	ECOCONT2070L1BCPU	2070L12130	Upgraded to 2002 TEES Controller.
7/3/2007	CHG	Eagle Traffic/Siemens ITS	EAGCONT2070L1BCPU	AAZ14068P019 w/ AAD13982P001 com module w/o software	Upgraded to 2002 TEES Controller.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC20-1STRC16-7	680028	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC20-1STRC16-4	680027	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWLI4P18AWGIMSAS50-2	680030	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWLI2P18AWGIMSAS50-2	680029	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWLI119STR14-2C50-2PE	675074	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWLI4P18AWGIMSAS50-2	680030	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWLI2P18AWGIMSAS50-2	680029	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC20-1STRC16-7	680028	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC20-1STRC16-4	680027	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC20-1STRC14-7	14 AWG-7/C Stranded 20-1	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC20-1STRC14-4	14 AWG-4/C Stranded 20-1	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC19-1STRC14-7	14 AWG-7/C Stranded 19-1	This product is no longer made.
5/9/2007	WIR	Nexans Energy USA Inc.	NEXWSC19-1STRC14-4	14 AWG-4/C Stranded 19-1	This product is no longer made.
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTIOAD12F	012RWF-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTA18F	018RW4-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTALST8F	08RS4-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTALST6F	06RS4-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTALST24F	024RS4-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTALST12F	012RS4-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTA8F	08RW4-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTA6F	06RW4-14101-A20	
8/2/2006	FOP	Corning Cable Systems	CORFOCABSMLTA24F	024RW4-14101-A20	
12/20/2005	LED	Dialight Corporation	DIASHVYLEDA12	430-3335-001	
12/20/2005	LED	Dialight Corporation	DIASHVRLLEDA12	430-1315-001	
12/20/2005	LED	Dialight Corporation	DIASHVGLEDA12	430-2375-001	
7/7/2005	LED	Cooper Lighting	COOSHVYLEDB12-2	CLBC12YA	
7/7/2005	LED	Cooper Lighting	COOSHVGLEDB12-2	CLBC12GA	
7/7/2005	LED	Cooper Lighting	COOSHVGLEDB8-2	CLBC8GA	



Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
7/7/2005	LED	Cooper Lighting	COOSHVYLED8-2	CLBC8YA	
7/7/2005	LED	Cooper Lighting	COOSHVRELB8-2	CLBC8RA	
7/7/2005	LED	Cooper Lighting	COOSHVGLEDA12-2	CLAC12GA	
7/7/2005	LED	Cooper Lighting	COOSHVYLEDA12-2	CLAC12YA	
7/7/2005	LED	Cooper Lighting	COOSHVRELEDA12-2	CLAC12RA	
7/7/2005	LED	Cooper Lighting	COOSHVRELEDB12-2	CLBC12RA	
9/27/2004	FOP	Corning Cable Systems	CORFOTK	T595	
8/10/2004	LED	Dialight Corporation	DIASHVGLEDB12-1	434-2270-008	This product is being removed because of reliability issues.
8/10/2004	LED	Dialight Corporation	DIASHVRELEDB12-2	434-1210-008	This product is being removed because of reliability issues.
8/10/2004	LED	Dialight Corporation	DIASHVYLEDB12	434-3230-008	This product is being removed because of reliability issues.
7/7/2004	SHG	Peek Traffic, Inc.	PEESHV3S12VAYGRYG	HSC83B300G if used without Peek backplate HSF83B300G may be used if Peek backplate is attached to signal head	New Part #'s added.
6/10/2004	FOP	Sterlite Optical Technologies	STEFOCABSMLTAD12FDC	12-S3-DL	
6/10/2004	FOP	Sterlite Optical Technologies	STEFOCABSMLTAD06FDC	06-S3-DL	
6/10/2004	FOP	Sterlite Optical Technologies	STEFOCABSMLTAD60F	60-S3-A1-01	
6/10/2004	FOP	Sterlite Optical Technologies	STEFOCABSMLTAD24F	24-S3-A1-01	
6/10/2004	FOP	Sterlite Optical Technologies	STEFOCABSMLTAD12F	12-S3-A1-01	
6/10/2004	FOP	Sterlite Optical Technologies	STEFOCABSMLTAD06F	06-S3-A1-01	
1/12/2004	SHG	Pelco Products, Inc.	PELSMHMAMAASBBMB	AB-0105	This product is being removed because of reliability issues.
1/12/2004	SHG	Pelco Products, Inc.	PELSMHMAMAABCMB2W	AB-0110	This product is being removed because of reliability issues.
1/12/2004	SHG	Pelco Products, Inc.	PELSMHMAMAABBMB5S	AB-0109	This product is being removed because of reliability issues.
1/12/2004	SHG	Pelco Products, Inc.	PELSMHMAMAABBMB	AB-0116	This product is being removed because of reliability issues.
1/12/2004	LED	Dialight Corporation	DIASHVGLEDB8	430-2175-001	Does not meet the July 2002 LED specification.
11/6/2003	WIR	Rome Cable Corp.	ROMWLIT27STR18-4CPE	81930	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWLI4P18AWGIMSAS0-2	84391	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWLI2P18AWGIMSAS0-2	84390	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWSC20-1STRC16-7	84393	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWSC20-1STRC16-4	84392	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWSC20-1STRC14-7	80098	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWSC20-1STRC14-4	80766	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWSC19-1STRC14-7	80097	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWSC19-1STRC14-4	80598	Rome Cable is no longer in business.
11/6/2003	WIR	Rome Cable Corp.	ROMWLIT119STR14-2C50-2PE	80749	Rome Cable is no longer in business.
10/9/2003	LED	Precision Solar Controls Inc.	PRESHVYLEDA12	1652	Replaced by Part# 2405.
10/9/2003	LED	Precision Solar Controls Inc.	PRESHVRELEDA12	1650	Replaced by Part# 2404.
10/9/2003	LED	Precision Solar Controls Inc.	PRESHVGLEDA12	1654	Replaced by Part# 2406.
7/2/2003	FOP	Force, Inc.	FORFOM232SMSTRCNHLC	2769XC-SCST	This product is being removed because of several quality and reliability issues.
7/2/2003	LED	Dialight Corporation	DIASHVRELEDB8-1	433-1110-801	Does not meet the July 2002 LED specification.
5/8/2003	SHG	U.S. Traffic Corp.	USTSHV5S12CAYERYGS	ST5T220T000 w/ 5SS0261FYL visor	LEDs do not fit the signal head door properly.
5/8/2003	SHG	U.S. Traffic Corp.	USTSHV4S12VAYERYGS	ST4T220C000 w/ 4SS0261FYL visor	LEDs do not fit the signal head door properly.
5/8/2003	SHG	U.S. Traffic Corp.	USTSHV3S12VAYERYGS	ST3T220C000 w/ 3SS0261FYL visor	LEDs do not fit the signal head door properly.
5/8/2003	SHG	U.S. Traffic Corp.	USTSHV1S12AYE	ST1F220T000 w/ 1SS0261FYL visor	LEDs do not fit the signal head door properly.
3/17/2003	PLH	Joslyn Manufacturing Co.	JOSWSCHDG5/8-2	J6822	This washer should be a 3" x 3" curved square washer.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
3/17/2003	PLH	Joslyn Manufacturing Co.	JOSWSCHDG5/8-1	J6821	This washer should be a 3" x 3" curved square washer.
3/17/2003	CHG	Anchor/Thomas & Betts	ANCESMMB100ARLO	URS1004-HPM-CPL	This product is no longer available.
12/12/2002	FOP	Corning Cable Systems	CORFOPSMSCZC6F	005802R5131006F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOPSMSCZC3F	005802R5131003F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOPSMSCZC1F	005802R5131001F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOPSMSCZC10F	005802R5131010F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOJDSMSCZC6F	585802R5131006F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOJDSMSCZC3F	585802R5131003F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOJDSMSCZC1F	585802R5131001F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOJDSMSCZC10F	585802R5131010F	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOCOUP6FSMSC	CCH-CP06-38	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOCOUP12FSMSC	CCH-CP12-38	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/12/2002	FOP	Corning Cable Systems	CORFOCONSMHCSC	95-200-08	Requested to be remove from QPL by TMSS. They no longer use SC connectors.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMST/PC6F	002501K3141006F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMST/PC3F	002501K3141003F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMST/PC1F	002501K5141001F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMST/PC10F	002501K3141010F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMSC/PC6F	003901K5141006F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMSC/PC3F	003901K5141003F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMSC/PC1F	003901K3141001F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOPMMSC/PC10F	003901K3141010F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOJDMST6F	252502K5141006F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOJDMST3F	252502K5141003F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOJDMST1F	252502K5141001F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
12/10/2002	FOP	Corning Cable Systems	CORFOJDM MST10F	252502K5141010F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOJDM MSC6F	393902K5141006F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOJDM MSC3F	393902K5141003F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOJDM MSC1F	393902K5141001F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOJDM MSC10F	393902K5141010F	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCOUP6FMMST	CCH-CP06-15T	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCOUP6FMMSC	CCH-CP06-39	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCOUP12FMMST	CCH-CP12-15T	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCOUP12FMMSC	CCH-CP12-39	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCONMMUVSC	95-100-06R	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCONMMUVCST	95-100-01R	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCONMMTRJU	92-201-97-P	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCONMMHCSC	95-100-08	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTALST8F	08K54-14130-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTALST6F	06K54-14130-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTALST24F	024K54-14130-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTALST12F	012K54-14130-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTA8F	08KW4-14101-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTA6F	06KW4-14101-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTA24F	024KW4-14101-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
12/10/2002	FOP	Corning Cable Systems	CORFOCABMMLTA12F	012KW4-14101-A20	Requested to be remove from QPL by TMSS. They no longer use Multimode cable.
9/20/2002	WIR	Alcatel Wire & Cable	ALCWSC20-1STRC14-7	14 AWG-7/C Stranded 20-1	Changed name to Nexans.
9/20/2002	WIR	Alcatel Wire & Cable	ALCWSC20-1STRC14-4	14 AWG-4/C Stranded 20-1	Changed name to Nexans.
9/20/2002	WIR	Alcatel Wire & Cable	ALCWSC19-1STRC14-7	14 AWG-7/C Stranded 19-1	Changed name to Nexans.
9/20/2002	WIR	Alcatel Wire & Cable	ALCWSC19-1STRC14-4	14 AWG-4/C Stranded 19-1	Changed name to Nexans.
8/20/2002	LED	Precision Solar Controls Inc.	PRESHVLEDB12	1630 Extended View	Does not meet the July 2002 LED specification.
8/20/2002	LED	Precision Solar Controls Inc.	PRESHVRLLEDB12	1877	Does not meet the July 2002 LED specification.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
8/20/2002	CHG	Econolite Control Products	ECOCONT2070L1BCPU	2070L12130	The 1B CPU module does not have enough available SRAM to operate State software.
8/20/2002	LED	Dialight Corporation	DIASHVRLEDB12-1	433-1210-801	Does not meet the July 2002 LED specification.
8/20/2002	LED	Dialight Corporation	DIASHVGLEDB12	430-2275-001	Does not meet the July 2002 LED specification.
8/20/2002	FOP	Corning Cable Systems	CORFOCABSMLTA12F	012RW4-14101-A20	The attenuation is compliant with the Project Special Provisions.
7/16/2002	CHG	Eagle Traffic Control Systems	EAGCONT2070L1ACPU-2	AAZ14068P010 w/ AAD13982P001 com module w/o software	The 1A CPU module does not have enough available SRAM to operate State software.
7/16/2002	CHG	Eagle Traffic Control Systems	EAGCONT2070L1ACPU-1	AAZ14068P002 w/ AAD13982P001 com module with software version 3.32NCd	The 1A CPU module does not have enough available SRAM to operate State software.
7/16/2002	WIR	Belden Wire & Cable Co.	BELWLIT119STR14-2C50-2PE-2	PDS-069323 P/N-580655	This product is no longer available.
7/16/2002	WIR	Belden Wire & Cable Co.	BELWLIT119STR14-2C50-2PE-1	PDS-049414 P/N 580680	This product is no longer available.
7/8/2002	PUL	Armorcast Products, Inc.	ARMPBCOMHDCOS	A6001640TAPCX28	This product was replaced by A6001640TAPCX24.
6/4/2002	FOP	Vilink	VILFOM232SMSTRCNHLLCC	VK220E-ST-03	This product is no longer available.
6/4/2002	FOP	Optelecom	OPTFOM232SMSTRCNHLLCC	9241-L1-ST	This product is no longer available.
4/2/2002	LED	GELcore	GELSHVRLEDB8	D08RA5-A4E	Changed Part Numbers.
4/2/2002	LED	GELcore	GELSHVRLEDB12	D12RA5-A4E	Changed Part Numbers.
4/2/2002	LED	GELcore	GELSHVRLEDA12	D12RA7-A4	Changed Part Numbers.
4/2/2002	LED	GELcore	GELSHVGLEDB12	D12GA5-4	Changed Part Numbers.
4/2/2002	LED	GELcore	GELSHVGLEDA12	D12GA7-4C	Changed Part Numbers.
3/12/2002	SHG	IDC -Display Solutions	IDCSHV3S8VAYGRYG	SE30222C221	
3/12/2002	SHG	IDC -Display Solutions	IDCSHV3S12VAYGRYG	ST30222C221	
12/18/2001	LED	Dialight Corporation	DIASHVRLEDB12-1	433-1210-801	Failed the visual test 3 times.
12/18/2001	LED	Dialight Corporation	DIASHVRLEDB12-1	433-1210-801	Failed the visual test 3 times.
12/6/2001	ATD	Emergency Preemption Systems, Inc.	EPSEVIPDSPCU4CH	EPS-II Control Unit with software version 4.26	This product is no longer available.
12/6/2001	ATD	Emergency Preemption Systems, Inc.	EPSEVIPDSD	EPS-II Detector	This product is no longer available.
6/13/2001	CHG	Econolite Control Products	ECOCONTS2T18PH	ASC/2S-1000 Part No. CAS-1000S010680	1.68 has problem with peds during preemption.
6/13/2001	CHG	Econolite Control Products	ECOCONTS18PH	ASC/2S-2100 Part No. CAS-3001S00680	1.68 has problem with peds during preemption.
5/14/2001	LED	Ecolux	ECLSHVRLEDB8	D08RA5-A4E - 8" ball	Ecolux was changed to GELcore.
5/14/2001	LED	Ecolux	ECLSHVRLEDB12	D12RA5-A4E - 12" ball	Ecolux was changed to GELcore.
5/14/2001	LED	Ecolux	ECLSHVRLEDA12	D12RA7-A4 - 12" arrow	Ecolux was changed to GELcore.
5/14/2001	WIR	BSCC	BSCWSC20-1STRC14-7	921407R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWSC20-1STRC14-4	921404R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWSC20-1STRC12-7	921207R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWSC20-1STRC12-4	921204R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWSC19-1STRC14-7	911407R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWSC19-1STRC14-4	911404R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWSC19-1STRC12-7	911207R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWSC19-1STRC12-4	911204R	BSCC was changed to Rome Cable Corp.
5/14/2001	WIR	BSCC	BSCWLI19STR14-2C50-2PE	941401NC DOT #06-03110	BSCC was changed to Rome Cable Corp.
4/17/2001	CHG	Peek Traffic, Inc.	PEECONTS18PH	Part No. 3820 with firmware version 4.5	Does not calculate volume density properly.
3/26/2001	PUL	Quazite Products/Strongwell	QUAPBCOMHDCSS	PC1118BA12 (Box) PC1118HA00 (Cover)	Corners breaking.
12/14/2000	CHG	Peek Traffic, Inc.	PEECONTS2T18PH	Part No. 3101 with firmware version 3.91	Does not calculate volume density properly.
11/2/2000	LSG	Durable Wood Preservers, Inc.	DURLS2PPES	Stat A Flex Loop Sealant	Not the correct manufacture.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
11/2/2000	WIR	Coleman/CCI	COLWSC20-1STRC14-7	559307	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWSC20-1STRC14-4	559304	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWSC20-1STRC12-7	559707	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWSC20-1STRC12-4	559704	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWSC19-1STRC14-7	559107	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWSC19-1STRC14-4	559104	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWSC19-1STRC12-7	559507	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWSC19-1STRC12-4	559504	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWLI19STR14-2C50-2PE	510048 DOT #06-03110	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	WIR	Coleman/CCI	COLWL14AWG19STRCPE	513496-xx-08 DOT #06-24273	This product is no longer available. Spoke with Metro Glowa on 11/02/00 to confirm.
11/2/2000	CHG	Econolite Control Products	ECOCONTS18PH-3	ASC/25-2100 Part No. CAS-3001S00610	Firmware version 1.61 was replaced by 1.67.
11/2/2000	CHG	Econolite Control Products	ECOCONTS2T18PH	ASC/25-1000 Part No. CAS-1000S010610	Firmware version 1.61 was replaced by 1.67.
8/9/2000	CHG	Peek Traffic, Inc.	PEECONTS18PH	Part No. 3820 with firmware version 3.8	Firmware version 3.8 was replaced by 4.5.
11/19/1999	FOP	Raychem Corporation	RAYFOASE24F-1	FOSC400	Not a Part Number.
10/25/1999	WIR	BSCC	BSCWL14AWG19STRCPE	1159301	This product is no longer available.
10/25/1999	CHG	Eagle Traffic Control Systems	EAGCONTS18PH-2	EPAC3118M34 with firmware version 3.30d	Controller's Red Clearance does not operate properly during preemption.
9/29/1999	CHG	Eagle Traffic Control Systems	EAGCONTS18PH-2	EPAC3118M34 with firmware version 3.30d	Controller firmware does not provide a preemption status output signal.
7/30/1999	SHG	Econolite Control Products	ECOSHV3S8VAYGRYG	EA31VSY2AGE0	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	SHG	Econolite Control Products	ECOSHV3S12VAYGRYG	TA31VSY2AGE0	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	SHG	Econolite Control Products	ECOSHV5S8CAYGRYGAGAG	EA56VSY1AGE0 (Left arrow) EA59VSY1AGE0 (Right arrow)	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	SHG	Econolite Control Products	ECOSHV5S12CAYGRYGAGAG	TA56VSY1AGE0 (Left arrow) TA59VSY1AGE0 (Right arrow)	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	SHG	Econolite Control Products	ECOSHV4S12VAYGRYGGA	TA44VSY2AGE0	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	SHG	Econolite Control Products	ECOSHV3S12VAYGRAYAGA	TA34VSY2AGE0	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	SHG	Econolite Control Products	ECOSHV1S12AYGY	TA12VSY1AGE0	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	SHG	Econolite Control Products	ECOSHV1S12AYGR	TA11VSY1AGE0	Signal Head terminal blocks and lamp sockets do not meet the spade connector requirement.
7/30/1999	CHG	Econolite Control Products	ECOCONTS18PH-2	ASC/2-2100 with firmware version 1.51	Firmware is not Y2K compliant.

Products Removed From QPL

DeleteDate	GRP	Manufacturer Name	MANUFACTURER PRODUCT NO ASSIGNED BY NCDOT	MANUFACTURER MODEL NUMBER OR OTHER DESIGNATION	Reason For Removal
7/30/1999	CHG	Econolite Control Products	ECOCONTS18PH-1	ASC/2-2100 with firmware version 1.50	Firmware is not Y2K compliant.
7/30/1999	CHG	Eagle Traffic Control Systems	EAGCONTS18PH	EPAC3118M10	M10 no long available.
6/10/1999	SHG	Econolite Control Products	ECOSHV3S8VAYGRYG	EA31Y1AGE0N	New part number for product.
6/10/1999	SHG	Econolite Control Products	ECOSHV3S12VAYGRYG	TA31Y1AGE0N	New part number for product.
6/1/1999	WIR	TW Comcorp/Anicom	TWCWSC19-1STRC14-7	14-AWG/7-C	This Company is a distributor, instead of a manufacturer.
6/1/1999	WIR	TW Comcorp/Anicom	TWCWSC19-1STRC14-4	14-AWG/4-C	This Company is a distributor, instead of a manufacturer.
6/1/1999	WIR	TW Comcorp/Anicom	TWCWSC19-1STRC12-7	12-AWG/7-C	This Company is a distributor, instead of a manufacturer.
6/1/1999	WIR	TW Comcorp/Anicom	TWCWSC19-1STRC12-4	12-AWG/4-C	This Company is a distributor, instead of a manufacturer.
5/18/1999	LSG	Compositite	COMLS2PPES	Flexible Loop Sealer II 9305	Company gone out of business.
5/7/1999	WIR	Clifford of Vermont	CLIWSC19-1STRC14-7	14-AWG/7-C	This Company is a distributor, instead of a manufacturer.
5/7/1999	WIR	Clifford of Vermont	CLIWSC19-1STRC14-4	14-AWG/4-C	This Company is a distributor, instead of a manufacturer.
5/7/1999	WIR	Clifford of Vermont	CLIWSC19-1STRC12-7	12-AWG/7-C	This Company is a distributor, instead of a manufacturer.
5/7/1999	WIR	Clifford of Vermont	CLIWSC19-1STRC12-4	12-AWG/4-C	This Company is a distributor, instead of a manufacturer.
3/22/1999	SHG	Dialight Corporation	DIASHVRLEDB8	430-1115-001 - 8" ball	Does not meet the VTCSH-2 Specifications.
3/22/1999	SHG	Dialight Corporation	DIASHVRLEDB12	430-1215-001 - 12" ball	Does not meet the VTCSH-2 Specifications.
2/24/1999	LSG	Dow Corning Corp.	DOWLS1PSR	Loop Detector Sealant	Part Number discontinued
1/13/1999	SHG	Hytron Electric Products	HYTLTS150W1950L130V8KH	30324	Not rated at minimum voltage of 130 volts
12/1/1998	SHG	Dialight Corporation	DIASHVRLEDA12	430-1314-001 - 12" arrow	1314 has wrong connector on it
12/1/1998	GHG	Apache Grounding	APAGRSCPLB5/8	GRC58	Company closing
12/1/1998	GHG	Apache Grounding	APAGRCBS10F5/8	GRS5810	Company closing
12/1/1998	GHG	Apache Grounding	APAGRCB10F5/8	GR5810	Company closing
9/1/1998	SHG	Pelco Products, Inc.	PELSMHSWSBAMISSHY1W-2	SP-5230 painted yellow	Balance Adjuster fails to maintain Signal Head angle. Also Division 3 reports breaking more than ten Balance Adjusters. All past Pelco samples collected were not painted yellow per specified method.
9/1/1998	SHG	Pelco Products, Inc.	PELSMHSWSBAMISSHY1W-1	SE-3151painted yellow	Balance Adjuster fails to maintain Signal Head angle. Also Division 3 reports breaking more than ten Balance Adjusters. All past Pelco samples collected were not painted yellow per specified method.
9/1/1998	SHG	Pelco Products, Inc.	PELBAMISSHY	SE-3108 painted yellow	Balance Adjuster fails to maintain Signal Head angle. Also Division 3 reports breaking more than ten Balance Adjusters. All past Pelco samples collected were not painted yellow per specified method.
	CHG	Intelight	INTCONT2070LX2009TEES1CM	YCT-1C-CPU	Not available