

CONTRACT: DA00711

TIP PROJECT: 15BPR.164

STATE OF NORTH CAROLINA
DIVISION OF HIGHWAYS

BEAUFORT COUNTY

LOCATION: FERRY TERMINAL BRIDGE NO. 060321 ON NC306
AT THE PAMLICO SOUND NEAR AURORA

FERRY TERMINAL BRIDGE NO. 060322 ON NC306
AT THE PAMLICO SOUND NEAR BAYVIEW

TYPE OF WORK: STRUCTURAL, MECHANICAL AND ELECTRICAL
REHABILITATION OF EXISTING RAMP STRUCTURES

INDEX OF SHEETS

G-1 INDEX OF SHEETS
G1-01 KEY PLAN AND GENERAL NOTES
S1-01 PRESTRESSED CORED SLAB REPAIR DETAILS
S1-02 DOLPHIN FENDER PANEL REPLACEMENT
S1-03 LIFT BENT REPAIR DETAILS
S1-04 STEEL BEAM CRACK REPAIR DETAILS
S1-05 BENT 1 STEEL PILE REPAIR DETAILS
S1-06 BENT 2 STEEL PILE REPAIR DETAILS
S1-07 LIFT BENT STEEL PILE REPAIR DETAILS
S1-08 BENT 2 PILE JACKET REPAIR DETAILS
S1-09 LIFT BENT PILE JACKET REPAIR DETAILS
S1-10 FRP PILE JACKET DETAILS
M1-01 MECHANICAL NOTES
M1-02 HYDRAULIC AND LUBRICATION REPAIRS
E1-01 ELECTRICAL GENERAL NOTES
E1-02 AREA LIGHTING REPAIR DETAILS
E1-03 CONDUIT REPAIR DETAILS
E1-04 JUNCTION BOX REPAIR DETAILS
E1-05 HPU CAPACITOR AND PENDANT REPAIR DETAILS

G2-01 KEY PLAN AND GENERAL NOTES
S2-01 DOLPHIN FENDER PANEL REPLACEMENT DETAILS
S2-02 STEEL BEARING REPAIR DETAILS
S2-03 STEEL BEAM CRACK REPAIR DETAILS
S2-04 LIFT BENT STEEL PILE REPAIR DETAILS
S2-05 BENT 2 PILE JACKET REPAIR DETAILS
S2-06 LIFT BENT PILE JACKET REPAIR DETAILS
S2-07 FRP PILE JACKET DETAILS
M2-01 MECHANICAL NOTES
M2-02 HYDRAULIC AND LUBRICATION REPAIRS
E2-01 ELECTRICAL GENERAL NOTES
E2-02 AREA LIGHTING REPAIR DETAILS
E2-03 CONDUIT REPAIR DETAILS
E2-04 RACEWAY REPAIR DETAILS
E2-05 JUNCTION BOX REPAIR DETAILS
SN STANDARD NOTES

STATE	STATE PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
N.C.	-- -- --	G-1	34
STATE PROJ. NO.	P.A. PROJ. NO.	DESCRIPTION	
15BPR.164.1	--	PE	
15BPR.164.3	--	CON	

