



STATE OF NORTH CAROLINA  
DEPARTMENT OF TRANSPORTATION

ROY COOPER  
GOVERNOR

J. ERIC BOYETTE  
SECRETARY

**ADDENDUM NO. 1**

December 12, 2022

Contract No. DK00342  
TIP No.: N/A  
Federal Aid No.: State Funded  
WBS Element: 2023CPT.11.05.10861, 2023CPT.11.05.20861  
County: Surry  
Description: Resurfacing, Milling, Patching, Shoulder Reconstruction, and Pavement Markings

**December 15, 2022 Bid Letting**

To Whom It May Concern:

Reference is made to the Contract Proposal located on the Division 11 Letting Page for the above-mentioned project.

The following revision has been made to the Contract Proposal:

**Page R-19 – ADJUSTMENT OF CATCH BASINS, MANHOLES, DROP INLETS, METER BOXES AND VALVE BOXES**, has been added. Please replace **Page R-19** in you contract proposal with the **revised Page R-19** attached to this addendum letter.

This revision is reflected in the Proposal currently posted on the Division 11 Letting Page.

If you have any questions regarding this matter, please feel free to contact me at 336-903-9115.

Sincerely,

DocuSigned by:

*Kenny Heavner*

910812B04BDC452...

Kenny H. Heavner, PE  
Division Contract Engineer

cc: M. L. Poe, PE, Division Engineer  
Division Maintenance Engineer  
I. H. Dishman, PE, Division Construction Engineer  
M. E. Evans, PE, Assistant Division Construction Engineer  
R. A. Shaw, PE, Division Project Development Engineer  
R. S. Miles, District Engineer

*Mailing Address:*  
NC DEPARTMENT OF TRANSPORTATION  
DIVISION 11  
P. O. BOX 250  
NORTH WILKESBORO, NC 28659

*Telephone:* (336) 667-9111  
*Fax:* (336) 667-4549  
*Customer Service:* 1-877-368-4968

*Website:* [www.ncdot.gov](http://www.ncdot.gov)

*Location:*  
801 STATESVILLE ROAD  
NORTH WILKESBORO, NC 28659

Bighorn GT  
ChariotHeron  
NordicRescue 911  
Rhino

On cut and fill slopes 2:1 or steeper add 20# Sericea Lespedeza January 1 - December 31.

Fertilizer shall be 10-20-20 analysis. A different analysis of fertilizer may be used provided the 1-2-2 ratio is maintained and the rate of application adjusted to provide the same amount of plant food as a 10-20-20 analysis and as directed.

**ADJUSTMENT OF CATCH BASINS, MANHOLES, DROP INLETS, METER BOXES  
AND VALVE BOXES:**

(11-15-22)

858

SP8 R98R

Revise the *2018 Standard Specifications* as follows:

**Page 8-38, Article 858-4 MEASUREMENT AND PAYMENT**, lines 10-11, delete and replace the fifth paragraph with the following:

Where any catch basin, drop inlet, manhole, meter box or valve box is adjusted more than once because of milling operations, each adjustment will be measured and paid.