



Group 220

| Map Number | Priority | Contract Group | County | FHWA | WBS | Pipe_No | Route | Location | Latitude | Longitude | Existing Length Size | Proposed Length Size | Crown to Bed | Dept | Recommended Pipe Size | Alt_1_Pipe Size | Alt_2_Pipe Size | Flood_Zone | Comments |
|------------|----------|----------------|--------|------|-----------------|----------|-------|--------------------------|-----------|------------|----------------------|----------------------|--------------|------|-----------------------|-----------------|-----------------|-----------------|---|
| 82022 | | 220 | 82 | | DF15003.2082035 | | 1625 | 0.30 mile South of NC55 | 35.281200 | -78.529700 | 40', 36" CMP | | 8 | SFB | 1 @ 72" w/hdwl | 2 @ 54" w/hdwl | | FEMA LDS | needs full replacement |
| 82027 | | 220 | 82 | | DF15003.2082038 | | 1823 | 0.3 mile West of SR 1817 | 35.117374 | -78.336872 | 80 feet | 80 feet | 9 | SFB | 1 @ 66" w/hdwl | 1 @ 87"x63" | 2 @ 48" w/hwll | Not in FEMA FHZ | Pipe completely washed out. 48" bridge size pipe. |
| 82029 | | 220 | 82 | | DF15003.2082112 | NIP 2057 | 1716 | 0.61 North of SR 1715 | 35.216515 | -78.267076 | | | | SFB | 1 @ 60" w/hdwl | | | | |