
This electronic collection of documents is provided for the convenience of the user and is Not a Certified Document –

The documents contained herein were originally issued and sealed by the individuals whose names and license numbers appear on each page, on the dates appearing with their signature on that page.

This file or an individual page shall not be considered a certified document.


INSET 41: INTER. ID 1569, SR-2137 (Old Oak Ridge Rd) & Knightwood Dr



REALIGN RAMPS AT 1569 A & B. AS PER **DESIGN**

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**

INSET 42: INTER. ID 1664, SR-2136 (Fleming Rd) & Southlake Dr



REALIGN RAMPS AT 1664 B & C. AS PER DESIGN

REMOVE RAMPS AT 1664 A & D AND PUT BACK **SIDEWALK**


SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**





REALIGN RAMP AT 1565A, AS PER DESIGN


SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**





SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**


CONTACT DDC AT 336-487-0000 TO REACH OUT TO UTILITY OWNER TO INSTALL SIDEWALK GUY. (PROVIDE 6' **CLEARANCE**)







INSET 53: INTER. ID 2111, SR-2147 (W Friendly Av) & SR-5104 (Woodstream Ln)




REALIGN RAMP AT 2111 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

MAINTAIN ALL RAMPS WITHIN EXISTING CROSSWALK LIMITS

INSET 54: INTER. ID 2104, SR-2147 (W Friendly Av) & Francis King St




CURVE SIDEWALK AROUND STREET SIGN AND REALIGN RAMP AT 2104A, SEE DESIGN.

CURVE SIDEWALK
AROUND CATCH BASIN
AND REALIGN RAMP AT
2104B, SEE DESIGN.

SEED ARES OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS/ RELOCATIONS.






RETROFIT DETECTABLE WARNING DOMES AT 2358 A & B.

EXISTING DOMES INCORRECTLY ALIGNED.

ALIGN THE DOMES IN DIRECTION OF TRAVEL TO OTHER RAMPS. (TYPE 1 DETAIL)



INSET 56 INTER. ID 2398, SR-1546 (Guilford College Rd) & Wendy Ct

> SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

REALIGN RAMP AT 2398 A & B, AS PER DESIGN



HYDRAULICS ENGINEER

PREPARED BY

DOCUMENT NOT CONSIDERED FIN NLESS ALL SIGNATURES COMPLE




RAISION

INSET 45: INTER. ID 1521, SR-2136 (Fleming Rd) & Fleming Terrace Rd



BEST FIT RAMPS AT 1521 A, B, C & D TO SERVE BOTH DIRECTIONS.

INSET 46: INTER. ID 1522, SR-2136 (Fleming Rd) & Fox Chase Rd



REALIGN SIDEWALK AND RAMP AT 1522 A & B, AS PER DESIGN

(ADD ADDITIONAL SIDEWALK TO MAKE CONNECTION, REMOVE EXISTING)

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REALIGN RAMPS AT 2094 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

MAINTAIN RAMPS WITHIN EXISTING CROSSWALK LIMITS.





REALIGN RAMPS AT 3057 A & D, AS PER DESIGN

(REALIGN SIDEWALK, REMOVE EXISTING)

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

PLACE RAMPS BACK WITHIN EXISTING HI-VIS CROSSWALK LIMITS.




HYDRAULICS ENGINEER

PREPARED BY





INSET 61: INTER. ID 2047, SR-1836 (Willard Dairy Rd) & Oak Chase Dr



REALIGN RAMP AT 2047 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 62: INTER. ID 2048, SR-1836 (Willard Dairy Rd) & Shadow Ridge Dr




REALIGN RAMP AT 2048 A & B, AS PER DESIGN

BEST FIT BETWEEN
TYPE 1 MOD AND 3 MOD
AT 2048 A.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 63 INTER. ID 2049, SR-1836 (Willard Dairy Rd) & Penny Rd




REALIGN SIDEWALK AND RAMP AT 2049 A & B. AS PER DESIGN.

ADD / REMOVE ADDITIONAL SIDEWALK AS ILLUSTRATED. SNAKE SIDEWALK AROUND THE POWER POLE.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REMOVE THE RAMP AND PLACE SIDEWALK BACK.



HYDRAULICS ENGINEER

PREPARED BY

DOCUMENT NOT CONSIDERED UNLESS ALL SIGNATURES COM



REVISION

INSET 57: INTER. ID 1537, SR-1546 (Guilford College Rd) & Hackney Rd



REALIGN RAMP AT 1537 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 58: INTER. ID 1541, SR-1546 (Guilford College Rd) & Hibler Rd




ALIGN RAMP AT 1541A, AS PER DESIGN.

CURVE SIDEWALK AND ALIGN RAMP AS ILLUSTRATED AT 1541B.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS/ RELOCATIONS.






UPGRADE RAMPS AT 2266 A & B TO TYPE 3 MOD.

UPGRADE RAMP AT 2266C TO TYPE 2B.

MAINTAIN ALL RAMPS WITHIN EXISTING SIDEWALK LIMITS.





REALIGN SIDEWALK AND RAMP AT 2046 A, AS PER DESIGN (REMOVE EXIST. AND PROVIDE NEW SIDEWALK CONNECTION)

ALIGN RAMP AT 2046B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

MAINTAIN RAMPS WITHIN EXISTING CROSSWALK LIMITS.



HYDRAULICS ENGINEER

PREPARED BY



SNOI

INSET 65: INTER. ID 2311, SR-5002 (Boulder Rd) & Entrance to Gasoline Tank field




REALIGN RAMPS AT 2311 A & B. TO EACH OTHER

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**



INSET 68: INTER. ID 2123,



REALIGN RAMPS AT 2059 A & B, AS PER DESIGN

2059A - CURVE SIDEWALK AROUND THE MANHOLE.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**





REALIGN RAMPS AT 2092 A & B, TO EACH OTHER

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**



REALIGN RAMP AT 2123 B TO 2123 A.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**




INSET 69 INTER. ID 1644, SR-2136 (Fleming Rd) & Pasquinelli Pl



REALIGN RAMPS AT 1644 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 70: INTER. ID 2013, SR-1546 (Guilford College Rd) & Barrington Place Ct



REMOVE RAMPS 2013 B AND C. DO NOT ADD SIDEWALK BACK

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

REALIGN RAMPS AT 2013 A & D. AS PER DESIGN.






REALIGN RAMP AT 2276 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

PLACE RAMPS IN EXISTING CROSSWALK LIMITS, IF POSSIBLE. IF NOT, RELOCATE THE CROSSWALK.



INSET 72: INTER. ID 2012, SR-1546 (Guilford College Rd) & Friendly Hills Church Entrance

> **RELOCATE AND ALIGN** THE RAMPS AT 2012 A & C. AS ILLUSTRATED.





INSET 49 INTER. ID 2119, SR-2147 (W Friendly Av) & Sheetz Entrance




REALIGN RAMP AT 2119A, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 50: INTER. ID 2114, SR-2147 (W Friendly Av) & Friendly Plantation Condos

INSET 52: INTER. ID 2112,



REALIGN RAMP AT 2114 A & B, AS PER DESIGN


SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REALIGN RAMP AT 2113 A, B & C, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



SR-2147 (W Friendly Av) & SR-5103 (Brushwood Ct)

PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

RAMP AT 2112 A & B, AS

RELOCATE CROSSWALK, AS PER DESIGN.



HYDRAULICS ENGINEER

PREPARED BY

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

INSET 77: INTER. ID 1922, SR-1424 (Hilltop Rd) & MacGregor PI Entrance



REALIGN RAMPS AT 1922 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 78: INTER. ID 1923, SR-1424 (Hilltop Rd) & Bridford Pkwy



REALIGN THE RAMPS AT 1923 A, B & H TO <u>TYPE 3</u> <u>MOD</u>, AS ILLUSTRATED.

REMOVE RAMPS AT 1923 C, F & G AND PLACE SIDEWALK CONNECTION BACK.

PLACE <u>TYPE 1 MOD</u> (BEST FIT) AT 1923D

BEST FIT <u>TYPE 1A</u> AT 1923 E.


PLACE RAMPS IN THE EXISTING CROSSWALK LIMITS.





REALIGN RAMPS AT 1924 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



INSET 80: INTER. ID 1925, SR-1424 (Hilltop Rd) & W Woodlyn Way

> REALIGN RAMPS AT 1925 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

REMOVE ADDITIONAL SIDEWALK.

SHEET NO. 24

NORTH CAROLINA
DEPARTMENT OF TRANSPORTATIC
CUILFORD COUNTY

DIVISION 7 DDC UNIT
ROADWAY DESIGN
ENGINEER

HYDRAULICS ENGINEER

PREPARED BY

CUMENT NOT CONSIDERED FINAL ESS ALL SIGNATURES COMPLETE

EVISION

INSET 81: INTER. ID 1926, SR-1424 (Hilltop Rd) & Mowbray Tr



REALIGN RAMPS AT 1926 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

REMOVE ADDITIONAL SIDEWALK.

INSET 82: INTER. ID 1928, SR-1424 (Hilltop Rd) & Ellery Ct




REALIGN RAMPS AT 1928 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

REMOVE ADDITIONAL SIDEWALK.





REALIGN RAMPS AT 1929 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

REMOVE ADDITIONAL SIDEWALK.



INSET 84: INTER. ID 1930, SR-1424 (Hilltop Rd) & Stanley Rd

> UPGRADE THE RAMPS AT 1930 A, D & E TO TYPE 3 MOD.

MAINTAIN ALL RAMPS WITHIN EXISTING CROSSWALK LIMITS.

REMOVE RAMPS AT 1930 B & C.

SEED AREAS OUTSIDE OF PROP. IMPROVEMENTS AFFECTED BY RAMP REMOVALS/ RELOCATIONS.




HYDRAULICS ENGINEER

PREPARED BY

DOUMENT NOT CONSIDERED F UNLESS ALL SIGNATURES COMPL

INSET 73: INTER. ID 1916, SR-1424 (Hilltop Rd) & Unitarian Universalist Church Entrance SR-1424 (Hilltop Rd) & Griffin Recreation Center Entrance



REALIGN RAMPS AT 1916 A & B. TO EACH OTHER

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**


INSET 74: INTER. ID 1918,



REALIGN RAMP AT 1918 B TO 1918A.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**





REALIGN RAMPS AT 1920 A & B, AS PER DESIGN.

REMOVE ADDITIONAL SIDEWALK

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**



INSET 76: INTER. ID 1921, SR-1424 (Hilltop Rd) & Adams Farm Pkwy

> **REALIGN RAMPS AT** 1921 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / **RELOCATIONS**

