

This electronic collection of documents is provided for the convenience of the user and is Not a Certified Document –


The documents contained herein were originally issued and sealed by the individuals whose names and license numbers appear on each page, on the dates appearing with their signature on that page.

This file or an individual page shall not be considered a certified document.





INSET 1: INTER. ID 1725 SR-1008 (W Market St) & Weslo Willow Dr




1725A - MAINTAIN 5' SPACING WHEN REALIGNING THE SIDEWALK LEADING TO RAMP

ALIGN DETECTABLE WARNING DOMES, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 2: INTER. ID 1727, SR-1008 (W Market St) & Friendway Rd



ALIGN WARNING DOMES AT 1727 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 3: INTER. ID 1732, SR-1008 (W Market St) & Village Ln



ALIGN WARNING DOMES AT 1732 A & B (NEW LOCATION), AS PER DESIGN.

CONTACT DIVISION TRAFFIC SERVICES AT 336-487-0000 FOR EVALUATION OF HIGH-VIS CROSSWALK



INSET 4: INTER. ID 1734, SR-1008 (W Market St) & Montlieu Av

> ALIGN WARNING DOMES AT 1734 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



HYDRAULICS ENGINEER

PREPARED BY

CUMENT NOT CONSIDERED FINAL ESS ALL SIGNATURES COMPLETE



SNOISIAE

INSET 5: INTER. ID 1735, SR-1008 (W Market St) & The Amesbury Apartments Entrance



ALIGN DETECTABLE WARNING DOMES AT 1735 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS


INSET 6: INTER. ID 1736, SR-1008 (W Market St) & Longale St



REALIGN SIDEWALKS AND DETECTABLE WARNING DOMES AT 1736 A & B, AS PER DESIGN


SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REALIGN SIDEWALKS AND DETECTABLE WARNING DOMES AT 1738 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP AND SIDEWALK REMOVALS / REALIGNMENTS



INSET 8: INTER. ID 1739, SR-1008 (W Market St) & S Walnut Cir

> REALIGN DETECTABLE WARNING DOMES AT 1738 A, B & C, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



HYDRAULICS ENGINEER

PREPARED BY

SNOISIA

INSET 9: INTER. ID 1741, SR-1008 (W Market St) & Supermart Entrance



REALIGN DETECTABLE WARNING DOMES AT 1741 A & B AS PER DESIGN.

MAINTAIN ALL RAMPS
WITHIN THE CROSSWALK
LIMITS. PROVIDE
CONNECTIVITY AS BEST
POSSIBLE, BASED ON
FIELD CONDITIONS.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 10: INTER. ID 3059, SR-1008 (W Market St) & Fanta City Mall



REALIGN DETECTABLE WARNING DOMES AT 3059 A & B AS PER DESIGN. (BEST FIT)

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 11: INTER. ID 3060, SR-1008 (W Market St) & DOLLAR GENERAL



DIRECTIONAL RAMP TYPE 1 MOD AT 3060A

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



INSET 12: INTER. ID 1742, SR-1008 (W Market St) & Thornton Ct

> REALIGN DETECTABLE WARNING DOMES AT 1742 A & B AS PER DESIGN. (BEST FIT)

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS




HYDRAULICS ENGINEER

PREPARED BY

UMENT NOT CONSIDERED FINA

FVTSTON

INSET 13: INTER. ID 1743, SR-1008 (W Market St) & Southern Oxygen Rd



DIRECTIONAL RAMP TYPE 1 AT 1743A

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 14: INTER. ID 1744, SR-1008 (W Market St) & Norwalk St



REALIGN DETECTABLE WARNING DOMES AT 1744 A & B AS PER DESIGN. (BEST FIT)


SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REALIGN DETECTABLE WARNING DOMES AT 1745 A & B AS PER DESIGN. (BEST FIT)

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





MAINTAIN ALL RAMPS
WITHIN THE
CROSSWALK LIMITS TO
SERVE BOTH
DIRECTIONS. PROVIDE
CONNECTIVITY AS BEST
POSSIBLE, BASED ON
FIELD CONDITIONS.





HYDRAULICS ENGINEER

PREPARED BY

JMENT NOT CONSIDERED FINA

EVISIONS


INSET 17: INTER. ID 1724, SR-1008 (W Market St) & Shoppes On Market Entrance



REALIGN DETECTABLE WARNING DOMES AT 1724 A, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS


INSET 18: INTER. ID 1719, SR-1008 (W Market St) & Revere Dr



REALIGN DETECTABLE WARNING DOMES AT 1719 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 19: INTER. ID 1718, SR-1008 (W Market St) & Dartmouth St



REALIGN DETECTABLE WARNING DOMES AT 1718 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REALIGN DETECTABLE WARNING DOMES AT 1717 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



HYDRAULICS ENGINEER

PREPARED BY

NOISIA

INSET 21: INTER. ID 1749, SR-1008 (W Market St) & Sheetz Entrance




REALIGN SIDEWALK AND DETECTABLE WARNING DOMES AT 1749 A, AS PER DESIGN.

REALIGN TWO SIDEWALKS TO CONVERGE TO TYPE 1 MOD RAMP (BEST FIT AS PER FIELD CONDITIONS)

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 22: INTER. ID 1714, SR-1008 (W Market St) & Starmount Dr




REALIGN DETECTABLE WARNING DOMES AT 1714 A, AS PER DESIGN.

TYPE 1 A IN THE CURVE (BEST FIT BASED ON FIELD CONDITIONS)

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS


INSET 23: INTER. ID 1713, SR-1008 (W Market St) & E Avondale Dr



REALIGN DETECTABLE WARNING DOMES AT 1713 A & B, AS PER DESIGN.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 24: INTER. ID 1712, SR-1008 (W Market St) & Homewood Av



REALIGN RAMP AT 1712 A & B, AS PER DESIGN.

ANGLE RAMP TO PROVIDE BEST FIT ALIGNMENT TO RAMP ACROSS THE STREET

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



HYDRAULICS ENGINEER


PREPARED BY

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETI



SNOISIAE

INSET 25: INTER. ID 1711, SR-1008 (W Market St) & SR-2175 (Green Valley Rd)



REALIGN SIDEWALKS AND RAMPS AT 1711 B & C, AS PER DESIGN

TYPE 3 MOD AT 1711 A & B.

PROVIDE TYPE 1 MOD AT 1711D, AS PER DESIGN

MAINTAIN ALL RAMPS WITHIN EXISTING CROSSWALK LIMITS

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 26: INTER. ID 2202, SR-3841 (W Market St) & RMP-4267 (N Lindell Rd)




REALIGN RAMPS AT 2202 D & A, AS PER DESIGN

MAINTAIN ALL RAMPS WITHIN EXISTING CROSSWALK LIMITS.

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REALIGN RAMPS AT 2201 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



INSET 28: INTER. ID 2199 SR-3841 (W Market St) & Ridgeway Dr

> REALIGN RAMPS AT 2199 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



HYDRAULICS ENGINEER

PREPARED BY

OCUMENT NOT CONSIDERED FIN NLESS ALL SIGNATURES COMPLE

EVISION

INSET 29: INTER. ID 2198, SR-3841 (W Market St) & W Greenway Dr S



REALIGN RAMPS AT 2198 A, B, C & D, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 30: INTER. ID 2197, SR-3841 (W Market St) & E Greenway Dr N



REALIGN RAMPS AT 2197 A, B, C & D, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS





REALIGN RAMPS AT 2194 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



INSET 32: INTER. ID 2193, SR-3841 (W Market St) & Arden Pl

> REALIGN RAMPS AT 2193 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



HYDRAULICS ENGINEER

PREPARED BY

CUMENT NOT CONSIDERED FINAL SS ALL SIGNATURES COMPLETE

NOISIA

INSET 33: INTER. ID 2192, SR-3841 (W Market St) & Overlook Dr



REALIGN RAMPS AT 2192 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS

INSET 34: INTER. ID 2191, SR-3841 (W Market St) & Mayflower Dr



REALIGN RAMPS AT 2191 A & B, AS PER DESIGN


SEED AREAS OUTSIDE
OF PROP. RAMP
AFFECTED BY RAMP
REMOVALS /
RELOCATIONS





REALIGN RAMPS AT 2205 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



INSET 36: INTER. ID 2206, SR-3841 (W Market St) & Hillcrest Dr

> REALIGN RAMPS AT 2206 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS




HYDRAULICS ENGINEER

PREPARED BY



1


INSET 37: INTER. ID 2100, SR-2137 (Old Oak Ridge Rd) & Deerwood Meadows Apt



REALIGN RAMPS AT 2100 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS


INSET 38: INTER. ID 2101, SR-2137 (Old Oak Ridge Rd) & Deerwood Meadows Apt



REALIGN RAMPS AT 2101 A & B, AS PER DESIGN

SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS






REALIGN RAMP AT 1638A, AS PER DESIGN

REALIGN SIDEWALK AND RAMP AT 1638B, AS PER DESIGN.


SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



INSET 40: INTER. ID 2103, SR-2137 (Old Oak Ridge Rd) & Oak Ridge Meadows Dr



SEED AREAS OUTSIDE OF PROP. RAMP AFFECTED BY RAMP REMOVALS / RELOCATIONS



HYDRAULICS ENGINEER

PREPARED BY

CUMENT NOT CONSIDERED FINAL ESS ALL SIGNATURES COMPLETE

KEVISION