

16_24 NCWedge Hangs on EOP

Question:

NCWedge hangs up when cropping EOP to cross sections.

Answer:

EOP design has curve elements as part of their EOP file. NCWedge does not work well with curves and is being re-written to "be nicer". In the meantime, make a copy of the eop file and trace over the curves with lines. Use this eop in your .par file and it should work.