Files that need re-mapping

DSN ROW SS DRN

Caution when remapping cells. The cells scale is not consistence. All D&C manager cells for automated quantities have to be reset after remapping.

Files that don't need re-mapping

PSH

PFL

TSH

DET

TYP

*XSC

XPL (delete because geoplot no longer used)

L&S and Photogrammetric files (Roadways copy, not the originals) should be converted

Shape files should be re-created.

*Depends on how far along the project you are. Whether or not you want to run V8 or V7 criteria.