

Class:		ABC Sampling				
Instructor: (Primary)		J.J. Myers			Instructor: (Secondary)	S. Jarman
Location:		Marion			Date:	6.11.19
Count	Last Name (first letter)	S.S.N. (last 4 digits)	Grade	Pass/Fail	Status (A / P / I)	Remarks
1	A	000-00-8179	96	Pass	Pending	
2	B	000-00-7643	96	Pass	Pending	
3	B	000-00-4418	92	Pass	Pending	
4	B	000-00-7966	96	Pass	Pending	
5	B	000-00-9166	92	Pass	Pending	
6	C	000-00-9666	76	Fail		
7	C	000-00-7995	100	Pass	Active	
8	C	000-00-6866	96	Pass	Pending	
9	F	000-00-7537	92	Pass	Pending	
10	G	000-00-4672	92	Pass	Pending	
11	H	000-00-7665	100	Pass	Pending	
12	H	000-00-8040	88	Pass	Pending	
13	K	000-00-8974	88	Pass	Pending	
14	M	000-00-9302	96	Pass	Pending	
15	M	000-00-0896	88	Pass	Pending	
16	N	000-00-2504	96	Pass	Pending	
17	P	000-00-4070	76	Fail		
18	P	000-00-9085	76	Fail		
19	R	000-00-0716	100	Pass	Active	
20	R	000-00-1829	96	Pass	Pending	
21	R	000-00-6725	100	Pass	Pending	
22	T	000-00-3889	100	Pass	Pending	
23	T	000-00-9968	100	Pass	Pending	
24	W	000-00-0293	92	Pass	Pending	
25	W	000-00-8139	88	Pass	Pending	
26	W	000-00-6512	100	Pass	Pending	
27	W	000-00-5529	100	Pass	Pending	
28	W	000-00-7913	84	Pass	Pending	
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						

Pass	Active
Fail	Pending
Incomplete	Incomplete
	See Remarks

ABC Sampling
Borrow Pit Sampling
Conventional Density
Nuclear Density Testing -Base, FDR, Select Materials
QMS Density Gauge
Nuclear Safety and Hazardous Materials
Nuclear Safety - Refresher Training
Chemical Stabilization - Subgrade/Base QA
QC/QA Aggregate Sampling
QC/QA Aggregate Testing

J.J. Myers
J. Gilliam
A. Hartel
S. Jarman
J. Sawyer
M.D. Ricker