Paint the shear connectors and all surfaces of the top lange with one coat of primer when using the System 1 paint system at the Section 442-7 of the Standard Specifications.