

Enacted August 1, 1963

<u>No.</u>	<u>Item</u>	<u>Page No.</u>
✓ 1	No Parking Ordinances	11-1
✓ 2	US Route Changes	11-2
✓ 3	60-50 Speed Zone	11-3
✓ 4	Restrictive Speed Zones	11-4 - 11-7
5	Yield Signs	11-8
6	Stop Signs	11-9 - 11-14

Enacted Aug. 1, 1963

NO PARKING ORDINANCES

The following ordinances were introduced by Commissioner _____, seconded by Commissioner _____, and upon being put to a vote were duly adopted:

"BE AND IT IS HEREBY ORDAINED that it shall be unlawful to park a motor vehicle on those sections of streets or highways particularly described as follows:

- ✓ Division 2
Craven County
RK Along both sides of SR 1154 (US 70 Service Road) from the intersection with SR 1140 southward for a distance of 500 feet.
- RK Craven County
Along the east side of SR 1140 from the intersection with SR 1154 northward for a distance of 250 feet.
- RK Division 6
Harnett County
Along the east side of SR 1757 from the intersection with SR 1765 northward for a distance of 135 feet.
- RK Harnett County
Along the east side of SR 1756 from the intersection with SR 1765 southward for a distance of 0.1 mile.
- RK Harnett County
Along the south side of SR 1765 from the intersection with SR 1757 westward for 0.1 mile.
- RK Division 8
Richmond County
Along either shoulder of SR 1608 (Lakeside Dr.) in and near Hamlet from a point 0.1 mi. south of its jct. with SR 1621 southward along SR 1608 for 0.25 mile.

"BE IT FURTHER RESOLVED that the Division Engineers of the above listed divisions cause to be erected appropriate signs indicating this action of the Commission and that these ordinances shall be in full force and effect from and after the erection of such signs."

Enacted Aug. 1, 1963

✓
US ROUTE CHANGES

The following resolutions were introduced by Commissioner _____, seconded by Commissioner _____, and upon being put to a vote were duly adopted:

WHEREAS, it is in the public interest and is needed for conformance with The American Association of State Highway Officials Manual for Signing and Pavement Marking of the National System of Interstate and Defense Highways and the simplification of signing; and

WHEREAS, it appears that certain changes and modifications should be made in the existing designation of US route numbers;

NOW, THEREFORE, BE IT HEREBY RESOLVED that certain changes be made in the US route numbered system as follows:

Division 4

Nash County

RK Delete US 64 from the intersection with the new US 64 Bypass (Project 8.11638) west of Nashville eastward along the present routing for 9.29 miles to the intersection with new US 64 at Rocky Mount.

RK Route US 64 Business from the west junction with the new US 64 Bypass eastward along old US 64 for 3.55 miles to the east junction with the new US 64 Bypass.

RK Route US 64 Bypass along the new Nashville Bypass (Project 8.11638) from the west junction with new US 64 Business eastward along the new bypass for 3.7 miles to the east junction with new US 64 Business.

RK Route US 64 from the east junction with new US 64 Business-Bypass eastward along the new project for 6.1 miles to the intersection with old US 64 at Rocky Mount.

Enacted Aug. 1, 1963

60-50 Speed Zone

The Following Addition is Enacted

RK
✓

<u>County</u>	<u>Loc.No.</u>	<u>Route</u>	<u>Description</u>	<u>Length (Miles)</u>	<u>Limit MPH</u>
Edgecombe	205	US 64	From the intersection with SR 1600 eastward along US 64 to the Pitt County Line	6.0	60-50

Enacted Aug. 1, 1963

Speed Zones

Delete and Rescind the Following

Location	7	NC 50	Pender County
"	14	US 264	Nash "
"	30	NC 41	Robeson "
"	42	US 25	Buncombe "

The Following Additions are Enacted

<i>RK</i>	County	Loc.No.	Route	Description	Length (Miles)	Limit MPH
✓	Brunswick	9	SR 1144	From a point 0.3 mi. east of the intersection with NC 904 eastward along SR 1144 for a distance of 0.8 mi.	0.8	35
✓	Pender	8	NC 50	From the intersection of SR 1552 southwestward along NC 50 to its southern terminus	1.7	35
✓	Pender	9	NC 50	From the intersection with SR 1552, northeastward along NC 50 for a distance of 2.3 mi.	2.3	45
✓	Sampson	14	NC 701	From the northern intersection with US 421, northward along NC 701, for a distance of 3.4 mi.	3.4	45
✓	Edgecombe	18	SR 1537	From the jct. with SR 1520 eastward along SR 1537 to the jct. with SR 1541	0.2	35
✓	Edgecombe	19	NC 97	From a point 0.25 mi. north of the jct. with NC 44 southward along NC 97 for 0.35 mi.	0.35	35
✓	Halifax	18	US 158 East	From the intersection with US 158 West (Second St.) eastward along US 158 East (Third St.) to the intersection with Walnut St. in the town of Weldon	0.5	35

Enacted Aug. 1, 1963

Speed Zones

County	Loc.No.	Route	Description	Length (Miles)	Limit MPH
✓ Halifax	19	US 158 West	From the intersection with Walnut St. westward along US 158 West (Second St.) to the intersection with US 158 East (Third St.) in the town of Weldon	0.5	35
✓ Johnston	28	US 70	From the east jct. with NC 42 westward along US 70 for 0.6 mi.	0.6	45
✓ Nash	26	US 264	From a point 0.05 mi. west of the jct. with NC 581 eastward along US 264 for 0.9 mi. in the town of Bailey	0.9	35
✓ Wake	129	SR 2567	From the jct. with SR 1004 (Garner Rd.) eastward along SR 2567 (Northview St.) for 0.45 mi.	0.45	35
✓ Wake	130	SR 2568	From the jct. with SR 2570 (Cason St.) eastward along SR 2568 (Southerlund Rd.) to the jct. with SR 2581 (Woodside Dr.)	0.55	35
✓ Wake	131	SR 2569	From the jct. with SR 1004 (Garner Rd.) eastward along SR 2569 (Meadowbrook St.) for 0.7 mi.	0.7	35
✓ Columbus	17	US 74- 76	From a point 0.2 mi. west of the intersection with SR 1706, eastward along US 74-76 for a distance of 0.85 mi.	0.85	45
✓ Robeson	33	NC 41	From the east intersection with SR 1945 westward along NC 41 for a distance of 0.65 mi.	0.65	45
✓ Alamance	68	SR 1306	From its jct. with SR 1158 (Huffman Mill Rd.) southwest of Burlington southeastward along SR 1306 (S. Mebane St.) to its jct. with Elderwood Land (non-system)	1.0	35
✓ Alamance	69	SR 1728	From its jct. with SR 1719 (Sellars Mill Rd.) northeast of Burlington eastward along SR 1728 (Morningside Dr) for 0.4 mi.	0.4	35

Enacted Aug. 1, 1963

Speed Zones

County	Loc.No.	Route	Description	Length (Miles)	Limit MPH
Orange	37	SR 1178	From its jct. with SR 1009 northwest of Carrboro southwestward along SR 1178 (Simpson St.) to its jct. with NC 54 Bus.	0.45	35
Chatham	21	NC 87	From a point 0.2 mi. north of its western jct. with US 64 in Pittsboro northwestward along NC 87 for 0.7 mi.	0.7	45
Richmond	37	SR 1974	From its jct. with US 1 south of Rockingham southeastward along SR 1974 (Forrest St.) to its jct. with SR 1972	0.35	35
Forsyth	69	SR 1349	From its jct. with Chester Rd. (SR 1352) west of Winston-Salem southward along Hertford Rd. (SR 1349) to its jct. with Saxon Lane (Also SR 1349)	0.3	35
Rowan	45	SR 1529	From its jct. with NC 150 in Rowan Mills south of Salisbury southward along SR 1529 (Sunset Dr.) for 0.75 mi.	0.75	35
Buncombe	42	US 25	From a point 0.4 mi. north of its jct. with NC 280 at Skyland southward along US 25 to its jct. with SR 3518	0.9	45
McDowell	12	SR 1001	From its jct. with SR 1271 south of Marion southward along SR 1001 for a distance of 0.6 mi.	0.6	45
Jackson	16	SR 1432	From its jct. with SR 1429 northeastward along SR 1432 to its jct. with SR 1442	0.7	45
Jackson	17	SR 1431	From its jct. with SR 1432 northeastward along SR 1431 to its jct. with SR 1437	0.55	45
Jackson	18	SR 1442	From its jct. with SR 1432 northward along SR 1442 to its jct. with SR 1443	0.2	35

Enacted Aug. 1, 1963

Speed Zones

<u>PK</u> County	<u>Loc.No.</u>	<u>Route</u>	<u>Description</u>	<u>Length (Miles)</u>	<u>Limit MPH</u>
✓ Cherokee	7	US 19-129	From a point 0.1 mi. west of its jct. with SR 1514 in Andrews westward for a distance of 0.6 mi.	0.6	45
✓ Macon	12	US 64	From a point 0.25 mi. north of its jct. with NC 28 in Highlands northward to a point 0.05 mi. north of its jct. with SR 1522	0.55	35
✓ Macon	13	US 64- NC 28	From a point 0.1 mi. west of its jct. with NC 106 in Highlands westward to its jct. with SR 1546	0.65	35
✓ Swain	6	US 19	From a point 0.25 mi. west of its jct. with SR 1158 in Bryson City westward for a distance of 0.8 mi.	0.8	45

Enacted Aug. 1, 1963

YIELD SIGN INVENTORY

County	Road Regulated	At Intersection With Thru Hiway	Intersection Type and No. of Signs
--------	----------------	---------------------------------	------------------------------------

ADDITIONS

Halifax	1645 1465	1629	T-1 ✓
"	1464	NC 48	T-1 ✓
"	US 158 E	US 301-US 158	T-1 ✓
"	US 301 N	US 301 S	T-1 ✓
"	US 158 W	US 158 E	T-1 ✓
Rockingham	NC 65	NC 704	X-1 ✓
Surry	1334	1338	Y-1 ✓
"	1648	1637	Y-1 ✓
"	1126	1127	Y-1 ✓
"	1607	1605	Y-1 ✓
Wilkes	1983	1971	Y-1 ✓
"	2438	2325	Y-1 ✓

STOP SIGN INVENTORY

County	Road Regulated	At Intersection With Thru Hiway	Intersection Type and No. of Signs
--------	----------------	---------------------------------	------------------------------------

DELETIONS

Halifax	1150	US 301	X-2 ✓
"	I-95 Ramp	US 158	T-2 ✓
Guilford	1125	1392	X-2 ✓
Rockingham	NC 704	NC 65	X-1 ✓
Anson	1634	1634	T-1 ✓
Stanley	1438	1434	T-1 ✓
"	1206	1208	T-1 ✓
Burke	1558	1124	T-1 ✓

ADDITIONS

New Hanover	1463	1481	T-1 ✓
Onslow	1136	NC 53	T-1 ✓
"	1136	NC 53	T-1 ✓
"	1246	1217	T-1 ✓
"	1456	1455	T-1 ✓
"	1455	1406	T-1 ✓
"	1455	1454	T-1 ✓
"	1453	1454	T-1 ✓
"	1453	1406	T-1 ✓
Pender	1558	NC 50	X-2 ✓
"	1557	NC 50	X-2 ✓
"	1556	NC 50	X-2 ✓
"	1550	NC 50	T-1 ✓
"	1552	NC 50	T-1 ✓
"	1550	1551	T-1 ✓
"	1550	1552	T-1 ✓
"	1553	NC 50	X-2 ✓
"	1554	NC 50	T-1 ✓
"	1559	NC 50	T-1 ✓
"	1576	NC 50	T-1 ✓
"	1558	NC 50	X-2 ✓
Halifax	1464	NC 48	T-1 ✓
"	1683	1619	T-1 ✓
"	1683	NC 48	T-1 ✓
"	1150	US 301	T-1 ✓
"	US 158 E	US 301-US 158	T-1 ✓
"	I-95 S. Bound Exit Ramp	US 158 E	X-2 ✓
"	I-95 S. Bound Exit Ramp	US 158	X-2 ✓
"	I-95 S. Bound Exit Ramp	US 158 W	T-2 ✓

Enacted Aug. 1, 1963

STOP SIGN INVENTORY

County	Road Regulated	At Intersection With Thru Hiway	Intersection Type and No. of Signs
Halifax	1465	1629	T-1 ✓
"	1465	1629	T-1 ✓
Johnston	1960	1959	T-1 ✓
Guilford	1392	1125	X-2 ✓
Rockingham	1776 1176	1110	T-1 ✓
"	1175	1169	T-1 ✓
"	1177	NC 704	T-1 ✓
"	1309	1308	X-1 ✓
"	1568	1535	T-1 ✓
"	2042	1990	Y-1 ✓
"	2450	2414	T-1 ✓
"	2451	2450	T-1 ✓
Moore	2058	2055	T-1 ✓
Randolph	1118	1114	T-1 ✓
"	1117	1115	T-1 ✓
"	1114	1115	T-1 ✓
"	1187	1109	T-1 ✓
"	1187	1111	T-1 ✓
"	1632	1621	T-1 ✓
"	1660	1658	T-1 ✓
"	1660	1638	T-1 ✓
"	1510	1508	T-1 ✓
"	1509	1508	T-1 ✓
"	1509	1508	T-1 ✓
"	1102	1183	T-1 ✓
Anson	1635	1634	T-1 ✓
"	1409	1443	T-1 ✓
Cabarrus	2415	2414	T-1 ✓
"	2415	2427	T-1 ✓
"	2640	2411	T-1 ✓
"	2640	2635	T-1 ✓
"	1123	1125	T-1 ✓
"	1110	1113	T-1 ✓
"	1606	1442	T-1 ✓
"	1606	1601	T-1 ✓
Mecklenburg	1627	1625	T-1 ✓
"	1629	1625	T-1 ✓
Stanley	1260	1249	T-1 ✓
"	1904	1905	T-1 ✓
"	1974	1972	T-1 ✓
"	1434	1438	T-2 ✓
"	1208	1206	T-1 ✓
"	1434	1432	T-1 ✓
"	1113	NC 205	T-1 ✓
"	1114	NC 205	T-1 ✓
Surry	1318	1301	T-1 ✓
"	1321	1301	T-1 ✓
"	1323	1301	T-1 ✓
"	1324	1301	Y-1 ✓
"	1342	1341	T-1 ✓
"	1353	1356	T-1 ✓

Q

Enacted Aug. 1, 1963

STOP SIGN INVENTORY

County	Road Regulated	At Intersection With Thru Hiway	Intersection Type and No. of Signs
Surry	1362	1356	T-1 ✓
"	1373 1363	1356	T-1 ✓
"	1340	1341	T-1 ✓
"	1144	1338	X-2 ✓
"	1143	1138	X-1 ✓
"	1143	1144	T-1 ✓
"	1167	US 21	T-1 ✓
"	1758	1756	X-2 ✓
"	1766	NC 89	T-1 ✓
"	1768	1766	T-1 ✓
"	1767	1766	T-1 ✓
"	1755	1754	T-1 ✓
"	1764	1763	T-1 ✓
"	1764	1763	T-1 ✓
"	1732	1731	T-1 ✓
"	1737	1738	T-1 ✓
"	1736	1737	T-1 ✓
"	1751	1750	T-1 ✓
"	1733	1732	T-1 ✓
"	2211	2200	T-1 ✓
"	2210	2200	T-1 ✓
"	2200	2209	T-1 ✓
"	2093	2035	T-1 ✓
"	2036	2035	T-1 ✓
"	2035	2033	T-1 ✓
"	2033	2038	T-1 ✓
"	2039	2038	T-1 ✓
"	2093	2033	T-1 ✓
"	2033	2034	X-2 ✓
"	1339	1338	T-1 ✓
"	1340	1338	T-1 ✓
"	1339	1334	T-1 ✓

STOP SIGN INVENTORY

County	Road Regulated	At Intersection With Thru Hiway	Intersection Type and No. of Sign
Surry	1129	1122	T-1 ✓
"	1128	1122	T-1 ✓
"	1707	US 52	T-1 ✓
"	1707	US 52	T-1 ✓
"	1705	US 52	T-1 ✓
"	1638	1637	T-1 ✓
"	1645	1638	T-1 ✓
"	1643	1645	T-1 ✓
"	1635	1643	X-2 ✓
"	1705	US 52	T-1 ✓
"	1380	1379	T-1 ✓
"	1383	1376	T-1 ✓
"	1382	1383	T-1 ✓
"	1382	1376	T-1 ✓
"	1386	1385	X-2 ✓
"	1636	1637	T-1 ✓
"	2006	2004	T-1 ✓
"	2005	2002	T-1 ✓
"	2002	2004	T-1 ✓
"	2005	2004	T-1 ✓
"	2003	2005	T-1 ✓
"	2009	2000	T-1 ✓
"	2008	2000	T-1 ✓
"	2007	2000	T-1 ✓
"	1112	1121	T-1 ✓
"	1111	1112	T-1 ✓
"	1123	1122	T-1 ✓
"	1123	1100	T-1 ✓
"	1319	1318	T-1 ✓
"	1320	1319	T-1 ✓
"	1319	1301	T-1 ✓
"	1301	1328 & 1301	T-1 ✓
"	1325	1328	T-1 ✓
"	1329	1328	T-1 ✓
"	1622	1621	T-1 ✓
"	1621	1623	T-1 ✓
"	1602	1623	T-1 ✓
"	1387	1376	T-1 ✓
"	1377	1376	T-1 ✓
"	1613	1345	T-1 ✓
"	1613	1397	T-1 ✓
"	1614	1397	T-1 ✓
"	1397	1605 & 1397	T-1 ✓
"	1614	1615	T-1 ✓
"	1609	1605	T-1 ✓
"	1608	1607	T-1 ✓
"	1608	1609	T-1 ✓
"	2088	2038	T-1 ✓
Watauga	1129	1124	T-1 ✓
"	1116	1121	T-1 ✓

Enacted Aug. 1, 1963

STOP SIGN INVENTORY

County	Road Regulated	At Intersection With Thru Hiway	Intersection Type and No. of Signs
Watauga	1207	1222	T-1 ✓
"	1221	1222	T-1 ✓
"	1221	1225	T-1 ✓
"	1580	NC 105	T-1 ✓
"	1313	1311	T-1 ✓
"	1312	1311	T-1 ✓
"	1368	US 421	T-1 ✓
"	1301	1303	T-1 ✓
"	1111	NC 105	T-1 ✓
"	1553	1552	T-1 ✓
"	1551	1552	T-1 ✓
"	1539	1538	T-1 ✓
"	1143	1145	T-1 ✓
"	1356	1355	T-1 ✓
"	1354	1355	T-1 ✓
"	1354	1351	T-1 ✓
"	1352	1351	T-1 ✓
"	1353	1351	T-1 ✓
"	1358	1353	T-1 ✓
"	1353	1357	T-1 ✓
"	1367	1359	T-1 ✓
Wilkes	2409	2408	T-1 ✓
"	2410	2408	T-1 ✓
"	2411	2410	T-1 ✓
"	2407	2408	T-1 ✓
"	2417	2418	T-1 ✓
"	2416	2418	T-1 ✓
"	2419	2418	T-1 ✓
"	2421	2418	T-1 ✓
"	2421	2412	T-2 ✓
"	2422	2412	T-1 ✓
"	2423	2424	T-1 ✓
"	2423	2412	T-1 ✓
"	2422	2418	T-1 ✓
"	2420	2418	T-1 ✓
"	2419	2420	T-1 ✓
"	2431	2418	T-1 ✓
"	2433	2325	T-1 ✓
"	2325	2433	T-1 ✓
"	2441	2418	T-1 ✓
"	2340	2418	X-2 ✓
"	2439	2418	T-1 ✓
"	2431	2418	T-1 ✓
"	2418	2325	T-1 ✓
"	2445	2443	T-1 ✓
"	2447	2443	T-1 ✓
"	2476	2474	T-1 ✓
"	2475	2477	T-1 ✓
"	2430	2475	T-1 ✓
"	2426	2425	T-1 ✓
"	2427	2425	T-1 ✓

Enacted Aug. 1, 1963

STOP SIGN INVENTORY

County	Road Regulated	At Intersection With Thru Hiway	Intersection Type and No. of Signs
Wilkes	2428	2425	T-1 ✓
"	2429	2425	T-1 ✓
"	2407	2406	T-1 ✓
"	1703	1716 - 1717	X-2 ✓
"	1711	1002	T-1 ✓
"	1757	NC 18	T-1 ✓
"	1973	1971	T-1 ✓
"	2346	US 421	T-1 ✓
"	2403	2405	T-1 ✓
"	2406	2403	T-1 ✓
"	2409	2403	T-1 ✓
"	2403	2409	T-1 ✓
"	2072	1966	T-1 ✓
"	1109	1108	T-1 ✓
"	2482	1001	T-1 ✓
Yadkin	1335	1334	T-1 ✓
"	1341	1334	T-1 ✓
"	1126	1136	T-1 ✓
"	1138	1136	T-1 ✓
"	1598	1597	T-1 ✓
"	1511	1518	T-1 ✓
"	1517	1518	T-1 ✓
Burke	1158	1124	T-1 ✓