

DIVISION - 6

**LOCATION: I-95 WELCOME CENTER-NORTH BOUND
ROWLAND – ROBESON COUNTY**

MISCELLANEOUS

FACILITY COORDINATOR:

JAMES BARNES

558 GILLESPIE ST. – FAYETTEVILLE – 28301
CR#14-55-24 TEL# 910-437-2611 FAX# 910-437-2577

78-25-09 – WELCOME CENTER BUILDING

78-25-10 – WELCOME CENTER RESTROOMS

78-25-11 – REST AREA STORAGE BUILDING #1


78-25-12 – REST AREA STORAGE BUILDING #2



**WELCOME CENTER
FA# 78-25-09**



**WELCOME CENTER RESTROOMS
FA# 78-25-10**



REST AREA STORAGE BUILDING #1
FA# 78-25-11



**REST AREA STORAGE BUILDING
FA# 78-25-12**

**PICTURES
OF
ROBESON COUNTY
I-95 WELCOME CENTER
NORTHBOUND
ROWLAND, NC**

#78-25

DIVISION - 6

**LOCATION: I-95 WELCOME CENTER-NORTH BOUND
ROWLAND – ROBESON COUNTY**

MISCELLANEOUS

FACILITY COORDINATOR:

JAMES BARNES

558 GILLESPIE ST. – FAYETTEVILLE – 28301
CR#14-55-24 TEL# 910-437-2611 FAX# 910-437-2577

78-25-09 – WELCOME CENTER BUILDING

78-25-10 – WELCOME CENTER RESTROOM BUILDING

78-25-11 – REST AREA STORAGE BUILDING #1


78-25-12 – REST AREA STORAGE BUILDING #2



**WELCOME CENTER
FA# 78-25-09**



**WELCOME CENTER RESTROOM BUILDING
FA# 78-25-10**



REST AREA STORAGE BUILDING #1
FA# 78-25-11



REST AREA STORAGE BUILDING #2
FA# 78-25-12

**I-95 WELCOME CENTER
NORTHBOUND
ROWLAND, NC**

#78-25

DIVISION - 6

**LOCATION: I-95 WELCOME CENTER-NORTH BOUND
ROWLAND – ROBESON COUNTY**

MISCELLANEOUS

FACILITY COORDINATOR:

JAMES BARNES

558 GILLESPIE ST. – FAYETTEVILLE – 28301
CR#14-55-24 TEL. # 910-437-2611 FAX# 910-437-2577

78-25-08 – VENDING MACHINE BUILDING

78-25-09 – WELCOME CENTER BUILDING

78-25-10 – WELCOME CENTER RESTROOMS

78-25-11 – REST AREA STORAGE BUILDING #1

78-25-12 – REST AREA STORAGE BUILDING #2



STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION

MICHAEL F. EASLEY
GOVERNOR

LYNDO TIPPETT
SECRETARY

February 21, 2005

MEMORANDUM

TO: James Barnes Courier No: 14/ 55/ 24
Facility Coordinator

FROM: Sandi Massello, Program Assistant
General Services
Transportation Building – Room #522
Raleigh
1525 MSC

SUBJECT: Facility Asbestos Notification Forms For Complex No:78- 25

Robeson County, MISCELLANEOUS- I-95 Welcome Center - Northbound

Attached are the original signed Asbestos Notification Form(s) for you to review and administer the Form(s) with employees, contractors, or contract employees performing facility related activities at the above noted location. Also, attached is a cover sheet listing all buildings that you are the Facility Coordinator. For the cover sheet to be used as "Acknowledgment of Notification", all buildings listed must be reviewed with employee, contractor, or contract employee.

If you have anyone refusing to sign the 1001S Form or the 1001C Form please have witnessed by two people and so noted on the Form. Make as many copies as necessary to have signed for "Acknowledgment of Notification". Return the fully executed Forms to this office (address above) and keep a copy for your file. If you need orientation on reviewing and administering the Form please contact me at (919) 715-0403 Ext. - 219 or the Division Safety Engineer.

It is required that employees watch the "Understanding Asbestos in the Workplace" Video as part of your Safety Program. The video may be scheduled and obtained through DOT Safety and Loss Control at (919) 250-4200.

SJM
Attachment

MAILING ADDRESS:
SANDRA MASSELLO, PROGRAM. ASST.
GENERAL SERVICES ADMINISTRATION
1525 MAIL SERVICE CENTER
RALEIGH, NC 27699-1525

TELEPHONE: 919-715-0403 EXT. 219
FAX: 919-715-0399
WEBSITE
smassello@dot.state.nc.us

LOCATION:
Transportation Building
1 South Wilmington Street
Raleigh, NC
State Courier: 51-31-00



**North Carolina Department of Transportation
COMPLEX COVER SHEET
FACILITY ASBESTOS NOTIFICATION**

FORM 1001C

Effective 4-1-97

Revised 1-30-03

Part I. NOTIFICATION

The North Carolina Department of Transportation is hereby notifying you that the buildings listed below have been tested for the presence of asbestos-containing materials (ACM). A survey report and the 1001S forms for each building listed is to be reviewed with you by the designated Facility Coordinator. This will be on file and may be requested by contacting the NC DOT Asbestos Program Manager at (919) 715-0403 EXT.- 217.

Part II. FACILITY INFORMATION

1. Facility Name:	I-95 WELCOME CENTER - NORTHBOUND - ROWLAND, NC
2. Facility - FA# / County / Unit	#78-25 / CUMBERLAND / MISCELLANEOUS

Part III. BUILDINGS COVERED BY THIS SHEET:

BUILDING NAME	FA#	BUILDING NAME	FA#
VENDING MACHINE BLDG.	78-25-08		
WELCOME CENTER BUILDING	78-25-09		
WELCOME CENTER RESTROOMS	78-25-10		
REST AREA STORAGE BLDG. #1	78-25-11		
REST AREA STORAGE BLDG. #2	78-25-12		

Part IV. ASBESTOS MANAGEMENT CERTIFICATION

Asbestos Management Planner (Signature) <i>Terry F. Russell, Sr. (Sjm)</i>	Accreditation Number 20641	Date 2/19/07	Phone Number 919-715-9344
---	--------------------------------------	------------------------	-------------------------------------

Part V. ACKNOWLEDGMENT OF NOTIFICATION

Name (Please Print Clearly)	Company	Company Phone Number
Signature:	Date:	

NOTE:
DO NOT remove any tags or labels from items labeled as ACM. If you must post any warning labels in association with your work, please remove immediately upon completion of work. If your work requires lockout/tagout of energy sources, please make sure the facility coordinator, for this facility, is fully aware of the extent of your activities. Your safety and health, while visiting our facility, is our paramount concern.



**North Carolina Department of Transportation
FACILITY ASBESTOS NOTIFICATION**

Form 1001S

Effective 8-1-96
Revised 8-21-96
Revised 1-23-03

Part I. NOTIFICATION

The North Carolina Department of Transportation is hereby notifying you that the building listed below has been tested for the presence of asbestos-containing materials (ACM). A survey report is on file and may be requested by contacting the NC DOT Asbestos Program Manager at (919) 715-0403 EXT. 217.

Part II. FACILITY INFORMATION

1. Facility Name/Identification Number:	WELCOME CENTER - FA# 78-25-09
2. Facility Address:	WELCOME CENTER I-95 NORTHBOUND - ROWLAND, NC

Part III. ASBESTOS STATUS:

<input checked="" type="radio"/>	1. No asbestos containing building material (ACBM) was located by asbestos inspection dated MAY 8, 1997
<input type="radio"/>	2. This building contains asbestos as follows: (Specify locations)
	Ceiling Tile/Panels/Areas Above the Ceiling: _____
	Floor Materials: _____
	Wall Board or Panels: _____
	Surfacing Material: _____
	Thermal Insulation: _____
	Other: (Describe) _____

Part IV. ASBESTOS MANAGEMENT CERTIFICATION

Asbestos Management Planner (Signature)	Accreditation Number	Date	Phone Number
<i>Terry F. Russell, Sr. (S/M)</i>	20641	2/21/05	919-715-0403 EXT.-217

Part V. ACKNOWLEDGMENT OF NOTIFICATION

Name (Please Print Clearly)	Company	Company Phone Number
Signature		Date

NOTE:

DO NOT remove any tags or labels from items labeled as ACM. If you must post any warning labels in association with your work, please remove immediately upon completion of work. If your work requires lockout/tagout of energy sources, please make sure the facility coordinator, for this facility, is fully aware of the extent of your activities. Your safety and health, while visiting our facility, is our paramount concern.



**North Carolina Department of Transportation
FACILITY ASBESTOS NOTIFICATION**

Form 1001S

Effective 8-1-96
Revised 8-21-96
Revised 1-23-03

Part I. NOTIFICATION

The North Carolina Department of Transportation is hereby notifying you that the building listed below has been tested for the presence of asbestos-containing materials (ACM). A survey report is on file and may be requested by contacting the NC DOT Asbestos Program Manager at (919) 715-0403 EXT. 217.

Part II. FACILITY INFORMATION

1. Facility Name/Identification Number:	WELCOME CENTER ESTROOM BUILDING - FA# 78-25-10
2. Facility Address:	WELCOME CENTER I-95 NORTHBOUND - ROWLAND, NC

Part III. ASBESTOS STATUS:

<input checked="" type="radio"/>	1. No asbestos containing building material (ACBM) was located by asbestos inspection dated MARCH 17,1999 - NEW CONSTRUCTION
<input type="radio"/>	2. This building contains asbestos as follows: (Specify locations)
	Ceiling Tile/Panels/Areas Above the Ceiling: _____
	Floor Materials: _____
	Wall Board or Panels: _____
	Surfacing Material: _____
	Thermal Insulation: _____
	Other: (Describe) _____

Part IV. ASBESTOS MANAGEMENT CERTIFICATION

Asbestos Management Planner (Signature)	Accreditation Number	Date	Phone Number
<i>Terry F. Russell, Sr. (SJM)</i>	20641	2/21/05	919-715-0403 EXT.-217

Part V. ACKNOWLEDGMENT OF NOTIFICATION

Name (Please Print Clearly)	Company	Company Phone Number
Signature		Date

NOTE:

DO NOT remove any tags or labels from items labeled as ACM. If you must post any warning labels in association with your work, please remove immediately upon completion of work. If your work requires lockout/tagout of energy sources, please make sure the facility coordinator, for this facility, is fully aware of the extent of your activities. Your safety and health, while visiting our facility, is our paramount concern.



**North Carolina Department of Transportation
FACILITY ASBESTOS NOTIFICATION**

Form 1001S

Effective 8-1-96
Revised 8-21-96
Revised 1-23-03

Part I. NOTIFICATION

The North Carolina Department of Transportation is hereby notifying you that the building listed below has been tested for the presence of asbestos-containing materials (ACM). A survey report is on file and may be requested by contacting the NC DOT Asbestos Program Manager at (919) 715-0403 EXT. 217.

Part II. FACILITY INFORMATION

1. Facility Name/Identification Number:	REST AREA STORAGE BUILDING #1 - FA# 78-25-11
2. Facility Address:	WELCOME CENTER I-95 NORTHBOUND - ROWLAND, NC

Part III. ASBESTOS STATUS:

<input checked="" type="radio"/>	1. No asbestos containing building material (ACBM) was located by asbestos inspection dated APRIL 11, 2000
<input type="radio"/>	2. This building contains asbestos as follows: (Specify locations)
	Ceiling Tile/Panels/Areas Above the Ceiling: _____
	Floor Materials: _____
	Wall Board or Panels: _____
	Surfacing Material: _____
	Thermal Insulation: _____
	Other: (Describe) _____

Part IV. ASBESTOS MANAGEMENT CERTIFICATION

Asbestos Management Planner (Signature)	Accreditation Number	Date	Phone Number
<i>Terry J. Russell, Sr. (Sym)</i>	20641	2/21/05	919-715-0403 EXT.-217

Part V. ACKNOWLEDGMENT OF NOTIFICATION

Name (Please Print Clearly)	Company	Company Phone Number
Signature	Date	

NOTE:

DO NOT remove any tags or labels from items labeled as ACM. If you must post any warning labels in association with your work, please remove immediately upon completion of work. If your work requires lockout/tagout of energy sources, please make sure the facility coordinator, for this facility, is fully aware of the extent of your activities. Your safety and health, while visiting our facility, is our paramount concern.



**North Carolina Department of Transportation
FACILITY ASBESTOS NOTIFICATION**

Form 1001S

Effective 8-1-96
Revised 8-21-96
Revised 1-23-03

Part I. NOTIFICATION

The North Carolina Department of Transportation is hereby notifying you that the building listed below has been tested for the presence of asbestos-containing materials (ACM). A survey report is on file and may be requested by contacting the NC DOT Asbestos Program Manager at (919) 715-0403 EXT. 217.

Part II. FACILITY INFORMATION

1. Facility Name/Identification Number:	REST AREA STORAGE BUILDING #2 - FA# 78-25-12
2. Facility Address:	WELCOME CENTER I-95 NORTHBOUND - ROWLAND, NC

Part III. ASBESTOS STATUS:

<input checked="" type="radio"/>	1. No asbestos containing building material (ACBM) was located by asbestos inspection dated APRIL 11, 2000
<input type="radio"/>	2. This building contains asbestos as follows: (Specify locations)
	Ceiling Tile/Panels/Areas Above the Ceiling: _____
	Floor Materials: _____
	Wall Board or Panels: _____
	Surfacing Material: _____
	Thermal Insulation: _____
	Other: (Describe) _____

Part IV. ASBESTOS MANAGEMENT CERTIFICATION

Asbestos Management Planner (Signature)	Accreditation Number	Date	Phone Number
<i>Terry F. Russell, Sr. (Spm)</i>	20641	2/21/05	919-715-0403 EXT.-217

Part V. ACKNOWLEDGMENT OF NOTIFICATION

Name (Please Print Clearly)	Company	Company Phone Number
Signature	Date	

NOTE:

DO NOT remove any tags or labels from items labeled as ACM. If you must post any warning labels in association with your work, please remove immediately upon completion of work. If your work requires lockout/tagout of energy sources, please make sure the facility coordinator, for this facility, is fully aware of the extent of your activities. Your safety and health, while visiting our facility, is our paramount concern.



Customer: CONTAMINANT CONTROL (344)
Address: 708 Martin Luther King Dr
Thomasville, NC 27360

Order #:	476878
-----------------	--------

Received 06/10/22
Analyzed 06/13/22
Reported 06/13/22

Attn:

Project: Vending Building ACM Survey
Location: Rowland
Number: 25275

PO Number: 25275

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
476878-001	06/09/22	25275-01	Old Inner Rf/Attic New Rf		

Layer 1: Felt Paper Black, Fibrous	No Asbestos Detected	65% CELLULOSE FIBER 15% MINERAL/GLASS WOOL 20% NON FIBROUS MATERIAL
---------------------------------------	----------------------	---

476878-002	06/09/22	25275-02	Old Inner Rf/Attic New Rf		
-------------------	----------	----------	---------------------------	--	--

Layer 1: Shingle Black, Bituminous/Granular	No Asbestos Detected	5% CELLULOSE FIBER 5% MINERAL/GLASS WOOL 90% NON FIBROUS MATERIAL
--	----------------------	---

Sample was inhomogenous, subsamples of each component were analyzed separately.

476878-003	06/09/22	25275-03	Mechanical Rm Doors		
-------------------	----------	----------	---------------------	--	--

Layer 1: Caulking Gray, Soft	No Asbestos Detected	100% NON FIBROUS MATERIAL
---------------------------------	----------------------	---------------------------

476878-004	06/09/22	25275-04	Vending Machine Rm Front		
-------------------	----------	----------	--------------------------	--	--

Layer 1: Caulking Brown, Soft	No Asbestos Detected	100% NON FIBROUS MATERIAL
----------------------------------	----------------------	---------------------------

476878-005	06/09/22	25275-05	Exterior Roof		
-------------------	----------	----------	---------------	--	--

Layer 1: Felt Paper Black, Fibrous	No Asbestos Detected	65% CELLULOSE FIBER 15% MINERAL/GLASS WOOL 20% NON FIBROUS MATERIAL
---------------------------------------	----------------------	---

476878-006	06/09/22	25275-06	Exterior Roof		
-------------------	----------	----------	---------------	--	--

Layer 1: Shingle Black, Bituminous/Granular	No Asbestos Detected	5% CELLULOSE FIBER 5% MINERAL/GLASS WOOL 90% NON FIBROUS MATERIAL
--	----------------------	---

Sample was inhomogenous, subsamples of each component were analyzed separately.

476878-007	06/09/22	25275-07	Roof Standalone Shelter		
-------------------	----------	----------	-------------------------	--	--

Layer 1: Shingle Black, Bituminous/Granular	No Asbestos Detected	5% CELLULOSE FIBER 5% MINERAL/GLASS WOOL 90% NON FIBROUS MATERIAL
--	----------------------	---

Sample was inhomogenous, subsamples of each component were analyzed separately.

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.

Project: Vending Building ACM Survey
Location: Rowland
Number: 25275

PO Number: 25275

Method: EPA 600/R-93/116 & 40 CFR App. E Sub. E Pt. 763

PLM Analysis

Sample ID	Collected	Cust. ID	Location	Asbestos Fibers	Other Materials
-----------	-----------	----------	----------	-----------------	-----------------

EPA Regulatory Limit: 1%

Total layers analyzed on order: 7

476878-06/13/22 01:17 PM



Analyst **Mohammed Hashim**



Reviewed By: **Senhory Abdellatif**
Analyst

Reporting Limit: 1% Gravimetrically Reduced Reporting Limit: 0.01% PLM analysis is based on Visual Estimation and NESHAP recommends that any friable sample with an asbestos content less than 10 percent be verified by Point Count or TEM Analysis. The EPA recommends that any attic loose fill vermiculite should be treated as asbestos containing material. This report must not be reproduced except in full with the approval of the laboratory. The test results apply to the sample as received.