

**Cutting and Removal of**  
**Vegetation at Bridge,**  
**Culvert, and Pipe**  
**Locations**

**Examples of before and after pictures**

**Before culvert clean up on I-95 SBL at MM 136.5**



## After culvert clean up on I-95 at mm 136.5



# Before culvert clean up on I-95 at mm 136.5



# After culvert clean up on I-95 SBL at mm 136.5



**Before clean up on Bridge #261 at US 264 EBL at mm 45.56 over Contentnea Creek**



**After clean up on Bridge #261 on US 264 EBL at mm 45.56 over Contentnea Creek**



**Before clean up on Bridge #261 on US 264 EBL at mm 45.56 over Contentnea  
Creek**





**After clean up on US 264 EBL at mm 45.56 over Contentnea  
Creek**



**Before clean up on Bridge #225 on US 264 EBL at mm 55.0 – SR 1526 overpass**



**After clean up at Bridge #225 on US 264 EBL at mm 55.0 – SR 1526 overpass**



**Before clean up on Bridge #225 on US 264 EBL at at mm 55.0 – SR 1526  
overpass**



**After clean up at Bridge #225 on US 264 EBL at mm 55.0 – SR 1526 overpass**



**Before clean up on Bridge #47 on US 117 Alt. - .57 miles south of US301  
over RR**



**After clean up on Bridge #47 at US 117 Alt. - .57 miles south of US 301 over  
RR**



**Before clean up Bridge #47 on US 117 Alt. - .57 miles south of US 301 over  
RR**





**After clean up on Bridge #47 at US 117 Alt. - .57 miles south of US 301 over  
RR**



**Before clean up on Bridge #47 at US 117 Alt. - .57 miles south of US 301 over  
RR**



**After clean up on Bridge #47 at US 117 Alt. - .57 miles south of US 301 over  
RR**



**Before clean up at culvert on US 117 Alt. – 264'ft south of US 301**



**After clean up at culvert on US 117 Alt. – 264'ft south of US 301**



**Before clean up at culvert on US 117 Alt. – 264'ft south of US 301**



**After clean up at culvert on US 117 Alt. – 264'ft south of US 301**



**After clean up at culvert on US 117 Alt. – 264'ft south of US 301**





**Before clean up on Bridge #107 on I-95 SBL @ MM 98 over RR**



**After clean up on Bridge #107 on I-95 SBL @ MM 98 over RR**



## Example of Height of Vegetation



**Before median clean up on I-795 Bridge in Wayne County**



**After median clean up on I-795 Bridge in Wayne County**



**Outside before clean up on I-795 Bridge in Wayne County**



**Outside after clean up on I-795 Bridge in Wayne County**



**Outside before clean up on I-795 Bridge in Wayne County**





**Outside after clean up on I-795 Bridge in Wayne County**



**Before Concrete Slope Protection on US 264**



## Before Concrete Slope Protection on US 264



**After Concrete Slope Protection on US 264**



**Before slope clean up on Bridge #107 on I-95 SBL @ MM 98 over RR**



**After slope clean up on Bridge #107 on I-95 SBL @ MM 98 over RR**

