STATE	STATE PROJECT REFERENCE NO.	SHEERT NO.	TOTAL SHEETS
NC	17BP.8.R.23	1A	14

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS
GEOTECHNICAL ENGINEERING UNIT

STRUCTURE SUBSURFACE INVESTIGATION

PROJECT_	17BP.8.R.2	3	
COUNTY_	RANDOLPH		
	DESCRIPTION _	REPLACE	STRUCTURE
	46 ON SR 1179		
CREEK			
SITE DESC	RIPTION PROP	POSED BRI	DGE ON
	OVER LANIERS		

CAUTION NOTICE

THE SUBSURFACE INFORMATION AND THE SUBSURFACE INVESTIGATION ON WHICH IT IS BASED WAS MADE FOR THE PURPOSE OF STUDY, PLANNING AND DESIGN, AND NOT FOR CONSTRUCTION OR PAY PURPOSES. THE VARIOUS FIELD BORING LOGS, ROCK CORES, AND SOIL TEST DATA AVAILABLE MAY BE REVIEWED OR INSPECTED IN RALEIGH BY CONTACTING THE N. C. DEPARTMENT OF TRANSPORTATION, GEOTECHNICAL UNIT © (919) 250–4088. NEITHER THE SUBSURFACE PLANS AND REPORTS, NOR THE FIELD BORING LOGS, ROCK CORES, OR SOIL TEST DATA IS PART OF THE CONTRACT.

GENERAL SOIL AND ROCK STRATA DESCRIPTIONS AND INDICATED BOUNDARIES ARE BASED ON A GEOTECHNICAL INTERPRETATION OF ALL AVAILABLE SUBSURFACE DATA AND MAY NOT NECESSARILY REFLECT THE ACTUAL SUBSURFACE CONDITIONS BETWEEN BORINGS OR BETWEEN SAMPLED STRATA WITHIN THE BOREHOLE. THE LABORATORY SAMPLE DATA AND THE IN STU (IN-PLACE) TEST DATA CAN BE RELIED ON ONLY TO THE DEGREE OF RELIABILITY INHERENT IN THE STANDARD TEST METHOD. THE OBSERVED WATER LEVELS OR SOIL MOISTURE CONDITIONS INDICATED IN THE SUBSURFACE INVESTIGATIONS ARE AS RECORDED AT THE TIME OF THE INVESTIGATION. THESE WATER LEVELS OR SOIL MOISTURE CONDITIONS MAY VARY CONSIDERABLY WITH TIME ACCORDING TO CLIMATIC CONDITIONS INCLUDING TEMPERATURES, PRECEPITATION AND WIND, AS WELL AS OTHER NON-CLIMATIC FACTORS.

THE BIDDER OR CONTRACTOR IS CAUTIONED THAT DETAILS SHOWN ON THE SUBSURFACE PLANS ARE PRELIMINARY ONLY AND IN MANY CASES THE FINAL DESIGN DETAILS ARE DIFFERENT. FOR BIDDING AND CONSTRUCTION PURPOSES, REFER TO THE CONSTRUCTION PLANS AND DOCUMENTS FOR FINAL DESIGN INFORMATION ON THIS PROJECT. THE DEPARTMENT DOES NOT WARRANT OR GUARANTEE THE SUFFICIENCY OR ACCURACY OF THE INVESTIGATION MADE, NOR THE INTERPRETATIONS MADE OR OPINION OF THE DEPARTMENT AS TO THE TYPE OF MATERIALS AND CONDITIONS TO BE ENCOUNTERED. THE BIDDER OR CONTRACTOR IS CAUTIONED TO MAKE SUCH INDEPENDENT SUBSURFACE INVESTIGATIONS AS HE DEEMS NECESSARY TO SATISFY HIMSELF AS TO CONDITIONS TO BE ENCOUNTERED ON THIS PROJECT. THE CONTRACTOR SHALL HAVE NO CLAIM FOR ADDITIONAL COMPRENSATION OR FOR AN EXTENSION OF TIME FOR ANY REASON RESULTING FROM THE ACTUAL CONDITIONS ENCOUNTERED AT THE SITE DIFFERING FROM THOSE INDICATED IN THE SUBSURFACE INFORMATION.

NOTE — THE INFORMATION CONTAINED HEREIN IS NOT IMPLIED OR GUARANTEED BY THE N. C. DEPARTMENT OF TRANSPORTATION AS BEING ACCURATE NOR IT IS CONSIDERED TO BE PART OF THE PLANS, SPECIFICATIONS, OR CONTRACT FOR THE PROJECT.

NOTE — BY HAVING REQUESTED THIS INFORMATION THE CONTRACTOR SPECIFICALLY WAIVES ANY CLAIMS FOR INCREASED COMPENSATION OR EXTENSION OF TIME BASED ON DIFFERENCES BETWEEN THE CONDITIONS INDICATED HEREIN AND THE ACTUAL CONDITIONS AT THE PROJECT SITE.

INVESTIGATED DI	J. WILLIAMSON L. CAMPOS	CAROLLINIA CAROLLINIA
SUBMITTED BYS&ME, INC	K. HILL C. ODOM	SEAL 031013 4: 1914
	J. JACKSON	SEAL ASINE PRINCIPLE SEAL
-		ART S. MILLING

STATE	STATE PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
NC	17BP.8.R.23	1B	14

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS
GEOTECHNICAL ENGINEERING UNIT

STRUCTURE SUBSURFACE INVESTIGATION

PROJECT _____17BP.8.R.23

COUNTY _____RANDOLPH

PROJECT DESCRIPTION ___REPLACE STRUCTURE
NO. 750346 ON SR 1179 OVER LANIERS

CREEK

SITE DESCRIPTION ___PROPOSED BRIDGE ON
SR 1179 OVER LANIERS CREEK

TABLE OF CONTENTS

NCDOT Geotechnical Unit Soil and Rock Classification Sheet

Sheets 2A & 2B

Site Vicinity Map

Sheet 3

Field Exploration Plan

Sheet 4

Test Boring Logs

Sheets 5 - 8

Core Photographs

Sheets 9 - 10

Site Photographs

Sheets 11 - 14

STATE	STATE PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
NC	17BP.8.R.23	2A	14

NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS GEOTECHNICAL UNIT SOIL AND ROCK LEGEND, TERMS, SYMBOLS, AND ABBREVIATIONS

				SOIL	DES	CRIP	MOIT	1								RADA			
WHICH CAN 100 BLOWS CLASSIFICATI	SIDERED TO E BE PENETRAT PER FOOT AC ION IS BASED	ED WIT CORDIN	H A CONT IG TO STA IE AASHTI	inuous Indard F D System	FLIGHT PENETRA 1 AND 1	POWER ATION TO BASIC D	AUGER EST (A ESCRIF	R, AND ASHTO PTIONS	WHICH T206, GENER	YIELDS LESS ASTM D-158 ALLY SHALL	THAN B6), SOIL INCLUDE;		WELL GRADED— INDICATES A GOUNIFORM— INDICATES THAT SOIL POORLY GRADED INDICATES A MID	KTURE OF	UNIFORM	PARTICLE	S OF TWO OR MO		
CONSISTENC	Y, COLOR, TE OGICAL COMP	XTURE,	MOISTURE	, AASHT	O CLAS	SIFICATI	ON, At	ND OTH	er pei	RTINENT FACT	TORS SUCH		THE ANGULARITY OR ROUNDNE				OF GRAINS SIGNATED BY THE	TERMS;	ANGULAR,
	VERY STIFF	, GRAY	SILTY CLAY,	MOIST W	TH INTERE	EDDED FI	ne sand	LAYERS	HIGHLY	PLASTIC, A-7	-6		SUBANGULAR, SUBROUNDED, OF	ROUNDED	ρ.				
05115011			GEND		AAS					TION			MINERALOGICAL COMPOSITION MINERAL NAMES SUCH AS QUARTZ, FELDSPAR, MICA, TALC, KAOLIN, ETC. ARE USED IN DESCRIPTIONS						
GENERAL CLASS.	(≤35	% PAS	MATERIA SING #2	00)		(> 355	FASS	iateria Sing #2	00)	L .	NIC MATER		WHENEVER THEY ARE CONSIDER		NIFICANCE			USED II	1 DESCRIPTIONS
GROUP CLASS.	A-1-a A-1-b	A-3	A-2-4 A-	A-2	6 4_2_7	A-4	A-5	A-6	A-7-5	A-1, A-2 A-3	A-4, A-5 A-6, A-7		SLIGHTLY COMPRESSI	RIF	COM	PRESS	IBILITY LIQUID LIMIT L	FSS THA	IN 30
SYMBOL	000000000000000000000000000000000000000						14.7		A-7-6				MODERATELY COMPRISIBLE HIGHLY COMPRESSIBLE	essible			LIQUID LIMIT 3	1-50	
% PASSING	0000000000	******	AND DESCRIPTION	CTESSES N. N.	- X:X:X:	100000000000000000000000000000000000000	SCHOOL S				SILT-	<u> </u>					F MATERIAL		
# 40	50 MX 30 MX 50 MX 15 MX 25 MX		35 MX 35	MX 35 M	X35 MX	36 MN	36 MN	36 MN	36 MN	GRANULAR SOILS	CLAY	MUCK, PEAT	ORGANIC MATERIAL TRACE OF ORGANIC MATTER	GRANULA SOILS 2 - 3%	3	F-CLAY SOILS - 5%		ACE	MATERIAL 1 - 10%
LIQUID LIMIT Plastic index	e uv		40 MX 41								WITH		LITTLE ORGANIC MATTER MODERATELY ORGANIC	3 - 5% 5 - 10	% 12	- 12% - 20%	LIT SO		10 - 20% 20 - 35%
GROUP INDEX	6 MX	N.P. 0	10 MX 10	-	NII MN MX	-	_	11 MN 16 MX				HIGHLY ORGANIC	HIGHLY ORGANIC	>10%		20%		HLY	35% AND ABOVE
USUAL TYPES										AMOUN ORGAN	ITS OF	SOILS	✓ WATER LI	EVEL IN B			WATER ATELY AFTER DR	ILLING.	
	Gravel and Sand	FINE SAND		DR CLAY		SIL		SOIL		MATTER			STATIC W	ATER LEV	EL AFTER	<u>24</u>	HOURS.		
GEN. RATING AS A	EXC	ELLEN	T TO GO	DD D		F	AIR T	O POO	R	FAIR TO POOR	POOR	UNSUITABLE	HC PERCHED		SATURATE	D ZONE	OR WATER BEAR	ING STR	MATA
SUBGRADE	DI	OF	A-7-5	≪ 1.	- 30	. PI	OF A	_7_6	+	L. – 30			O 000	OR SEEPA	GE				
		. 01		SISTE		OR I	DEN:	SENE	SS					MIS	SCELLA	NEOU	S SYMBOLS		
PRIMARY	SOIL TYPE	0	OMPACTN CONSIST		PI	ENETRA	TION R		RD ICE	COMPRE	OF UNCONF SSIVE STRI ONS/FT2)	NGTH	ROADWAY EMBANK WITH SOIL DESCRII			SPT DPT VET	OPT DMT TEST BORIN	IG	SAMPLE
GENER	ALLY	+	VERY LO	OSE			N-VAL <4	.UE)		(1)	UN3/F12)	<u> </u>	SOIL SYMBOL	FIION		О	AUGER BORING		DESIGNATIONS
GRANL	JLAR		LOOSE MEDIUM				4 TO 0 TO				N/A		↓	THER THAI	N	Ψ	ACOLIN DOMINO		S - BULK SAMPLE SS - SPLIT SPOON
MATER (NON-	-COHESIVE)		DENSE VERY DE				50 TO >50	50					ARTIFICIAL FILL OF ROADWAY EMBANK		-	φ.	CORE BORING		SAMPLE
		+	VERY SC	FT			<2		-		<0.25		— INFERRED SOIL BO	UNDARIES	,	Ô	MONITORING WEL		ST - SHELBY TUBE SAMPLE
GENER SILT-C			SOFT MEDIUM	STIFF			2 TO 4 TO				.25 TO 0.5 0.5 TO 1	5	TISINE INFERRED ROCK L	INE		^	PIEZOMETER		RS - ROCK SAMPLE
MATER (COHE			Stiff Very St	FF			8 TO 5 TO				1 TO 2 2 TO 4	2	ALLUVIAL SOIL BO	UNDARY		_	INSTALLATION SLOPE INDICATO		RT — RECOMPACTED TRIAXIAL SAMPLE
			HARD				>30				>4		25/025 DIP/DIP DIRECTION ROCK STRUCTURES			\bigcirc	INSTALLATION		CBR - CBR SAMPLE
			<u> </u>	XTURI									O SOUNDING ROD			\bigcirc	SPT N-VALUE		
U.S. STD. S OPENING (M				4 1.76	10 2.0	40 0.4:		60 0.25	200 0.07	270 5 0.053			300NDING KOD		ARE	DEVIA	TIONS		
BOULDI		BBLE		RAVEL		COAR			FINE	s '	SILT	CLAY	AR — AUGER REFL	JSAL	ADL) \ L V F	PMT - PRESS	JREMETE	ER TEST
GRAIN I	.) ((MM 305	COB.)	75	GR.)	2.0	(CSE.	SD.)	0.25	(F. SI		(SL.) 0.005	(CL.)	BT — BORING TERI CL. — CLAY	MINATED			SD. – SAND, : SL. – SILT, SI	SANDY	
	N. 12"		3"		2.0			0.23		0.03	0.003		CPT - CONE PENE CSE COARSE	TRATION	TEST		SLI SLIGHTI TCR - TRICON		SAL
			<u>IOIST</u>				ATIC	O NC	F T	ERMS			DMT - DILATOMETE DPT - DYNAMIC P		ON TEST		7 - UNIT V		
	MOISTURE S RBERG LIMIT				MOIS CRIPTI			GUID	FOR	FIELD MOIS	STURE DES	CRIPTION	e - VOID RATIO F FINE				√d - DRY U W - MOISTURE		
					ATURA (SAT.)	TED -				QUID; VERY			FOSS. — FOSSILIFE FRAC. — FRACTURI				V VERY VST - VANE S		
LL PLASTIC	LIQUID	LIMIT	-		JA1.,								FRAGS. — FRAGME MED. — MEDIUM	NTS					
RANGE (PI)				-	WET -	(W)				REQUIRES (IMUM MOIS)			EQU	IPMEN ⁻	T USE	ON	SUBJECT P	ROJEC	T
``" PLL	+ PLAST	IC LIM	т.										DRILL UNITS:	ADVA	NCING TO	OLS:		НАМ	IMER TYPE:
OM SL				- 1	IOIST -	- (M)		SOLID	AT	OR NEAR O	PTIMUM MC	DISTURE	MOBILE B	□	6" CONTIN	iuous fl	IGHT AUGER		AUTOMATIC MANUAL
				- (DRY -	(D)				ADDITIONAL			DIEDRICH D-50	\vdash	8" HOLLO			_	E SIZE:
					<u> ΣΑ Ι</u>	TICIT	Y							\vdash	HARD FAC				-B
						INDEX				DRY STR	ENGTH		CME-550x		TUNGCA		SERIS ADVANCER	=	-N <u>Q2</u>
NONPLASTIC					0-5 6-1		-			VERY I SLIGH			CME-750		TRICONE		* STEEL TEETH	ᆫᅳ	-H
MED. PLAS	TICITY				16-2	5	-			MEDIU	JM		PORTABLE HOIST	1 =	TRICONE		" TUNGCARB.	HAN	ND TOOLS: POST HOLE DIGGER
HIGH PLAS	IIOIT					OLOR				пог	'			$\vdash =$	CORE BIT		•	╽ᆸ	HAND AUGER
DESCRI	DESCRIPTIONS MAY INCLUDE COLOR OR COLOR COMBINATIONS (TAN, RED, YEL-BRN, BLUE-GRAY)							AY)	OTHER		OTHER	3-1/4"	H.S.A.		SOUNDING ROD				
	ERS SUCH A											•	OTHER		OTHER			ᅵᅢ	VANE SHEAR TEST OTHER
													1						

1	STATE	STATE PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
	NC	17BP.8.R.23	2B	14

NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS GEOTECHNICAL UNIT SOIL AND ROCK LEGEND, TERMS, SYMBOLS, AND ABBREVIATIONS


			ROCK	DESCRIPTION		TERMS AND DEFINITIONS		
ROCK LINE SPT REFUS IN NON-CO OF WEATHE	INDICATE AL IS PEI ASTAL PL RED ROC	S THE LEVEL A NETRATION BY AIN MATERIAL, K.	NN MATERIAL THAT AT WHICH NON-CO A SPLIT SPOON S	WHEN TESTED, WOULD YIELD SPT RI ASTAL PLAIN MATERIAL WOULD YIELD AMPLER EQUAL TO OR LESS THAN O TWEEN SOIL AND ROCK IS OFTEN REP	SPT REFUSAL. .1 FOOT PER 60 BLOWS.	ALLUVIUM (ALLUY.) — SOILS WHICH HAVE BEEN TRANSPORTED BY WATER. AQUIFER — A WATER BEARING FORMATION OR STRATA. ARENACEOUS — APPLIED TO ROCKS THAT HAVE BEEN DERIVED FROM SAND OR THAT CONTAIN SAND.		
WEATHERED ROCK (WR)	KIALS AF			LAIN MATERIAL THAT YIELDS SPT N	VALUES > 100 BLOWS	ARGILACEOUS — APPLIED TO ALL ROCKS OR SUBSTANCES COMPOSED OF CLAY MINERALS, OR HAWING A NOTABLE PROPORTION OF CLAY IN THEIR COMPOSITION, AS SHALE, SLATE, ETC. ARTESIAN — GROUND WATER THAT IS UNDER SUFFICIENT PRESSURE TO RISE ABOVE THE LEVEL		
CRYSTALLINE ROCK (CR)				GRAIN IGNEOUS AND METAMORPHIC T REFUSAL IF TESTED. ROCK TYPE SCHIST, ETC.		- AT WHICH IS IS ENCOUNTERED, BUT WHICH DOES NOT NECESSARILY RISE TO OR ABOVE THE GROUND SURFACE. - CALCAREOUS (CALC.) — SOILS WHICH CONTAIN APPRECIABLE AMOUNTS OF CALCIUM CARBONATE.		
NON-CRYSTAL ROCK (NCR)			FINE TO COARSE SEDIMENTARY RO	GRAIN METAMORPHIC AND NON-COA CK THAT WOULD YEILD SPT REFUSAL TE, SLATE, SANDSTONE, ETC.		OCILIVIUM - ROCK FRAGMENTS MIXED WITH SOIL DEPOSITED BY GRAVITY ON SLOPE OR AT BOTTOM OF SLOPE.		
COASTAL PLAI SEDIMENTARY (CP)	N ROCK			SEDIMENTS CEMENTED INTO ROCK, BU COCK TYPE INCLUDES LIMESTONE, SAI		CORE RECOVERY (REC.) — TOTAL LENGTH OF ALL MATERIAL RECOVERED IN THE CORE BARREL DIVIDED BY TOTAL LENGTH OF CORE RUN AND EXPRESSED AS A PERCENTAGE.		
			WE.	ATHERING		DIKE - A TABULAR BODY OF IGNEOUS ROCK THAT CUTS ACROSS THE STRUCTURE OF ADJACENT ROCKS OR CUTS MASSIVE ROCK.		
FRESH	HAMMER	R IF CRYSTALLI	NE.	INTS MAY SHOW SLIGHT STAINING. R		DIP - THE ANGLE AT WHICH A STRATUM OR ANY PLANAR FEATURE IS INCLINED FROM THE HORIZONTAL.		
VERY SLIGHT (V. SLI.)	CRYSTA		KEN SPECIMEN FAC	D, SOME JOINTS MAY SHOW THIN CL E SHINE BRIGHTLY. ROCK RINGS UND		<u>DIP DIRECTION (DIP AZIMUTH)</u> — THE DIRECTION OR BEARING OF THE HORIZONTAL TRACE OF THE LINE OF DIP, MEASURED CLOCKWISE FROM NORTH.		
SLIGHT (SLI.)	ROCK G	ENERALLY FRE	SH, JOINTS STAINE	D AND DISCOLORATION EXTENDS INTO AY. IN GRANITOID ROCKS SOME OCC	CASIONAL FELDSPAR	FAULT — A FRACTURE OR FRACTURE ZONE ALONG WHICH THERE HAS BEEN DISPLACEMENT OF THE SIDES RELATIVE TO ONE ANOTHER PARALLEL TO THE FRACTURE.		
MODERATE				CRYSTALLINE ROCKS RING UNDER H ISCOLORATION AND WEATHERING EFF		FISSILE — A PROPERTY OF SPLITTING ALONG CLOSELY SPACED PARALLEL PLANES. FLOAT — ROCK FRAGMENTS ON SURFACE NEAR THEIR ORIGINAL POSITION AND DISLODGED FROM		
(MOD.)	GRANITO	OID ROCKS, MO	ST FELDSPARS AR	E DULL AND DISCOLORED, SOME SHO D SHOWS SIGNIFICANT LOSS OF STRE	W CLAY. ROCK HAS	PARENT MATERIAL. FLOOD PLAIN (F.P.) - LAND BORDERING A STREAM, BUILT OF SEDIMENTS DEPOSITED BY		
MODERATELY		RESH ROCK. CK EXCEPT QU	ARTZ DISCOLORED	OR STAINED. IN GRANITOID ROCKS,	ALL FELDSPARS DULL	THE STREAM.		
SEVERE AND DISCOLORED AND A MAJORITY SHOW KAOLINIZATION. ROCK SHOWS SEVERE LOSS OF STRENGTH (MOD. SEV.) AND CAN BE EXCAVATED WITH A GEOLOGIST'S PICK. ROCK GIVES "CLUNK" SOUND WHEN STRUCK. IF TESTED, WOULD YELD SPY REFUSAL					ere loss of strength	<u>EORNATION (FM.)</u> — A MAPPABLE GEOLOGIC UNIT THAT CAN BE RECOGNIZED AND TRACED IN THE FIELD.		
SEVERE				OR STAINED. ROCK FABRIC CLEAR	AND EVIDENT BUT REDUCED	JOINT - FRACTURE IN ROCK ALONG WHICH NO APPRECIABLE MOVEMENT HAS OCCURRED.		
(SEV.)	IN STRE	NGTH TO STRO SOME FRAGE	ONG SOIL. IN GRAI MENTS OF STRONG	NITOID ROCKS ALL FELDSPARS ARE N ROCK USUALLY REMAIN.		LEDGE — A SHELF—LIKE RIDGE OR PROJECTION OF ROCK WHOSE THICKNESS IS SMALL COMPARED TO ITS LATERAL EXTENT. LENS — A BODY OF SOIL OR ROCK THAT THINS OUT IN ONE OR MORE DIRECTIONS.		
VERY SEVERE (V. SEV.)	ALL RO	CK EXCEPT QU SS IS EFFECTIV	VELY REDUCED TO	OR STAINED. ROCK FABRIC ELEMEN SOIL STATUS, WITH ONLY FRAGMENTS OF ROCK WEATHERED TO A DEGREE	S OF STRONG ROCK	MOTTLED (MOT.) — IRREGULARLY MARKED WITH SPOTS OF DIFFERENT COLORS. MOTTLING IN SOILS USUALLY INDICATES POOR AERATION AND LACK OF GOOD DRAINAGE. PERCHED WATER — WATER MAINTAINED ABOVE THE NORMAL GROUND WATER LEVEL BY THE PRESENCE OF AN		
			GINAL ROCK FABRIC			INTERVENING IMPERVIOUS STRATUM.		
COMPLETE	SCATTER			NOT DISCERNIBLE, OR DISCERNIBLE (MAY BE PRESENT AS DIKES OR STRI		RESIDUAL SOIL — SOIL FORMED IN PLACE BY THE WEATHERING OF ROCK. ROCK QUALITY DESIGNATION (R.Q.D.) — A MEASURE OF ROCK QUALITY DESCRIBED BY: TOTAL LENGTH OF ROCK SEGMENTS EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY THE TOTAL LENGTH OF CORE RUN A		
			ROCK	HARDNESS		EXPRESSED AS A PERCENTAGE.		
VERY HARD			HED BY KNIFE OR S	SHARP PICK. BREAKING OF HAND SI ISTS PICK.	PECIMENS REQUIRES	SAPROLITE (SAP.) - RESIDUAL SOIL WHICH RETAINS THE RELIC STRUCTURE OR FABRIC OF THE PARENT ROCK.		
HARD	TO DE	TACH HAND SP	PECIMEN.	ONLY WITH DIFFICULTY. HARD HAM		SILL – AN INTRUSIVE BODY OF IGNEOUS ROCK OF APPROXIMATELY UNIFORM THICKNESS AND RELATIVELY THIN COMPARED WITH ITS LATERAL EXTENT, WHICH HAS BEEN EMPLACED PARALLEL TO THE BEDDING OR SCHISTOSITY OF THE INTRUDED ROCKS		
MODERATELY HARD	EXCAV		BLOW OF A GEOL	. GOUGES OR GROOVES TO 0.25 IN OGISTS PICK. HAND SPECIMENS CAR		SLICKENSIDE — POLISHED AND STRIATED SURFACE THAT RESULTS FROM FRICTION ALONG A FAULT OR SUP PLANE.		
MEDIUM HARD	CAN B POINT	E EXCAVATED OF A GEOLOGI	IN SMALL CHIPS T ISTS PICK.	CHES DEEP BY FIRM PRESSURE OF K O PEICES 1 INCH MAXIMUM SIZE BY	HARD BLOWS OF THE	STANDARD PENETRATION TEST (PENETRATION RESISTANCE) (SPT) — NUMBER OF BLOWS (N OR B.P.F.) OF A 140 LB. HAMMER FALLING 30 INCHES REQUIRED TO PRODUCE A PENETRATION OF 1 FOOT INTO SOIL WITH A 2 INCH OUTSIDE DIAMETER SPLIT SPOON SAMPLER. SPT REFUSAL IS LESS THAN 0.1 FOOT PENETRATION WITH 60 BLOWS.		
SOFT	FROM	CHIPS TO SEVI		BY KNIFE OR PICK. CAN BE EXCAV/ ZE BY MODERATE BLOWS OF A PICK ESSURE.		STRATA CORE RECOVERY (SREC.) — TOTAL LENGTH OF STRATA MATERIAL RECOVERED DIVIDED BY TOTAL LENGTH OF STRATUM AND EXPRESSED AS A PERCENTAGE.		
VERY SOFT		RE IN THICKNE		EXCAVATED READILY WITH POINT OF N BY FINGER PRESSURE. CAN BE S		STRATA ROCK QUALITY DESIGNATION (S.R.Q.D.) — A MEASURE OF ROCK QUALITY DESCRIBED BY: TOTAL LENGTH OF ROCK SEGMENTS WITHIN A STRATUM EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY THE TOTAL LENGTH OF STRATA AND EXPRESSED AS A PERCENTAGE.		
FF		RE SPAC	ING	BEDDIN	IG	<u>IOPSOIL (T.S.)</u> — SURFACE SOILS USUALLY CONTAINING ORGANIC MATTER.		
TERM			ACING	<u>TERM</u> VERY THICKLY BEDDED	THICKNESS > 4 FEET	BENCH MARK: RR SPIKE IN 18" OAK TREE		
VERY WIDE		3 TO 10	han 10 feet) feet	THICKLY BEDDED	1.5 - 4 FEET 0.16 - 1.5 FEET	ELEVATION: 383.40'		
MODERATE CLOSE	LY CLOS	E 1 TO 3 0.16 TO		THINLY BEDDED VERY THINLY BEDDED	0.03 - 0.16 FEET			
VERY CLO	SE		IAN 0.16 FEET	THICKLY LAMINATED THINLY LAMINATED	0.008 - 0.03 FEET < 0.008 FEET	NOTES:		
FOR SEDIMENT	ARY ROC	(S. INDURATIO		JRATION IG OF THE MATERIAL BY CEMENTING,	HEAT, PRESSURF, FTC.			
	IABLE	,	RUBBING	WITH FINGER FREES NUMEROUS GRA BLOW BY HAMMER DISINTEGRATES SA	INS;			
мо	MODERATELY INDURATED GRAINS CAN BE SEPARATED FROM SAMPLE WITH STEEL PROBE; BREAKS EASILY WHEN HIT WITH HAMMER.							


GRAINS ARE DIFFICULT TO SEPARATE WITH STEEL PROBE; DIFFICULT TO BREAK WITH HAMMER.

SHARP HAMMER BLOWS REQUIRED TO BREAK SAMPLE; SAMPLE BREAKS ACROSS GRAINS.

INDURATED


EXTREMELY INDURATED





DOT.GDT


NCDOT BORE SINGLE 346.GPJ NC



DOT.GDT

346.GPJ NC


NCDOT BORE SINGLE



WBS	N/A				TIP	17BP	.8.R.23	С	OUNT	Y F	Randolph	GEOLOGIST J. Williamson	_	
SITE	DESCR	RIPTION	Pro	posed Br	idge o	n SR 1	179 Over	Lanie	ers Cr	eek			GROUND	WTR (ft
BORI	NG NO	. EB1-	В		STA	TION	12+79			OF	FSET 13 ft RT	ALIGNMENT -L-	0 HR.	N/A
COLL	AR EL	EV . 38	2.7 ft		тот	AL DE	PTH 21.	1 ft		NC	DRTHING 662,285	EASTING 1,707,794	24 HR.	FIAD
DRILL	RIG/HA	MMER E	FF./DA	TE CME-	55 90%	8/17/20)12				DRILL METHOD 3 1	/4" HSA/NQ2 CORE HAM	MER TYPE AL	utomatic
DRIL	LER C	. Odom	1		STAI	RT DA	TE 07/26	5/12		CC	OMP. DATE 07/26/12	SURFACE WATER DEPTH	I/A	
COR	E SIZE	NQ2			TOT	AL RU	N 9.4 ft							
ELEV (ft)	RUN ELEV (ft)	DEPTH (ft)	RUN (ft)	DRILL RATE (Min/ft)	REC. (ft) %	JN RQD (ft) %	SAMP. NO.	STR REC. (ft) %	RQD (ft) %	L O G	ELEV. (ft)	DESCRIPTION AND REMARKS		DEPTH (f
371												Begin Coring @ 11.7 ft		
370	371.0	11.7	4.4	2:45/1.0	(4.4) 100%	(3.7) 84%		(9.3) 99%	(5.9) 63%		371.0 Gray Metamudstone,	NON-CRYSTALLINE ROCK Fresh to Very Slightly Weathered, Ha	rd to Moderatel	11. y
				3:30/1.0							Weathered, Close to	Moderately Close Fracture Spacing 30° and 2 Joints at 60°	with 26 Joints at	
				3:15/1.0						蘆				
		Ī		3:00/1.0										
	366.6	16.1	5.0	5:00/0.4 3:00/1.0	(4.9)	(2.2)				蓋	-			
365	•	Ť		3:15/1.0	98%	44%				蓋	-			
	-	Ť		3:30/1.0						薹	_			
		t		3:30/1.0							-			
		t		4:00/1.0							-			
	361.6	21.1		4.00/1.0			-				361.6	ted at Elevation 361.6 ft In Non-Cryst	allina Dock	21.
		t									boning remina	(Metamudstone)	alline Rock	
	-	†									1) 3 1/4" H	Hollow Stem Augers Advanced to 11.7	Feet	
		+									2) Standa	ard Penetration Test Refusal at 11.7 NW Casing Advanced to 11.7 Feet	Feet	
		+									4) l	NQ2 Coring From 11.7 to 21.1 Feet 5) Water Used as Coring Fluid		
		+									6) App	proximate Coring Fluid Density 62.4 p	cf	
		1									-			
	_	1									_			
		1									-			
											_			
	,													
	-	Ť									_			
	•	Ť									-			
	•	†									-			
		†									†			
		†									 			
	-	†									-			
		+									-			
		+									-			
		1									-			
		1									_			
	_	1												
		1												
	·													
		T												
	•	Ť									<u> </u>			
		†									-			
	-	†									_			
		†									-			
		+									-			
		+									-			


DOT.GDT

NCDOT BORE SINGLE 346.GPJ NC



346.GPJ NC

NCDOT BORE SINGLE



NBS	N/A				TIP	17BP	.8.R.23	C	DUNT	Y F	Randolph	1	GE	OLOGIST J. Willia	mson		
SITE	DESCR	IPTION	Pro	posed Br	idge o	n SR 1	1179 Ove	Lanie	ers Cr	eek						GROUND W	TR (ft
BORI	NG NO.	EB2-	В		STA	TION	13+69			OF	FSET 8	B ft RT	AL	IGNMENT -L-		0 HR.	N/A
COLL	AR ELI	EV. 38	5.7 ft		тот	AL DE	PTH 20.	2 ft		-		662,375	EA	ASTING 1,707,810		24 HR.	6.5
				TE CME-				-				DRILL METHOD 3			НАММ	ER TYPE Auto	
	LER C						TE 07/2	5/12		co	MP. DA	TE 07/25/12		IRFACE WATER DEF			
	E SIZE				TOTA	AI DII	N 8.5 ft	0/ 12		-		12 01/20/12	00	NI AOL WATER DE	111 14/		
	RUN	· ·		DRILL	REC.	JN		STR	ATA	L							
(ft)	ELEV (ft)	DEPTH (ft)	RUN (ft)	RATE (Min/ft)	REC. (ft) %	RQD (ft) %	SAMP. NO.	REC. (ft) %	RQD (ft) %	Ō	ELEV. (21	DESC	RIPTION AND REMARK	S		EDTU #
074	(11)			(IVIIII/IL)	<u> </u>	%		%	%	۳	ELEV. (1	t)	D-	nin Coninn @ 44.7#		U	EPTH (f
374	374.0	11.7	5.0	3:30/1.0	(5.0)	(2.4)		(1.6)	(0.9)		374.0			gin Coring @ 11.7 ft DN-CRYSTALLINE ROCI			11.
	-	+		3:15/1.0	100%	48%		100%	56%		- 372.4			e, Fresh to Very Slightly se Fracture Spacing with			13.
	-	+		2:15/1.0				(1.8) 100%	(0.0) 0%	薿	_		NO	N-CRYSTALLINE ROC	Κ		
	-	}		2:30/1.0				100 /0	070		370.6			e, Fresh to Very Slightly se Fracture Spacing with			15.
370	_	-		3:15/1.0				(4.1) 100%	(3.8) 93%		_	Bluish Grav Metam		ON-CRYSTALLINE ROCI e, Fresh to Very Slightly		ed Hard Close	
	369.0	16.7	3.5		(2.4)	(2.2)		.0070	0070		_	to Moderately Close	e Fractu	ure Spacing with 5 Joints	at 30° an	nd 1 Joint at 60°	
	-	1	3.5	3:45/1.0	(3.4) 97%	(2.3) 66%					<u> </u>						
		1		3:30/1.0							- 222 -						
	205 -			4:15/1.0				(0.9)	(0.0)		366.5			N-CRYSTALLINE ROC			19.
ł	365.5	20.2		3:45/0.5				90%	_0%_		365.5	Bluish Gray Metamond to Moderately Close	nudston e Fractı	e, Slightly to Moderately ure Spacing with 7 Joints	Weathere at 10-20	ed, Hard, Close of and 1 Joint at	20.
													60°;	; Other Joints Indiscernib at Elevation 365.5 ft In No	le		l
	-	Ī										Boning remiir	nateu a	(Metamudstone)	iri-Ci ystai	IIII ROCK	
	•	Ī									_			v Stem Augers Advanced			
	•	†									_			Penetration Test Refusal Casing Advanced to 11.7		eet	
	-	t									_	4	4) NQ2	Coring From 11.7 to 20.2 Vater Used as Coring Flu	2 Feet		
	-	†									_	6) A _l	pproxin	mate Coring Fluid Density	/ 62.4 pcf	f	
	-	t									_						
	-	+									_						
		+									_						
	-	 									_						
	-	-									_						
	-	-									_						
	-	<u> </u>									_						
		1									_						
	-	1									_						
	•	ľ															
	-	Ī															
	•	†									_						
	-	t									_						
	-	t									-						
	-	<u> </u>									_						
	-	+									_						
		-									_						
	-	ļ									-						
	_	<u> </u>									_						
	-	1									L						
		1															
	•																
	•	Ī															
	-	†									-						
	-	t		1							-						



Project No: 1351-11-343G	Project No: 1351-11-343G										
Site Description: Proposed B	Site Description: Proposed Bridge on SR 1179 over Laniers Creek										
Collar Elev.: 382.7	Core Size: NQ-2	Equipment: CME-55	Geologist. J. Williamson								
Elev. at T.D.: 361.6	Total Depth: 21.1'	Total Run: 9.4'	Date: 7/26/2012								




Box 1 of 1

Top of Box @ 11.7 feet; Bottom of Box @ 21.1 feet



Project No: 1351-11-343G	Project No: 1351-11-343G								
Site Description: Proposed B	Driller. C. Odom								
Collar Elev.: 385.7	Core Size: NQ-2	Equipment: CME-55	Geologist. J. Williamson						
Elev. at T.D.: 365.5	Total Depth: 20.2'	Total Run: 8.5'	Date: 7/25/2012						



Top of Box @ 11.7 feet; Bottom of Box @ 20.2 feet



Photograph No. 1: View looking north up-station from south approach



Photograph No. 2: View looking south down-station from north approach




Photograph No. 3: View looking west upstream from bridge deck



Photograph No. 4: View looking east downstream from bridge deck



Photograph No. 5: View looking south at left side of End Bent 1



Photograph No. 6: View looking south at right side of End Bent 1



Photograph No. 7: View looking north at left side of End Bent 2



Photograph No. 8: View looking north at right side of End Bent 2