


Figure 6  
**BRIDGE DEFICIENCIES**



## ANSON COUNTY

### CTP Analysis and Information

- Bridge Features
- Deficient Bridge
  - Bridge
  - Other Structure
- Other Features
- Study Road



WebAddress



Sheet 3 of 3


Base map date: September 20, 2021

**Legal Disclaimer**

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

**WORKING COPY**  
 Plan Date: March 23, 2022

Figure 6  
**BRIDGE DEFICIENCIES**



**ANSON COUNTY**  
**TOWN OF WADESBORO INSET**  
 CTP Analysis and Information

Bridge Features

- Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road



WebAddress



Sheet 3A of 4  
 Inset A

Base map date: September 20, 2021

**Legal Disclaimer**

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

**WORKING COPY**  
 Plan Date: April 01, 2022