










Figure 2

BRIDGE DEFICIENCIES



FAMPO & CUMBERLAND COUNTY
INSET MAPS
CTP Analysis and Information

Bridge Features

- Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road
-  FAMPO
-  Mid-Carolina RPO



Full report at:
Tinyurl.com/FAMPOCTP



Sheet 1A of 1

Base map date: November 07, 2019

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

Plan Date: April 21, 2021