




Figure 6

BRIDGE DEFICIENCIES

DAVIE YADKIN AND SURRY COUNTIES REGIONAL
CTP Analysis and Information

Bridge Features

- # Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road
- MPO_Name
- Northwest Piedmont RPO

Full report at:
<https://tinyurl.com/DavSurYadRegCTP>

0 1 2 4 6 8 10 12 Miles

Sheet 3 of 3

Base map date: March 13, 2019

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

WORKING COPY
Plan Date: May 27, 2020





Figure 6
BRIDGE DEFICIENCIES

**DAVIE YADKIN AND SURRY COUNTIES REGIONAL
 DAVIE COUNTY TOWNS INSETS
 CTP Analysis and Information**

Bridge Features

- Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road
- MPO_Name
- Northwest Piedmont RPO

Full report at:
<https://tinyurl.com/DavSurYadRegCTP>

0 0.3 0.6
 Miles

**Sheet 3A of 4
 Inset A**

Base map date: March 13, 2019

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

WORKING COPY
 Plan Date: May 28, 2020




Figure 6

BRIDGE DEFICIENCIES



DAVIE YADKIN AND SURRY COUNTIES REGIONAL

YADKIN COUNTY INSET

CTP Analysis and Information

Bridge Features

#

Deficient Bridge

■

Bridge

■

Other Structure

Other Features

—

Study Road

▤

MPO_Name

▤

Northwest Piedmont RPO



Full report at:
<https://tinyurl.com/DavSurYadRegCTP>

00.512345

Miles

Sheet 3A of 4

Inset A

Base map date: March 13, 2019

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

WORKING COPY

Plan Date: May 28, 2020







Figure 6

BRIDGE DEFICIENCIES

DAVIE YADKIN AND SURRY COUNTIES REGIONAL
YADKIN COUNTY TOWNS INSETS
CTP Analysis and Information

Bridge Features

- # Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road
- ▨ MPO_Name
- ▨ Northwest Piedmont RPO

Full report at:
<https://tinyurl.com/DavSurYadRegCTP>

0 0.4 0.8 Miles

Sheet 3A of 4
Inset A


Base map date: March 13, 2019

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

WORKING COPY
Plan Date: May 28, 2020

BRIDGE DEFICIENCIES



WORKING COPY
Plan Date: May 28, 2020







Figure 6

BRIDGE DEFICIENCIES

DAVIE YADKIN AND SURRY COUNTIES REGIONAL
SURRY COUNTY TOWNS INSETS
CTP Analysis and Information

Bridge Features

- # Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road
- MPO_Name
- Northwest Piedmont RPO

Full report at:
<https://tinyurl.com/DavSurYadRegCTP>

0 0.5 1 Miles

Sheet 3A of 4
Inset A

Base map date: March 13, 2019

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

WORKING COPY
Plan Date: May 28, 2020