


Figure 6
BRIDGE DEFICIENCIES



POLK COUNTY
 (Isothermal RPO CTP)

CTP Analysis and Information

Bridge Features

- # Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road



Full report at:
<https://qrco.de/bbAY17>



Sheet 3 of 4

Base map date: March 18, 2018

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.

DRAFT WORKING MAP
 Plan Date: April 07, 2020